WASHINGTON COUNT			
OREGO			
Chadybraak			

ADA Curb Ramp New Construction Inspection Form (Parallel)

OREGON					
Shadybrook	24952.54	Y	orkshire		
North-South Road Name	Project No. Sheet No.	Intersection No.	ast-West R	Road Name See https://www.oregon.gov/odot/Engineering/Doc	
	Calibration Date 1	0/25/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corne Use Washington County corner numbering sys	
R/	Fail				
PL	AMP RUN 1	Pass 5.4 ≤ 2.0% > 2.0		Corner	2
Ramp Style Ru	unning Slope 1			Corner	1
*The passing value for Gutter Flow Slope (GFS)	oss Slope 1	≤ 2.0% > 2.0	% ■	Position 3 2A	
	etectable Warning	N Y N			
Midblock (MB), GFS must be ≤ Slope of the	o Height	0.5 ≤ 1/4" > 1/4	ı" 	1	
Noda, at signalized of official folica (30), dis	_	==,,		3A North	
must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	utter Flow Slope	1.6 ≤ * ■ > *		1	
	urb Running Slope(avg)	6.9 ≤ 8.3% ■ > 8.3	%> 🔲		
*1 If Back of Ramp Obstruction is Yes, turn	ounter Slope (+/-)*2	1.6 ≤ 5.0% > 5.0	0%	1 Ramp 1 Positions	
-	et. warning full width of ramp			Ramp	
—— Clear Space area is the width of Ramp Run 1	AMP RUN 2	Pass	Fail	Position	
	unning Slope 2			PE Stamp (require private developme	
		≤ 8.3%	·% <u> </u>	p. Nate developms	Circy
(inlets, alianment, etc.)	ength 2	5.6 4 ≤ 2.0% > 2.0	% =		
_	oss Slope 2				
R/	AMP RUN 3	Pass	Fail		
Program 3 Program Ru	unning Slope 3	≤ 8.3%	3% ■		
The Run 2	ength 3	5			
Cr	ross Slope 3	5.2 ≤ 2.0% > 2.0	0% ■		
Counter slope TU	JRN SPACE	Pass	Fail	Comments:	
	/idth X	3.65 ≥ 4.0' < 4.0		CRK curb & gutt. No td.	
	ength Y	5.0 ≥ 4.0'*1 ■ < 4.0)'*1		
Tradition (C.C)	ack of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 ■ < 5.0	וי*1		
DECEMBER OF THE SECOND STATE OF THE SECOND S	ope X (Cross Slope 1)	≤ 2.0% > 2.0			
Detectable Warning Surface					
Cross Slope (2.0% max.)	ope Y (Running Slope 1)	5.4 ≤ 2.0% > 2.0)% 🔳		
Running Stope (8.3% max.) Counter Stope (5.0% max.)	IISCELLANEOUS	Pass	Fail	Inspector's Signature Date ((mm/dd/yy
	ear Width (feet)	3.65 ≥ 4.0' < 4.0	0' 🔲	Darrell Wyant 5263	
ln'	tersection Control Type	SY Slope of Rd. 3.6			cation No
Gutter Flow Slope (as directed)	orizontal Gaps	o ≤ 1/2" ■ > 1/2	 2"	3J Consulting	
1.0		, = <u>-</u> , -,		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





