WASHINGTON COUNTY	1
OREGON	,
NW Main	
North-South Road Name	
	PL
	Ramp Sty
*The passing value for Gutter depends on the Intersection C Midblock (MB), GFS must be ≤ Road, at Signalized or Uncontr	Control Type. At a Slope of the
must be ≤ 5.0%, and at Stop	, ,,
or Yield (SY), GFS must be ≤ 2.	0%.

(inlets, alignment, etc.)

*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.

 *2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / $4' \times 4'$ min.)* * If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

Ramp Style

				West F	Road Name See https://www.oregon.gov/odot/Engineering/Documents _RoadwayEng/ADA_ExhibitA.pdf for more corner styles.			
	Calibration Date	7/16/2024 (mm,	/dd/yy)				County corner num	
	RAMP RUN 1	F	Pass	Fail	3	1 11		2
	Running Slope 1	≤ 2.0%	> 2.0%		Corner	F	Corner Positions	1 XX
	Cross Slope 1	≤ 2.0%	> 2.0%		Position	3	5 2	2A
	Detectable Warning	Y	■ N					3
	Lip Height	≤ 1/4"	> 1/4"		(3A	<u> </u>	
	Gutter Flow Slope	7.9 ≤ *	> *			2	North	2
	Curb Running Slope(avg)	4.32 ≤ 8.3%	> 8.3%>			4	Dama	1
	Counter Slope (+/-)*2	^{7.8} ≤ 5.0%	 5.0%		2	12	Ramp 1	
	Det. warning full width of ramp	Y	N		Ramp Position		5	
	RAMP RUN 2		Pass	Fail			PE Stamp	required for
	Running Slope 2	15.4 ≤ 8.3%	> 8.3%					velopment)
	Length 2	20.5						
	Cross Slope 2	≤ 2.0%	2.0%					
	RAMP RUN 3		Pass	Fail				
	Running Slope 3	≤ 8.3%	> 8.3%					
	Length 3							
	Cross Slope 3	≤ 2.0%	= > 2.0%		<u> </u>			
	TURN SPACE Pass			Fail	Comment			
	Width X	4.65 ≥ 4.0'	■ <4.0'		DWS III	D Fails RR 1		
	Length Y	10.15 ≥ 4.0'*1	4.0 '*1					
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	= < 5.0'*1					
	Slope X (Cross Slope 1)	6.4 ≤ 2.0%	> 2.0%					
	Slope Y (Running Slope 1)	3.3 ≤ 2.0%	> 2.0%					
	MISCELLANEOUS	l	Pass	Fail	Inspector's S	ignature		Date (mm/dd/y
	Clear Width (feet)	^{4.65} ≥ 4.0'	< 4.0'		Darrell \	•		52638
	Intersection Control Type	SY Slope of	f Rd. 7.2		Print name o			Certification N
	Horizontal Gaps		> 1/2"	 1/2"	3J Consulti			
					Company/Ag	gency		

NW Lenox



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





