WASHINGTON COUNTY			
OREGON			
NW 309th			
North-South Road Name			

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

	NW 309th	24952.54	Tur	el	
	North-South Road Name	Project No. Sheet No.	Intersection No. East-	-West Road Nar	
		Calibration Date	10/25/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.
	PL	RAMP RUN 1	Pass	Fail 2	2
	Ramp Style	Running Slope 1	≤ 2.0%  > 2.0%	Corne	Corner
*The	passing value for Gutter Flow Slope (GFS)	Cross Slope 1	5.2 ≤ 2.0%  > 2.0%	Positi	on 3 Positions 2A
depe	nds on the Intersection Control Type. At a	Detectable Warning	N Y N		
	lock (MB), GFS must be ≤ Slope of the , at Signalized or Uncontrolled (SU), GFS	Lip Height	0.5 ≤ 1/4" > 1/4"		3A 1
	be ≤ 5.0%, and at Stop	Gutter Flow Slope	5.7 ≤ * > *		North
or Yie	eld (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	≤ 8.3%  ■ > 8.3%>		
	Back of Ramp Obstruction is Yes, turn e length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	7.4 ≤ 5.0%  >  5.0%		4 Ramp 1 Positions
		Det. warning full width of ramp	N Y N	Ramp Positi	92.0
* <sup>2</sup> Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		RAMP RUN 2	Pass	Fail	PE Stamp (required for
	,	Running Slope 2	2.9 ≤ 8.3% ■ > 8.3%		private development)
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2	6.7		
		Cross Slope 2	≥ 2.0%  > 2.0%		
		RAMP RUN 3	Pass	Fail	
		Running Slope 3	11.3 ≤ 8.3% > 8.3%		
7	of hun 3	Length 3	8	_	
7	Fun 2 g	Cross Slope 3	≤ 2.0% > 2.0%		
Counter slope Gutter flow slope		TURN SPACE	Pass	Fail	nents:
	에서 <del>개선</del> 가 문학생으로	Width X	4.1 ≥ 4.0' < 4.0'	No T	d. CRK curb and gutter.
			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	PARALLEL RAMP (PL)	Length Y		<u> </u>	
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1		
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	5.2 ≤ 2.0%  > 2.0%		
	Detectable Warning Surface  Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	≤ 2.0% > 2.0%		
•	Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspect	or's Signature Date (mm/dd/yy)
	Counter Slope (5.0% max.)  Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	4.1 ≥ 4.0' < 4.0'	Darr	ell Wyant 52638
	* If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SY Slope of Rd. 4.9	Print na	ame clearly Certification No
	Gutter Flow Slope (as directed)	Horizontal Gaps	○ ≤ 1/2" <b>■</b> > 1/2"		nsulting
			,- = -,-	└─   Compa	ny/Agency



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





