	WASHINGTON COUNTY	
	OREGON	
	NW 307th Ave	
	North-South Road Name	
		PL
		Ramp Sty
dep	e passing value for Gutter Flow S ends on the Intersection Control block (MB), GFS must be ≤ Slope	Type. At a

must be  $\leq$  5.0%, and at Stop or Yield (SY), GFS must be  $\leq 2.0\%$ .

(inlets, alignment, etc.)

Road, at Signalized or Uncontrolled (SU), GFS

\*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.

 $^{*2}$  Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

**Detectable Warning Surface** Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. /  $4' \times 4'$  min.)\* \* If constrained at back of walk, min. Y length is 5'.

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

23885.56

Ramp Style

Project No. Sheet No.	Intersection No	). Ea	st-West F	Road Name		ov/odot/Engineering/Documents hibitA.pdf for more corner styles.
Calibration Date	7/2/2024 (m	nm/dd/yy)				nty corner numbering system.
RAMP RUN 1		Pass	Fail	3	1	2
Running Slope 1	2.2 ≤ 2.0%	% <b>■</b> > 2.0%	6	Corner		orner sitions
Cross Slope 1	14.1 ≤ 2.0%		6	Position	3	5 2A
Detectable Warning	N Y	N			1	3
Lip Height	0 ≤ 1/4	." <b>=</b> > 1/4'	'	(	3A	<b>^</b> .
Gutter Flow Slope	12.6 ≤ *	> *			2 No	orth 2
Curb Running Slope(avg)	7.1 ≤ 8.3%	% <b>■</b> > 8.3%	6> <u> </u>		4	1
Counter Slope (+/-)*2	6.4 ≤ 5.0%	6	%  <b>I</b>	1		amp 1
Det. warning full width of ramp	Y	N		Ramp Position		5
RAMP RUN 2		Pass	Fail			PE Stamp (required for
Running Slope 2	18 ≤ 8.3%	%	<b>6</b> ■			private development)
Length 2	7.8					
Cross Slope 2	2.0 ≤ 2.0%	% <b>■</b> > 2.0%	%			
RAMP RUN 3		Pass	Fail			
Running Slope 3	5.4 ≤ 8.3%	% <b>■</b> > 8.3°	%			
Length 3	7.4					
Cross Slope 3	1.5 ≤ 2.0%	% <b>=</b> > 2.0°	%	Comment		
TURN SPACE		Pass	Fail	Comment	S	
Width X	5 ≥ 4.0'	■ < 4.0	·	IITD		
Length Y	5 ≥ 4.0'*	*1 < 4.0'	*1			
Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*	*1 < 5.0'	*1			
Slope X (Cross Slope 1)	2.2 ≤ 2.0%	6  > 2.09	% <b>=</b>			
Slope Y (Running Slope 1)	14.1 ≤ 2.0%	6	<b>/</b>			
MISCELLANEOUS		Pass	Fail	Inspector's S	ignature	Date (mm/dd/
Clear Width (feet)	5.0 ≥ 4.0'	< 4.0	·	Darrell \		52638
Intersection Control Type	SY Slope	of Rd. 10.8		Print name o	•	Certification
Horizontal Gaps	≤ 1/2'	> 1/2	"	3J Consulti Company/A	-	

NW Highland Ct



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





