WASHINGTON COUNTY			
OREGON			
NW 307th			

ADA Curb Ramp New Construction Inspection Form (Parallel)

NW 307th	23885.56 Eggiman Ct			
North-South Road Name	Project No. Sheet I	No. Intersection No. East-V		v/odot/Engineering/Documents
	Calibration Dat	re 7/10/2024 (mm/dd/yy)	_ ,	ibitA.pdf for more corner styles. ty corner numbering system.
PL	RAMP RUN 1	Pass	Fail 1	2
Ramp Style	Running Slope 1	0.9 ≤ 2.0% ■ > 2.0%	Corner	orner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	2.7 ≤ 2.0% > 2.0%	Position 3	2A 1
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the	Detectable Warning	Y N		3
Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4" ■ > 1/4"	3A 3.	^
must be $\leq 5.0\%$, and at Stop	Gutter Flow Slope	1.2 ≤ * ■ > *	2 No	orth 2
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	0.8 ≤ 8.3% ■ > 8.3%>		amp 1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	5.8 ≤ 5.0% ■ > 5.0%	1 Pos	sitions
* ² Clear Space area is the width of Ramp Run 1	Det. warning full width of ra	mp Y N	Ramp Position	5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail	PE Stamp (required for
	Running Slope 2	^{8.5} ≤ 8.3% > 8.3%		private development)
See also <u>Standard Drawings</u> to assess provisions not shown:	Length 2	4.2		
(inlets, alignment, etc.)	Cross Slope 2	0.8 ≤ 2.0% ■ > 2.0%		
~~ ~ *	RAMP RUN 3	Pass	Fail	
18 Page 3 Trape	Running Slope 3	5 ≤ 8.3% > 8.3%		
To Run 2 / Run 2	Length 3	4.35		
Counter slope Conter flow slope	Cross Slope 3	1.9 ≤ 2.0% ■ > 2.0%	Comments:	
	TURN SPACE	Pass	Fail) IITD
	Width X	4.95 ≥ 4.0' ■ < 4.0'	Poor craftsmanship, RR2	2, 1110
PARALLEL RAMP (PL)	Length Y	7.45 ≥ 4.0'*1 ■ < 4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0'*1		
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	2.7 ≤ 2.0% > 2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	0.9 ≤ 2.0% ■ > 2.0%		
Funning Slope (8.3% max.) Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	MISCELLANEOUS	Pass	Fail Inspector's Signature	Date (mm/dd/yy)
	Clear Width (feet)	^{4.95} ≥ 4.0' < 4.0'	Darrell Wyant	52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SY Slope of Rd. 0.1	Print name clearly	Certification No
Gutter Flow Slope (as directed)	Horizontal Gaps	o ≤ 1/2" ■ > 1/2"	3J Consulting	
	Tiorizonital Gaps		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





