


ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OREGON		•
NW Kaye	24952.54 NW Fair	
North-South Road Name	Project No. Sheet No. Intersection No. East-West Road Name)
	Calibration Date (mm/dd/yy)	k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Pass Fail Running Slope 1 ≤ 8.3% >8.3% 4 ler	Corner
he passing value for Gutter Flow Slope (GFS)	Length 1	3 Positions 2A
epends on the Intersection Control Type. At a lidblock (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1 9.0 ≤ 2.0% >2.0%	1 2 3
gnalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N) Y N	3A North
0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height 1/4" ■ >1/4"	2 North
If Back of Ramp Obstruction is Yes, turn space ngth Y must be minimum 5.0 ft.	Gutter Flow Slope $\frac{0}{3.0} \le *$ $>*$	4
	Curb Running Slope (avg) 1.88 ≤ 8.3% >8.3%	Ramp 1 Positions
Clear Space area is the width of Ramp Run 1 and tends 4.0 ft into the roadway.	Counter Slope (+/-) *2	5
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form) < 5.0' ≥ 5.0'	PE Stamp (requi private develop
Su Me Market Mar	Detectable warning extends full width of ramp throat opening	
	TURN SPACE LANDING NONE Pass Fail	
	Width X ≥ 4.0' < 4.0'	
Counter slope Gurler Flow slope	Length Y ≥ 4.0'*1 < 4.0'*1 Commen	
	Back of Ramp Obstruction (Y/N) ≥ 5.0'*1	RR
PERPENDICULAR RAMP (PR)	Slope X ≤2.0%	
Pedestrian Access Route (to measure Clear Width)	Slope Y ≤2.0% ■ >2.0%	
Detectable Warning Surface	MISCELLANEOUS Traversable Pass Fail	
Cross Slope (2.0% max.)	Flare Slope 1 ≤ 10% < 10% Inspector's	Signature
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2 < 10% <10%	
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet) 2.95 $\geq 4.0'$ \sim Clear Width (feet) \sim Print name	
Gutter Flow Slope (as directed)	Intersection Control Type Slope of Pood 30	
Section of the Control of the Contro	Horizontal Gaps SY Slope of Road 23 3J Consulti Company/A	•
	Company/A	0~1



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





