

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

K	W Main	23885.56				NW L	anav	
	rth-South Road Name		et No. In	tersection N	lo.			pad Name
. • •			7/16/2024	_		Last W	236 110	k - ')' - ' ' ' '
			7/10/2024	4 (11111) du,			F. 11	y '‡ '# ' · · · ·
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Positions
The pas	sing value for Gutter Flow Slope (GFS)	Length 1	5.35					Position 3
•	ls on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1		≤ 2.0%		>2.0%		1 2 3
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N	Ш	3A -
5.0%, an	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	2.3	≤ *		>*		1 A Ramp
		Curb Running Slope (avg)	6.92	≤ 8.3%		>8.3%		Ramp Positions
extends 4 See also	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	8.8	≤ 5.0%		> 5.0%		Position PE Stamp (required
	Standard <u>Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		private developme
1	X X X	Detectable warning extends full width of ramp throat opening		Υ		N		
Counter slope Guiter Flow slope		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	5.1	≥ 4.0'		< 4.0'		
		Length Y	6.0	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1		DWS IITD Fails RR 1
PI	SHOP BY TALLEY SHOW DOWN DOWN THE BEST OF BY	Slope X	2.9	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	
(Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1	8.0	≤ 10%		< 10%	\Box	Inspector's Signature Date (mm)
4	Counter Slope (6.5% max.)	Flare Slope 2	1.9	≤ 10%		<10%		
- T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.0	≥ 4.0'		< 4.0'		Darrell Wyant 52638
Υ.	* If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU	Slope of	Boad			Print name clearly Certificati
-	Gutter Flow Slope (as directed)	,,	30	•				3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





