	WASHINGTON COUNTY
	OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

	C394.C. C					
NW Curtis St		23885.56	N\	N Highland Ct		
	North-South Road Name	Project No. Sheet No.	Intersection No. Eas	t-West Road Name	1 ,, 0 0 , , 0	
		Calibration Date	7/2/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner st Use Washington County corner numbering system	
	Di	RAMP RUN 1	Pass	Fail		n
	PL	Running Slope 1	2.7 ≤ 2.0% > 2.0%	3	Corner	2
*The passing value for Gutter Flow Slope (GFS)				Position		1
		Cross Slope 1	2.1 ≤ 2.0% > 2.0%	` <u> </u>	5 2	
		Detectable Warning	N Y N		3)
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS		Lip Height	0 ≤ 1/4" ■ > 1/4"		3A 1	
Node, at signalized of official folice (50), of 5		Gutter Flow Slope	1.6 ≤ * ■ > *		North	
	eld (SY), GFS must be ≤ 2.0%.		,======================================		2	
*1 If Back of Ramp Obstruction is Yes, turn		Curb Running Slope(avg)	4.6 ≤ 8.3% ■ > 8.3%	·>	4 Ramp	
	e length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	^{7.3} ≤ 5.0% ■ > 5.0%		Positions Positions	
*2 Clear Space area is the width of Ramp Run 1		Det. warning full width of ramp	Y N	Ramp Position	1 5	
		RAMP RUN 2	Pass	Fail	PE Stamp (required fo	or
See also Standard Drawings to assess provisions not shown:		Running Slope 2	8.1 ≤ 8.3% ■ > 8.3%		private development	
		Length 2	6.0			
		Cross Slope 2	1.8 ≤ 2.0% ■ > 2.0%			
		RAMP RUN 3	Pass	Fail		
		Running Slope 3	8.0 ≤ 8.3% ■ > 8.3%	6 🔲 📗		
$\leq \neq$	15 Page 3 Brus 1/ Page 2	Length 3	7.3			
7	Fun 2 g	Cross Slope 3	1.3 ≤ 2.0% ■ > 2.0%	6		
Counter slope Tow slope T		TURN SPACE	Pass	Fail	ents:	
		Width X	5 ≥ 4.0' ■ < 4.0'	IITD		
			1 01/1			
	i rubicala ib um (i a)	Length Y		<u> </u>		
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 ■ < 5.0'*	^{*1}		
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	2.7 ≤ 2.0% > 2.0%	6 		
\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		Slope Y (Running Slope 1)	2.1	6		\neg
	Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspector	's Signature Date (mm	/dd/yy)
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.0 ≥ 4.0' < 4.0'	Darrel	II Wyant 5263	8
	* If constrained at back of walk, min, Y length is 5'.	Intersection Control Type	SY Slope of Rd. 0.2	Print nam	ne clearly Certificati	on No
	Gutter Flow Slope (as directed)	Horizontal Gaps	≤ 1/2" ■ > 1/2'	3J Cons		
		Horizontal Gaps	= 1/2	Company	//Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





