	WASHINGTON COUNTY OREGON	
9		
	NW Main	
	North-South Road Name	
		PL
		Ramp Sty
dep Mid Roa mus	e passing value for Gutter Flow SI ends on the Intersection Control block (MB), GFS must be \leq Slope d, at Signalized or Uncontrolled (St be \leq 5.0%, and at Stop field (SY), GFS must be \leq 2.0%.	Гуре. At a of the
	f Back of Ramp Obstruction is Yes ce length Y must be minimum 5.0	
* ² (and	Clear Space area is the width of Raextends 4.0 ft into the roadway.	mp Run 1

(inlets, alignment, etc.)

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

	23885.56		NW Leno	iox	
	Project No. Sheet No.	Intersection No.	East-West F	t Road Name See https://www.oregon.gov/odot/Engineering/Documents	
	Calibration Date	(mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.	
RAN	1P RUN 1	Pass	Fail		la la
Running Slope 1		≤ 2.0%	> 2.0%	Corner	
Cross Slope 1		≤ 2.0%	> 2.0%	Position 3	_
Detectable Warning		Y ■	N	3	
Lip H	Height	≤ 1/4" ■ >	> 1/4"	3A	
Gut	ter Flow Slope	7.9 ≤ *	>*	2 North	
Cur	b Running Slope(avg)	4.32 ≤ 8.3% ■ >	> 8.3%>	Ramp 1	
Cou	nter Slope (+/-)*2	^{7.8} ≤ 5.0% ■ >	> 5.0%	Positions Positions	_
Det.	warning full width of ramp	Y	N	Ramp Position	
RAN	/IP RUN 2	Pass	Fail	PE Stamp (required for	
Run	ning Slope 2	15.4 ≤ 8.3%	> 8.3%	private development)	
Leng	gth 2	20.5			
Cros	ss Slope 2	≤ 2.0%	> 2.0%		
RAN	/IP RUN 3	Pass	Fail		
Run	ning Slope 3	≤ 8.3%	> 8.3%		
Leng	gth 3				
Cros	ss Slope 3	≤ 2.0%	> 2.0%	Sammants:	
TUR	N SPACE	Pass	Fail	Comments:	7
Wid	lth X	4.65 ≥ 4.0'	< 4.0'	DWS IITD Fails RR 1	
Len	gth Y	10.15 ≥ 4.0'*1	< 4.0'*1		
Back	of Ramp Obstruction (Y/N)	≥ 5.0'*1 ■	< 5.0'*1	1	
Slop	De X (Cross Slope 1)	6.4 ≤ 2.0%	> 2.0%		
	DEY (Running Slope 1)		> 2.0%		
MIS	CELLANEOUS	Pass	Fail	Inspector's Signature Date (mm/dd	/уу
Clea	r Width (feet)	4.65 ≥ 4.0'	< 4.0'	Darrell Wyant 52638	
Inter	rsection Control Type	Slope of Rd.	7.2	Print name clearly Certification	No
Hori	izontal Gaps	0 ≤ 1/2"	> 1/2"	3J Consulting Company/Agency	

Ramp Style



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





