

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	- contr							
N	IW 209th	24952.54				Nw Ki	ng	
No	orth-South Road Name	Project No. Shee	et No. In	tersection N	lo.	East-W	est Ro	pad Name
		Calibration Date	7/30/202	4 (mm/dd,	/yy)			k - ')' - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
	Ramp Style PR	RAMP RUN 1			Pass		Fail	midblock
	The style The	Running Slope 1	8.6	≤ 8.3%		>8.3%		Corner
	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at ed or Uncontrolled (SU), GFS must be ≤	Length 1						Position 3
		Cross Slope 1	4.95	≤ 2.0%		>2.0%		1 2 3
Signalize		Detectable Warning (Y,N)	Υ	Y		N		3A
5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%		Lip Height	0	1/4"		>1/4"		North
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Gutter Flow Slope	0.8	 ≤ *		>*		
		Curb Running Slope (avg)	8.52	≤ 8.3%		>8.3%		1 Ramp 1 Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	1.0	≤ 5.0%		> 5.0%		Position 5
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (requir private developm
Counter slope		Detectable warning extends full width of ramp throat opening	Υ	Υ		N		
		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X		≥ 4.0'		< 4.0'		
			=		\equiv			Comments:
		Length Y	fail	≥ 4.0'*¹		< 4.0'*1	Ш	
		Back of Ramp Obstruction (Y/N)	Υ	≥ 5.0' * 1		< 5.0'*1		
PE	Service AV Contract Service Se	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (m
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.95	≥ 4.0'		< 4.0'		Darrell Wyant 526 Print name clearly Certifica
	Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of	Road	0.9		
	- I on stops (as another)	Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting Company/Agency
		I		-, -		/-		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





