WASHINGTON COUNTY
OREGON
Nw 320th
North-South Road Name

ADA Curb Ramp New Construction Inspection Form (Parallel)

	Nw 320th	24952.54		acific			
	North-South Road Name	Project No. Sheet No.	. Intersection No. Ea	ast-West F		oregon.gov/odot/Engineeri	
		Calibration Date	10/8/2024 (mm/dd/yy)		_ , ,	g/ADA_ExhibitA.pdf for morngton County corner numbe	,
	PL	RAMP RUN 1	Pass	Fail	2		2
	Ramp Style	Running Slope 1	≤ 2.0% > 2.09	%	Corner	Corner Positions	
The passing value for Gutter Flow Slope (GFS		Cross Slope 1	≤ 2.0% > 2.09	%	Position 3	5 2	A
•	ends on the Intersection Control Type. At a	Detectable Warning	Y Y N				3
Road	block (MB), GFS must be ≤ Slope of the I, at Signalized or Uncontrolled (SU), GFS	Lip Height	1.0 ≤ 1/4" > 1/4	" 🔳	3A -)	
	be ≤ 5.0%, and at Stop	Gutter Flow Slope	1.7 ≤* >*		2	North	2
	eld (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	1.36 ≤ 8.3% ■ > 8.39	%>	4	(1	
	Back of Ramp Obstruction is Yes, turn e length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	<u>5.5</u> ≤ 5.0% ■ > 5.0	0%	1 Ramp	Ramp 1 Positions	
Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ramp	p Y N		Position	5	
		RAMP RUN 2	Pass	Fail		PE Stamp (re	quired for
		Running Slope 2	11.0 ≤ 8.3% > 8.3	% =		private deve	lopment)
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2	7.15				
		Cross Slope 2	≤ 2.0% > 2.00	%			
.03		RAMP RUN 3 Pass Fail					
		Running Slope 3	5.6 ≤ 8.3% ■ > 8.3	%			
7	15 Run 3	Length 3	7.1				
Z	1 Guillar in	Cross Slope 3	1.6 ≤ 2.0% ■ > 2.0	%	Comments		
Counter slope		TURN SPACE	Pass	Fail	Comments:		
		Width X	5.1 ≥ 4.0' ■ < 4.0		IITD GT2		
	PARALLEL RAMP (PL)	Length Y	7.4 ≥ 4.0'*1 ■ < 4.0	·*1			
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 < 5.0	*1			
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	4.7 ≤ 2.0% > 2.0	% ■			
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	≤ 2.0% > 2.0	%			
	Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature		Date (mm/dd/yy)
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* *If constrained at back of wells, min. Y length in 5'	Clear Width (feet)	5.1 ≥ 4.0' < 4.0)'	Darrell Wyant		52638
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SY Slope of Rd. 1.5	\neg	Print name clearly		Certification No
	Gutter Flow Slope (as directed)	Horizontal Gaps	No ≤ 1/2" > 1/2		3J Consulting		
					Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





