309th	24952.54	24952.54 Yorkshii		re l		
North-South Road Name	Project No. Sheet No.		East-West	Road Name		egon.gov/odot/Engineering/Docu
	Calibration Date	10/25/2024 (mm/dd/yy)				on County corner numbering syste
PL	RAMP RUN 1	Pass	Fail	1		15
Ramp Style The passing value for Gutter Flow Slope (GFS)	Running Slope 1	≤ 2.0%	2.0%	Corner		Corner Positions
	Cross Slope 1	≤ 2.0%	2.0%	Position	3	5 2A
epends on the Intersection Control Type. At a	Detectable Warning	N Y	N 🔳		1	2
Aidblock (MB), GFS must be ≤ Slope of the oad, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ >	1/4"		3A	^
must be \leq 5.0%, and at Stop	Gutter Flow Slope		>* I		2	North
r Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	, = =	8.3%>			(A)
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		7.5 ≤ 5.0% ■ >		1	4	Ramp 1
	Counter Slope (+/-)*2			Ramp		Positions
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ram	Pass	N Fail	Position		
				1		PE Stamp (required private developme
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Running Slope 2	≤ 8.3% >	8.3%			private developrite
	Length 2	1.4 ≤ 2.0%	2.00/			
	Cross Slope 2			.		
Counter slope Counter slope	RAMP RUN 3	Pass	Fail			
	Running Slope 3	20.8 ≤ 8.3%	> 8.3% ■			
	Length 3					
	Cross Slope 3	≤ 2.0%	> 2.0%			
	TURN SPACE	Pass	Fail	Commen	ts:	
	Width X	4.7 ≥ 4.0'	< 4.0'	No td		
PARALLEL RAMP (PL)	Length Y	4.9 ≥ 4.0'*1 <	4.0'*1			
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 <	< 5.0'*1			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	11.4 ≤ 2.0%	≥ 2.0%			
Detectable Warning Surface	Slope Y (Running Slope 1)	≤ 2.0%	> 2.0% ■			
	- SIONE I MAININE SIONE II	= = -				

Gutter Flow Slope (as directed)

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

4.7

SY

Date (mm/dd/yy)

52638

Certification No.

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

Pass

Slope of Rd. 11.0

≤ 1/2" ■ > 1/2"

< 4.0'


≥ 4.0'

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





