| 320th   | 24952.54                                |                         | Pacific   |                  |               |   |
|---|---|-------------------------|-----------|------------------|---------------|---|
| North-South Road Name   | Project No. Sheet No.  Calibration Date |                         | East-West | Road Name        | _RoadwayEng/A | egon.gov/odot/Engineering/Docum<br>NDA_ExhibitA.pdf for more corner s<br>on County corner numbering syste |
| PL  | RAMP RUN 1                              | Pass                    | Fail      | 3                |               |   |
| Ramp Style  *The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a | Running Slope 1                         | ≤ 2.0%                  | 2.0%      | Corner           | _             | Corner  |
|   | Cross Slope 1                           | 10.6 ≤ 2.0%             | 2.0%      | Position         | 3             | Positions 2A  |
|   | Detectable Warning                      | Y Y                     | N         |                  | 1             | 2   |
| Aidblock (MB), GFS must be ≤ Slope of the   |   | 0 < 1/4"                | 1/4       |                  | 1             | A 3   |
| load, at Signalized or Uncontrolled (SU), GFS   | Lip Height                              |                         | 1/4"      |                  | 3A            | North   |
| must be ≤ 5.0%, and at Stop<br>or Yield (SY), GFS must be ≤ 2.0%.   | Gutter Flow Slope                       | 6 ≤ *                   | >*        |                  | 2             | 2   |
|   | Curb Running Slope(avg)                 | 2.86 ≤ 8.3% ■ >         | 8.3%>     |                  |               | (1)   |
| <sup>1</sup> If Back of Ramp Obstruction is Yes, turn pace length Y must be minimum 5.0 ft.               | Counter Slope (+/-)*2                   | 5.2 ≤ 5.0%  <b>■</b> >  | 5.0%      | 1                | 1 2           | Ramp 1  |
| *2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.                       | Det. warning full width of ram          | p Y Y                   | N         | Ramp<br>Position |               | 5   |
|   | RAMP RUN 2                              | Pass                    | Fail      | 1 GSIGIGIT       |               | PE Stamp (required  |
|   | Running Slope 2                         | 2.2 ≤ 8.3% ■ >          | 8.3%      |                  |               | private developmer  |
| See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)                      | Length 2                                | 7.25                    |           |                  |               |   |
|   | Cross Slope 2                           | 1.3 ≤ 2.0%              | 2.0%      |                  |               |   |
| Counter slope  Counter slope  Counter slope   | RAMP RUN 3                              | Pass                    | Fail      | 1                |               |   |
|   | Running Slope 3                         | 16.6 ≤ 8.3%             | > 8.3%    |                  |               |   |
|   | Length 3                                | 7.2                     |           |                  |               |   |
|   | Cross Slope 3                           | ≤ 2.0%                  | > 2.0%    |                  |               |   |
|   | TURN SPACE                              | Pass                    | Fail      | Comment          |               |   |
|   | Width X                                 | 4.95 ≥ 4.0'             | < 4.0'    | IITD gt2         | <u>)</u>      |   |
| PARALLEL RAMP (PL)  | Length Y                                | 6.7 ≥ 4.0'*1 <b>■</b> < | < 4.0'*1  |                  |               |   |
| PARALLEL RAMP (PL)  | Back of Ramp Obstruction (Y/N)          | Y ≥ 5.0'*1 <            | < 5.0'*1  |                  |               |   |
| Pedestrian Access Route (to measure Clear Width)  | Slope X (Cross Slope 1)                 |                         | > 2.0%    |                  |               |   |
| Detectable Warning Surface  |   |                         |           |                  |               |   |
| [mmmmm]   | Slope Y (Running Slope 1)               | ≤ 2.0%     >            | > 2.0%    |                  |               |   |

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

4.95

SY

Pass

Slope of Rd. 5.5

≤ 1/2" ■ > 1/2"

< 4.0'

≥ 4.0'

Date (mm/dd/yy)

52638

Certification No.

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





