

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

-	CANAL A							
N	Nw glencoe rd	24952.54				Comn	nerci	al
No	orth-South Road Name	Project No. Shee	et No. In	tersection N	lo.	East-W	est Ro	oad Name
		Calibration Date	8/30/2024	(mm/dd,	/yy)			k - ') · · · · · · · · · · · · · · · · ·
	Ramp Style PR	RAMP RUN 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
	ssing value for Gutter Flow Slope (GFS) ds on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Running Slope 1 Length 1	7.95	= 0.075				Corner Position 3 Positions 2A
•		Cross Slope 1		≤ 2.0%		>2.0%		2 2 3
•	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		3A
5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Lip Height		1/4"		>1/4"		2 North
length Y must be minimum 5.0 ft.		Gutter Flow Slope	A	≤ *		>*		
		Curb Running Slope (avg)	6.8800	≤ 8.3%	.3%	>8.3%		Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	3.3	≤ 5.0%		> 5.0%		Position
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (require private developm
1	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Υ		N		
Counter slope Girjer Flow slope Counter slope		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	5.1	≥ 4.0'		< 4.0'		
		Length Y	5.0	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		IITD
Р	ERPENDICULAR RAMP (PR)	Slope X	1.4	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	2.0	≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	ble		Pass		Fail	
4	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (n
\mathcal{I}	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 526 Print name clearly Certifica
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	1.6		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





