WASHINGTON COUNTY
OREGON
NW Timeric
North-South Road Name

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

NVV Timeric	23885.56	NW	Lenox				
North-South Road Name	Project No. Sheet	No. Intersection No. East-V	Vest Road Name	See https://www.oregon.gov/odot/Engineering/D			
Calibration Date  7/16/2024  (mm/dd/yy)							
PL	RAMP RUN 1	Pass	Fail 2		2		
Ramp Style	Running Slope 1	≤ 2.0%  > 2.0%	Corner	Corner Positions	The same of the sa		
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Cross Slope 1	≤ 2.0% > 2.0%	Position	3 5 2A	1		
	Detectable Warning	Y N		1			
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4"  > 1/4"		3A -			
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	2.7 ≤ * <b>■</b> > *		2 North			
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	<b>4.74</b> ≤ 8.3%  > 8.3%>					
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	12.9 ≤ 5.0%  <b>■</b> >  5.0%	1	Ramp 1 Positions			
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ra	amp Y N	Ramp Position	5			
	RAMP RUN 2	Pass	Fail	PE Stamp (regui	ired for		
	Running Slope 2	≤ 8.3% > 8.3%		private develop	ment)		
See also Standard Drawings to assess provisions not shown:	Length 2	6.3					
(inlets, alignment, etc.)	Cross Slope 2	4.1 ≤ 2.0%  > 2.0%					
COMPART SECTION TO THE	RAMP RUN 3	Pass	Fail				
If Pain 3 Tage	Running Slope 3	≤ 8.3%  > 8.3%					
To nun 2 / nun 2	Length 3	7.35					
Outles res	Cross Slope 3	10 ≤ 2.0% > 2.0%					
Counter slope	TURN SPACE	Pass	Fail				
	Width X	4.9 ≥ 4.0'	NO DW	S Fail RR and Turn Space			
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 <b>■</b> < 4.0'*1					
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0'*1					
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%					
Detectable Warning Surface  Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	≤ 2.0% > 2.0%					
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspector's S	Signature Date	e (mm/dd/yy		
Counter Slope (5.0% max.)  Turning Space (X & Y) (2.0% max. / 4" x 4" min.)*	Clear Width (feet)	<sup>4.9</sup> ≥ 4.0' < 4.0'	Darrell '	Wyant 5:	2638		
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*  * If constrained at back of walk, min. Y length is 5'.  Gutter Flow Slope (as directed)	Intersection Control Type	SU Slope of Rd. 3.3	Print name	clearly	ification No		
			3J Consulti	ing			
	Horizontal Gaps	≤ 1/2" > 1/2"	Company/A	gency			



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





