WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constr	uction Inspection Form (Para	allel)	
Nw 311 st	24952.54	Nw comr	mercial st	
North-South Road Name	Project No. Sheet No.	Intersection No. East-West F	Road Name See https://www.oregon.gov/odot/Engineering/Docu RoadwayEng/ADA ExhibitA.pdf for more corner	
	Calibration Date	8/30/2024 (mm/dd/yy)	Use Washington County corner numbering syst	,
PL	RAMP RUN 1	Pass Fail		2
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Running Slope 1	1.8 ≤ 2.0% > 2.0%	Corner Positions Positions	
	Cross Slope 1	0.5 ≤ 2.0% ■ > 2.0%	Position 3 Positions 2A	2A X1
	Detectable Warning	Y • N	2 2 3)
	Lip Height	≤ 1/4" > 1/4"	3A 1	
must be \leq 5.0%, and at Stop	Gutter Flow Slope	0.9 ≤ * > *	2 North	
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	1.1 ≤ 8.3% > 8.3%>		-
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	3.9 ≤ 5.0% > 5.0%	Positions 1	
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ramp	y N	Ramp Position	
	RAMP RUN 2	Pass Fail	PE Stamp (required	d for
	Running Slope 2	5.2 ≤ 8.3% ■ > 8.3%	private developme	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Length 2	11.55		
	Cross Slope 2	2.9 ≤ 2.0% > 2.0% ■		
Counter slope Counter slope	RAMP RUN 3	Pass Fail		
	Running Slope 3	≤ 8.3% > 8.3%		
	Length 3	9.3		
	Cross Slope 3	2.2 ≤ 2.0% > 2.0% ■		
	TURN SPACE	Pass Fail	Comments:	
	Width X	5.0 ≥ 4.0' ■ < 4.0'		
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ < 4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0'*1		

Pedestrian Access Route (to measure Clear Width)

Detectable Warning Surface

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

0.5

1.8

≤ 2.0% ■ > 2.0%

| ≤ 2.0% | ■ | > 2.0%

Pass

< 4.0'

> 1/2"

≥ 4.0'

≤ 1/2"

Slope of Rd.

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

Date (mm/dd/yy)

Certification No.

52638

Slope X (Cross Slope 1)

Slope Y (Running Slope 1)

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





