WASHINGTON COUNTY OREGON	ADA C	urb Ramp New	/ Constru	action Inspec	tion F	orm (Par	allel)			
		24952.54		1		1				
North-South Road Name		Project No.	Sheet No.	Intersection No		East-West	Road Name	, ,,	regon.gov/odot/Enginee	O,
		Calibrat	ion Date 9	/5/2024 (m	m/dd/yy)			_ ,	ADA_ExhibitA.pdf for m ton County corner numl	
	PL R	AMP RUN 1			Pass	Fail			61.	1
'		unning Slope 1		≤ 2.0%	6 >	2.0%	Corner		Corner Positions	1
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		ross Slope 1	≤ 2.0%	2.0%	Position	3	5	2A 1		
		etectable Warning		Υ		N		1	2	
		p Height		≤ 1/4	" = >	1/4"		3A 1		3
		outter Flow Slope	0.7 ≤ *		>*		2	North (1	2	
		Curb Running Slope	2.46 ≤ 8.3%	6 = >	8.3%>					
1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)	¢2	≤ 5.0%	🔳 >	5.0%		12	Ramp 1	
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		Det. warning full width of ramp		Y		N	Ramp Position		5	
		AMP RUN 2			Pass	Fail			PE Stamp (required for
	F	unning Slope 2		6.0 ≤ 8.3%	6 = >	8.3%			private dev	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		ength 2		12.5						
		ross Slope 2		1.5 ≤ 2.0%	6 🔳 >	2.0%				
St. Run 3 TO Fair 1/ Run 2 Gutter How slope Counter slope		AMP RUN 3			Pass	Fail				
		unning Slope 3		7 ≤ 8.3%	6 = :	> 8.3%				
		ength 3		8						
		cross Slope 3		1.8 ≤ 2.0%	6 = :	> 2.0%				
		TURN SPACE		Pass F			Comment	S:		
		Vidth X		5.0 ≥ 4.0'		< 4.0'				
PARALLEL RAMP (PL)		ength Y		4.75 ≥ 4.01%	*1	< 4.0'*1				
PARALLEL RAMP (PL)	E	ack of Ramp Obstructio	on (Y/N)	≥ 5.0'*	:1 <	< 5.0'*1 ■				
Pedestrian Access Route (to measure Clear V	vidth)	lope X (Cross Slope 1)		≤ 2.0%	; [] ;	> 2.0%				
Detectable Warning Surface Cross Slope (2.0% max.)	S	lope Y (Running Slope 1	.)	≤ 2.0%	;	> 2.0%				
Running Slope (8.3% max.)	1	/ISCELLANEOUS			Pass	Fail	Inspector's S	Signature		Date (mm/
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' mir	,,*	lear Width (feet)		5.0 ≥ 4.0'		< 4.0'	Darrell \	Wyant		52638

Intersection Control Type

Horizontal Gaps

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

Slope of Rd. 0.3

≤ 1/2" ■ > 1/2"

Certification No.

Print name clearly

Company/Agency

3J Consulting



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





