	WASHINGTON COUNTY
	OREGON

ADA Curb Ramp New Construction Inspection Form (Parallel)

	Nw 314th ave.	24952.54	Nw. Co	ottage st
	North-South Road Name	Project No. Sheet No.	Intersection No. East-Wes	t Road Name See https://www.oregon.gov/odot/Engineering/Documents
		10/9/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.	
	PL	RAMP RUN 1 Running Slope 1	Pass Fai 9.4 ≤ 2.0% > 2.0% ■	
depe Midb Road must or Yie *1 If space	passing value for Gutter Flow Slope (GFS) ands on the Intersection Control Type. At a block (MB), GFS must be ≤ Slope of the at Signalized or Uncontrolled (SU), GFS be ≤ 5.0%, and at Stop eld (SY), GFS must be ≤ 2.0%. Back of Ramp Obstruction is Yes, turn elength Y must be minimum 5.0 ft.	Gutter Flow Slope Curb Running Slope(avg) Counter Slope (+/-)*2	1.4 $\leq 2.0\%$ $\Rightarrow 2.0\%$ N Y N 0.5 $\leq 1/4$ " $\Rightarrow 1/4$ " 0.7 $\leq *$ $\Rightarrow *$ 2.34 $\leq 8.3\%$ $\Rightarrow 8.3\%$ 10.5 $\leq 5.0\% $ $\Rightarrow 5.0\% $ N Y N	3 2 2A 3
and extends 4.0 ft into the roadway. See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		RAMP RUN 2 Running Slope 2 Length 2 Cross Slope 2	Pass Fai 12.6 ≤ 8.3% > 8.3% ■ ≤ 2.0% > 2.0%	PE Starrip (required for
Counter slope Counter slope Counter slope		RAMP RUN 3 Running Slope 3 Length 3 Cross Slope 3 FURN SPACE Width X	Pass Fai 13.4 ≤ 8.3% > 8.3% ≤ 2.0% > 2.0% Pass Fai 4.5 ≥ 4.0' < 4.0'	Comments:
	(7) (4)	Length Y Back of Ramp Obstruction (Y/N)	$\ge 4.0^{1*1}$ $< 4.0^{1*1}$ $< 5.0^{1*1}$ $< 5.0^{1*1}$	
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope X (Cross Slope 1) Slope Y (Running Slope 1)	1.4 ≤ 2.0% > 2.0% 9.4 ≤ 2.0% > 2.0%	
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'. Gutter Flow Slope (as directed)	MISCELLANEOUS Clear Width (feet) ntersection Control Type	Pass Fai 4.5 ≥ 4.0'	Inspector's Signature Date (mm/dd/yy Darrell Wyant Print name clearly Certification No. 3J Consulting
		Horizontal Gaps	○ ≤ 1/2" ■ > 1/2"	Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





