	WASHINGTON COUNTY						
	OREGON						
	NW Main						
	North-South Road Name						
		PL					
		Ramp Sty					
dep Mid Roa mus	*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be $\leq$ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be $\leq$ 5.0%, and at Stop or Yield (SY), GFS must be $\leq$ 2.0%.						
	f Back of Ramp Obstruction is Yes, ce length Y must be minimum 5.0						
* <sup>2</sup> C and	Clear Space area is the width of Ra extends 4.0 ft into the roadway.	mp Run 1					

(inlets, alignment, etc.)

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

**Detectable Warning Surface** Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

23885.56

Ramp Style

Project No. Sheet No.	Intersection No.	East-West F	Road Name	See https://www.oregor		
Calibration Date		_RoadwayEng/ADA Use Washington C	_ExhibitA.pdf for m County corner numb			
RAMP RUN 1	Pass	Fail	4			2
Running Slope 1	≤ 2.0% >	2.0%	Corner		Corner Positions	1
Cross Slope 1	≤ 2.0% >	2.0%	Position	3	5	2A
Detectable Warning	Y	N		1	t	3
Lip Height	≤ 1/4" <b>■</b> >	1/4"		3A	<b>.</b>	
Gutter Flow Slope	5.3 ≤ *	>*		2	North	2
Curb Running Slope(avg)	8.1 ≤ 8.3% ■ >	8.3%>		4	Pama (1	
Counter Slope (+/-)*2	6.9 ≤ 5.0%  <b>■</b> >	5.0%	2 Pamp	2	Ramp 1	
Det. warning full width of ramp	Υ	N	Ramp Position		5	
RAMP RUN 2	Pass	Fail			PE Stamp (	required for
Running Slope 2	≤ 8.3% >	8.3%			private dev	
Length 2	7.05					
Cross Slope 2	≤ 2.0%   >	2.0%				
RAMP RUN 3	Pass	Fail				
Running Slope 3	3.6 ≤ 8.3% ■ >	8.3%				
Length 3	7.2					
Cross Slope 3	0.8 ≤ 2.0% ■ >	2.0%	Comment			
TURN SPACE Pass Fail						
Width X	4.9 ≥ 4.0'	< 4.0'	DWS III	TD Fails RR 1		
Length Y	6.1 ≥ 4.0'*1 <b>■</b> <	4.0'*1				
Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 ■ <	5.0'*1				
Slope X (Cross Slope 1)	≤ 2.0% >	2.0%				
Slope Y (Running Slope 1)	≤ 2.0% >	2.0%				
MISCELLANEOUS	Pass	Fail	Inspector's	Signature		Date (mm/dd/y
Clear Width (feet)	4.9 ≥ 4.0' <	< 4.0'	Darrell '			52638
Intersection Control Type	SY Slope of Rd.	5.0	Print name			Certification N
Horizontal Gaps		1/2"	3J Consulti	-		
·			Company/A	gency		

NW Lenox



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





