	WASHINGTON COUNT	Y
	OREGO	N
	NW Timeric	
	North-South Road Name	_
*The	passing value for Gutte	er
depe	nds on the Intersection	ן (
Midb	olock (MB), GFS must be	e :
Road	l, at Signalized or Unco	nt
	: be ≤ 5.0%, and at Stop	
	eld (SY), GFS must be ≤	
* ¹ If	Back of Ramp Obstruct	ic

ADA Curb Ramp New Construction Inspection Form (Parallel)

	NW Timeric	24952.54		NW North	th Ave		
	North-South Road Name	Project No. Sheet No.	Intersection No.	East-West F		ww.oregon.gov/odot/Engineer	
		Calibration Date	10/22/2024 (mm/dd/yy)			yEng/ADA_ExhibitA.pdf for mo shington County corner numb	
	PL	RAMP RUN 1	Pass	Fail	1		2
		Running Slope 1	9.7	2.0%	Corner	Corner Positions	
The	passing value for Gutter Flow Slope (GFS)	Cross Slope 1		2.0%	Position 3	5 2	ZA
•		Detectable Warning	N Y	N 🔳		1	3
	lock (MB), GFS must be ≤ Slope of the , at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1	1/4"	3A	1. C	
	be ≤ 5.0%, and at Stop	Gutter Flow Slope	5.2 ≤ *	> *	2	North	2
_	eld (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	7.4 ≤ 8.3% ■ > 8	8.3%>	4	1 (1	F
	Back of Ramp Obstruction is Yes, turn elength Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	4.1 ≤ 5.0%	5.0%	1 Ramp	Ramp 1 Positions	
² Cle	ear Space area is the width of Ramp Run 1	Det. warning full width of ramp	p N Y	N 🔳	Position	5	
nd extends 4.0 ft into the roadway.		RAMP RUN 2 Pass Fai				PE Stamp (re	equired for
		Running Slope 2	1.7 ≤ 8.3% ■ > 8	8.3%		private deve	elopment)
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2	5.35				
		Cross Slope 2	_{7.2} ≤ 2.0% > 2	2.0%			
course descriptions and		RAMP RUN 3 Pass Fail					
,/		Running Slope 3	≤ 8.3% >	8.3%			
7	pf Fran 3	Length 3	6.2				
7	Fun 2 B	Cross Slope 3	7.7 ≤ 2.0% >	2.0%			
Counter slope Gutter Now slope		TURN SPACE Pass Fail			Comments:		
				4.0'			
		Width X					
	PARALLEL RAMP (PL)	Length Y		4.0'*1			
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 ■ < 5	5.0'*1			
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	4.1 ≤ 2.0% > 3	2.0%			
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	9.7 ≤ 2.0% > 1	2.0%			
	Running Stope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature		Date (mm/dd/yy
	Counter Slope (5.0% max.)	Clear Width (feet)	3.9 ≥ 4.0' <	4.0'	Darrell Wyant		52638.0
	* If constrained at back of walk, min, Y length is 5'.	Intersection Control Type	SU Slope of Rd. 4		Print name clearly		Certification No
	Gutter Flow Slope (as directed)	Horizontal Gaps		1/2"	3J Consulting		
		Tiorizoritai Gaps		-12	Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





