WASHINGTON COUNT					
	OREGO				
Nw 314th ave.					

ADA Curb Ramp New Construction Inspection Form (Parallel)

	OKEGON							
Nw 314th ave. North-South Road Name		24952.54 Nw. Cot			tage st			
		Project No. Sheet No. Intersection No. E		East-West I		See https://www.oregon.gov/odot/Engineering/Documents		
		Calibration Date	10/9/2024 (mm/dd/yy)			_RoadwayEng/ADA_ExhibitA.pdf for more corner style Use Washington County corner numbering system.		
	PL	RAMP RUN 1	Pass	Fail	2	Tax. c	2	
	Ramp Style	Running Slope 1	9.4 ≤ 2.0%	2.0%	Corner	Corner Positions	1	
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		Cross Slope 1	1.4 ≤ 2.0%	2.0%	Position 3	5	2A	
		Detectable Warning	N Y	N 🔳	1		3	
		Lip Height	0.5 ≤ 1/4" >	1/4"	3A) 1		
		Gutter Flow Slope	0.7 ≤ *	>*	2	North	2	
		Curb Running Slope(avg)	2.34 ≤ 8.3% ■ >	8.3%>	4	1 0	1	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)*2	10.5 ≤ 5.0% ■ >	5.0%	1	Ramp 1 Positions		
∗2 Cle	ear Space area is the width of Ramp Run 1	Det. warning full width of ram	np N Y	N 🔳	Ramp Position	5		
and extends 4.0 ft into the roadway.		RAMP RUN 2	Pass	Fail	PE Stamp (required			
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)		Running Slope 2	≤ 8.3% >	8.3%		private dev	velopment)	
		Length 2						
		Cross Slope 2	≤ 2.0% >	2.0%				
of Run 3 19 Run 2		RAMP RUN 3	Pass	Fail	1			
		Running Slope 3	13.4 ≤ 8.3% >	> 8.3% ■				
		Length 3						
		Cross Slope 3	≤ 2.0% >	2.0%				
Co	ounter slope	TURN SPACE	Pass	Fail	Comments:			
		Width X	4.5 ≥ 4.0' ■ <	< 4.0'	No dome,no RR2,	No dome,no RR2,no RR3		
	PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ <	4.0'*1				
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 <	5.0'*1				
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.4 ≤ 2.0% >	2.0%				
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	9.4 ≤ 2.0% >	2.0%				
	Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail	Inspector's Signature		Date (mm/dd/y	
	Counter Slope (5.0% max.)	Clear Width (feet)	4.5 ≥ 4.0' <	< 4.0'	Darrell Wyant		52638.0	
Turning Space (X & Y) (2.0% max. / 4 * If constrained at back of walk, min. Gutter Flow Slope (as directed)	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU Slope of Rd.				Certification N	
	Gutter Flow Slope (as directed)			> 1/2"				
		Horizontal Gaps	Gaps 0 ≤ 1/2" ■ >		Company/Agency	ompany/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





