

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OREGON							
NW 285th Dr	24952.54				NW S	hado	lon St
North-South Road Name	Project No. Shee	et No.	Intersection N	0.	East-W	est Ro	pad Name
	Calibration Date	3/13/2024	(mm/dd/	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Positions
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Length 1	12.5			2.00/		Position 3
Aidblock (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1 Detectable Warning (Y,N)	N	≤ 2.0%		>2.0% N	H	3
ignalized or Uncontrolled (SU), GFS must be ≤ .0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height	0	Y 1/4"		>1/4"	H	3A North
If Back of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	0.9			>*	d	
ngth Y must be minimum 5.0 ft.	Curb Running Slope (avg)	3.78	≤ 8.3%		>8.3%		1 Ramp Positions
² Clear Space area is the width of Ramp Run 1 and xtends 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Position
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.3	< 5.0'		≥ 5.0'		PE Stamp (require private developm
Run 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1	Detectable warning extends full width of ramp throat opening	Υ	Y		N		
	TURN SPACE LANDING	G NO	NE	Pass		Fail	
	Width X	4.8	≥ 4.0'		< 4.0'		
	Length Y	5.7	≥ 4.0'*1		< 4.0'*1		Comments: TJITS and j box in TS rr1 icrr
	Back of Ramp Obstruction (Y/N)	N	≥ 5.0' * 1		< 5.0'*1		13113 and 1 box iii 13 ii 1 ioii
PERPENDICULAR RAMP (PR)	Slope X		≤2.0%		>2.0%		
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface	Slope Y		≤2.0%		>2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ıble		Pass		Fail	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (m
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certifica
Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road			3J Consulting
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





