WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constru	uction Inspection Form (Para	allel)
311th	24952.54	Claxter	
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date	9/20/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass Fail	4 2
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner Positions
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0%  > 2.0%	Position 3
depends on the Intersection Control Type. At a	Detectable Warning	Y	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1/4"	3A 1
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	0.7 ≤ * ■ > *	North 2
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	2.4 ≤ 8.3% ■ > 8.3%>	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	5.2 ≤ 5.0%  ► >  5.0%	1 Ramp Positions
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Y Y N	Position 5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail	PE Stamp (required for
See also Standard Drawings to assess provisions not shown:	Running Slope 2	1.3 ≤ 8.3% ■ > 8.3%	private development)
	Length 2	7.3	
(inlets, alignment, etc.)	Cross Slope 2	1.3 ≤ 2.0% ■ > 2.0%	
Counter slope  Series Flow slope  Counter slope	RAMP RUN 3	Pass Fail	
	Running Slope 3	≤ 8.3%  > 8.3%	
	Length 3	7.25	
	Cross Slope 3	3.6 ≤ 2.0%  > 2.0%	Commonte
	TURN SPACE	Pass Fail	Comments:
	Width X	4.95 ≥ 4.0'	IITD, gt2. BOR sign.
PARALLEL RAMP (PL)	Length Y	4.9 ≥ 4.0'*1  < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%	

**Detectable Warning Surface** 

Cross Slope (2.0% max.)

Running Slope (8.3% max.)

Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. /  $4' \times 4'$  min.)\* \* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

nspector's Signature	Date (mm/dd/yy)

Fail	Inspector's Signature
	Darrell Wyant

Print name clearly 3J

3J Consulting		
Company/Agency		

Slope Y (Running Slope 1)

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

4.9

SY

≤ 2.0%

≥ 4.0'

> 2.0%

< 4.0'

Pass

Slope of Rd. 0.9

≤ 1/2" ■ > 1/2"

52638

Certification No.



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





