WASHINGTON COUNTY	4				
OREGON					
NW Main					
North-South Road Name					
	PL				
	Ramp Sty				
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.					
*1 If Back of Ramp Obstruction is Yes, space length Y must be minimum 5.0					
*2 Clear Space area is the width of Rai and extends 4.0 ft into the roadway.	mp Run 1				

(inlets, alignment, etc.)

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

Project No. Sheet No. Intersection No. Eas			ast-West Road Name		See https://www.oregon.gov/odot/Engineering/Documents RoadwayEng/ADA ExhibitA.pdf for more corner styles.			
	Calibration Date	7/16/2024	(mm/dd/yy)			_ ,	on County corner nui	
PL	RAMP RUN 1		Pass	Fail	2		Stark.	2
Ramp Style	Running Slope 1	≤ 2	2.0% > 2.0)%	Corner		Corner Positions	1 XX
ne (GFS)	Cross Slope 1	≤ 2	2.0%)%	Position	3	5	2A 1
pe. At a	Detectable Warning		Y N			1/1		3
the), GFS	Lip Height	≤	1/4" 🔳 > 1/4	4"		3A -	\uparrow	,
	Gutter Flow Slope	1.4	≤ * ■ > *			2	North	2
	Curb Running Slope(avg)	8.04 ≤ 8	8.3% = > 8.3	3%>				1
urn	Counter Slope (+/-)*2	7.1 ≤ <u>5</u>	5.0% = > 5.	0%	1	4	Ramp 1] Positions	
ıp Run 1	Det. warning full width of ramp		Y		Ramp Position		5	
ip itali 1	RAMP RUN 2		Pass	Fail			PE Stamp	(required for
	Running Slope 2	≤ ≥	8.3%	3%			private de	evelopment)
not shown:	Length 2							
	Cross Slope 2	≤ 2	2.0%)%				
	RAMP RUN 3		Pass	Fail				
	Running Slope 3	10.1 ≤ 8	8.3% > 8.	3% ■				
	Length 3	7.2						
	Cross Slope 3	≤ 2	2.0% > 2.	0%	Comments:			
	TURN SPACE		Pass	Fail				
	Width X	5.0 ≥	4.0' ■ < 4.	0'	DWS IITI	J		
	Length Y	6.25 ≥ ∠	4.0'*1 < 4.0)'*1 <u> </u>				
	Back of Ramp Obstruction (Y/N)	≥ 5	5.0'*1 < 5.0)'*1 <u> </u>				
/idth)	Slope X (Cross Slope 1)	≤ 2	2.0% > 2.0	0%				
	Slope Y (Running Slope 1)	≤ 2	2.0% > 2.0	0%				
1.)* s 5'.	MISCELLANEOUS		Pass	Fail	Inspector's Sig	gnature		Date (mm/dd/y
	Clear Width (feet)	5.0 ≥ 4	4.0' <4.	0'	Darrell W			52638
	Intersection Control Type	SY Slo	ope of Rd. 0.0)	Print name cle			Certification N
	Horizontal Gaps	0 ≤ 1	1/2" > 1/	′2"	3J Consulting			
					COIIIDAIIY/Age	TILV		

NW Lenox

PARALLEL RAMP (PL)

See also Standard Drawings to assess provisions not shown:

Running Slope (8.3% max.) Counter Slope (5.0% max.)

PARALLEL RAMP (PL)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed



