WASHINGTON COUNTY OREGON ADA	A Curb Ramp New Constru	uction Inspection Form (Para	allel)	
	24952.54			
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engin	
	Calibration Date	9/23/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for Use Washington County corner nur	
PL	RAMP RUN 1	Pass Fail	- Z	15:
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner	0 1
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0% > 2.0%	Position 3 Positions	2A 1
depends on the Intersection Control Type. At a	Detectable Warning	Y N		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4" > 1/4"	3A -	9
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	≤ * > *	North	2
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	≤ 8.3% > 8.3%>		1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	≤ 5.0% > 5.0%	1 Ramp 1	
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Y	Ramp Position	
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail		required for
	Running Slope 2	≤ 8.3% > 8.3%	II ·	evelopment)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2			
	Cross Slope 2	≤ 2.0% > 2.0%		
	RAMP RUN 3	Pass Fail	-	
	Running Slope 3	≤ 8.3% > 8.3%	1	
	Length 3			
	Cross Slope 3	≤ 2.0% > 2.0%		
	·		Comments:	
	TURN SPACE	Pass Fail	-	
	Width X	≥ 4.0'		
PARALLEL RAMP (PL)	Length Y	≥ 4.0'*1 < 4.0'*1		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0'*1		
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	≤ 2.0% > 2.0%		
Running Stope (8.3% max.)	MISCELLANEOUS	Pass Fail	Inspector's Signature	Date (mm/de
Counter Slope (5.0% max.)	Clear Width (feet)	≥ 4.0' < 4.0'	Darrell Wyant	52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	` ,		Print name clearly	Certification
0 11-15-01-16-16-16-16	Intersection Control Type	Slope of Rd.	·	

Horizontal Gaps

Gutter Flow Slope (as directed)

3J Consulting

Company/Agency

> 1/2"

≤ 1/2"



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





