WASHINGTON COUNTY OREGON ADA	Curb Ramp New Constr	uction Inspection Form (Para	allel)
Main	24952.54	Commer	cial
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date	10/8/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass Fail	1 2
Ramp Style	Running Slope 1	7.7 ≤ 2.0% > 2.0%	Corner Positions
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0% > 2.0%	Position 3
depends on the Intersection Control Type. At a	Detectable Warning	N Y N	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" <b>■</b> > 1/4"	3A 1
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	3.9 ≤ * > *	North
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	4.08 ≤ 8.3%	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	<u>8.3</u> ≤ 5.0%	1 Pamp Positions
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ramp	Y N	Ramp Position
	RAMP RUN 2	Pass Fail	PE Stamp (required for
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Running Slope 2	≤ 8.3%  > 8.3%	private development)
	Length 2	7.4	
	Cross Slope 2	14.3 ≤ 2.0% > 2.0%	
Counter slope  Series Flow slope  Counter slope	RAMP RUN 3	Pass Fail	
	Running Slope 3	≤ 8.3%  > 8.3%	
	Length 3	7.3	
	Cross Slope 3	13.3 ≤ 2.0%  > 2.0%  ■	
	TURN SPACE	Pass Fail	Comments:
	Width X	5.3 ≥ 4.0' <b>■</b> < 4.0'	No Td. Asphalt.
PARALLEL RAMP (PL)	Length Y	5.25 ≥ 4.0'*1 <b>■</b> < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%	

**Detectable Warning Surface** 

Cross Slope (2.0% max.)

Running Slope (8.3% max.)

Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. /  $4' \times 4'$  min.)\* \* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

/ 2.0/6			
Pass	Fail	Inspector's Signature	Date (mm/dd/yy)
< 4.0'		Darrell Wyant	52638

Print name clearly

3J Consulting Company/Agency

WashCo ADA 01 (4-2020)

Certification No.

Slope Y (Running Slope 1)

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

7.7

5.25

SY

≤ 2.0%

≥ 4.0'

Slope of Rd. 1.9

> 1/2"



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





