WASHINGTON COUNTY
OREGON
Shadybrook
North-South Road Name

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

Shadybrook	24952.54 Yorkshire				
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West		regon.gov/odot/Engineering/Documents
	Calibration Date	10/25/2024 (mm/dc	d/yy)		ADA_ExhibitA.pdf for more corner styles. con County corner numbering system.
PL	RAMP RUN 1	Pa	ss Fail	3	2
	Running Slope 1	2.9 ≤ 2.0%	> 2.0%	Corner	Corner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0%	> 2.0%	Position 3	5 2A
	Detectable Warning	N Y	N 🔳	1	3
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	ip Height	0 ≤ 1/4"	> 1/4"	3A	1
	Gutter Flow Slope	1 ≤ *	>*	2	North
	Curb Running Slope(avg)	14.08 ≤ 8.3%	> 8.3%>		1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	6 ≤ 5.0%	>  5.0%	1	Ramp 1
* <sup>2</sup> Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	N Y	N 🔳	Ramp Position	5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pa	iss Fail		PE Stamp (required for
	Running Slope 2	≤ 8.3%	> 8.3%		private development)
	Length 2	6.8			
(inlets, alignment, etc.)	Cross Slope 2	2.8 ≤ 2.0%	> 2.0%		
	RAMP RUN 3 Pass Fail				
	Running Slope 3	≤ 8.3%	> 8.3%		
B Pain 3 The State of the State	Length 3	7.9			
Quitier 15	Cross Slope 3	3.1 ≤ 2.0%	> 2.0%	Comments:	
Counter slope	ΓURN SPACE	Pa	ss Fail		
,	Width X	3.8 ≥ 4.0'	< 4.0' ■	No Td.	
PARALLEL RAMP (PL)	Length Y	5.1 ≥ 4.0'*1	■ < 4.0'*1 <b></b>		
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1	< 5.0'*1		
A	Slope X (Cross Slope 1)	≤ 2.0%	> 2.0% ■		
Detectable Warning Surface  Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	2.9 ≤ 2.0%	> 2.0%		
	MISCELLANEOUS	Pa	iss Fail	Inspector's Signature	Date (mm/dd/yy
Counter Slope (5.0% max.)  Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	3.8 ≥ 4.0'	< 4.0'	Darrell Wyant	52638
"Il constrained at back of walk, min. 1 length is 5.	ntersection Control Type	SY Slope of F	Rd. 0.5	Print name clearly	Certification N
Gutter Flow Slope (as directed)	Horizontal Gaps		> 1/2"	3J Consulting	
	10112011ta1 0ap3	/-		Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





