OREGON	23885.56	uction Inspection Form (Para	·
North-South Road Name	Project No. Sheet No. Calibration Date	Intersection No. East-West F	Road Name See https://www.oregon.gov/odot/Engineering/Documents _RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%. *1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	RAMP RUN 1 Running Slope 1 Cross Slope 1 Detectable Warning Lip Height Gutter Flow Slope Curb Running Slope(avg) Counter Slope (+/-)*2	Pass Fail 556.0 ≤ 2.0% > 2.0% ■ ≤ 2.0% > 2.0% □ Y N □ ≤ 1/4" > 1/4" □ 566 ≤ * ■ > * ≤ 8.3% ■ > 8.3%> □ ≤ 5.0% > 5.0% □	Corner Positions 3 Corner Positions 3 North Ramp Ramp
*2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway. See also Standard Drawings to assess provisions not shown:	Det. warning full width of ramp RAMP RUN 2 Running Slope 2 Length 2	Y N Pass Fail ≤ 8.3% ■ > 8.3%	Position PE Stamp (required for private development)
(inlets, alignment, etc.)	Cross Slope 2 RAMP RUN 3 Running Slope 3 Length 3 Cross Slope 3	Section 2.0%	Comments:
PARALLEL RAMP (PL) PARALLEL RAMP (PL)	TURN SPACE Width X Length Y Back of Ramp Obstruction (Y/N)	Pass Fail $\geq 4.0^{\circ}$ $< 4.0^{\circ}$ $\geq 4.0^{\circ*1}$ $< 4.0^{\circ*1}$ $\geq 5.0^{\circ*1}$ $< 5.0^{\circ*1}$	
Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)	Slope X (Cross Slope 1) Slope Y (Running Slope 1) MISCELLANEOUS	556.0 ≤ 2.0%	Inspector's Signature Date (mm/dd,
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'. Gutter Flow Slope (as directed)	Clear Width (feet) Intersection Control Type	≥ 4.0'	Darrell Wyant 52638 Print name clearly Certification 3J Consulting

Horizontal Gaps

≤ 1/2"

> 1/2"

Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





