Nw 289	24952.54	Nw	union		
North-South Road Name	Project No. Sheet No.	Intersection No. East-	-West Road Name	See https://www.oregon.gov/odot/Engineering/Docum	
	Calibration Date	Calibration Date 8/20/2024 (mm/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for more corner st Use Washington County corner numbering system	
PL	RAMP RUN 1	Pass	Fail	1	
Ramp Style The passing value for Gutter Flow Slope (GFS)	Running Slope 1	9.0 ≤ 2.0% > 2.0%	Corner	Corner Positions	
	Cross Slope 1	≤ 2.0% > 2.0%	Position	3 Fositions 2A	
depends on the Intersection Control Type. At a	Detectable Warning	Y N		2	
Midblock (MB), GFS must be ≤ Slope of the	Lip Height	≤ 1/4" > 1/4"		1	
Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop				3A North	
by Yield (SY), GFS must be $\leq 2.0\%$.	Gutter Flow Slope	2.1	닏 .	2	
, <i>"</i>	Curb Running Slope(avg)	1.84 ≤ 8.3% > 8.3%>	· 🔲	4	
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	^{5.7} ≤ 5.0% ■ > 5.0%	ı 🗌 🗀	Ramp 1 Positions	
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Det. warning full width of ramp	Y	Ramp Position	5	
	RAMP RUN 2	Pass	Fail	PE Stamp (required f	
	Running Slope 2	≤ 8.3% ■ > 8.3%		private developmen	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Length 2				
	Cross Slope 2	≤ 2.0% ■ > 2.0%			
18 Pain 3 Run 1 Pain 2 B	RAMP RUN 3	Pass	Fail		
	Running Slope 3	≤ 8.3% ■ > 8.3%			
	Length 3				
	Cross Slope 3	≤ 2.0% ■ > 2.0%			
- Outlier / //	1			ς.	
Counter slope Gutter Now slope	TURN SPACE	Pass	Fail	<u>. </u>	
Counter slope Gutter Flow slope	TURN SPACE Width X	Pass 5.9 ≥ 4.0'	Fail		
			Fail		
PARALLEL RAMP (PL)	Width X	5.9 ≥ 4.0' ■ < 4.0'	Fail		
	Width X Length Y	5.9 $\geq 4.0'$ $< 4.0'$ 4.95 $\geq 4.0'*1$ $< 4.0'*1$	Fail	·	

Cross Slope (2.0% max.)

Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Slope Y (Running Slope 1)

MISCELLANEOUS

Clear Width (feet)

Horizontal Gaps

Intersection Control Type

Pass

≤ 1/2" ■ > 1/2"

< 4.0'

≥ 4.0'

Slope of Rd.

Date (mm/dd/yy)

Certification No.

52638

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





