WASHINGTON COUNT			
OREGO			
NIM 300th Ave			

ADA Curb Ramp New Construction Inspection Form (Parallel)

NVV 309th Ave	24952.54	NVV	Brooking Ct				
North-South Road Name	Project No. She	et No. Intersection No. East-	-West Road Name	1 // 0 0 / / 0 0/			
Calibration Date 10/22/2024 (mm/dd/yy) RoadwayEng/ADA_ExhibitA.pdf for more corner styles. Use Washington County corner numbering system.							
PL	RAMP RUN 1	Pass	Fail 1		2		
Ramp Style	Running Slope 1	4.8 ≤ 2.0% > 2.0%	Corner	Positions 1			
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0% > 2.0%	Position	3 5 2A			
depends on the Intersection Control Type. At a	Detectable Warning	N Y N)		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0.5 ≤ 1/4" > 1/4"		3A -			
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	7.9 ≤* >*		North			
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	9.16 ≤ 8.3% > 8.3%>	. 🔳				
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	4.6 ≤ 5.0% ■ > 5.0%	ı 🗌 🗓	Ramp 1 Positions			
* ² Clear Space area is the width of Ramp Run 1	Det. warning full width of	ramp N Y N	Ramp Position	n 5			
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail	PE Stamp (required	for		
	Running Slope 2	≤ 8.3% > 8.3%		private developmen			
See also Standard Drawings to assess provisions not shown:	Length 2						
(inlets, alignment, etc.)	Cross Slope 2	3.2 ≤ 2.0% > 2.0%					
~	RAMP RUN 3	Pass	Fail				
	Running Slope 3	≤ 8.3% > 8.3%					
18 Pain 3 Thomas 17 Pain 17 Pain 2	Length 3						
Gutter For	Cross Slope 3	4.4 ≤ 2.0% > 2.0%					
Counter slope	TURN SPACE	Pass	Fail	ents:			
	Width X	≥ 4.0' < 4.0'					
PARALLEL RAMP (PL)	Length Y	≥ 4.0'*1 < 4.0'*1					
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/I	N) $N \ge 5.0^{1*1}$ $< 5.0^{1*1}$					
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%					
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	4.8 ≤ 2.0% > 2.0%					
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspector	r's Signature Date (m	nm/dd/yy)		
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	≥ 4.0' < 4.0'	Darre	II Wyant 526	38		
"Il constrained at back of walk, min. Thengur is 5.	Intersection Control Type	SY Slope of Rd. 5.6	Print nam	ne clearly Certifica	ation No		
Gutter Flow Slope (as directed)	Horizontal Gaps	○ ≤1/2" ■ >1/2"	3J Cons				
		1/2	Company	y/Agency			



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





