WASHINGTON COUNTY OREGON AE	OA Curb Ramp New Cons	struction Inspection	on Form (Con	nbination)	
Nw 287	24952.54		Nw mays		
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West Road N	lame o:	-)
	Calibration Date	nan (mm/dd	l/yy)	K - ') - U ‡ #	
Ramp Style C	RAMP RUN 1	Pas		- 8A	2
* The passing value for Gutter Flow Slope (GFS) depends on the Intersection Condition Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be 2.0%. * ¹If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 feet. * ² Clear Space area is the width of Ramp Run 1 and extends 4.0' into the roadway. See also Standard Drawings to assess provisions not shown:	Running Slope 1 Length 1 Cross Slope 1 Detectable Warning (Y/N) Lip Height Gutter Flow Slope Curb Running Slope (avg) Counter Slope (+/-)*2	3.9 ≤ 8.3% ■ 4.9 1.1 ≤ 2.0% ■ Y ■ ≤ 1/4" ■ 0.9 ≤ * ■ 8.7399 ≤ 8.3% ■ 3.6 ≤ 5.0% ■	> 2.0% N > 1/4" > * > *8.3%	3A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Corner Positions North Ramp Positions
(inlets, alignment, etc.)	RAMP RUN 2	Pas		Position	5
Pass Fail	Running Slope 2	7.6 ≤ 8.3%		1	PE Stamp (required fo private development)
Longest distance from detectable warning corner to back of curb (to nearest inch) $< 5.0'$ $\ge 5.0'$	Length 2 Cross Slope 2	4.45 1.1 ≤ 2.0%	<u> </u>		
Detectable warning extends full width of ramp throat opening	RAMP RUN 3 Running Slope 3 Length 3 Cross Slope 3	Pas 4.2 ≤ 8.3% ■ 4.5 ■ 1.4 ≤ 2.0% ■	> 8.3%		
Flare Slope Run 3 Run 2 Run 1 Counter slope Counter slope	TURN SPACE	Pas	<u> </u>	Comments:	_
	Width X Length Y	6.15 ≥ 4.0' ■ 4.95 ≥4.0'*1 ■	< 4.0' < 4.0'*1	IITD RR1 fail	
COMBINATION RAMP (C)	Back of Ramp Obstruction (Y/N		< 5.0'*1		
100	Slope X	2.5 ≤2.0%	> 2.0%		
COMBINATION RAMP (C) Pedestrian Access Route (to measure Clear Width)	Slope Y	≤2.0%	> 2.0%		
Detectable Warning Surface	MISCELLANEOUS Traversab				
	Flare Slope 1	≤ 10%	> 10%	In an actual Ciny	Date (mm/d
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2	≤ 10%	> 10%	Inspector's Signature	
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	4.95 ≥ 4.0'	< 4.0'	Darrell Wyant Print name clearly	52638 Certification
* If constrained at back of walk, min. Y length is 5'. Gutter Flow Slope (as directed)	Horizontal Gaps (Y/N)	≤ 1/2"	1/2"	3J Consulting	
	Intersection Control Type	SU Slope of Ro	ad 1.3	Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





