WASHINGTON COUNT
OREGO

ADA Curb Ramp New Construction Inspection Form (Parallel)

							_
	Nw. Glencoe rd	24952.54 Nw. Pacific st.					1
	North-South Road Name	Project No. Sheet No.	Intersection No.	East-West F		oregon.gov/odot/Engineering/Do	
		Calibration Date	10/9/2024 (mm/dd/yy)		_ , ,	g/ADA_ExhibitA.pdf for more cor gton County corner numbering s	
	Pi Pi	RAMP RUN 1	Pass	Fail			\ n
Ramp Style		Running Slope 1	1.5 ≤ 2.0% ■ > 2		2 Corner	Corner	2
					Position 3	Positions 2A	1
*The passing value for Gutter Flow Slope (GFS)		Cross Slope 1	1.8 ≤ 2.0% ■ > 2	.0%		5 2	
		Detectable Warning	Y	N []			
Midblock (MB), GFS must be ≤ Slope of the		Lip Height	0 ≤ 1/4" ■ > 1	/4"	1	A	
indud, at signalized of official trailed (50), at s					3A 2	North	
or Yield (SY), GFS must be ≤ 2.0%.		Gutter Flow Slope	1.5 ≤ * ►	т <u>Ш</u>		2	
		Curb Running Slope(avg)	4.04 ≤ 8.3% ■ > 8	.3%>	4	(1)	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.		Counter Slope (+/-)*2	≤ 5.0% ■ >	5.0%	1	Ramp 1	
•		Det. warning full width of ram	p Y Y	N	Ramp Position	5	
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.		RAMP RUN 2	Pass	Fail	Position	PE Stamp (requir	rad far
		Running Slope 2	3.4 ≤ 8.3% ■ > 8	3.3%		private developn	
See also Standard Drawings to assess provisions not shown:		Length 2	7.8	- Ц			
(inlet	alignment, etc.)	Cross Slope 2	1.3 ≤ 2.0% ■ > 2	0%			
Counter slope Counter slope T		RAMP RUN 3	Pass	Fail			
		Running Slope 3		3.3%			
		Length 3	14.25				
		Cross Slope 3		2.0%			
		·			Comments:		
		TURN SPACE	Pass	Fail			
		Width X		4.0'			
	PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 ■ < 4	l.0'*1			
	PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5	5.0'*1			
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.8 ≤ 2.0% > 2	2.0%			
		Slope Y (Running Slope 1)	1.5 ≤ 2.0% ■ > 2	2.0%			
	The State of Control o	MISCELLANEOUS	Pass	Fail	Inspector's Signature	Date	e (mm/dd/y
	Counter Slope (5.0% max.)	Clear Width (feet)	5.0 ≥ 4.0' < 4	4.0'	Darrell Wyant	52	638.0
	* If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU Slope of Rd. 2.6		Print name clearly		fication N
	Gutter Flow Slope (as directed)				3J Consulting		
		Horizontal Gaps □ ≤ 1/2" ■		> 1/2"	Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





