
WASHINGTON COUNTY OREGON ADA Curb Ramp New Construction Inspection Form (Combination)					
NW 307th	23886.56		NW Pacific		
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West Road Na		-)
Calibration Date $7/10/2024$ (mm/dd/yy)					
Ramp Style C	RAMP RUN 1	Pas		2	2
* The passing value for Gutter Flow Slope (GFS) depends on the Intersection Condition Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be 2.0%.	Running Slope 1 Length 1 Cross Slope 1 Detectable Warning (Y/N)	8.8 ≤ 8.3% 3.4 1.4 ≤ 2.0% Y	N	Corner Position 3	Corner Positions 2A
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 feet.	Lip Height	≤ 1/4"	> 1/4"	2	North
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0' into the roadway. See also Standard Drawings to assess provisions not shown:	Gutter Flow Slope Curb Running Slope (avg) Counter Slope (+/-)*2	1.1 ≤ * ■ 1.98 ≤ 8.3% ■ 6.3 ≤ 5.0%	> *	1 A 4 Ramp Position	Ramp Positions
(inlets, alignment, etc.)	RAMP RUN 2	Pas	s Fail		PE Stamp (required for
Pass Fail	Running Slope 2	11.7 ≤ 8.3%	> 8.3%		private development)
Longest distance from detectable warning corner to back of curb (to nearest inch) $< 5.0'$ $\geq 5.0'$	Length 2 Cross Slope 2	5.5 3.4 ≤ 2.0%	> 2.0%		
Detectable warning	RAMP RUN 3	Pass			
extends full width of ramp throat opening Y N	Running Slope 3 Length 3	8.6 ≤ 8.3% L	> 8.3% ■		
Flore Slope B Run 3 Run 2 B Run 2	Cross Slope 3	1.5 ≤ 2.0%	> 2.0%		
	TURN SPACE	Pas	s Fail	Comments:	
	Width X	3.0 ≥ 4.0'	< 4.0' ■	IITD	
Counter slope Gutter Flow slope	Length Y	5.0 ≥4.0'*1 ■	< 4.0'*1		
COMBINATION RAMP (C)	Back of Ramp Obstruction (Y/N)	≥5.0'*1	< 5.0'*1		
COMBINATION RAMP (C)	Slope X	3.0 ≤2.0%	> 2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y	2.1 ≤2.0%	> 2.0%		
Detectable Warning Surface	MISCELLANEOUS Traversable				
	Flare Slope 1	≤ 10%	> 10%		Date (////)
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2	≤ 10%	> 10%	Inspector's Signature Darrell Wyant	Date (mm/dd/yy) 52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	3.0 ≥ 4.0'	< 4.0'	Print name clearly	Certification No
Gutter Flow Slope (as directed)	Horizontal Gaps (Y/N)	≤ 1/2"	1/2"	3J Consulting	
	Intersection Control Type	SY Slope of Roa	ad 0.4	Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





