

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw 288 ter	24952.54		N	lw carver	st
North-South Road Name	Project No. Shee	et No. Intersectio	n No. Ea	st-West Ro	ad Name
	Calibration Date	nan	'dd/yy)		k - ') - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR	RAMP RUN 1 Running Slope 1	≤ 8.3	Pass >8.1	Fail	Corner Corner
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Length 1 Cross Slope 1	9.6 2.8 ≤ 2.0 ^o	~ %	0%	Position 3 Positions 2A
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Y	■ N		3A North
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%. ¹ If Back of Ramp Obstruction is Yes, turn space	Lip Height Gutter Flow Slope	1/4' _{'∆} 1.6 ≤ *	>1/		North
length Y must be minimum 5.0 ft. ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	4.78 ≤ 8.3° 3.2 ≤ 5.09			Ramp Position
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	2.25 < 5	0' ■ ≥5	5.0'	PE Stamp (require private developm
Aun 1 / Au Mar	Detectable warning extends full width of ramp throat opening	Y		N 🔲	
	TURN SPACE LANDIN	G NONE	Pass	Fail	
	Width X	5.0 ≥ 4.0	' ■ <4.	.0'	
Counter slope Counter slope	Length Y	5.6 ≥ 4.0'°	< 4.0	0'*1	Comments:
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*	< 5.0	0'*1	IITD tool joints in turn space
PERPENDICULAR RAMP (PR)	Slope X	≤2.0%	>2.0	0%	
Pedestrian Access Route (to measure Clear Width)	Slope Y	≤2.0%	>2.0	0%	
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able	Pass	Fail	
Running Slope (8.3% max.)	Flare Slope 1	≤ 10	% 🔳 < 10	0%	Inspector's Signature Date (n
Counter Slope (5.0% max.)	Flare Slope 2	≤ 109	√ (10)%	Darrell Wyant 526
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	≥ 4.0	< 4	.0'	Print name clearly Certifica
Gutter Flow Slope (as directed)	Intersection Control Type	SY Slope	of Road 0.9		3J Consulting
	Horizontal Gaps	≤1/2	" > 1/	/2"	Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





