

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

N	w 289 ave	24952.54		Nw Keenon st						$\neg$	
North-South Road Name		Project No. Sheet No.		Intersection No.		East-We	East-West Road Name				
		Calibration Date	8/6/2024	(mm/dd/	/yy)			k - ') y ‡ #	- 		
	Ramp Style PR	RAMP RUN 1		Pass				4 Co	rner	A	
Γhe passi	\ <i>"</i>	Running Slope 1 Length 1	9.5	≤ 8.3%		>8.3%	Ч	Corner Position 3	itions 2A	11	
•		Cross Slope 1	1.2	≤ 2.0%		>2.0%			2 1	3	
•		Detectable Warning (Y,N)	Υ	Y		N		3A No	-th		
	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height	0	1/4"		>1/4"		2 No	2		
If Back of Ramp Obstruction is Yes, turn space ength Y must be minimum 5.0 ft.			N/A 1.8	≤ *		>*		4 Ba	amp 1		
_		Curb Running Slope (avg)	9.58	≤ 8.3%		>8.3%		/ 510	itions		
	pace area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.9	≤ 5.0%		> 5.0%			DE Stanon (no		
	Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	2.1	< 5.0'		≥ 5.0'		1	PE Stamp (re private deve	•	
/.	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N					
/ * * * / F // * * /		TURN SPACE LANDIN	G NC	ONE 🔳	Pass		Fail				
	Run 1	Width X	4.2	≥ 4.0'		< 4.0'					
Counter slope Guiter Flow slope		Length Y	9.3	≥ 4.0'*1		< 4.0'*1		Comments:			
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*1		< 5.0'*1					
P	ERPENDICULAR RAMP (PR)	Slope X	1.3	≤2.0%		>2.0%					
	Pedestrian Access Route (to measure Clear Width)	Slope Y	1.8	≤2.0%		>2.0%					
	Detectable Warning Surface	MISCELLANEOUS Traversa		Pass	ass	Fail		Γ			
<b>₩</b>	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature	L	ate (mr	
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Dormall Whent			
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant Print name clearly		52638 ertificat	
-	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	1.8		3J Consulting			
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency			



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





