

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

OREGON	·				- <u> </u>		<u>,                                      </u>	
North Couth Dood North	24952.54 Shoo	at No. Ja	* N	1-	5	t D -	and Maria	
North-South Road Name			tersection N	10.	East-W	est Ro	oad Name	
	Calibration Date	7/30/2024	4 (mm/dd,	/yy)			y ; #	
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	midblock Corner	
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Length 1						Position 3 Positions 2A	7
Midblock (MB), GFS must be $\leq$ Slope of the Road, at	Cross Slope 1	11.15	≤ 2.0%		>2.0%	Щ	3	
Signalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Υ	Υ		N	Ц	3A North	
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height	0	1/4"		>1/4"	Ш	2 NOITH	
<sup>1</sup> If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope	1.3	≤ *		>*		nan 4 Ramp 1	
<sup>2</sup> Clear Space area is the width of Ramp Run 1 and	Curb Running Slope (avg)	4.58	≤ 8.3%		>8.3%		Ramp Positions	
extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Position 5	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (red private devel	-
X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Υ		N			
/ * * * * / * // * * /	TURN SPACE LANDING	G NON	E	Pass		Fail		
Run !/	Width X		≥ 4.0'		< 4.0'			
Counter slope Counter slope	Length Y	2.3	≥ 4.0'*1		< 4.0'*1		Comments:	
	Back of Ramp Obstruction (Y/N)		≥ 5.0' <b>*</b> 1		< 5.0'*1		RR1 ICRR	
PERPENDICULAR RAMP (PR)	Slope X	Y	≤2.0%		>2.0%	$\overline{\Box}$		
Pedestrian Access Route (to measure Clear Width)			≤2.0%		>2.0%	$\Box$		
Detectable Warning Surface	Slope Y	السلام	32.070	Davis	2.070			
Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	bie		Pass		Fail	i L	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%	Щ	< 10%	Щ	Inspector's Signature Da	ate (mm/
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%	Ш	Darrell Wyant 5	52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*  * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.8	≥ 4.0'		< 4.0'			rtificatio
Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of				3J Consulting	
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





