	WASHINGTON COUNTY	1			
OREGON					
	NW Timeric				
	North-South Road Name				
		PL			
		Ramp Sty			
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.					
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.					
	*2 Clear Space area is the width of Ramp Run 2 and extends 4.0 ft into the roadway.				

(inlets, alignment, etc.)

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

Project No. Sheet No. Intersection No. East-West Roa				oad Name See https://www.oregon.gov/odot/Engineering/Documents RoadwayEng/ADA_ExhibitA.pdf for more corner styles.	
	Calibration Date	Use Washington County corner numbering system.			
PL	RAMP RUN 1	Pass	Fail		
Ramp Style	Running Slope 1	≤ 2.0%	%	Corner Position Positions	
pe (GFS) pe. At a the), GFS	Cross Slope 1	≤ 2.0% > 2.0	%	Position 3	
	Detectable Warning	Υ N			
	Lip Height	≤ 1/4"	" 🔳	3A 1	
	Gutter Flow Slope	2.7 ≤ * ■ > *		2 North	
	Curb Running Slope(avg)	4.74 ≤ 8.3% > 8.3	%>	Ramp 1	
urn	Counter Slope (+/-)*2	12.9 ≤ 5.0% ■ > 5.0)%	Positions Positions	
p Run 1	Det. warning full width of ramp	o Y N		Ramp Position	
	RAMP RUN 2	Pass	Fail	PE Stamp (required for	
	Running Slope 2	≤ 8.3% > 8.3	%	private development)	
not shown:	Length 2	6.3			
	Cross Slope 2	4.1 ≤ 2.0% > 2.0	% ■		
	RAMP RUN 3	Pass	Fail		
	Running Slope 3	≤ 8.3% > 8.3	3%		
	Length 3	7.35			
	Cross Slope 3	10 ≤ 2.0% > 2.0)% 🔳	- Comments:	
	TURN SPACE	Pass	Fail		
	Width X	4.9 ≥ 4.0')'	NO DWS Fail RR and Turn Space	
	Length Y	5.0 ≥ 4.0'*1 ■ < 4.0	'*1 <u> </u>		
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 < 5.0	ا*۱		
/idth)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0)%		
	Slope Y (Running Slope 1)	≤ 2.0% > 2.0)%		
	MISCELLANEOUS	Pass	Fail	Inspector's Signature Date (mm/dd/yy)	
	Clear Width (feet)	4.9 ≥ 4.0' < 4.0)'	Darrell Wyant 52638	
	Intersection Control Type	Slope of Rd. 3.3	}	Print name clearly Certification No	
	Horizontal Gaps	≤ 1/2" > 1/		3J Consulting Company/Agency	

NW Lenox



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





