Început la	luni, 11 mai 2020, 20:34
Status	Terminat
Completat la	luni, 11 mai 2020, 20:42
Timp luat	8 min
Notează	**8,00** din maxim 10,00 (**80**%) posibil

1 întrebare
Corect
Marcat 2,00 din 2,00

Why do we have to wait after sending a single byte write command (START-0xA0-0x00-0x00-STOP) to the 24c02 serial memory, via IIC?

Alegeți o opțiune:

- a. to allow the device to reply with the content of the memory
- b. to allow the device to write the information in the memory ✔
- c. to wait until the slave parse the entire message/communication
- d. to allow another slave to respond and to avoid the collision

Răspunsul dumneavoastră este corect.

Răspunsul corect este: to allow the device to write the information in the memory

2 întrebare
Corect
Marcat 2,00 din 2,00

What is the difference between the next 2 headers: 0xA0 and 0xA1?

Alegeți o opțiune:

- a. NACK/ACK
- b. 2 different slaves
- c. No difference - the last bit is ignored and it is used only for back compatibility
- d. Read/Write ✔

Răspunsul dumneavoastră este corect.

Răspunsul corect este: Read/Write

3 întrebare
Corect
Marcat 2,00 din 2,00

What happens if the master replies with NACK after the first received byte?

Alegeți o opțiune:

- a. The communication will stop and the slave will not send any other byte ✔
- b. The slave will retransmit the last byte because it the master signalized that receiving was un-normal
- c. The slave will issue a STOP condition
- d. Nothing - the slave will continue to send bytes (the ACK from master is optional)

Răspunsul dumneavoastră este corect.

Răspunsul corect este: The communication will stop and the slave will not send any other byte

4 întrebare

Incorect

Marcat 0,00 din 2,00

How many I2C slaves may be addressed by ATmega324?

Alegeți o opțiune:

- a. 128
- b. 8 ✖
- c. 7 (because of the transmit/receive last bit from the header)
- d. 127 (because of the transmit/receive last bit from the header)

Răspunsul dumneavoastră este incorect.

Răspunsul corect este: 128

5 întrebare

Corect

Marcat 2,00 din 2,00

How many wires are needed to connect one I2C master to 3 slaves (besides POWER and GND)?

Alegeți o opțiune:

- a. only 2 ✔
- b. only 3
- c. 3 and another 3 for each slave
- d. more than 3

Răspunsul dumneavoastră este corect.

Răspunsul corect este: only 2

◄ Test Laborator 0xC5 - SPI

Salt la...

Test Laborator 0XC5 - SPI (Laborant: Vlad Isuf) ►