SAMSUNG

N233284

DOA Certificate No	4339314356
DOA Issue Date	23/11/2021

ORIGINAL

YESINO

NU

NO

NC

NO

N

					DOA	A Issue Date	23/11/2021	
			DEAD ON AF	RRIVAL (DOA)	ERTIFICATE		ORIGIN	
Service Centre Name & Dealer Name & Address :		Finance	Finance: Inactive Financer:					
SS Quick Garag lezzanina Fir, Of IAGAR, DR.HON IASIK 22011	1,182, 1st F	Ir RV		Paste II	MEI Label of SWAP S	Sct (To be done	by dealer)	
Vork order No.	: 4336314	4356		Work order Da	te: 10/11/2021			
				Customer Info	rmation			
Name		ABHIJEE"	SUNIL SOMNI					
Contact No(Mo	ob)				ntact No(Fixed)	7738394501		
Address		NASHIK F Maharash		SHIK ROAD NASH	IK DAATAMANDIR BYIT	CO POINTG NASH	HIKNASHIK NASHIK27	
				Product Infor	mation			
Model SM-A037FZKGINS		KGINS	S/N	R9ZR80E85QF	IMEI/RSN/ESN	*******6531	531406	
mouti			OD HAIDERA	Sim activation date	e 08-11-2021			
Invoice No Defect report Defect diagno Remark : H/W	PROBLEM	ngineer FOUND WI	The second second second	OUND WITH IN 14				
Invoice No Defect report Defect diagno Remark : H/W I	ed by Cus osed by E PROBLEM	ngineer FOUND WI	VHITE SPOT ON D HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin	OUND WITH IN 14	DAYS y Service Centre Engl		YESING	
Defect reports Defect diagno Remark : H/W S.No. Checkpo	ed by Cus psed by E PROBLEM pint Descri	FOUND WI	WHITE SPOT ON D HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the s	OUND WITH IN 14 ts (To be filled b	DAYS y Service Centre Engli e time of purchase?		Y 🖾 N	
Defect reported to the problem of th	ed by Cus osed by E PROBLEM oint Descri g all access	ngineer FOUND WI iption series as we	VHITE SPOT ON D HW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the s and diagnosed by	OUND WITH IN 14 ts (To be filled beales package at the	DAYS y Service Centre Engli e time of purchase?		Y N	
Defect report Defect diagno Remark : H/W I S.No. Checkpo 1 Box containing 2 Is the problem IMEU/RSN/ESM	ed by Cus osed by E PROBLEM Dint Descri g all access reported by N & Serial N	iption sories as we y customar	VHITE SPOT ON DI HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the s and diagnosed by ce is matching with	OUND WITH IN 14 ts (To be filled because package at the engineer, reproduct that of the Product	DAYS y Service Centre Engli e time of purchase?		Y N N	
Defect reports Defect diagno Remark : H/W I S.No. Checkpo 1 Box containing 2 Is the problem IMEI/RSN/ESN There are no s	ed by Cus psed by E PROBLEM Dint Descri g all access reported b N & Serial N	iption sories as we ye customar	WHITE SPOT ON DITHW PROBLEM FOR THE IN 14 DAYS DOA Checkpoin as provided in the sand diagnosed by the sand di	OUND WITH IN 14 Its (To be filled be bales package at the engineer, reproduct that of the Product?	DAYS y Service Centre Engli e time of purchase? cible ?		Y N N Y N N	
Defect reports Defect diagno Remark : H/W I S.No. Checkpo 1 Box containing 2 Is the problem IMEI/RSN/ESN There are no s	ed by Cus psed by E PROBLEM Dint Descri g all access reported b N & Serial N	iption sories as we ye customar	VHITE SPOT ON DI HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the s and diagnosed by ce is matching with	OUND WITH IN 14 Its (To be filled be bales package at the engineer, reproduct that of the Product?	DAYS y Service Centre Engli e time of purchase? cible ?		Y N N	
Defect reports Defect diagno Remark : H/W I S.No. Checkpo 1 Box containing 2 Is the problem IMEI/RSN/ESN There are no s	ed by Cuspsed by E PROBLEM Dint Describ g all access reported by N & Serial N Signs of una	iption sories as we y customer look on Involutharized (Out-	VHITE SPOT ON DITHW PROBLEM FOR THE IN 14 DAYS DOA Checkpoin as provided in the seand diagnosed by the seand diagnosed by the seand (Tampering) and no side/inside) and no side/inside) and no side/inside).	OUND WITH IN 14 Its (To be filled be bales package at the engineer, reproduct that of the Product?	DAYS y Service Centre Engli e time of purchase? cible ?		Y N N	
Invoice No Defect report Defect diagno Remark: H/W S.No. Checkpo 1 Box containing 2 Is the problem IMEL/RSN/ESN There are no s i Unit is not phy 3 Product is not	ed by Cuspsed by E PROBLEM Dint Descri g all access reported by N & Serial N signs of una vsically dam	ingineer FOUND WI Iption sories as we y customer No. on Invol authorized re haged (Outside	VHITE SPOT ON DITHW PROBLEM FOR THE IN 14 DAYS DOA Checkpoin as provided in the seand diagnosed by the seand diagnosed by the seand (Tampering) and no side/inside) and no side/inside) and no side/inside).	OUND WITH IN 14 te (To be filled be bales package at the engineer, reproduct that of the Product?	DAYS y Service Centre Engli e time of purchase? cible ?		Y N N	
Invoice No Defect report Defect diagno Remark: H/W S.No. Checkpo 1 Box containing 2 Is the problem IMEL/RSN/ESN There are no s i Unit is not phy 3 Product is not	ed by Cuspsed by E PROBLEM Dint Descri g all access reported by N & Serial N signs of una vsically dam	ingineer FOUND WI Iption sories as we y customer No. on Invol authorized re haged (Outside	WHITE SPOT ON DI HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the si and diagnosed by ce is matching with epair (Tampering) side/inside) and no of Inside)?	OUND WITH IN 14 te (To be filled be bales package at the engineer, reproduct that of the Product?	DAYS y Service Centre Engli e time of purchase? cible ? ti ?		Y 2 N Y 2 N Y 3 N Y 4 N Y 4 N Y 5 N	
Invoice No Defect report Defect diagno Remark: H/W S.No. Checkpo 1 Box containing 2 Is the problem IMEL/RSN/ESN There are no s i Unit is not phy 3 Product is not	ed by Cuspsed by E PROBLEM Dint Descri g all access reported by N & Serial N signs of una vsically dam	ingineer FOUND WI Iption sories as we y customer No. on Invol authorized re haged (Outside	WHITE SPOT ON DI HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the si and diagnosed by ce is matching with epair (Tampering) side/inside) and no of Inside)?	OUND WITH IN 14 te (To be filled be bales package at the engineer, reproduct that of the Product? p scratches on cost and the product that of th	DAYS y Service Centre Engli e time of purchase? cible ? ti ?		Y 2 N Y 2 N Y 3 N Y 4 N Y 4 N Y 5 N	
Invoice No Defect report Defect diagno Remark: H/W S.No. Checkpo 1 Box containing 2 Is the problem IMEI/RSN/ESN There are no s I Unit is not phy 3 Product is not 7 IMEI Label or	ed by Cuspsed by E PROBLEM Dint Description of the properties of the properties of the properties of the properties of the product is the pro	iption sories as we y customer vo. on Involutharized in neged (Outside not tamper	WHITE SPOT ON DI HAW PROBLEM FO TH IN 14 DAYS DOA Checkpoin as provided in the si and diagnosed by ce is matching with epair (Tampering) side/inside) and no of Inside)?	ound with in 14 ts (To be filled be bales package at the engineer, reproduct in that of the Product? construction of the product in that of the Product in the Product i	DAYS y Service Centre Engli e time of purchase? cible ? at ? metic /covers ?	neer)	Y 2 N Y 2 N Y 3 N Y 4 N Y 4 N Y 5 N	

Customer has to visit dealer alongwith sealed set & certificate to get the replacement (swap by dealer). +Customer Signature

DOA Authorization

Service centre has to ensure proper check before issuing DOA as per policy. Make sure product has been packed properly alongwith all genuine accessories and DOA certificate (sealed with unique seals).

Remarks by Service Centre Engineer (fault reproduction

Remarks by Service Centre Manager

(Engineer Name & Signature) (Manager Name & Signature)

-THIS CERTIFICATE IS VALID FOR 7 DAYS ONLY FROM THE DATE OF ISSUES

(Service

e Slamp

NMSUNG

Acknowledgement of Service Request

Service Centre: 0002450421 -- GSS Quick Garage India Pvt Ltd
Address: Mezzanine Fir, DII.182, 1st FI
Nagar, Dr.Homi Bebs Nagar, Nasik422011
Contact Centre: 1800408AMSUNG

(1800-40-7267864)

Track Your Repair Status online: www.samsung.com/in/support



om No 1 41	136314356 Call Fo	4336314366 or Status : 91-7305023008 Delivery	Time : 11 a.	m. to 6 p.m	n. CSR Pr	int Date : 10.1	1,2021 Time 11,10,202 12:28:37	: 12:31:32
		ABHIJEET SUNIL SOMNI NASHIK ROAD NASHIK NASHII			THE WOLD IN	BVITCO FOIN	TG NASHIK	NASHIK
ustomer	Name	WASHIN BOAD NASHIK NASHI	K ROAD NAS	SHIK DAAT	AMANDIN	Billoon		
Admis		NASHIK27 Maharashtra IN			Engineer		KIRANW	AGH
Appointment Date 11.10.2021 (12.17.08)					ASSESSMENT OF THE PARTY OF THE		7219076	
				Fax No Purchase Date			11 09.2021	
Telephon	10	SM A037FZKGINS	A ADSTETKGINS			And the second s	Carry In	
Model Name SM AUSTERNAM			05)		Service Type		Warranty	
	o (CRT/ESN/IMEI)	MY Lab	or Only	Part	s Only	-	rvairainy	
	ty Status	Full Warranty Ca Lab				ompleted	-	
	Received				Return b		-	
	Delivered	WHITE SPOT ON DISPLAY			B2B SV		N	
-	Description	HANDSET SUBMITED (WITH	HALL ACCES	SSORY)				-
Acces		SIM , MMC RETURN , DATA	LOSS (WIT)	IIN 14 DAYS	S)			-
Remail	And in column 2 and in column 2 in case of the last	SIM, MINE RETORN !						
COMPANDED TO SERVICE STATE	Description	Symptom Code		Defect Cod	ie	Repair	Code	
Condit	Ion Code	Symptom	-					Part Return
No	Parts No	Description		Location	Qty	Unit Price (INR)	Amount (INR)	Date
- more to to							-	-
-								
_	1							0.00
			1	Total Parts	Cost	INF		0.00
				abor		INF		0.00
				Transportat	tlon	INF		0.00
	1			Other amou	unt	INF	-	0.00
	1 3130	7		Tax		INF		0.00
	1/40			Grand Tota	1	INF		0.00
1	ny full satisfaction.	have received my product in good work				1		
	regard to hazardous spare parts and the and safeguard the o		e-waste to pro	the street	Reo	eived by:	10.2021 12:2	3:37
	waste. Therefore I a	dge that the replaced defective part may am feaving the same at Service Center I	for safe dispos	al.	Deli	vered by:		
	OR ABI	Meet	oliect defective	OR e part of			1	1
	my product the sal acknowledge that	rage that I have chosen to receive and o me may be an environmentally hazardo I shall handle it responsibly in an enviro	us E-waste.	further _			A	EU,
	rannem							

Sinnature of Customer & Collection Date

For Service Center

DOA AMSUNG

Acknowledgement of Service Request

Service Centre: 0002450421 - - G38 Quick Garage India Pvt Ltd Address: Mezzanine Fir, Off.182, 1st Fi

Nagar, Dr.Homl Baba Nagar, Nasik422011 Contact Centre: 1800405AMSUNG

(1500-40-7207864)

Track Your Repair Status online: www.samsung.com/in/support



4336314306

EIII No : 4336314350 Com		Request	Date	1,2021 Time : 12:31:32 11 10.2021 12:28:37			
Customer Name	ABHIJEET SUNIL SO NASHIK ROAD NAS	MAIN BO	AD NASHIK DAAT	AMANDIF	BYITCO POL	NTG NASHI	KNASHIK
	NASHIK ROAD NAS	HIK NASHIK KO	AD I WILLIAM			Tourse	MARKE
Address	NASHIK27-Maharasi		Englnee			KIRAN WAGH	
Appointment Date	11.10.2021 (12:17:00 [Home]7738394501	01	Fax No.			7219076829	
Telephone	[Homa]//38394501		Purchas	e Date	and the last of th	11.09.2021	
Model Name	SM A037FZKGINS		Service	Туре	Carry In		
Serial No. (CRT/ESN/IME)	AL REAL PROPERTY AND ADDRESS OF THE PARTY AND	R9ZR80E85QF (******6531406)				Warranty	
Warranty Status	Full Warranty	Labor Cr	17		Completed		
Repair Received				Commence of the Commence of th	by / Date		
Goods Delivered		DICTI IV		B2B SV		N	
Defect Description	WHITE SPOT ON	DISPLAY	ACCESSORY)				
Accessory	HANDSET SUBMI	TED (WITH ALL	(WITHIN 14 DAYS	5)			
Remark	SIM, MMC RETU	RN DATA LOSS	(100				
Repair Description	Sumpto	m Code	Defect Code	0	Repai	r Code	1
No Parts No	Descri		Location	Qty	Unit Price (INR)	Amount (INR)	Part Return Date
-							
				-	-	4	-
				-			-
				-	-		-
			Total Parts C	ost	INI	3	0.00
			Labor		INI	?	0.00
			Transportati	011	INI	3	0.00
1			Other amou	nt	IN	3	0.00
000	7		Tax		1/1	3	0.00
1/40			Grand Total		INI	7	0.00
my full satisfaction. I have read and unders regard to hazardous na spare parts and the reand safeguard the env. I hereby acknowledge waste. Therefore I am.	tood the communication interest of the electrical and ed for safe handling and ironment. That the replaced defectioning the same at Service in the same at Serv	brought to my kno electronic equipm disposal of e-wast	e-	CC	elved by tokemalb on 11	.10.2021 12:2	18:37

Signature of Customer & Collection Data

For Service Center