



Enabling the future of Air conditioning



"Safety has to be everyone's responsibility... Everyone needs to know that they are empowered to speak up if there's an issue."



"सुरक्षा हर किसी की ज़िम्मेदारी होनी चाहिए... हर किसी को यह जानना होगा कि यदि कोई समस्या है तो वे बोलने के लिए सशक्त हैं।"



URL: www.esaplling.com

Your Personal protective Equipment's





आपके व्यक्तिगत सुरक्षा उपकरण

Welding equipment



वेल्डिंग उपकरण





Welding Safety Rules





Conduct in a designated safe location



Protect yourself from fire hazards



Consider the risks



Maintain your equipment



Protect yourself with the correct PPE



Check for ventilation



Protect yourself from fumes and gases



Protect other workers



Read warning labels, relevant documents and keep training



Enforce Safety Procedures





In Case of Emergency

आपात्कालीन स्थिति में



Safety Officer:

PMO:

Ambulance:

Fire :





We ensuring the safety and well-being of our workforce is our top priority. As we continue to strive for excellence in our operations, it is

crucial that we maintain a strong focus on labour safety and the proper use of Personal Protective Equipment (PPE).

Your family is waiting for you at home. आपका परिवार घर पर आपका इंतजार कर रहा है

Always wear the required PPE: Helmets, gloves, safety glasses, ear protection, and other PPE must be worn as specified for different tasks.

Proper Usage: Ensure that you know how to correctly use and wear your PPE. If you are unsure, please ask your supervisor for guidance.



Inspect your PPE: Before using any PPE, inspect it for any damage or wear. Damaged PPE should be replaced immediately.

Maintenance: Keep your PPE clean and store it properly to extend its lifespan and effectiveness.

URL: www.esaplling.com

Welding and Cutting

Do's

- 1. Wear required Personal Protective Equipment (PPE)
- 2. Protect other workers from flashes.
- 3. Have an adequate fire extinguisher readily available.
- 4. Provide fire watch if needed.
- 5. Remove combustible materials from the vicinity of cutting and welding operations.
- 6. Secure all connections, couplings and fittings on your rig.
- 7. Inspect equipment before use.
- 8. Contain sparks and slag created by welding or burning operations.
- 9. Protect welding leads and burning hoses by covering or suspending.
- 10. Store gas cylinders upright with the valve end up.
- Separate oxygen and acetylene in storage by 20 feet or a five-foot, half-hour rated fire wall.
- 12. Clear debris from work area after work is completed.

Don'ts

- 1. Cut or weld in an area with oily rags, dust or other combustible material nearby.
- 2. Weld in an area unless other workers have a welding screen to protect them from the welding arc.
- 3. Transport bottles with gauges installed.
- Use worn cable.
- Use worn hoses.
- 6. Wear clothes of synthetic fabrics.
- 7. Assist anyone cutting or welding unless you are wearing eye protection.
- 8. Leave your area of work without notifying others of the burn hazard.
- 9. Work in an area that is not grounded.
- 10. Weld or cut hot tanks or pipe without proper precautions.
- 11. Run welding leads and burning hoses through doorways.
- 12. Attempt to transfer compressed gas from one cylinder to another.
- 13. Use valve protection caps to lift cylinders.





Do's







URL: www.esaplling.com

Know the right Fire Protection















How to Use Fire Extinguisher


PASS Method







AIM



SQUEEZE



SWEEP