$$(\downarrow) -T+T+dT+qdz=0$$

(Q5)
$$-M+H+dM-Tdz+qdz\frac{dz}{2}=0$$

$$N'+p=0$$
infin. and di
ordine dz^2

$$N(z) = -P - \int_{0}^{z} r dz$$

$$N(0) := \lim_{z \to 0} N(z) = -P$$


Re
$$\rightarrow$$
 N(e) = \rightarrow N(e) = \rightarrow Ne \rightarrow T(e) = \rightarrow Te \rightarrow M(e) = Re \rightarrow Ne

$$N(0) = -F_0 \cdot k$$

$$T(0) = -F_0 \cdot j$$

$$M(0) = -F_0 \cdot j$$


ESTREHO VINCOLATO



$$N(\ell) = F_{\ell} \cdot k$$

$$T(\ell) = F_{\ell} \cdot j$$

$$M(\ell) = R_{\ell}$$



$$N(0) = -F_0 \cdot k =: N_0$$

$$T(0) = -F_0 \cdot j =: T_0$$

$$M(0) = -R_0 =: M_0$$