



EMERGENCY RESCUE SHEET

Freightliner eCascadia: Models 2022 to Present



					
Electric Propulsion	Charge Port	High-Voltage Li-ion Battery	High Voltage Component	Cable Cut	Airbag Inflator/ Stored Gas Inflator*
					
Low-Voltage Battery	Exits	High-Voltage Power Cable	Disconnect High Voltage	Airbag*	
					* If Equipped

⚠ WARNING

If high-voltage equipment or high-voltage cables (orange sheathing) are damaged due to an accident related to the equipment shown above, there may be a short circuit. Be sure to put on insulated protective gear, such as insulated clothes and gloves, before starting rescue operations.

NEVER CUT HIGH-VOLTAGE CABLES (ORANGE SHEATHING)



EMERGENCY RESCUE SHEET

Freightliner eCascadia: Models 2022 to Present

WARNING

For extrication purposes, the electric vehicle is expected to contain at least one and potentially two or more occupants, depending on cab type and other factors. The optimal cut locations to disconnect the high-voltage system are positioned externally to the cab, beneath the driver and passenger doors, between the A-pillar and B-pillar, as illustrated.

If equipped, no airbag inflators, pyrotechnic devices, or related components are expected in proximity to the designated cut points external to the cab; nonetheless check before piercing vehicle, as the vehicle may be modified from the as-built configuration.