





EMERGENCY RESCUE SHEET

Freightliner eM2: Models 2023 to Present



				
Electric Propulsion	Charge Port	High-Voltage Li-Ion Battery	High Voltage Component	Cable Cut
				
Low-Voltage Battery	Exits	High-Voltage Power Cable	Disconnect High Voltage	

⚠ WARNING

If high-voltage equipment or high-voltage cables (orange sheathing) are damaged due to an accident related to the equipment shown above, there may be a short circuit. Be sure to put on insulated protective gear, such as insulated clothes and gloves, before starting rescue operations.

NEVER CUT HIGH-VOLTAGE CABLES (ORANGE SHEATHING)



EMERGENCY RESCUE SHEET

Freightliner eM2: Models 2023 to Present

WARNING

For extrication purposes, the electric vehicle is expected to contain up to two occupants. The optimal cut locations to disconnect the high-voltage system are positioned externally to the cab, beneath the driver and passenger doors, between the A-pillar and B-pillar, as illustrated.

No airbag inflators, pyrotechnic devices, or related components are expected in proximity to the designated cut points external to the cab; nonetheless check before piercing vehicle, as the vehicle may be modified from the as-built configuration.