


POSTED 2107-044

**EWR D&I ANNOTATION**

FAN-000001L064001DP88-1444

**Artemis # :** 000001L064001DP88**Record Created Date :** 07/24/2007**Printed Date :** 08/01/2007

**Description :** THE DRIVER OF THE SUBJECT VEHICLE WAS TRAVELING NORTHBOUND ON A LOCAL ROAD WHEN, FOR UNKNOWN REASONS, THE VEHICLE VEERED OFF THE ROAD INTO A DITCH, WHERE THE VEHICLE STRUCK A TREE. THE DRIVER SUFFERED SEVERE INJURIES, HOWEVER, TWO PASSENGERS SUFFERED FATAL INJURIES. NO DEFECT ALLEGATIONS WERE INCLUDED IN THE RESPONSE. THE POLICE REPORT INDICATES THAT THE DRIVER FAILED TO CONTROL THE VEHICLE. THE REPORT ALSO INDICATES THAT ALL THREE VEHICLE OCCUPANTS FAILED TO WEAR THWIE SAFETY RESTRAINTS. THE OWNER OF THE VEHICLE TOLD POLICE THAT THE VEHICLE HAD PREVIOUSLY RECEIVED RECALL RELATED WORK ON THE AIRBAGS AND WINDSHIELD WIPER SWITCH. THE SUBJECT VEHICLE MANUFACTURER HAS MADE NO ASSESSMENT OF THIS CRASH EVENT. THERE ARE NO APPARENT SAFETY RECALLS THAT RELATE TO THE ISSUES IN REGARDS TO THIS CRASH EVENT.

Print

Close

Copyright © 2007 Artemis. All rights reserved.

Version 3.0.2

IN-06-033  
SCI • ~~CAOS-049~~



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

1200 New Jersey Ave., S.E.  
Washington, D.C. 20590

**CERTIFIED MAIL**  
**RETURN RECEIPT REQUESTED**

MAY - 7 2007

Ms. Gay Kent  
General Motors Corp.  
Mail Code 480-210-G11  
30001 Van Dyke  
Warren, MI 48090

NVS-217ph  
DI07-044

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors (GM) in its light early warning report from 4th quarter of 2006. We are writing to request additional information about the following incidents:

| Selected Death and Injury Incidents                                                                                                                          |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| For Reporting Category: L                                                                                                                                    |  |
| For the following Sequence IDs: 30, 40, 88, 91, 103, 116, 135, 137, 140, 155, 221, 244, 246, 256, 257, 273, 274, 285, 295, 345, 360, 368, 401, 424, 436, 439 |  |

Unless otherwise stated in the text, the following definitions apply to these information requests:

**Incident:** each incident identified in the table above.

**Claim and Notice:** shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

**Manufacturer:** refers to GM.

**Vehicle:** the vehicle produced by GM that is identified in the claim or notice.

**Tire:** the tire produced by GM that is identified in the claim or notice.



VEHICLE SAFETY HOTLINE  
888-327-4236



**Equipment:** the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

**Defect:** means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

**Document:** "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


This letter is being sent to GM pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49 and to request reports and the production of things. It constitutes a new request for information. GM's failure to respond promptly and fully to this letter could subject GM to civil penalties pursuant to 49 U.S.C. § 30165 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163. (Other remedies and sanctions are available as well.) Section 5(a) of the TREAD Act, codified at 49 U.S.C. § 30165(b), provides for civil penalties of up to \$5,000 per day, with a maximum of \$16,050,000 for a related series of violations, for failing or refusing to perform an act required under 49 U.S.C. § 30166. See 49 CFR 578.6 (as amended by 69 Fed. Reg. 57864 (Sept. 28, 2004)). This includes failing to respond to ODI information requests.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590.

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **June 8, 2007**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief  
Early Warning Division  
Office of Defects Investigation  
Enforcement





GENERAL MOTORS NORTH AMERICA  
Structure & Safety Integration

June 7, 2007

Ms. Christina Morgan, Chief  
Early Warning Division  
Office of Defects Investigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, DC 20590

NVS-217ph  
DI07-044

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated May 7, 2007 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from 4th quarter of 2006.

GM's response is comprised of 29 CDs for the incidents that are the subject of DI07-044.

Attachment "A" includes instructions for navigating the CD. Each CD, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 256 210873110 - 625130 and 2004 Chevrolet Suburban 1500. When the CD is launched, this identification number appears again along with all of the documents (including photographs and videos) on the CD listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 256 210873110 - 625130 **\_00\_Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the first two Inquiries and Responses in the index for the CD are as follows:

DI07-044  
256 210873110 - 625130  
2004 CHEVROLET SUBURBAN 1500

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 256 210873110 - 625130 **\_01\_1** - is the first document responsive to Inquiry no. 1.  
256 210873110 - 625130 **\_02\_1** - is the first document responsive to Inquiry no. 2.

**Product Investigations**

Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090  
DI07-044 Response.doc



Letter to Ms. Christina Morgan  
 DI07-044 Response  
 June 7, 2007  
 Page 2 of 5

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

The table below lists the incidents that are the subject of DI07-044, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR), or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further. As such, the document included in response to Inquiry 1 that can be found on the enclosed CD for the PAR and Rumor case listed in the table, may not be a claim or notice of the type generally defined as such by §579.4(c).

| (26 Vehicles from the Light Vehicle Template) |                                     |       |
|-----------------------------------------------|-------------------------------------|-------|
| SEQUENCE ID                                   | VEHICLE IDENTIFICATION NUMBER (VIN) | TYPE  |
| ✓ 30                                          | 1G6DP577770                         | NISM  |
| ✓ 40                                          | 1G6KD54Y05U                         | NISM  |
| ✓ 88                                          | 1G1AK52F657                         | RUMOR |
| ✓ 91                                          | 1G1AK52F957                         | RUMOR |
| ✓ 103                                         | 1G1AL15F877                         | NISM  |
| ✓ 116                                         | 1GNFG15T851                         | LIT   |
| ✓ 135                                         | 2G1WH52K349                         | NISM  |
| ✓ 137                                         | 2G1WH52K249                         | NISM  |
| ✓ 140                                         | 2G1WF52E159                         | LIT   |
| ✓ 155                                         | 1G1ND52J83M                         | NISM  |
| ✓ 221                                         | 2GCEC19T041                         | LIT   |
| ✓ 244                                         | 1GCHK29U23E                         | LIT   |
| ✓ 246                                         | 1GCHK23225F                         | LIT   |
| ✓ 256                                         | 1GNFK16T74J                         | LIT   |
| ✓ 257                                         | 3GNFK16T64G                         | RUMOR |
| ✓ 273                                         | 1GNEC13V74J                         | LIT   |
| ✓ 274                                         | 1GNEC13TX5F                         | LIT   |
| ✓ 285                                         | 1GNDS13S822                         | LIT   |
| ✓ 295                                         | 1GNDT13S542                         | RUMOR |
| ✓ 345                                         | 1GTEC14T74Z                         | LIT   |
| ✓ 360                                         | 1GKEC16Z14R                         | LIT   |
| ✓ 368                                         | 5GTDN136468                         | RUMOR |
| ✓ 401                                         | 1G2ZG58B574                         | NISM  |
| ✓ 424                                         | 2G2WP552661                         | RUMOR |
| ✓ 436                                         | 1G8AJ52F14Z                         | LIT   |
| ✓ 439                                         | 1G8AJ55F96Z                         | NISM  |



Letter to Ms. Christina Morgan  
DI07-044 Response  
June 7, 2007  
Page 3 of 5

**2. Provide a copy of the Police Accident Report.**

Response: See Attached Documents.

**3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**


To date, General Motors' investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators, and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




Gay P. Kent <sup>FOR</sup>  
Director  
Product Investigations

Enclosures: 29 Discs  
Attachment A


Letter to Ms. Christina Morgan  
 DI07-044 Response  
 June 7, 2007  
 Page 4 of 5

## Attachment A Instructions for using CD Viewer

1. Insert the CD into the CD ROM drive; the CD will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



### Product Investigations

Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090  
 DI07-044 Response.doc







**DI07-044**  
**88 210872965 – 624620**  
**2005 CHEVROLET COBALT**

**Request for Information:**

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Documents and Photographs.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: To date, General Motors' investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.



# TwinCities.com

## PIONEER PRESS

Our Local Channels ▸ News ▾ Business ▾ Sports ▾ Entertainment ▾ Living ▾ C

## Archives

### Article Search Results (Articles older than 7 days)

[Archive Advanced Search](#) | [Archive](#)

Search  for

**Note:** Searching is always free. There is a \$2.95 fee to view the full-text of any article.  
Check out our [Pricing Options](#).

#### Searched for "woodville AND accident".

Returning 3 articles of 3 found.

If this is too many articles to browse, you may refine your search with additional terms:

Article 1 of 3; 333 words

## 2ND TEEN DIES FROM CAR CRASH

## OCTOBER INCIDENT STILL UNDER INVESTIGATION

**Source:** JOHN BREWER, Pioneer Press

A second passenger has died after a late October car crash in rural St. Croix County that remains under investigation. [REDACTED] died over the weekend at Regions Hospital in St. Paul, a hospital spokesperson said. The Albert Lea, Minn., resident and 2006 graduate had been in critical condition at the hospital since the Oct. 24 accident on County Road N. She was one of three occupan Chevrolet Cobalt that left the road about 8 p.m., went into a

Published on November 7, 2006, Page B4, St. Paul Pioneer Press (MN)

Article 2 of 3; 5532 words

## OBITUARIES

[REDACTED] Former Employee of US West, [REDACTED] 10/25/2006. Survived by [REDACTED] Private Services. [REDACTED], Family Owned Since 1864. Guest book: [simonettfuneralhome.com/Battles](http://simonettfuneralhome.com/Battles), [REDACTED] Age [REDACTED] of Cottage Grove, Or 2006. Preceded in death by her husband, [REDACTED]; parents, [REDACTED] and [REDACTED]; brothers, [REDACTED] Survived by ([REDACTED] and [REDACTED] ([REDACTED] [REDACTED] grandchildren, [REDACTED] [REDACTED]; brother, [REDACTED]

Published on October 29, 2006, Page B8, St. Paul Pioneer Press (MN)

Article 3 of 3; 283 words

## 1 TEEN KILLED, 2 INJURED IN CRASH

## **GIRL WHO DIED WAS IN 10TH GRADE; FRIENDS IN CRITICAL CONDITION AFTER CAR HIT TREES**

**Source: KEVIN HARTER, Pioneer Press**

A Woodville teen was killed and two of her friends were seriously injured Tuesday night when the car they were riding in left a rural County roadway and struck several trees. Front-seat passenger [REDACTED] of Woodville, was taken by rescue workers to St. Croix County Hospital in St. Paul after the crash, St. Croix County Sheriff Dennis Hillstead said. The Baldwin-Woodville High School sophomore was dead at the hospital. She was riding in a 2005 Chevrolet Cobalt driven

**Published on October 26, 2006, Page B1, St. Paul Pioneer Press (MN)**

All content copyrighted and may not be republished without permission.



## Officer's Opinion of Possible Contributing Circumstances

| Driver Factors                                |                                               | Vehicle Factors                               |                                               | Highway Factors                               |                                               |
|-----------------------------------------------|-----------------------------------------------|-----------------------------------------------|-----------------------------------------------|-----------------------------------------------|-----------------------------------------------|
| Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10<br>N/A |
| 1. Exceeding Speed Limit                      | 1. Brake System                               | 1. Snow, Ice or Wet                           | 1. Exceeding Speed Limit                      | 1. Brake System                               | 1. Snow, Ice or Wet                           |
| 2. Speed Too Fast/Condition                   | 2. Tires                                      | 2. Narrow Shoulder                            | 2. Speed Too Fast/Condition                   | 2. Tires                                      | 2. Narrow Shoulder                            |
| 3. Fail to Yield Right of Way                 | 3. Steering System                            | 3. Low Shoulder                               | 3. Fail to Yield Right of Way                 | 3. Steering System                            | 3. Low Shoulder                               |
| 4. Inattentive Driving                        | 4. Turn Signals                               | 4. Soft Shoulder                              | 4. Inattentive Driving                        | 4. Turn Signals                               | 4. Soft Shoulder                              |
| 5. Following Too Close                        | 5. Head Lamps                                 | 5. Loose Gravel                               | 5. Following Too Close                        | 5. Head Lamps                                 | 5. Loose Gravel                               |
| 6. Improper Turn                              | 6. Stop Lamps                                 | 6. Rough Pavement                             | 6. Improper Turn                              | 6. Stop Lamps                                 | 6. Rough Pavement                             |
| 7. Left of Center                             | 7. Tail Lamps                                 | 7. Debris From Prior Accident                 | 7. Left of Center                             | 7. Tail Lamps                                 | 7. Debris From Prior Accident                 |
| 8. Disregarded Traffic Control                | 8. Disabled in Prior Accident                 | 8. Other Debris                               | 8. Disregarded Traffic Control                | 8. Disabled in Prior Accident                 | 8. Other Debris                               |
| 9. Improper Overtaking                        | 9. Other Disabled                             | 9. Sign Obscured or Missing                   | 9. Improper Overtaking                        | 9. Other Disabled                             | 9. Sign Obscured or Missing                   |
| 10. Unsafe Backing                            | 10. Mirrors                                   | 10. Narrow Bridge                             | 10. Unsafe Backing                            | 10. Mirrors                                   | 10. Narrow Bridge                             |
| 11. Failure to Have Control                   | 11. Suspension System                         | 11. Construction Zone                         | 11. Failure to Have Control                   | 11. Suspension System                         | 11. Construction Zone                         |
| 12. Driver Condition                          | 12. Other                                     | 12. Visibility Obscured                       | 12. Driver Condition                          | 12. Other                                     | 12. Visibility Obscured                       |
| 13. Physically Disabled                       |                                               | 13. Other                                     | 13. Physically Disabled                       |                                               | 13. Other                                     |
| 14. Other                                     |                                               |                                               | 14. Other                                     |                                               |                                               |

## OFFICER INFORMATION

Last Johnson First Eric J M.I.

Law Enforcement Agency Address 1101 Carmichael Rd

City & State Hudson WI 54016 ZIP

Phone Number (715) 381-4320

Agency # 5500 Enforcement Agency St Croix Co. Officer ID # 8821

## Date Notified

MONTH DAY YEAR

Jan 24 06

Feb

Mar

Apr

May

June

July

Aug

Sept

Oct

Nov

Dec

## Time Notified (Military Time)

HOUR MIN

19 57

20 05

21 05

22 05

23 05

24 05

25 05

26 05

27 05

28 05

29 05

30 05

31 05

32 05

33 05

34 05

35 05

36 05

37 05

38 05

39 05

40 05

41 05

42 05

43 05

44 05

45 05

46 05

47 05

48 05

49 05

50 05

51 05

52 05

53 05

54 05

55 05

56 05

57 05

58 05

59 05

60 05

## Time Arrived (Military Time)

HOUR MIN

20 05

21 05

22 05

23 05

24 05

25 05

26 05

27 05

28 05

29 05

30 05

31 05

32 05

33 05

34 05

35 05

36 05

37 05

38 05

39 05

40 05

41 05

42 05

43 05

44 05

45 05

46 05

47 05

48 05

49 05

50 05

51 05

52 05

53 05

54 05

55 05

56 05

57 05

58 05

59 05

60 05

## Date of Report

MONTH DAY YEAR

Jan 25 06

Feb

Mar

Apr

May

June

July

Aug

Sept

Oct

Nov

Dec

## Truck &amp; Bus Accident Information (This Section Must Be Completed for Each Truck or Bus Involved in this Accident.)

When To Use This Section: Did the accident involve... 136

Part A

A truck with at least two axles and six tires? ☒ (Y) ☐ (N)

A truck with a hazardous materials placard? ☒ (Y) ☐ (N)

A bus designed to carry 16 or more persons, including the driver? ☒ (Y) ☐ (N)

STOP! If all the responses to Part A are "NO" do not complete this Truck & Bus Accident Information Section. If there are any "YES" answers, continue to Part B.

Part B

Any person who was fatally injured? ☒ (Y) ☐ (N)

Any injured person who required transport for immediate medical treatment? ☒ (Y) ☐ (N)

One or more vehicles that had to be towed from the scene as a result of the accident? ☒ (Y) ☐ (N)

STOP! If all the responses to Part B are "NO" do not continue. If there are any "YES" answers, please complete this Truck & Bus Accident Information Section...

## Hazardous Material Information

137 • Hazardous Material Class Numbers (1-2 digit):

• Hazardous Material "UN" Numbers (4 digit):

• Hazardous Material Placard Displayed? ☒ (Y) ☐ (N)

• Hazardous Cargo was Released? ☒ (Y) ☐ (N)

List the Hazardous Material(s) by Name in this Load:

List the Name(s) of Released Hazardous Material(s):

## Carrier Information

• Interstate Carrier? ☒ (Y) ☐ (N) 138

Carrier Name 139

## Carrier Identification Numbers

US DOT 140 LC

ICC MC  IC

Carrier Address 142

## Source:

☐ Vehicle Side

☐ Shipping Papers

☐ Trip Manifest

☐ Driver

☐ Log Book

## Vehicle Information

Gross Vehicle Weight Rating 143 LBS Total # of Axles 144

Vehicle Configuration

1. Bus

2. Single unit truck, 2 axles, 6 tires

3. Single unit truck, 3 axles

4. Truck Tractor

5. Tractor Semi-Trailer

6. Tractor Doubles

7. Tractor Triples

8. Flatbed

9. Tanker

10. Log Truck

## SEQUENCE OF EVENTS FOR THIS VEHICLE 146

(Mark a total of one to four events in the order that they occurred.)

1. 2. 3. 4. Ran off Road

1. 2. 3. 4. Collision Involving Motor Vehicle in Transp.

1. 2. 3. 4. Collision Involving Parked Motor Vehicle

1. 2. 3. 4. Collision Involving Train

1. 2. 3. 4. Collision Involving Pedalcycle

1. 2. 3. 4. Collision Involving Animal

1. 2. 3. 4. Collision Involving Fixed Object

1. 2. 3. 4. Collision Involving Other Object

1. 2. 3. 4. Other

## Cargo Body Type

1. Bus

2. Van Enclosed box

3. Cargo Tank

4. Flatbed

5. Dump

6. Concrete Mixer

7. Auto Transporter

8. Garbage Refuse


9. Other

10. Log Truck

Supplemental Reports 101 (N) Witness Statements 102 (Y) Measurements Taken 103 (N)

FEET

Surface Type: Asphalt



Unit one was eastbound on CTH N.  
Unit one entered the south ditch and struck a tree.  
The driver was transported by ground ambulance to Regions Hospital.  
The position 4 passenger was air lifted to Regions hospital from the scene.  
The position 3 passenger was transported by ground ambulance to the Hudson Medical center and air lifted from there to Regions Hospital. On 10-24-06 at 2318 the position 3 passenger was pronounced dead at Regions hospital.

## Digital Photographs

|                 |                 |                 |         |
|-----------------|-----------------|-----------------|---------|
| WITNESS<br>NAME | Last            | First           | M.I.    |
| 107             |                 |                 |         |
| ADDRESS         | Street & Number | Date of Birth   |         |
| 108             |                 | 109             |         |
| City & State    | ZIP             | Phone<br>Number | 111 ( ) |
| 110             |                 |                 |         |

**ACCESS CONTROL**

☒ No Control  
(Unlimited Access)

☐ Full Control  
(Only Ramp Entry/Exit)

☐ Partial Control

**ROAD TERRAIN** 11

**Part A**

☐ Straight

☒ Curve

**Part B**

☒ Level/Flat

☐ Hill

**LIGHT CONDITION**

① Daylight  
② Dark—Not Lighted  
③ Dark—Lighted  
④ Dawn  
⑤ Dusk  
⑥ Unknown

**TRAFFIC WAY**

- Not Physically Divided (2-Way Traffic)
- ② Divided Highway, Median Strip, without Traffic Barrier
- ③ Divided Highway, Median Strip, with Traffic Barrier
- ④ One-Way Traffic
- ⑤ Parking Lot or Private Property

**ROAD SURFACE CONDITION**

☒ Dry

☐ Wet

☐ Snow/Slush

☐ Ice

☐ Sand, Mud, Dirt, Oil

☐ Other

☐ Unknown

| RELATION TO ROADWAY                                    |  | 117       |
|--------------------------------------------------------|--|-----------|
| ① On Roadway                                           |  |           |
| ② Parking Lot or Private Property                      |  |           |
| ③ Shoulder (Other Than Shoulder within Median or Gore) |  |           |
| ④ Median (Other Than Median within Gore)               |  |           |
| ⑤ Outside Shoulder—Left                                |  |           |
| ⑥ Outside Shoulder—Right                               |  |           |
| ⑦ Off Roadway—Location Unknown                         |  | ⑨ On Ramp |
| ⑧ Gore (Area between Ramp & Highway)                   |  | ⑩ Unknown |

Photos By: 105 Deputy Sommers

| Unit Number              |           |
|--------------------------|-----------|
| <input type="checkbox"/> | ② ③ ④ ⑤   |
| <input type="checkbox"/> | ⑥ ⑦ ⑧ ⑨ ⑩ |

- |    |                           |      |
|----|---------------------------|------|
| 1  | Going Straight            | (1)  |
| 2  | Making Left Turn          | (2)  |
| 3  | Making Right Turn         | (3)  |
| 4  | Slowing or Stopping       | (4)  |
| 5  | Stopped in Traffic        | (5)  |
| 6  | Legally Parked            | (6)  |
| 7  | Violating No Passing Zone | (7)  |
| 8  | Illegally Parked          | (8)  |
| 9  | Parking Maneuver          | (9)  |
| 10 | Backing Maneuver          | (10) |
| 11 | Changing Lanes            | (11) |
| 12 | Overtaking on Left        | (12) |
| 13 | Overtaking on Right       | (13) |
| 14 | Making U Turn             | (14) |
| 15 | Turning on Red            | (15) |
| 16 | Merging                   | (16) |
| 17 | Negotiating Curve         | (17) |
| 18 | Other                     | (18) |

| Unit Number           |                       |                       |                       |                       |
|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| <input type="radio"/> | <input type="radio"/> | <input type="radio"/> | <input type="radio"/> | <input type="radio"/> |
| 2                     | 3                     | 4                     | 5                     |                       |
| 6                     | 7                     | 8                     | 9                     | 10                    |

- |                                                                                       |                          |      |
|---------------------------------------------------------------------------------------|--------------------------|------|
|  | No Control               | (1)  |
|  | Traffic Signal Operating | (2)  |
|  | Traffic Signal Flashing  | (3)  |
|  | Stop Sign                | (4)  |
|  | Stop Sign with Flasher   | (5)  |
|  | Warning                  | (6)  |
|  | Warn Sign with Flasher   | (7)  |
|  | Yield Sign               | (8)  |
|  | Traffic Control Person   | (9)  |
|  | RR-xing Signal           | (10) |
|  | Other                    | (11) |

## Officer's Opinion of Possible Contributing Circumstances

(b) (6)

| Driver Factors |                       |     |    |                          |             |     |                            |     |     |                             |     |
|----------------|-----------------------|-----|----|--------------------------|-------------|-----|----------------------------|-----|-----|-----------------------------|-----|
| Unit Number    |                       |     |    |                          | Unit Number |     |                            |     |     |                             |     |
| 1              | 2                     | 3   | 4  | 5                        | 6           | 7   | 8                          | 9   | 10  |                             |     |
| 6              | 7                     | 8   | 9  | 10                       | N/A         | N/A | N/A                        | N/A | N/A |                             |     |
| 1              | Exceeding Speed Limit | ( ) | 2  | Speed Too Fast-Condition | ( )         | 3   | Fail to Yield Right of Way | ( ) | 4   | Inattentive Driving         | ( ) |
| 5              | Following Too Close   | ( ) | 6  | Improper Turn            | ( )         | 7   | Left of Center             | ( ) | 8   | Disregarded Traffic Control | ( ) |
| 9              | Improper Overtaking   | ( ) | 10 | Unsafe Backing           | ( )         | 11  | Failure to Have Control    | ( ) | 12  | Driver Condition            | ( ) |
| 13             | Physically Disabled   | ( ) | 14 | Other                    | ( )         |     |                            |     |     |                             |     |

| Vehicle Factors |                |     |    |            |             |     |                   |     |     |                            |     |
|-----------------|----------------|-----|----|------------|-------------|-----|-------------------|-----|-----|----------------------------|-----|
| Unit Number     |                |     |    |            | Unit Number |     |                   |     |     |                            |     |
| 1               | 2              | 3   | 4  | 5          | 6           | 7   | 8                 | 9   | 10  |                            |     |
| 6               | 7              | 8   | 9  | 10         | N/A         | N/A | N/A               | N/A | N/A |                            |     |
| 1               | Brake System   | ( ) | 2  | Tires      | ( )         | 3   | Steering System   | ( ) | 4   | Turn Signals               | ( ) |
| 5               | Head Lamps     | ( ) | 6  | Stop Lamps | ( )         | 7   | Tail Lamps        | ( ) | 8   | Disabled in Prior Accident | ( ) |
| 9               | Other Disabled | ( ) | 10 | Mirrors    | ( )         | 11  | Suspension System | ( ) | 12  | Other                      | ( ) |

| Highway Factors |                          |     |    |                 |             |     |                            |     |     |                     |     |
|-----------------|--------------------------|-----|----|-----------------|-------------|-----|----------------------------|-----|-----|---------------------|-----|
| Unit Number     |                          |     |    |                 | Unit Number |     |                            |     |     |                     |     |
| 1               | 2                        | 3   | 4  | 5               | 6           | 7   | 8                          | 9   | 10  |                     |     |
| 6               | 7                        | 8   | 9  | 10              | N/A         | N/A | N/A                        | N/A | N/A |                     |     |
| 1               | Snow, Ice or Wet         | ( ) | 2  | Narrow Shoulder | ( )         | 3   | Low Shoulder               | ( ) | 4   | Soft Shoulder       | ( ) |
| 5               | Loose Gravel             | ( ) | 6  | Rough Pavement  | ( )         | 7   | Debris From Prior Accident | ( ) | 8   | Other Debris        | ( ) |
| 9               | Sign Obscured or Missing | ( ) | 10 | Narrow Bridge   | ( )         | 11  | Construction Zone          | ( ) | 12  | Visibility Obscured | ( ) |
| 13              | Other                    | ( ) |    |                 |             |     |                            |     |     |                     |     |

## OFFICER INFORMATION

|                                |                    |              |
|--------------------------------|--------------------|--------------|
| Last                           | First              | M.I.         |
| 125                            |                    |              |
| Law Enforcement Agency Address |                    |              |
| 126                            |                    |              |
| City & State                   |                    |              |
| 127                            |                    |              |
| Phone Number                   |                    |              |
| ( ) 128                        |                    |              |
| Agency #                       | Enforcement Agency | Officer ID # |
| 129                            | 130                | 131          |

## Date Notified

| MONTH | DAY | YEAR |
|-------|-----|------|
| Jan   | 132 |      |
| Feb   |     |      |
| Mar   |     |      |
| Apr   |     |      |
| May   |     |      |
| June  |     |      |
| July  |     |      |
| Aug   |     |      |
| Sept  |     |      |
| Oct   |     |      |
| Nov   |     |      |
| Dec   |     |      |

## Time Notified (Military Time)

| HOUR | MIN. |
|------|------|
| 133  |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |

## Time Arrived (Military Time)

| HOUR | MIN. |
|------|------|
| 134  |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |
|      |      |

## Date of Report

| MONTH | DAY | YEAR |
|-------|-----|------|
| Jan   | 135 |      |
| Feb   |     |      |
| Mar   |     |      |
| Apr   |     |      |
| May   |     |      |
| June  |     |      |
| July  |     |      |
| Aug   |     |      |
| Sept  |     |      |
| Oct   |     |      |
| Nov   |     |      |
| Dec   |     |      |

## Truck &amp; Bus Accident Information (This Section Must Be Completed for Each Truck or Bus Involved in this Accident.)

When To Use This Section: Did the accident involve... 136

Part A

A truck with at least two axles and six tires? (Y) (N)

A truck with a hazardous materials placard? (Y) (N)

A bus designed to carry 16 or more persons, including the driver? (Y) (N)

STOP! If all the responses to Part A are "NO" do not complete this Truck & Bus Accident Information Section. If there are any "YES" answers, continue to Part B.

Part B

Any person who was fatally injured? (Y) (N)

Any injured person who required transport for immediate medical treatment? (Y) (N)

One or more vehicles that had to be towed from the scene as a result of the accident? (Y) (N)

STOP! If all the responses to Part B are "NO" do not continue. If there are any "YES" answers, please complete this Truck & Bus Accident Information Section...

## Hazardous Material Information

137

Hazardous Material Class Numbers (1-2 digit):

Hazardous Material "UN" Numbers (4 digit):

Hazardous Material Placard Displayed? (Y) (N)

Hazardous Cargo was Released? (Y) (N)

List the Hazardous Material(s) by Name in this Load:

List the Name(s) of Released Hazardous Material(s):

## Carrier Information

## Carrier Identification Numbers

## Source:

- Vehicle Side 141
- Shipping Papers
- Trip Manifest
- Driver
- Log Book

Interstate Carrier? (Y) (N) 138

Carrier Name 139

US DOT 140

ICC MC 141

Carrier Address 142

## Vehicle Information

Gross Vehicle Weight Rating 143

LBS

Total # of Axles 144

## Vehicle Configuration

145

1 2 3 4 5 6 7 8 9 10

Bus

Single unit truck + 3 axles

Tractor Trailer

Tractor Doubles

Tractor Semi-Trailer

Tractor Triples

Log Truck

## SEQUENCE OF EVENTS FOR THIS VEHICLE 146

(Mark a total of one to four events in the order that they occurred.)

1 2 3 4 Ran off Road

1 2 3 4 Collision Involving Motor Vehicle in Transp.

1 2 3 4 Collision Involving Parked Motor Vehicle

1 2 3 4 Collision Involving Train

1 2 3 4 Collision Involving Pedalcycle

1 2 3 4 Collision Involving Animal

1 2 3 4 Collision Involving Fixed Object

1 2 3 4 Collision Involving Other Object

1 2 3 4 Other

## Cargo Body Type 147

1 2 3 4 5 6 7 8 9 10

Box

Van Enclosed box

Cargo Tank

Flatbed

Dump

Concrete Mixer

Auto Transporter

Garbage Refuse

Other

Log Truck



## Supplemental Reports 101 (Y) (N) Witness Statements 102 (Y) (N) Measurements Taken 103 (Y) (N)

|        |     |        |
|--------|-----|--------|
| Unit 1 | 100 | Unit 2 |
|--------|-----|--------|

FFET

Surface  
Type: \_\_\_\_\_

**Photos By:**

| Unit Number |   |   |   |   |     | Unit Number |   |   |   |   |
|-------------|---|---|---|---|-----|-------------|---|---|---|---|
| ①           | ② | ③ | ④ | ⑤ | 119 | ①           | ② | ③ | ④ | ⑤ |
| ⑥           | ⑦ | ⑧ | ⑨ | ⑩ |     | ⑥           | ⑦ | ⑧ | ⑨ | ⑩ |

- |   |                           |   |
|---|---------------------------|---|
| ① | Going Straight            | ① |
| ② | Making Left Turn          | ② |
| ③ | Making Right Turn         | ③ |
| ④ | Slowing or Stopping       | ④ |
| ⑤ | Stopped in Traffic        | ⑤ |
| ⑥ | Legally Parked            | ⑥ |
| ⑦ | Violating No Passing Zone | ⑦ |
| ⑧ | Illegally Parked          | ⑧ |
| ⑨ | Parking Maneuver          | ⑨ |
| ⑩ | Backing Maneuver          | ⑩ |
| ⑪ | Changing Lanes            | ⑪ |
| ⑫ | Overtaking on Left        | ⑫ |
| ⑬ | Overtaking on Right       | ⑬ |
| ⑭ | Making U Turn             | ⑭ |
| ⑮ | Turning on Red            | ⑮ |
| ⑯ | Merging                   | ⑯ |
| ⑰ | Negotiating Curve         | ⑰ |
| ⑱ | Other                     | ⑱ |

| Unit Number |   |   |   |   |
|-------------|---|---|---|---|
| ①           | ② | ③ | ④ | ⑤ |
| ⑥           | ⑦ | ⑧ | ⑨ | ⑩ |

- |   |                          |   |
|---|--------------------------|---|
| ① | No Control               | ① |
| ② | Traffic Signal Operating | ② |
| ③ | Traffic Signal Flashing  | ③ |
| ④ | Stop Sign                | ④ |
| ⑤ | Stop Sign with Flasher   | ⑤ |
| ⑥ | Warning                  | ⑥ |
| ⑦ | Warn Sign with Flasher   | ⑦ |
| ⑧ | Yield Sign               | ⑧ |
| ⑨ | Traffic Control Person   | ⑨ |
| ⑩ | RR-xing Signal           | ⑩ |
| ⑪ | Other                    | ⑪ |

| LIGHT CONDITION |                  | 114 |
|-----------------|------------------|-----|
| ①               | Daylight         |     |
| ②               | Dark—Not Lighted |     |
| ③               | Dark—Lighted     |     |
| ④               | Dawn             |     |
| ⑤               | Dusk             |     |
| ⑥               | Unknown          |     |

**WEATHER** 118

- ① Clear...
- ② Cloudy
- ③ Rain
- ④ Snow
- ⑤ Fog, Smog, Smoke
- ⑥ Sleet, Hail  
(Freezing Rain or Drizzle)
- ⑦ Blowing Sand, Soil,  
Dirt, Snow
- ⑧ Severe Crosswinds
- ⑨ Other
- ⑩ Unknown

AT APPROXIMATELY 0015 I SPOKE WITH STAFF FROM REGIONS HOSPITAL BY PHONE. THEY SAID [REDACTED] HAD BEEN PRONOUNCED DEAD ON 10/24/06 AT 2318. THEY SAID [REDACTED] WAS UNCONSCIOUS, INTUBATED, AND IN CRITICAL CONDITION. THEY SAID [REDACTED] WAS UNCONSCIOUS AND IN CRITICAL CONDITION.

THE VEHICLE WAS REMOVED FROM THE SCENE BY JERRY'S TOWING. DEPUTY KOENIG FOLLOWED THE VEHICLE TO THE SHERIFF'S DEPARTMENT IMPOUND LOT. DEPUTY KOENIG AND I THEN INVENTORIED THE VEHICLE.

TROOPER TRAYNOR HAD REQUESTED THAT I CONTACT THE VEHICLE OWNER [REDACTED] AND ASK HIM TO CONSENT TO HAVING THE "SDM" REMOVED FROM THE VEHICLE. TROOPER TRAYNOR ADVISED THAT THE "SDM" COULD POSSIBLY HOLD DATA THAT WOULD HELP DETERMINE WHY THE AIRBAGS HAD NOT DEPLOYED.

ON 10/25/06 I SPOKE WITH [REDACTED] BY PHONE. [REDACTED] SAID THAT HE WOULD MEET WITH ME THE NEXT DAY TO SIGN THE CONSENT FORM. ON 10/26/06 I PHONED [REDACTED] AGAIN TO ARRANGE A MEETING. [REDACTED] TOLD ME THAT HIS INSURANCE COMPANY'S LAWYER HAD TOLD HIM ONLY TO SIGN THE CONSENT FORM IF THEY WERE ALLOWED TO BE THERE WHEN THE SDM WAS REMOVED AND WERE GIVEN ACCESS TO THE DATA ON IT. I TOLD [REDACTED] THAT I WOULD RELAY THEIR REQUEST TO TROOPER TRAYNOR.

I ASKED [REDACTED] IF THE VEHICLE HAD EVER BEEN INVOLVED IN AN ACCIDENT BEFORE. [REDACTED] SAID A DEER HAD "BRUSHED" THE REAR DRIVER'S SIDE ONCE BUT THERE WAS NO DAMAGE. [REDACTED] SAID OTHER THAN OIL CHANGES THE ONLY TIME THE VEHICLE HAD BEEN WORKED ON WAS AT JACOBSON CHEVROLET, 1860 10 AVE BALDWIN WI 54002, 715-684-4600, FOR A RECALL CAMPAIGN. [REDACTED] BELIEVED THE RECALL WAS FOR SOMETHING TO DO WITH THE AIRBAGS AND MAYBE A WINDSHIELD WIPER SWITCH. [REDACTED] SAID NONE OF THE WARNING LIGHTS ON THE DASH HAD BEEN ILLUMINATED PRIOR TO THE ACCIDENT.

I SPOKE WITH TROOPER YOUNG BY PHONE. TROOPER YOUNG ADVISED THAT THEY WOULD MOST LIKELY JUST GET A WARRANT FOR THE SDM. HE ALSO REQUESTED A FULL COPY OF THE ACCIDENT REPORT FOR THE RECONSTRUCTION.

ON 10/26/06 I SPOKE WITH RONALD DRAHOS BY PHONE. RONALD SAID THAT HE WAS AFFILIATED WITH THE TRANSPORTATION RESEARCH CENTER AT INDIANA UNIVERSITY WHO WAS UNDER CONTRACT WITH THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION. RONALD SAID THEY INVESTIGATED TRAFFIC CRASHES OF "SPECIAL INTEREST". RONALD SAID THIS WAS A CRASH OF SPECIAL INTEREST BECAUSE THE AIR BAGS HAD ALLEGEDLY NOT DEPLOYED IN A SITUATION WHEN THEY SHOULD HAVE. I ARRANGED FOR RONALD TO EMAIL ME A FORMAL REQUEST FOR THE INFORMATION THEY WISHED TO ATTAIN (ATTACHED).

ON 10/27/06 I SPOKE WITH REGIONS HOSPITAL STAFF BY PHONE. THEY SAID THAT [REDACTED] AND [REDACTED] WERE STILL IN CRITICAL CONDITION AND NEITHER WAS CONSCIOUS. I ALSO SPOKE WITH THE RAMSEY COUNTY MEDICAL EXAMINERS OFFICE. THEY SAID THAT AN AUTOPSY HAD BEEN DONE ON [REDACTED] AND THEY WOULD SEND US A COPY OF THE REPORT WHEN IT WAS COMPLETED IN 6 TO 8 WEEKS.

CLEAR.

ON 10/24/06 AT 1957 I DEPUTY ERIC JOHNSON WAS DISPATCHED TO RESPOND TO THE AREA OF 1248 CTH N FOR A SINGLE VEHICLE ACCIDENT WITH MULTIPLE PERSONS INJURED. WI STATE TROOPERS LOONSFOOT, SHILTS, AND DEPUTY SOMMERS ALSO RESPONDED.

ON ARRIVAL I SAW THE ABOVE VEHICLE IN THE SOUTH DITCH FACING SOUTH. THE VEHICLE HAD SEVERE FRONT END DAMAGE. THERE WAS A LARGE CLUMP OF TREES WITH DAMAGED BARK IN FRONT OF THE VEHICLE. THERE WAS A LARGE TREE BRANCH/TRUNK LYING ACROSS THE TOP OF THE VEHICLE. THE TROOPERS WERE ALREADY ON SCENE AND ASSISTING THE THREE FEMALE OCCUPANTS. ONE OCCUPANT WAS SEATED IN THE DRIVER'S SEAT, ONE IN THE FRONT PASSENGER SEAT, AND ONE IN THE REAR DRIVER'S SIDE SEAT. THE VEHICLE AIRBAGS WERE NOT DEPLOYED AND THE SEATBELTS DID NOT APPEAR TO HAVE BEEN USED.

I HELD C-SPINE ON THE DRIVER UNTIL EMS ARRIVED. THE DRIVER WAS SITTING ON THE FLOOR IN FRONT OF THE DRIVER'S SEAT WITH HER LEGS ENTRAPPED UNDER THE DASHBOARD. THE DRIVER APPEARED TO BE SEVERELY INJURED BUT WAS CONSCIOUS. THE DRIVER SAID HER NAME WAS [REDACTED]. I ASKED [REDACTED] WHAT HAD HAPPENED. [REDACTED] SAID SHE DIDN'T KNOW. EMS ARRIVED AND STARTED EVALUATING [REDACTED]. [REDACTED] WAS LATER IDENTIFIED BY A WI PICTURE INSTRUCTION PERMIT LOCATED IN THE VEHICLE.

THE FRONT SEAT PASSENGER LATER IDENTIFIED AS [REDACTED] WAS BREATHING BUT UNRESPONSIVE AND ENTRAPPED. [REDACTED] WAS SEATED IN THE FRONT PASSENGER SEAT WHICH WAS PUSHED FORWARD. [REDACTED] WAS ENTRAPPED BETWEEN THE SEAT, THE DASH, AND THE PASSENGER SIDE DOOR.

THE BACK SEAT PASSENGER [REDACTED] WAS LATER IDENTIFIED BY A MN PICTURE DRIVER'S LICENSE LOCATED IN THE VEHICLE. [REDACTED] WAS BREATHING BUT UNRESPONSIVE. [REDACTED] FEET WERE ON THE FLOOR BEHIND THE DRIVER'S SEAT. [REDACTED] TORSO WAS LYING ACROSS THE REAR BENCH SEAT FACE UP WITH HER HEAD TOWARDS THE PASSENGER SIDE.

FIRE AND EMS REMOVED THE OCCUPANTS FROM THE VEHICLE. [REDACTED] WAS TRANSPORTED BY GROUND AMBULANCE TO REGIONS HOSPITAL IN ST PAUL. [REDACTED] WAS TRANSPORTED BY GROUND AMBULANCE TO THE HUDSON MEDICAL CENTER AND AIR LIFTED FROM THERE TO REGIONS HOSPITAL. [REDACTED] WAS AIR LIFTED FROM THE SCENE TO REGIONS HOSPITAL.

I SPOKE WITH THE COMPLAINANTS [REDACTED] AND [REDACTED] AND [REDACTED] TOLD ME THAT THEY HAD BEEN EASTBOUND ON CTH N. THEY SAID THERE HAD BEEN TWO OR THREE VEHICLES IN FRONT OF THEM. [REDACTED] SAID WHEN THEY CAME UPON THE VEHICLE IN THE DITCH THEY THOUGHT IT WAS AN OLD ACCIDENT. THEY SAID THE CARS IN FRONT OF THEM HADN'T STOPPED BUT AS THEY WENT BY THEY NOTICED SMOKE COMING FROM UNDER THE HOOD OF THE VEHICLE. THEY SAID THEY TURNED AROUND AND APPROACHED THE VEHICLE. THEY SAID AS THEY APPROACHED THE VEHICLE THEY HEARD SCREAMING AND THEN SAW THE THREE OCCUPANTS. THEY SAID AT THE SAME TIME [REDACTED] CAME FROM HER HOUSE AND THEY YELLED FOR HER TO CALL 911. [REDACTED] SAID NONE OF THE OCCUPANTS CHANGED POSITIONS IN THE VEHICLE BEFORE THE POLICE ARRIVED.

[REDACTED] SAID SHE HAD HEARD THE ACCIDENT BUT HADN'T SEEN IT. [REDACTED] SAID THAT WHEN SHE WENT OUTSIDE TO SEE WHAT HAD HAPPENED THE GUYS TOLD HER TO CALL 911.

DEPUTY SOMMERS TOOK DIGITAL PHOTOGRAPHS OF THE SCENE. WI STATE TROOPERS TRAYNOR AND YOUNG RESPONDED TO RECONSTRUCT THE ACCIDENT.

I NOTIFIED [REDACTED]'S PARENTS AND HUSBAND OF THE ACCIDENT. I NOTIFIED [REDACTED]'S PARENTS OF THE ACCIDENT. WITH THE ASSISTANCE OF [REDACTED]'S ROOMMATE [REDACTED] I WAS ABLE TO LOCATE AND NOTIFY [REDACTED]'S MOTHER OF THE ACCIDENT.



[REDACTED]  
SPRING VALLEY WI [REDACTED]  
[REDACTED]

[REDACTED] S PARENTS:

[REDACTED]  
WOODVILLE WI [REDACTED]  
[REDACTED]

FRONT PASSENGER / DECEASED:

[REDACTED]  
WOODVILLE WI [REDACTED]  
[REDACTED]

[REDACTED]  
WOODVILLE WI [REDACTED]  
[REDACTED]

REAR PASSENGER:

[REDACTED]  
ALBERT LEA [REDACTED]  
[REDACTED]

HAD BEEN STAYING AT BELOW ADDRESS SINCE LATE AUGUST 2006

[REDACTED]  
WOODVILLE WI [REDACTED]

[REDACTED] AND STEPMOTHER:

[REDACTED]  
ALBERT LEA MN [REDACTED]  
[REDACTED]

[REDACTED] S MOTHER:

[REDACTED]  
BALDWIN WI [REDACTED]  
[REDACTED]

[REDACTED] S ROOMMATE:

[REDACTED]  
WOODVILLE WI [REDACTED]  
[REDACTED]

VEHICLE:

2005 CHEVROLET COBALT, 4 DOOR, WHITE, VIN= 1G1AK52F657 [REDACTED]  
WI AUTO PLATE= [REDACTED]

Entered By: Eric J Johnson, On 10/27/2006 10:53:46 PM  
Edited By: Eric J Johnson, On 10/27/2006 11:35:48 PM

Title: FATAL MOTOR VEHICLE ACCIDENT

ST CROIX COUNTY SHERIFF'S DEPARTMENT  
1101 CARMICHAEL RD  
HUDSON WI 54016  
(715)381-4320

DEPUTY ERIC JOHNSON

FATAL MOTOR VEHICLE ACCIDENT

CASE# [REDACTED]

MV 4000# 8929339

10/24/06 @ 1955

LOCATION:

CTH N .5 MILE EAST OF NORTH SKYLINE DRIVE

COMPLAINANTS:

[REDACTED]  
BALDWIN WI [REDACTED]  
[REDACTED]

[REDACTED]  
[REDACTED]  
SPRING VALLEY [REDACTED]  
[REDACTED]

[REDACTED]  
ROBERTS WI [REDACTED]  
[REDACTED]

DRIVER:

[REDACTED]  
[REDACTED]  
SPRING VALLEY WI [REDACTED]  
[REDACTED]

[REDACTED] IS HUSBAND:

[REDACTED]  
[REDACTED]  
SPRING VALLEY WI [REDACTED]  
[REDACTED]

[REDACTED] S FATHER / VEHICLE OWNER:  
[REDACTED]

TA000093339

DEPUTY ERIC JOHNSON

SUPPLEMENTAL TO 06-9697

DECEASED:

[REDACTED]  
[REDACTED]  
ALBERT LEA MN [REDACTED]  
[REDACTED]

HAD BEEN STAYING AT BELOW ADDRESS SINCE LATE AUGUST 2006

[REDACTED]  
WOODVILLE WI [REDACTED]

ON 11/05/06 I WAS ADVISED BY STAFF AT REGIONS HOSPITAL THAT [REDACTED] HAD BEEN  
PRONOUNCED DEAD AT REGIONS HOSPITAL ON 11/04/06 AT 1019 HOURS.

I HAD DISPATCH SEND THE FATALITY NOTIFICATION TTY. I ALSO AMENDED THE MV4000 AND MOTOR  
VEHICLE FATALITY SUPPLEMENT REPORT TO REFLECT THE FATALITY.

CLEAR.



# MOTOR VEHICLE FATAL SUPPLEMENT REPORT

Wisconsin Department of Transportation  
MV3400 801

1. Document No.  
From MV4000

(b) (6)

## ACCIDENT INFORMATION

|                                                                                                                                                  |                                                                              |                                                                                                                                                                                                |                                                                                                                                                                                          |                                                                                                                                                                                                                                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2. Accident Date (Mo-Day-Yr)<br><b>10-24-06</b>                                                                                                  | 3. No. of Travel Lanes<br><b>2</b>                                           | 4. Time Ambulance NOTIFIED<br><b>7:59</b> AM <input checked="" type="radio"/> PM                                                                                                               | 5. Time Ambulance Arrived at SCENE<br><b>8:10</b> AM <input checked="" type="radio"/> PM                                                                                                 | 6. Time Ambulance Arrived at HOSPITAL<br><b>9:11</b> AM <input checked="" type="radio"/> PM                                                                                                                                     |
| 7. Roadway Surface Type<br>1 Concrete<br>2 Blacktop (Bituminous)<br>3 Brick or Block<br>4 Slag, Gravel or Stone<br>5 Dirt<br>8 Other<br><b>2</b> | 8. Roadway Profile<br>1 Level<br>2 Grade<br>3 Hillcrest<br>4 Sag<br><b>2</b> | 9. Special Jurisdiction<br>0 No Special Jurisdiction<br>1 National Park Service<br>2 Military<br>3 Indian Reservation<br>4 College/University Campus<br>5 Other Federal Properties<br><b>0</b> | 10. Relation To Roadway<br>1 On Roadway<br>2 Shoulder<br>3 Median<br>4 Roadside<br>5 Outside Right of Way<br>6 Off Roadway - Location Unknown<br>7 In Parking Lane<br>8 Gore<br><b>5</b> | 11. Trafficway Flow<br>1 Not Physically Divided (Two Way Trafficway)<br>2 Divided Highway, Median Strip (Without Traffic Barrier)<br>3 Divided Highway, Median Strip (With Traffic Barrier)<br>4 One Way Trafficway<br><b>1</b> |

## VEHICLE INFORMATION

|                                                                                                                                                                       |                                                                                                                                                                              |                                                                                                                           |                                                                        |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| 12. Special Use<br>0 No Special Use<br>1 Taxi<br>2 Vehicle Used as School Bus<br>3 Vehicle Used as Other Bus<br>4 Military<br>5 Police<br>6 Ambulance<br>7 Fire Truck | 13. Emergency Use Y/N<br>See s.340.01(3);<br>346.03 Wis. Stats.<br>Unit 1 <input checked="" type="radio"/> N<br>Unit 2 <input type="radio"/><br>Unit 3 <input type="radio"/> | 14. Fire Y/N<br>Unit 1 <input checked="" type="radio"/> N<br>Unit 2 <input type="radio"/><br>Unit 3 <input type="radio"/> | 15. Estimated Travel Speed<br>Unit 1 <b>50 MPH</b><br>Unit 2<br>Unit 3 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|

## SURVIVING DRIVER INFORMATION

|                                                                                                                  |                                                                                                                                                                                                                  |                                                                                                                         |
|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| Unit 1                                                                                                           | 16. Ejected Y/N <input checked="" type="radio"/> N                                                                                                                                                               | 17. Ejected Y/N <input checked="" type="radio"/> Y                                                                      |
| 19. Alcohol Test Given Y/N <input checked="" type="radio"/> N                                                    | 21. Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed | 22. Drug Test Given Y/N <input checked="" type="radio"/> N                                                              |
| 20. Alcohol Test Results - Circle One<br>1. Actual-Give Results Results<br>2. Test Refused<br>3. Results Unknown | 23. Drug Test Type - Circle One<br>Blood<br>Urine                                                                                                                                                                | 24. Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown |
| Unit 2                                                                                                           | NAME First MI Last                                                                                                                                                                                               | Ejected Y/N <input type="radio"/> Extricated Y/N <input type="radio"/>                                                  |
| Alcohol Test Given Y/N <input type="radio"/>                                                                     | Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed     | Drug Test Given Y/N <input type="radio"/>                                                                               |
| Alcohol Test Results - Circle One<br>1. Actual-Give Results Results<br>2. Test Refused<br>3. Results Unknown     | Drug Test Type - Circle One<br>Blood<br>Urine                                                                                                                                                                    | Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown     |
| Unit 3                                                                                                           | NAME First MI Last                                                                                                                                                                                               | Ejected Y/N <input type="radio"/> Extricated Y/N <input type="radio"/>                                                  |
| Alcohol Test Given Y/N <input type="radio"/>                                                                     | Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed     | Drug Test Given Y/N <input type="radio"/>                                                                               |
| Alcohol Test Results - Circle One<br>1. Actual-Give Results Results<br>2. Test Refused<br>3. Results Unknown     | Drug Test Type - Circle One<br>Blood<br>Urine                                                                                                                                                                    | Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown     |

## FATALITY INFORMATION

|                                                                   |                                                    |                                                       |                                      |                                                                          |
|-------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|--------------------------------------|--------------------------------------------------------------------------|
| 25. Name - First MI Last                                          | 26. Ejected Y/N <input checked="" type="radio"/> N | 27. Extricated Y/N <input checked="" type="radio"/> Y | 28. Date of Death<br><b>10/24/06</b> | 29. Time of Death<br><b>11:18</b> AM <input checked="" type="radio"/> PM |
| 1.                                                                | <input type="radio"/>                              | <input type="radio"/>                                 |                                      | AM <input type="radio"/> PM <input type="radio"/>                        |
| 2.                                                                | <input type="radio"/>                              | <input type="radio"/>                                 |                                      | AM <input type="radio"/> PM <input type="radio"/>                        |
| 3.                                                                | <input type="radio"/>                              | <input type="radio"/>                                 |                                      | AM <input type="radio"/> PM <input type="radio"/>                        |
| 30. Officer Completing Report - Print Name<br><b>CPIC JOURNAL</b> | 31. Officer ID No.<br><b>8891</b>                  | 32. Enforcement Agency Name<br><b>ST. JOSEPH</b>      | 33. Report Date<br><b>10-26-06</b>   |                                                                          |

TA000093341

\* Amended 11-09-06, Fatality #2 added

# MOTOR VEHICLE FATAL SUPPLEMENT REPORT

Wisconsin Department of Transportation  
MV5400 891

1. Document Number  
(From MV4000)

(b) (6)

## ACCIDENT INFORMATION

|                                                                                                                                                  |                                                                              |                                                                                                                                                                                                |                                                                                                                                                                                          |                                                                                                                                                                                                                                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2. Accident Date (Mo-Day-Yr)<br><b>10-24-06</b>                                                                                                  | 3. No. of Travel Lanes<br><b>2</b>                                           | 4. Time Ambulance NOTIFIED<br><b>7:59 AM</b>                                                                                                                                                   | 5. Time Ambulance Arrived at SCENE<br><b>8:10 AM</b>                                                                                                                                     | 6. Time Ambulance Arrived at HOSPITAL<br><b>9:11 AM</b>                                                                                                                                                                         |
| 7. Roadway Surface Type<br>1 Concrete<br>2 Blacktop (Bituminous)<br>3 Brick or Block<br>4 Slag, Gravel or Stone<br>5 Dirt<br>8 Other<br><b>2</b> | 8. Roadway Profile<br>1 Level<br>2 Grade<br>3 Hillcrest<br>4 Sag<br><b>2</b> | 9. Special Jurisdiction<br>0 No Special Jurisdiction<br>1 National Park Service<br>2 Military<br>3 Indian Reservation<br>4 College/University Campus<br>5 Other Federal Properties<br><b>0</b> | 10. Relation To Roadway<br>1 On Roadway<br>2 Shoulder<br>3 Median<br>4 Roadside<br>5 Outside Right of Way<br>6 Off Roadway - Location Unknown<br>7 In Parking Lane<br>8 Gore<br><b>5</b> | 11. Trafficway Flow<br>1 Not Physically Divided (Two Way Trafficway)<br>2 Divided Highway, Median Strip (Without Traffic Barrier)<br>3 Divided Highway, Median Strip (With Traffic Barrier)<br>4 One Way Trafficway<br><b>1</b> |

## VEHICLE INFORMATION

|                                                                                                                                                                       |                                                                                                                                |                                                                                |                                                                                                 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|
| 12. Special Use<br>0 No Special Use<br>1 Taxi<br>2 Vehicle Used as School Bus<br>3 Vehicle Used as Other Bus<br>4 Military<br>5 Police<br>6 Ambulance<br>7 Fire Truck | 13. Emergency Use Y/N<br>See s.340.01(3), 346.03 Wis. Stats.<br>Unit 1<br><b>N</b><br>Unit 2<br><b>N</b><br>Unit 3<br><b>N</b> | 14. Fire Y/N<br>Unit 1<br><b>N</b><br>Unit 2<br><b>N</b><br>Unit 3<br><b>N</b> | 15. Estimated Travel Speed<br>Unit 1<br><b>50 MPH</b><br>Unit 2<br><b></b><br>Unit 3<br><b></b> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|

## SURVIVING DRIVER INFORMATION

|                                                   |                                                                                                                            |                                                                                                                                                                                                                                        |                                     |
|---------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| Unit 1                                            | 16. NAME First MI Last<br><b>[REDACTED]</b>                                                                                | 17. Ejected Y/N<br><b>N</b>                                                                                                                                                                                                            | 18. Ejected Y/N<br><b>Y</b>         |
| 19. Alcohol Test Given Y/N<br><b>N</b>            | 20. Alcohol Test Results - Circle One<br>1. Actual-Give Results<br>2. Test Refused<br>3. Results Unknown<br><b>Results</b> | 21. Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed<br><b>5. Observed</b> | 22. Drug Test Given Y/N<br><b>N</b> |
| 23. Drug Test Type - Circle One<br>Blood<br>Urine | 24. Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown    |                                                                                                                                                                                                                                        |                                     |
| Unit 2                                            | NAME First MI Last<br><b>[REDACTED]</b>                                                                                    | Ejected Y/N<br><b></b>                                                                                                                                                                                                                 | Ejected Y/N<br><b></b>              |
| Alcohol Test Given Y/N<br><b></b>                 | Alcohol Test Results - Circle One<br>1. Actual-Give Results<br>2. Test Refused<br>3. Results Unknown<br><b>Results</b>     | Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed                           | Drug Test Given Y/N<br><b></b>      |
| Drug Test Type - Circle One<br>Blood<br>Urine     | Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown        |                                                                                                                                                                                                                                        |                                     |
| Unit 3                                            | NAME First MI Last<br><b>[REDACTED]</b>                                                                                    | Ejected Y/N<br><b></b>                                                                                                                                                                                                                 | Ejected Y/N<br><b></b>              |
| Alcohol Test Given Y/N<br><b></b>                 | Alcohol Test Results - Circle One<br>1. Actual-Give Results<br>2. Test Refused<br>3. Results Unknown<br><b>Results</b>     | Alcohol Test Type - Circle One<br>1. Evidential Test - Circle One<br>1A. Breath; 1B. Blood; 1C. Urine<br>2. Preliminary Breath Test (PBT)<br>3. Behavioral<br>4. Passive Alcohol Sensor (PAS)<br>5. Observed                           | Drug Test Given Y/N<br><b></b>      |
| Drug Test Type - Circle One<br>Blood<br>Urine     | Drug Test Results - Circle One<br>1. No Drugs Reported<br>2. Drugs Reported - Specify<br>3. Tested, Results Unknown        |                                                                                                                                                                                                                                        |                                     |

## FATALITY INFORMATION

|                                                                       |                                  |                                                    |                                      |                                      |
|-----------------------------------------------------------------------|----------------------------------|----------------------------------------------------|--------------------------------------|--------------------------------------|
| 25. Name - First MI Last<br><b>[REDACTED]</b>                         | 26. Ejected Y/N<br><b>N</b>      | 27. Ejected Y/N<br><b>Y</b>                        | 28. Date of Death<br><b>10/24/06</b> | 29. Time of Death<br><b>11:18 AM</b> |
| 1. <b>[REDACTED]</b>                                                  | <b>N</b>                         | <b>Y</b>                                           | <b>10/24/06</b>                      | <b>11:18 AM</b>                      |
| 2. <b>[REDACTED]</b>                                                  | <b>N</b>                         | <b>N</b>                                           | <b>11-04-06</b>                      | <b>10:19 AM</b>                      |
| 3. <b>[REDACTED]</b>                                                  | <b></b>                          | <b></b>                                            | <b></b>                              | <b>AM PM</b>                         |
| 30. Officer Completing Report - Print Name<br><b>F.R.I.C. JOHNSON</b> | 31. Officer ID No<br><b>8821</b> | 32. Enforcement Agency Name<br><b>ST. CROIX CO</b> | 33. Report Date<br><b>10-26-06</b>   |                                      |

|                                                                        |                                                                                                                 |                                                                                                                                        |                                 |                         |                  |                     |                                                                                 |
|------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|-------------------------|------------------|---------------------|---------------------------------------------------------------------------------|
| Occupant<br>Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) | NAME Last First M.I.                                                                                            | Date of Birth                                                                                                                          | Sex<br>(M) (F)                  | Severity<br>(A) (B) (C) | SEAT<br>Position | SAFETY<br>Equipment | AIRBAG<br>(1) Deployed<br>(2) Non Deployed<br>(3) Not Applicable<br>(4) Unknown |
|                                                                        | ADDRESS Street & Number City & State ZIP                                                                        |                                                                                                                                        |                                 |                         |                  |                     |                                                                                 |
| Address Same<br>as Operator<br>Yes<br>No                               | EJECTED<br>(1) Not Applicable<br>(2) Not Ejected<br>(3) Totally Ejected<br>(4) Partially Ejected<br>(5) Unknown | TRAPPED/<br>EXTRICATED<br>(1) Not Applicable<br>(2) Not Trapped<br>(3) Trapped/Extricated<br>(4) Trapped/Not Extricated<br>(5) Unknown | Medical<br>Transport<br>(Y) (N) | Agency Space            |                  |                     |                                                                                 |

|                                                                        |                                                                                                                 |                                                                                                                                        |                                 |                         |                  |                     |                                                                                 |
|------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|-------------------------|------------------|---------------------|---------------------------------------------------------------------------------|
| Occupant<br>Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) | NAME Last First M.I.                                                                                            | Date of Birth                                                                                                                          | Sex<br>(M) (F)                  | Severity<br>(A) (B) (C) | SEAT<br>Position | SAFETY<br>Equipment | AIRBAG<br>(1) Deployed<br>(2) Non Deployed<br>(3) Not Applicable<br>(4) Unknown |
|                                                                        | ADDRESS Street & Number City & State ZIP                                                                        |                                                                                                                                        |                                 |                         |                  |                     |                                                                                 |
| Address Same<br>as Operator<br>Yes<br>No                               | EJECTED<br>(1) Not Applicable<br>(2) Not Ejected<br>(3) Totally Ejected<br>(4) Partially Ejected<br>(5) Unknown | TRAPPED/<br>EXTRICATED<br>(1) Not Applicable<br>(2) Not Trapped<br>(3) Trapped/Extricated<br>(4) Trapped/Not Extricated<br>(5) Unknown | Medical<br>Transport<br>(Y) (N) | Agency Space            |                  |                     |                                                                                 |

### Type of Accident

First Harmful Event  
Most Harmful Event

|                                                            |                                                            |
|------------------------------------------------------------|------------------------------------------------------------|
| Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) | Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) |
|------------------------------------------------------------|------------------------------------------------------------|

(select one per vehicle)

#### Collision With Object Not Fixed

|   |                                                |   |
|---|------------------------------------------------|---|
| 1 | Motor Vehicle in Transport                     | 1 |
| 2 | Parked Motor Vehicle                           | 2 |
| 3 | Deer                                           | 3 |
| 4 | Pedalcycle                                     | 4 |
| 5 | Pedestrian                                     | 5 |
| 6 | Railway Train                                  | 6 |
| 7 | Other Animal                                   | 7 |
| 8 | Motor Vehicle in Transport<br>In Other Roadway | 8 |
| 9 | Other Object (Not Fixed)                       | 9 |

#### Collision With Fixed Object

|    |                    |    |
|----|--------------------|----|
| 10 | Traffic Sign Post  | 10 |
| 11 | Traffic Signal     | 11 |
| 12 | Utility Pole       | 12 |
| 13 | Lum. Light Support | 13 |
| 14 | Other Post         | 14 |
| 15 | Tree               | 15 |
| 16 | Mailbox            | 16 |
| 17 | Guardrail Face     | 17 |
| 18 | Guardrail End      | 18 |
| 19 | Median Barrier     | 19 |
| 20 | Bridge Parapet End | 20 |
| 21 | Bridge/Pier/Abut.  | 21 |
| 22 | Impact Attenuator  | 22 |
| 23 | Overhead Sign Post | 23 |
| 24 | Bridge Rail        | 24 |
| 25 | Culvert            | 25 |
| 26 | Ditch              | 26 |
| 27 | Curb               | 27 |
| 28 | Embankment         | 28 |
| 29 | Fence              | 29 |
| 30 | Other Fixed Object | 30 |
| 31 | Unknown            | 31 |

#### Non-Collision

|    |                     |    |
|----|---------------------|----|
| 32 | Overturn            | 32 |
| 33 | Fire/Explosion      | 33 |
| 34 | Immersion           | 34 |
| 35 | Jackknife           | 35 |
| 36 | Other Non-Collision | 36 |

### Driver Condition

|                                                            |                                                            |
|------------------------------------------------------------|------------------------------------------------------------|
| Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) | Unit Number<br>(1) (2) (3) (4) (5)<br>(6) (7) (8) (9) (10) |
|------------------------------------------------------------|------------------------------------------------------------|

#### Driver Factors (Or Pedestrians)

|   |                   |   |
|---|-------------------|---|
| 1 | Appeared Normal   | 1 |
| 2 | Reduced Alertness | 2 |
| 3 | Ability Impaired  | 3 |
| 4 | Not Observed      | 4 |

#### Presence

|   |                                   |   |
|---|-----------------------------------|---|
| 5 | Neither Alcohol nor Drugs Present | 5 |
| 6 | Yes—Alcohol Present               | 6 |
| 7 | Yes—Drugs Present                 | 7 |
| 8 | Yes—Alcohol & Drugs Present       | 8 |
| 9 | Unknown                           | 9 |

#### Alcohol

|          |                                 |    |
|----------|---------------------------------|----|
| AC Value | AC Value                        |    |
| 10       | Test Not Given                  | 10 |
| 11       | Test Refused                    | 11 |
| 12       | Test Given, Alcohol Unknown     | 12 |
| 13       | Test Given, No Alcohol Reported | 13 |

#### Drugs

|    |                                |    |
|----|--------------------------------|----|
| 14 | Test Not Given                 | 14 |
| 15 | Test Refused                   | 15 |
| 16 | Test Given, Drugs Unknown      | 16 |
| 17 | Test Given, No Drugs Reported  | 17 |
| 18 | Drugs Reported (Specify Below) | 18 |
| 19 | Marijuana                      | 19 |
| 20 | Cocaine                        | 20 |
| 21 | Opiates                        | 21 |
| 22 | Amphetamines                   | 22 |
| 23 | PCP                            | 23 |
| 24 | Other Drug Medication          | 24 |
| 25 | Type Unknown                   | 25 |

### Pedestrian

|                                                    |                                                                                         |                                                                                                                                                |
|----------------------------------------------------|-----------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|
| Unit #<br>(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) | Location<br>(1) In Crosswalk<br>(2) In Roadway<br>(3) Not in Roadway<br>(4) On Sidewalk | Action<br>(1) Walking not Facing Traffic<br>(2) Disregarded Signal<br>(3) Darting into Road<br>(4) Dark Clothing<br>(5) Walking Facing Traffic |
|----------------------------------------------------|-----------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|

### Manner of Collision

|   |                                              |
|---|----------------------------------------------|
| 1 | No Collision with Motor Vehicle in Transport |
| 2 | Rear-end                                     |
| 3 | Head On                                      |
| 4 | Rear to Rear                                 |
| 5 | Angle                                        |
| 6 | Sideswipe, Same Direction                    |
| 7 | Sideswipe, Opposite Direction                |
| 8 | Unknown                                      |

### Unit #

|                                                    |                                           |
|----------------------------------------------------|-------------------------------------------|
| Unit #<br>(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) | Darken Numbered Area(s) of Vehicle Damage |
|----------------------------------------------------|-------------------------------------------|

|    |                             |    |               |
|----|-----------------------------|----|---------------|
| 10 | None                        | 10 | Undercarriage |
| 11 | Total (Damage to All Areas) | 11 | Very Minor    |
| 12 | Other                       | 12 | Minor         |
| 13 | Unknown                     | 13 | Moderate      |

### Extent of Damage

|   |            |   |             |
|---|------------|---|-------------|
| 1 | None       | 4 | Severe      |
| 2 | Very Minor | 5 | Very Severe |
| 3 | Moderate   | 6 | Unknown     |

Vehicle Towed Due to Damage (Y) (N) 96

Vehicle Removed By: 97

### Unit #

|                                                    |                                           |
|----------------------------------------------------|-------------------------------------------|
| Unit #<br>(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) | Darken Numbered Area(s) of Vehicle Damage |
|----------------------------------------------------|-------------------------------------------|

|    |                             |    |               |
|----|-----------------------------|----|---------------|
| 10 | None                        | 10 | Undercarriage |
| 11 | Total (Damage to All Areas) | 11 | Very Minor    |
| 12 | Other                       | 12 | Minor         |
| 13 | Unknown                     | 13 | Moderate      |

### Extent of Damage

|   |            |   |             |
|---|------------|---|-------------|
| 1 | None       | 4 | Severe      |
| 2 | Very Minor | 5 | Very Severe |
| 3 | Moderate   | 6 | Unknown     |

Vehicle Towed Due to Damage (Y) (N) 96

Vehicle Removed By: 97

### Fixed Object Struck

|        |        |        |        |
|--------|--------|--------|--------|
| Unit # | Unit # | Unit # | Unit # |
|--------|--------|--------|--------|

Govt. Damage Tag # 84

### PROPERTY

|                         |                  |
|-------------------------|------------------|
| OWNER 84                | Last First M.I.  |
| ADDRESS Street & Number |                  |
| City & State ZIP        | Phone Number ( ) |

# Wisconsin Motor Vehicle Accident Report

Document Number Override

(b) (6)

Police No. 06-9697

## INSTRUCTIONS

Please use a Black Ink Pen or #2 Pencil.

Mark Areas as shown:

Correct Mark

Incorrect Marks

Reportable Accident

Y N

County MUN/TWP

55 11

Accident Date

MONTH DAY YEAR

Jan Feb Mar Apr May Jun Jul Aug Sept Oct Nov Dec

24 06

Time of Accident (Military Time)

HOUR MIN

5 00 00

Total Number

UNITS INJURED KILLED

6 0 0

Hit & Run  
Government Property  
Fire (Narrative)  
Photos Taken (Narrative)  
Trailer or Towed (Narrative)  
Truck or Bus (Last Page)  
Load Spillage  
Construction Zone  
Names Exchanged

Unit #

Sheet No. Of

16

## ACCIDENT LOCATION

Public Highway, Intersection/Related  
Public Highway, Non-Intersection  
Parking Lot  
Private Property or Road

Latitude (GPS) Degrees: 12 Minutes: Seconds: Longitude (GPS) Degrees: 13 Minutes: Seconds:

ON Hwy No. and / Street Name Estimated FROM/AT Hwy No. and / Street Name

House # Fire # Other Utility # Railroad # Agency Space Special Study

Unit Number Unit Type Total Number of Occupants Direction of Travel (Before the Accident) Unit Number Unit Type Total Number of Occupants Direction of Travel (Before the Accident)

Speed Limit OPERATOR Last First M.I. Speed Limit OPERATOR Last First M.I.

ADDRESS Street & Number ADDRESS Street & Number

City & State ZIP Phone Number City & State ZIP Phone Number

Driver's License Number State Exp. Year Driver's License Number State Exp. Year

Date of Birth Sex Operating as Classified: Class (Mark Only One) Endorse (Mark All That Apply) Date of Birth Sex Operating as Classified: Class (Mark Only One) Endorse (Mark All That Apply)

On Duty Accident On Duty Accident

Severity SEAT SAFETY AIRBAG EJECTED Severity SEAT SAFETY AIRBAG EJECTED

TRAPPED/EXTRICATED TRAPPED/EXTRICATED

Vehicle Owner Same Last Name First Last Name First

Street Address Street Address

City & State ZIP Phone Number City & State ZIP Phone Number

Year of Vehicle Make Model Body Style Color Year of Vehicle Make Model Body Style Color

Vehicle ID Number Vehicle ID Number

License Plate Number Plate Type State Exp. Year License Plate Number Plate Type State Exp. Year

Policy Holder's Name Citation Policy Holder's Name

Liability Insurance Company Stat. # Liability Insurance Company Stat. #

Occupant Unit Number NAME Last First M.I. Date of Birth Sex Severity SEAT SAFETY AIRBAG

ADDRESS Street & Number City & State ZIP

Address Same as Operator EJECTED TRAPPED/EXTRICATED

MV4000 899 EMS Number



|                                                 |                                                                                                       |                                                                                                                          |                          |                             |                    |                       |                                                                         |
|-------------------------------------------------|-------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------|--------------------|-----------------------|-------------------------------------------------------------------------|
| Occupant Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 | NAME Last First M.I.                                                                                  | Date of Birth                                                                                                            | Sex<br>M F               | Severity<br>K N<br>A B<br>C | SEAT Position<br>4 | SAFETY Equipment<br>0 | AIRBAG<br>1 Deployed<br>2 Non Deployed<br>3 Not Applicable<br>4 Unknown |
|                                                 | ADDRESS Street & Number City & State                                                                  |                                                                                                                          | Alber Lea MN             |                             |                    |                       |                                                                         |
| Address Same as Operator<br>Yes No              | EJECTED<br>1 Not Applicable<br>2 Not Ejected<br>3 Totally Ejected<br>4 Partially Ejected<br>5 Unknown | TRAPPED/EXTRICATED<br>1 Not Applicable<br>2 Not Trapped<br>3 Trapped/Extricated<br>4 Trapped-Not Extricated<br>5 Unknown | Medical Transport<br>Y N | Agency Space                |                    |                       |                                                                         |

|                                                 |                                                                                                       |                                                                                                                          |                          |                             |               |                  |                                                                         |
|-------------------------------------------------|-------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------|---------------|------------------|-------------------------------------------------------------------------|
| Occupant Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 | NAME Last First M.I.                                                                                  | Date of Birth                                                                                                            | Sex<br>M F               | Severity<br>K N<br>A B<br>C | SEAT Position | SAFETY Equipment | AIRBAG<br>1 Deployed<br>2 Non Deployed<br>3 Not Applicable<br>4 Unknown |
|                                                 | ADDRESS Street & Number City & State                                                                  |                                                                                                                          | ZIP                      |                             |               |                  |                                                                         |
| Address Same as Operator<br>Yes No              | EJECTED<br>1 Not Applicable<br>2 Not Ejected<br>3 Totally Ejected<br>4 Partially Ejected<br>5 Unknown | TRAPPED/EXTRICATED<br>1 Not Applicable<br>2 Not Trapped<br>3 Trapped/Extricated<br>4 Trapped-Not Extricated<br>5 Unknown | Medical Transport<br>Y N | Agency Space                |               |                  |                                                                         |

### Type of Accident

| First Harmful Event                    |                                        |
|----------------------------------------|----------------------------------------|
| Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 |
| (select one per vehicle)               |                                        |

#### Collision With Object Not Fixed

- |                                                |    |
|------------------------------------------------|----|
| 1 Motor Vehicle in Transport                   | 2  |
| 3 Parked Motor Vehicle                         | 4  |
| 5 Deer                                         | 6  |
| 7 Pedalcycle                                   | 8  |
| 9 Pedestrian                                   | 10 |
| 11 Railway Train                               | 12 |
| 13 Other Animal                                | 14 |
| 15 Motor Vehicle in Transport In Other Roadway | 16 |
| 17 Other Object (Not Fixed)                    | 18 |

#### Collision With Fixed Object

- |                       |    |
|-----------------------|----|
| 19 Traffic Sign Post  | 20 |
| 21 Traffic Signal     | 22 |
| 23 Utility Pole       | 24 |
| 25 Lum. Light Support | 26 |
| 27 Other Post         | 28 |
| 29 Tree               | 30 |
| 31 Mailbox            | 32 |
| 33 Guardrail Face     | 34 |
| 35 Guardrail End      | 36 |
| 37 Median Barrier     | 38 |
| 39 Bridge Parapet End | 40 |
| 41 Bridge/Pier/Abut.  | 42 |
| 43 Impact Attenuator  | 44 |
| 45 Overhead Sign Post | 46 |
| 47 Bridge Rail        | 48 |
| 49 Culvert            | 50 |
| 51 Ditch              | 52 |
| 53 Curb               | 54 |
| 55 Embankment         | 56 |
| 57 Fence              | 58 |
| 59 Other Fixed Object | 60 |
| 61 Unknown            | 62 |

#### Non-Collision

- |                        |    |
|------------------------|----|
| 63 Overturn            | 64 |
| 65 Fire/Explosion      | 66 |
| 67 Immersion           | 68 |
| 69 Jackknife           | 70 |
| 71 Other Non-Collision | 72 |

### Driver Condition

|                                        |                                        |
|----------------------------------------|----------------------------------------|
| Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 | Unit Number<br>1 2 3 4 5<br>6 7 8 9 10 |
|----------------------------------------|----------------------------------------|

#### Driver Factors (Or Pedestrians)

- |                     |   |
|---------------------|---|
| 1 Appeared Normal   | 2 |
| 3 Reduced Alertness | 4 |
| 5 Ability Impaired  | 6 |
| 7 Not Observed      | 8 |

#### Presence

- |                                     |    |
|-------------------------------------|----|
| 9 Neither Alcohol nor Drugs Present | 10 |
| 11 Yes—Alcohol Present              | 12 |
| 13 Yes—Drugs Present                | 14 |
| 15 Yes—Alcohol & Drugs Present      | 16 |
| 17 Unknown                          | 18 |

#### Alcohol

|                                    |          |
|------------------------------------|----------|
| AC Value                           | AC Value |
| 19 Test Not Given                  | 20       |
| 21 Test Refused                    | 22       |
| 23 Test Given, Alcohol Unknown     | 24       |
| 25 Test Given, No Alcohol Reported | 26       |

#### Drugs

- |                                   |    |
|-----------------------------------|----|
| 27 Test Not Given                 | 28 |
| 29 Test Refused                   | 30 |
| 31 Test Given, Drugs Unknown      | 32 |
| 33 Test Given, No Drugs Reported  | 34 |
| 35 Drugs Reported (Specify Below) | 36 |
| 37 Marijuana                      | 38 |
| 39 Cocaine                        | 40 |
| 41 Opiates                        | 42 |
| 43 Amphetamines                   | 44 |
| 45 PCP                            | 46 |
| 47 Other Drug Medication          | 48 |
| 49 Type Unknown                   | 50 |

Unit # 2 3 4 5 6 7 8 9 10

#### Pedestrian


- | Location         | Action                       |
|------------------|------------------------------|
| 1 In Crosswalk   | 1 Walking not Facing Traffic |
| 2 In Roadway     | 2 Disregarded Signal         |
| 3 Not in Roadway | 3 Darting into Road          |
| 4 On Sidewalk    | 4 Dark Clothing              |
|                  | 5 Walking Facing Traffic     |

#### Manner of Collision

- |                                                |    |
|------------------------------------------------|----|
| 1 No Collision with Motor Vehicle in Transport |    |
| 2 Rear-end                                     | 3  |
| 4 Head On                                      | 5  |
| 6 Rear to Rear                                 | 7  |
| 8 Angle                                        | 9  |
| 10 Sideswipe, Same Direction                   | 11 |
| 12 Sideswipe, Opposite Direction               | 13 |
| 14 Unknown                                     | 15 |

Unit # 1 2 3 4 5 6 7 8 9 10

#### Darken Numbered Area(s) of Vehicle Damage



- |                               |                 |
|-------------------------------|-----------------|
| 1 None                        | 2 Undercarriage |
| 3 Total (Damage to All Areas) | 4 Other         |
| 5 Unknown                     | 6 Unknown       |


#### Extent of Damage

- |              |               |
|--------------|---------------|
| 1 None       | 2 Severe      |
| 3 Very Minor | 4 Very Severe |
| 5 Minor      | 6 Unknown     |
| 7 Moderate   |               |

Vehicle Towed Due to Damage: 1  
Vehicle Removed By: Perry's Towing

Unit # 1 2 3 4 5 6 7 8 9 10

#### Darken Numbered Area(s) of Vehicle Damage



- |                               |                 |
|-------------------------------|-----------------|
| 1 None                        | 2 Undercarriage |
| 3 Total (Damage to All Areas) | 4 Other         |
| 5 Unknown                     | 6 Unknown       |

#### Extent of Damage

- |              |               |
|--------------|---------------|
| 1 None       | 2 Severe      |
| 3 Very Minor | 4 Very Severe |
| 5 Minor      | 6 Unknown     |
| 7 Moderate   |               |

Vehicle Towed Due to Damage: 1  
Vehicle Removed By: 2

#### Fixed Object Struck

|          |          |          |          |
|----------|----------|----------|----------|
| Unit # 1 | Unit # 2 | Unit # 3 | Unit # 4 |
| 30       |          |          |          |

Govt. Damage Tag # 84

PROPERTY Last First M.I.

OWNER SBC Telephone

ADDRESS Street & Number

85 212 Main St

City & State ZIP

81 Roberts WI 54023

Phone Number (1-800)

87 276-2990

8929339

Amended Document On Emergency

Wisconsin Motor Vehicle  
Accident Report

Document Number Override

## INSTRUCTIONS

Please use a  
Black Ink Pen  
or #2 Pencil.

Mark Areas as shown:

Correct Mark

Incorrect Marks

Reportable  
Accident

County

SS

MUN/TWP

11

Accident Date

MONTH DAY YEAR

24 06

Time of Accident  
(Military Time)

HOUR MIN.

19 55

Total Number

UNITS INJURED KILLED

01 02 01

Hit &amp; Run

Government Property

Fire (Narrative)

Photos Taken (Narrative)

Trailer or Towed (Narrative)

Truck or Bus (Last Page)

Load Spillage

Construction Zone

Names Exchanged

Sheet No.

Of

11

## ACCIDENT LOCATION

☐ Public Highway, Intersection/Related☒ Public Highway, Non-Intersection☐ Parking Lot☐ Private Property or Road

LATITUDE (GPS) Degrees: Minutes: Seconds: LONGITUDE (GPS) Degrees: Minutes: Seconds:

ON Hwy No. and / Street Name Estimated FT. MI. FROM/AT Hwy No. and / Street Name

CTH N .5 North Skyline Drive

House # Fire # Other Agency Space Special Study

Unit Number Unit Type Total Number of Occupants Direction of Travel (Before the Accident)

Unit Number Unit Type Total Number of Occupants Direction of Travel (Before the Accident)

Speed Limit OPERATOR Last First M.I. Speed Limit OPERATOR Last First M.I.

ADDRESS Street &amp; Number ADDRESS Street &amp; Number

City &amp; State ZIP Phone Number City &amp; State ZIP Phone Number

Driver's License Number State Exp. Year Driver's License Number State Exp. Year

Date of Birth Sex (M) Operating as Classified: Class (Mark Only One) Endorse (Mark All That Apply)

On Duty Accident: Police E. EMT/First Responder F. Fire Fighter H. Winter Hwy Maintenance

Severity SEAT SAFETY AIRBAG EJECTED Severity SEAT SAFETY AIRBAG EJECTED

TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I. TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I.

Street Address Street Address

City &amp; State ZIP Phone Number City &amp; State ZIP Phone Number

Year of Vehicle Make Model Body Style Color Year of Vehicle Make Model Body Style Color

Vehicle ID Number Vehicle ID Number

License Plate Number License Plate Number

Policy Holder's Name Policy Holder's Name

Liability Insurance Company Erie Insurance

Occupant Unit Number NAME Last First M.I. Date of Birth Sex

ADDRESS Street &amp; Number City &amp; State ZIP

Severity SEAT SAFETY AIRBAG EJECTED Severity SEAT SAFETY AIRBAG EJECTED

TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I. TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I.

Street Address Street Address

City &amp; State ZIP Phone Number City &amp; State ZIP Phone Number

Year of Vehicle Make Model Body Style Color Year of Vehicle Make Model Body Style Color

Vehicle ID Number Vehicle ID Number

License Plate Number License Plate Number

Policy Holder's Name Policy Holder's Name

Liability Insurance Company Erie Insurance

Occupant Unit Number NAME Last First M.I. Date of Birth Sex

ADDRESS Street &amp; Number City &amp; State ZIP

Severity SEAT SAFETY AIRBAG EJECTED Severity SEAT SAFETY AIRBAG EJECTED

TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I. TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I.

Street Address Street Address

City &amp; State ZIP Phone Number City &amp; State ZIP Phone Number

Year of Vehicle Make Model Body Style Color Year of Vehicle Make Model Body Style Color

Vehicle ID Number Vehicle ID Number

License Plate Number License Plate Number

Policy Holder's Name Policy Holder's Name

Liability Insurance Company Erie Insurance

Occupant Unit Number NAME Last First M.I. Date of Birth Sex

ADDRESS Street &amp; Number City &amp; State ZIP

Severity SEAT SAFETY AIRBAG EJECTED Severity SEAT SAFETY AIRBAG EJECTED

TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I. TRAPPED/ EXTRICATED Vehicle Owner Last Name First M.I.

Street Address Street Address

City &amp; State ZIP Phone Number City &amp; State ZIP Phone Number

Year of Vehicle Make Model Body Style Color Year of Vehicle Make Model Body Style Color

Vehicle ID Number Vehicle ID Number

License Plate Number License Plate Number

Policy Holder's Name Policy Holder's Name

Liability Insurance Company Erie Insurance

Occupant Unit Number NAME Last First M.I. Date of Birth Sex

ADDRESS Street &amp; Number City &amp; State ZIP

TA000093346

# **COLLISION ANALYSIS & RECONSTRUCTION REPORT**



**EAU CLAIRE POST CASE #** [REDACTED]

**ST. CROIX COUNTY CASE #** [REDACTED]

**COLLISION DATE: 10-24-2006**

**LOCATION: CTH N East of North Skyline Drive  
ST CROIX COUNTY, WI**

**PREPARED BY: KEITH A. YOUNG**

**TROOPER  
TECHNICAL RECONSTRUCTION UNIT  
WISCONSIN STATE PATROL ACADEMY  
608-269-2500**

**REPORT DATE: February 14, 2007**

# TABLE OF CONTENTS

|                                                     |          |
|-----------------------------------------------------|----------|
| INFORMATION UTILIZED FOR COMPLETION OF REPORT ..... | 3        |
| SYNOPSIS .....                                      | 4        |
| OBJECTIVE .....                                     | 4        |
| COLLISION SCENE.....                                | 4        |
| COLLISION SEQUENCE.....                             | 5        |
| SERVICE BULLETIN .....                              | 6        |
| VEHICLE INSPECTION .....                            | 6        |
| FORENSIC SCENE MAPPING .....                        | 7        |
| SENSING AND DIAGNOSTIC MODULE.....                  | 7        |
| EXEMPLAR VEHICLE MEASUREMENTS.....                  | 8        |
| SPEED ANALYSIS .....                                | 9        |
| VEHICLE FACTORS.....                                | 9        |
| HUMAN FACTORS.....                                  | 10       |
| ENVIRONMENTAL FACTORS .....                         | 10       |
| WEATHER.....                                        | 10       |
| MOON POSITION .....                                 | 11       |
| ROADWAY CONDITION .....                             | 11       |
| VISIBILITY CONDITIONS.....                          | 11       |
| INVESTIGATIVE SUMMARY .....                         | 11       |
| APPENDIX .....                                      | 12       |
| TROOPER TRAYNOR'S REPORT .....                      | ATTACHED |
| INSPECTOR WRIGHT'S REPORT .....                     | ATTACHED |
| SCALED SCENE DRAWING.....                           | ATTACHED |
| VETRONIX CRASH DATA RETRIEVAL REPORT .....          | ATTACHED |



## **INFORMATION UTILIZED FOR COMPLETION OF REPORT**

- 1. Wisconsin Motor Vehicle Accident Report MV4000 completed by Deputy Eric Johnson.**
- 2. Narrative Reports by St Croix County Sheriff's Department Deputy Eric Johnson.**
- 3. Narrative Report by Trooper William Traynor.**
- 4. Forensic Mapping Measurements by Troopers Keith Young and William Traynor.**
- 5. Scene Photographs by Deputy Sommers and Trooper Young.**
- 6. SDM Photographs at St Croix County impound lot by Trooper Young.**
- 7. Moon Position Data, U.S. Naval Observatory.**
- 8. Weather Conditions Data, Weather Underground.**
- 9. Vetronix CDR Report for 2005 Chevrolet Cobalt VIN; 1G1AK52F657 [REDACTED]**
- 10. Interview by Deputy Johnson with:**
  - [REDACTED]**
  - [REDACTED]**
  - [REDACTED]**
- 11. Wisconsin Department of Transportation Records for [REDACTED]**

## SYNOPSIS

On October 24, 2006, a Chevrolet Cobalt driven by [REDACTED] was eastbound on CTH N just east of North Skyline Drive. The [REDACTED] vehicle traveled onto the south shoulder and into the south ditch. The vehicle then launched off of the west edge of a driveway and became airborne. The vehicle landed and traveled through the ditch before striking a telephone junction box and two trees. The vehicle then rotated clockwise coming to rest in the south ditch facing south. [REDACTED] sustained serious injuries. The right front seat passenger [REDACTED] and left rear seat passenger [REDACTED] later died as a result of injuries they received in the crash.


## OBJECTIVE

The primary objective of this analysis is to evaluate the speed and positions of the [REDACTED] vehicle during the collision sequence. A study of the vehicle, human or environmental factors including safety belt use and airbag non-deployment will also be performed.

## COLLISION SCENE


The crash scene is located on CTH N east of Skyline Drive in the Township of Kinnickinnic. This is a rural area of St. Croix County. The pavement in the area of the crash is traveled asphalt flanked by gravel shoulders. Traffic traveling east on CTH N has a downgrade of approximately 0.05 percent.

Upon my arrival on scene I viewed the scene with Deputy Mark Sommers and Trooper William Traynor. The roadway leading up to the crash scene was inspected for any indication as to why the [REDACTED] vehicle left the road. The first evidence that could be observed was gravel from the shoulder scattered onto the eastbound lane approximately 195 feet west of the driveway at 1237 CTH N. This was most likely caused by the tires of the [REDACTED] vehicle as they left the roadway. There were rolling tire marks in the south ditch that lead up to the edge of the driveway. The vehicle then struck the sloped driveway embankment and vaulted approximately 59 feet through the air. The vehicle landed and traveled another 82 feet before striking a telephone junction box. The vehicle then traveled an additional 46 feet before striking a grouping of two trees, and rotating approximately 94 degrees. The vehicle came to rest just north of the trees, facing south in the south ditch.



## COLLISION SEQUENCE

As the [REDACTED] vehicle traveled down a slight grade her vehicle went onto the south shoulder and into the south ditch. When the vehicle approached the driveway at house number 1237 it launched off of the west edge of the driveway and was airborne for approximately 59 feet. The vehicle landed and traveled approximately 82 feet before striking a telephone junction box and knocking it down. The vehicle then traveled another 46 feet through some brush before striking two larger trees. The vehicle then rotated clockwise approximately 94 degrees while traveling another 14 feet before coming to rest.



## SERVICE BULLETIN

On October 27, 2006, I obtained a printout of a General Motors document ID# 1686453 (*A/C system wiring or dual stage airbag module wiring # 05034A – (07/22/2005)*) for a 2005 Chevrolet Cobalt. I also obtained a copy of the GM Vehicle Inquiry System Summary for the 2005 Chevrolet Cobalt VIN: 1G1AK52F657 [REDACTED]. These reports were forwarded to State Patrol Inspector George Wright. Inspector Wright reviewed the two GM reports to determine if the appropriate repairs were made. Inspector Wright advised me that the air conditioning wiring repair was the correct repair for this vehicle and that the reports indicate that the air conditioning wiring repair was done. Inspector Wright further advised that the dual stage airbag module wiring was not required to be changed on this vehicle. (*See Inspector Wright's report*).

## VEHICLE INSPECTION

**2005 CHEVROLET COBALT VIN 1G1AK52F657 [REDACTED] DRIVER: [REDACTED]**

On October 24, 2006, while at the scene I examined the vehicle and the following observations were made:

There was heavy frontal contact damage concentrated on the right side and induced damage to the roof and passenger side. Emergency medical services (EMS) had removed the right front passenger door and cut both A-pillars to extricate the front seat occupants.



### Tires

Left Front tire, P195 60 R15 Continental, tire flat 0/32 tread depth  
Right Front tire, P195 60 R15 Continental, 1/32 – 2/32 tread depth  
Left Rear tire, P195 60 R15 Continental, 6/32 – 6/32 tread depth  
Right Rear tire, P195 60 R15 Continental, 5/32 – 6/32 tread depth

### Seatbelts

Driver seat belt retracted, no signs of use  
Right Front passenger seat belt retracted, no signs of use  
Left Rear passenger seat belt retracted, no signs of use  
Center Rear passenger seat belt retracted, no signs of use  
Right Rear passenger seat belt locked retracted, no signs of use

On December 11, 2006, I met with Robert Wozniak an engineer from Skogen Engineering at the St. Croix County impound lot to inspect the vehicle. The fuse block was examined, it was determined that fuse number 28 for the audio system was blown. It was also confirmed that the airbag wiring procedure noted in service bulletin #05034A had not been done.

**\*\* Note:** As mentioned in the above section titled *Service Bulletin*, the airbag wiring procedure did not apply to this vehicle.




## FORENSIC SCENE MAPPING

On October 24, 2006, with the assistance of Trooper William Traynor the crash scene was mapped with the State Patrol's Geodimeter 610 Total Station. Detailed measurements of the scene were taken locating roadway and lane edges, tire marks, a utility box and tree as well as the final rest position of the vehicle involved in the crash. The measurements obtained using the total station were then used in *Crash Zone*, a *Computer Aided Drawing (CAD)* program to produce a forensic map of the crash scene.



On November 6, 2006, Trooper Traynor and myself went to the St. Croix County Impound Lot to measure the damage profile of the [REDACTED] vehicle. Using the State Patrol's Geodimeter 610 Total Station, measurements of the [REDACTED] vehicle were taken to determine the amount of deformation that was caused by the collision with the trees.



## SENSING AND DIAGNOSTIC MODULE

On November 8, 2006, I obtained a signed release to retrieve the data stored in the Sensing and Diagnostic Module (SDM) from [REDACTED] the registered owner of the 2005 Chevrolet Cobalt VIN: 1G1AK52F657[REDACTED].

On November 13, 2006, Trooper Traynor and myself returned to the St. Croix County Impound Lot. We located the SDM between the front seats of the [REDACTED] vehicle. I photographed the SDM prior to and after its removal. The SDM appeared to be connected and undamaged.

On November 15, 2006, I used the State Patrol's Vetronix Crash Data Retrieval (CDR) equipment connected directly to the module to read the information recorded on the SDM. The data was successfully downloaded to my Panasonic CF-28 laptop computer. The data retrieved from the SDM was recorded on the CDR File Report (*See attached CDR report*).

## SPEED ANALYSIS

The ***Vault Formula*** was used to determine the speed of the vehicle when it vaulted off of the driveway. The vault speed was calculated to be approximately 48 mph. A crush analysis was also performed to determine the speed lost impacting the grouping of two trees and damaging the front of the vehicle. The crush calculations indicated a speed of approximately 38 mph at the trees.

## VEHICLE FACTORS

The ignition switch on the [REDACTED] vehicle appears to have been in the accessory position when it impacted the trees preventing the airbags from deploying. A search of the National Highway Transportation Safety Administration (NHTSA) web site indicates five complaints of 2005 Chevrolet Cobalt ignition switches turning off while the vehicle was being driven. Three of the complaints talk about the knee or leg touching the ignition or key chain causing the engine to turn off.

On December 12, 2006, a printout of General Motors Document ID# 1869035 (***inadvertent turning of key cylinder, loss of electrical system and no DTSS # 05-02-35-007A-(10/25/2006)***) for the 2005 – 2007 Chevrolet Cobalt was obtained. The bulletin discusses the potential for the driver to inadvertently turn off the ignition due to low key cylinder torque/effort.

The bulletin goes on to mention that the condition is more likely to occur if the driver is short and the key chain is large and/or heavy. A shorter person would have the seat position closer to the steering column.

It appears likely that the vehicles' key turned to accessory as a result of the low key cylinder torque/effort.

While both front tires of the [REDACTED] vehicle had illegal tread depth it does not appear that this condition contributed to the crash in any way. There was an inspection of the pavement for several hundred feet leading up to the point that the [REDACTED] vehicle went onto the gravel, no tire or rim marks of any kind were found. If a vehicle has a flat tire causing loss of control, some tire marking from the flat tire and/or the metal rim should have been visible on the asphalt pavement.


## HUMAN FACTORS

██████████ was traveling east down a slight grade on a straight portion of CTH N. For some unknown reason the vehicle traveled off of the pavement at a gradual angle into the south ditch. A review of ██████████ Wisconsin drivers' license status showed that she had a valid instruction permit. The instruction permit requires a qualified licensed driver be seated in the right front seat. According to the Wisconsin Department of Transportation driver license files, the right front seat passenger ██████████ did not have a drivers' license and was not a qualified licensed driver.

## ENVIRONMENTAL FACTORS

### Weather

The weather conditions were reported by the Weather Underground for New Richmond, Wisconsin (*the nearest reporting station*) on October 24, 2006, at 7:55 pm as mostly cloudy skies, visibility was 10 miles, the wind was out of the east south east at 3.5 mph and the temperature was 37.8 degrees. The weather does not appear to have been a factor in the crash.



### **Moon Position**

U.S. Naval observatory data indicates that on October 24, 2006, at 7:55 pm the moon was below the horizon and would not have been a factor in the crash.

### **Roadway Condition**

The roadway surface for CTH N is a traveled asphalt pavement. The surface was dry. The yellow centerlines and white edge stripes were clearly visible. The road does not appear to have been a factor in the crash.

### **Visibility Conditions**


There were no observed visibility conditions that contributed to the crash.

## **INVESTIGATIVE SUMMARY**

*The following statements are opinions and inferences of this author. They are based upon the information reviewed to date. These statements are accurate to a reasonable degree of scientific certainty:*

- None of the occupants were wearing their safety belts at the time of the crash.
- The two front seat airbags did not deploy. It appears that the ignition switch had somehow been turned from the run position to accessory prior to the collision with the trees.
- [REDACTED] drivers' license status was a valid instruction permit. [REDACTED] was violating the restrictions on her instruction permit by operating a vehicle without a qualified licensed driver in the right front seat.
- The front tires of the [REDACTED] vehicle did not have the required minimum legal tire tread depth of 2/32 inch in two or more places on each front tire.
- The speed calculated from the vault at the driveway of 48 mph and the crush speed at the trees of 38 mph do not match the information recorded in the five seconds of pre-crash data on the SDM; this may be due to power loss.

Respectfully Submitted,



Keith A. Young  
Accredited Crash Reconstruction Specialist ACTAR #1426  
Wisconsin State Patrol





# **APPENDIX**

**Trooper Traynor's Narrative Report**  
**Inspector Wrights Narrative Report**  
**Vetronix Crash Data Retrieval Report**  
**Scaled Scene Drawing**

**CRASH RECONSTRUCTION REPORT SUPPLEMENT  
WISCONSIN STATE PATROL NORTHWEST REGION**



**CASE NUMBER:** (b) (6)

**REPORTING INVESTIGATOR:** Trooper William Traynor

**CRASH TYPE:** Fatal

(715) 839-3800

**CRASH INFORMATION**

**Date of Activity**

On Tuesday, October 24 2006, I was called out from my residence to respond to a serious personal injury motor vehicle crash in the 1200 block of CTH N in St. Croix County. I responded to the scene arriving at 9:30pm. DSP Technical Reconstruction Unit (TRU) Investigator Keith Young, and DSP Troopers Lance Loonsfoot and Korey Shilts met me at the scene. St. Croix County (SCSO) Deputies Eric Johnson and Marc Sommers were also on scene. Information I received at the scene indicated a one-vehicle crash involving collision with a tree. All three occupants of the vehicle had been transported from the scene prior to my arrival. Vehicle was a white Chevrolet Cobalt displaying Wisconsin registration (b) (6). Inspecting the scene it appeared the vehicle was eastbound on CTH N when vehicle left the roadway to the right entering a steep ditch where it continued striking a driveway embankment at 1248 CTH N. Vehicle appeared to vault after impact with the driveway continuing in an south easterly decent into the ditch where it struck a phone junction box and continuing into a tree where it impacted in the right front causing the vehicle to rotate clockwise before final rest. Vehicle sustained major frontal structure damage.

Vehicle examination showed that there were no airbag(s) deployment and a visual inspection revealed airbags still seeded inside of their steering wheel cavity and dash compartment. I was advised the occupants were not restrained inside of the vehicle. Front tires on the vehicle displayed excessive wear. Vehicle was towed to the St. Croix County Impound lot in Hudson under escort by SCSO deputy Dick Koenig.

Young and myself set up the Geodimeter 610 Total Station unit and mapped the roadway profile, tire marks, tree and final rest of the vehicle. We completed the on-scene mapping at approximately 1:00am.

On Monday, November 6, 2006 at approximately 11:00am, where I met with TRU Investigator Young. There was also a representative from the National Highway Safety Institute was inspecting the vehicle due to the non-deployment of supplement restraint system. Again using the Geodimeter 610 unit, Young and I mapped the vehicle profile of the Chevrolet Cobalt recording crush damage.

Respectfully submitted,

William Traynor  
Technical Crash Investigator  
Wisconsin State Patrol  
Northwest Region, Eau Claire Post



## Wisconsin Department of Transportation



State Patrol Headquarters District 3  
Junction Highways 41 & 151  
PO Box 984  
Fond du Lac, WI 54936-0984  
Telephone (920) 929-3700  
Office Fax (920) 929-7666  
Radio Fax (920) 929-2770

11-16-06

N501 State Highway 40  
Elk mound, WI 54739

Trooper Young,

On 11-16-06, I, Inspector G. Wright, stopped at Sheboygan Chevrolet and spoke with the Service Manager, Tim Wilsing. I had him look up the recall information on VIN number 1G1AK52F657 [REDACTED]. I was informed that the recall was completed on this vehicle. I asked him if we removed the airbag/seatbelt module would have any effect on future testing, he then called and asked the technician which we were informed that this would not be a problem.

Sincerely,

Inspector G. Wright

## CDR File Information

|                                        |                                                                               |
|----------------------------------------|-------------------------------------------------------------------------------|
| Vehicle Identification Number          | 1G1AK52F657                                                                   |
| Investigator                           | Keith Young                                                                   |
| Case Number                            |                                                                               |
| Investigation Date                     | Wednesday, November 15 2006                                                   |
| Crash Date                             | Tuesday, October 24 2006                                                      |
| Filename                               | 1G1AK52F657 CDR                                                               |
| Saved on                               | Wednesday, November 15 2006 at 08:01:06 AM                                    |
| Collected with CDR version             | Crash Data Retrieval Tool 2.800                                               |
| Collecting program verification number | 9238B95E                                                                      |
| Reported with CDR version              | Crash Data Retrieval Tool 2.800                                               |
| Reporting program verification number  | 9238B95E                                                                      |
| Interface used to collect data         | Block number: 00<br>Interface version: 4A<br>Date: 11-08-05<br>Checksum: 7500 |
| Event(s) recovered                     | Non-Deployment                                                                |

## SDM Data Limitations

## SDM Recorded Crash Events:

There are two types of SDM recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event is an event severe enough to "wake up" the sensing algorithm but not severe enough to deploy the air bag(s). It can contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle forward velocity change. This event will be cleared by the SDM after the ignition has been cycled 250 times.

The second type of SDM recorded crash event is the Deployment Event. It also can contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events, if they occur within five seconds of one another. Deployment Events cannot be overwritten or cleared from the SDM. Once the SDM has deployed the air bag, the SDM must be replaced. The data in the Non-Deployment Event file will be locked after a Deployment Event, if the Non-Deployment Event occurred within 5 seconds before the Deployment Event unless a Deployment Level Event occurs within 5 seconds after the Deployment Event, then the Deployment Level Event will overwrite the Non-Deployment Event file.

## SDM Data Limitations:

- SDM Recorded Vehicle Forward Velocity Change reflects the change in forward velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Forward Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. This data should be examined in conjunction with other available physical evidence from the vehicle and scene when assessing occupant or vehicle forward velocity change. For Deployment Events and Deployment Level Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM will record up to the first 300 milliseconds of data after algorithm enable. The minimum SDM Recorded Vehicle Forward Velocity Change, that is needed to record a Non-Deployment Event, is 5 MPH.
- Maximum Recorded Vehicle Velocity Change is the maximum recorded velocity change in the vehicle's combined "X" and "Y" axis.
- Calculated Principal Direction of Force (PDOF) is the arctangent of the maximum observed lateral velocity change divided by the maximum observed longitudinal velocity change. PDOF is displayed where zero degrees is located at the front of the vehicle, with 90 degrees is displayed to the right side of the vehicle and so on, clockwise around the vehicle.
- Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.
- SDM Recorded Vehicle Speed accuracy can be affected if the vehicle has had the tire size or the final drive axle ratio changed from the factory build specifications.
- Brake Switch Circuit Status indicates the status of the brake switch circuit.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if the SDM receive an invalid message from the module sending the pre-crash data.
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), will always report a default value of "Buckled".
- The Time Between Non-Deployment and Deployment Events is displayed in seconds. If the time between the two events is greater than 5 seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

**SDM Data Source:**

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.



### System Status At AE

|                                              |             |
|----------------------------------------------|-------------|
| Vehicle Identification Number                | **1AK52F*5* |
| Low Tire Pressure Warning Lamp (If Equipped) | Invalid     |
| Vehicle Power Mode Status                    | Accessory   |
| Remote Start Status (If Equipped)            | Inactive    |
| Run/Crank Ignition Switch Logic Level        | Inactive    |
| Brake System Warning Lamp (If Equipped)      | OFF         |

### System Status At 1 second

|                                                   |             |
|---------------------------------------------------|-------------|
| Transmission Range (If Equipped)                  | Fourth Gear |
| Transmission Selector Position (If Equipped)      | Fourth Gear |
| Traction Control System Active (If Equipped)      | Invalid     |
| Service Engine Soon (Non-Emission Related) Lamp   | OFF         |
| Service Vehicle Soon Lamp                         | OFF         |
| Outside Air Temperature (degrees F) (If Equipped) | 38.3        |
| Left Front Door Status (If Equipped)              | Closed      |
| Right Front Door Status (If Equipped)             | Closed      |
| Left Rear Door Status (If Equipped)               | Unused      |
| Right Rear Door Status (If Equipped)              | Unused      |
| Rear Door(s) Status (If Equipped)                 | Closed      |

### Pre-crash data


| Parameter                                         | -2 sec | -1 sec |
|---------------------------------------------------|--------|--------|
| Reduced Engine Power Mode                         | OFF    | OFF    |
| Cruise Control Active (If Equipped)               | No     | No     |
| Cruise Control Resume Switch Active (If Equipped) | No     | No     |
| Cruise Control Set Switch Active (If Equipped)    | No     | No     |

### Pre-crash data


| Parameter                                                 | -5 sec  | -4 sec  | -3 sec  | -2 sec  | -1 sec  |
|-----------------------------------------------------------|---------|---------|---------|---------|---------|
| Vehicle Speed (MPH)                                       | 71      | 71      | 71      | 0       | 0       |
| Engine Speed (RPM)                                        | 2496    | 2496    | 2496    | 0       | 0       |
| Percent Throttle                                          | Invalid | Invalid | Invalid | Invalid | Invalid |
| Accelerator Pedal Position (percent)                      | Invalid | Invalid | Invalid | Invalid | Invalid |
| Antilock Brake System Active (If Equipped)                | Invalid | Invalid | Invalid | Invalid | Invalid |
| Lateral Acceleration (feet/s <sup>2</sup> ) (If Equipped) | Invalid | Invalid | Invalid | Invalid | Invalid |
| Yaw Rate (degrees per second) (If Equipped)               | Invalid | Invalid | Invalid | Invalid | Invalid |
| Steering Wheel Angle (degrees) (If Equipped)              | Invalid | Invalid | Invalid | Invalid | Invalid |
| Vehicle Dynamics Control Active (If Equipped)             | Invalid | Invalid | Invalid | Invalid | Invalid |

## System Status At Non-Deployment

|                                                                    |           |
|--------------------------------------------------------------------|-----------|
| Ignition Cycles At Investigation                                   | 2784      |
| SIR Warning Lamp Status                                            | OFF       |
| SIR Warning Lamp ON/OFF Time (seconds)                             | 655200    |
| Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously | 2783      |
| Ignition Cycles At Event                                           | 2784      |
| Ignition Cycles Since DTCs Were Last Cleared                       | 254       |
| Driver's Belt Switch Circuit Status                                | UNBUCKLED |
| Diagnostic Trouble Codes at Event, fault number: 1                 | N/A       |
| Diagnostic Trouble Codes at Event, fault number: 2                 | N/A       |
| Diagnostic Trouble Codes at Event, fault number: 3                 | N/A       |
| Diagnostic Trouble Codes at Event, fault number: 4                 | N/A       |
| Diagnostic Trouble Codes at Event, fault number: 5                 | N/A       |
| Diagnostic Trouble Codes at Event, fault number: 6                 | N/A       |
| Maximum SDM Recorded Velocity Change (MPH)                         | 59.84     |
| Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)    | 170       |
| Driver First Stage Deployment Loop Commanded                       | No        |
| Driver Second Stage Deployment Loop Commanded                      | No        |
| Driver Side Deployment Loop Commanded                              | No        |
| Driver Pretensioner Deployment Loop Commanded                      | No        |
| Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded         | No        |
| Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded         | No        |
| Driver Knee Deployment Loop Commanded                              | No        |
| Passenger First Stage Deployment Loop Commanded                    | No        |
| Passenger Second Stage Deployment Loop Commanded                   | No        |
| Passenger Side Deployment Loop Commanded                           | No        |
| Passenger Pretensioner Deployment Loop Commanded                   | No        |
| Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded      | No        |
| Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded      | No        |
| Passenger Knee Deployment Loop Commanded                           | No        |
| Second Row Left Side Deployment Loop Commanded                     | No        |
| Second Row Left Pretensioner Deployment Loop Commanded             | No        |
| Third Row Left Roof Rail/Head Curtain Loop Commanded               | No        |
| Second Row Right Side Deployment Loop Commanded                    | No        |
| Second Row Right Pretensioner Deployment Loop Commanded            | No        |
| Third Row Right Roof Rail/Head Curtain Loop Commanded              | No        |
| Second Row Center Pretensioner Deployment Loop Commanded           | No        |
| Multiple Event Counter                                             | 0         |
| An Event(s) Preceded the Recorded Event(s)                         | No        |
| An Event(s) was In Between the Recorded Event(s)                   | No        |
| An Event(s) Followed the Recorded Event(s)                         | No        |
| The Event(s) Not Recorded was a Deployment Event(s)                | No        |
| The Event(s) Not Recorded was a Non-Deployment Event(s)            | No        |
| Crash Record Locked                                                | No        |
| Vehicle Event Data (Pre-Crash) Associated With This Event          | Yes       |
| Deployment Event Recorded in the Non-Deployment Record             | No        |
| Event Recording Complete                                           | Yes       |
| Estimated Principal Direction of Force (PDOF) degrees              | 5         |



|                                     |        |        |        |        |        |        |        |        |        |        |        |        |        |        |        |
|-------------------------------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Time (milliseconds)                 | 10     | 20     | 30     | 40     | 50     | 60     | 70     | 80     | 90     | 100    | 110    | 120    | 130    | 140    | 150    |
| Longitudinal Axis Recorded Velocity | 0.00   | 0.00   | -0.68  | -4.07  | -10.17 | -18.98 | -27.11 | -34.57 | -44.74 | -51.52 | -53.55 | -54.90 | -56.28 | -57.82 | -58.29 |
| Time (milliseconds)                 | 160    | 170    | 180    | 190    | 200    | 210    | 220    | 230    | 240    | 250    | 260    | 270    | 280    | 290    | 300    |
| Longitudinal Axis Recorded Velocity | -58.97 | -58.65 | -58.97 | -58.97 | -58.97 | -58.97 | -58.97 | -58.97 | -58.97 | -58.29 | 0.00   | 0.00   | 0.00   | 0.00   | 0.00   |



|                                             |       |       |       |       |       |       |       |       |       |       |       |       |       |       |       |
|---------------------------------------------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Time (milliseconds)                         | 10    | 20    | 30    | 40    | 50    | 60    | 70    | 80    | 90    | 100   | 110   | 120   | 130   | 140   | 150   |
| Lateral Axis Recorded Velocity Change (MPH) | 0.00  | 0.00  | 0.00  | 0.00  | -2.03 | -3.39 | -4.10 | -4.10 | -4.74 | -4.74 | -4.74 | -4.74 | -4.74 | -4.74 | -4.74 |
| Time (milliseconds)                         | 160   | 170   | 180   | 190   | 200   | 210   | 220   | 230   | 240   | 250   | 260   | 270   | 280   | 290   | 300   |
| Lateral Axis Recorded Velocity Change (MPH) | -4.74 | -4.07 | -4.07 | -4.74 | -4.07 | -4.07 | -4.74 | -4.74 | -4.07 | -4.74 | 0.00  | 0.00  | 0.00  | 0.00  | 0.00  |

## Hexadecimal Data

This page displays all the data retrieved from the air bag module.  
It contains data that is not converted by this program.

```

$01 08 00 00 00 00 00 00
$02 30 00 00 00 00 00 00
$03 00 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 03 0A 00 00
$07 00 20 00 00 00 00 00
$08 00 00 00 00 00 00 00
$09 00 00 00 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 0F 0F 03 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 00 00 00 00 00 00 00
$11 00 00 00 00 00 00 00
$12 00 00 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 00 00 00 00 00 00 00
$18 00 00 00 00 00 00 00
$19 00 00 00 00 00 00 00
$1B 3F 30 00 66 00 79 00
$1C 3F 00 00 02 00 18 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 20 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 BE 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 0A D2 00 00
$2F 00 FE 0A E0 00 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 27 2B 25 80 00
$32 00 00 00 00 00 00 00
$33 00 00 65 67 65 80 00
$34 00 00 27 27 27 00 00
$35 00 00 72 72 72 00 00
$36 00 00 00 00 00 80 00
$37 00 00 00 04 04 00 E2
$38 57 00 C0 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4B 35 32 46 00
$3E 35 56 54 54 00 00 00
$3F 00 00 40 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF E0 0A DF 00 00


```



```

$45 07 01 07 01 05 01
$46 FF 1A 1A 64 64
$47 0A 64 02 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 39 34 33 32 32 33 31 4B 43 37 20 20 20 20
$B7 50 AA 01 0F 01
$B8 54 41 68 04 02
$C1 30 46 30 31
$CA 30 46 30 31
$CB 00 E8 B0 18
$CC 00 E8 B0 18
$D1 00 00
$DB 00 00
$DC 00 00


```



Wisconsin State Patrol - Northwest Region

Scale Diagram

Measured By: Trooper Young  
 Trooper Traynor  
 Drawn By: Trooper Young  
 Date of Crash: October 24, 2008  
 Time of Crash: 7:55 PM  
 WSP Incident #: 06-49110  
 Location: 1237 CTH N  
 Municipality: Town of Kinnickinnic  
 County: St. Croix



SCALE

## WISCONSIN STATE PATROL DATA COLLECTION REPORT

Prj/Incident: (b) (6) Time: 22.5528  
 TS Operator: KAY Temp: 40.0  
 Survey Date: 2006.1024 Pressure: 29.00

OS: 1 IH: 5.600  
 N: 0.000 Pcode:CP1  
 E: 0.000 PD: CP1  
 ELE: 0.000

BS: 2 SH: 0.600 HA: 0.000  
 N: 51.940 Pcode:CP2 VT: 93.064  
 E: 0.000 PD: CP2 DS: 52.020  
 ELE: 2.175

|        |            |             |             |     |
|--------|------------|-------------|-------------|-----|
| PN:100 | SH:0.600   | Pcode:CP2   | PD: CP2     |     |
|        | HA:0.000   | VA: 93.064  | SD: 52.020  |     |
|        | N: 51.940  | E: 0.000    | ELE:2.175   | CM: |
| PN:101 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:78.186  | VA: 94.434  | SD: 204.370 |     |
|        | N: 41.250  | E: 199.450  | ELE:-11.845 | CM: |
| PN:102 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:75.465  | VA: 95.095  | SD: 155.380 |     |
|        | N: 38.010  | E: 150.010  | ELE:-8.985  | CM: |
| PN:103 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:70.080  | VA: 96.124  | SD: 98.480  |     |
|        | N: 33.270  | E: 92.080   | ELE:-5.655  | CM: |
| PN:104 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:50.114  | VA: 98.553  | SD: 45.450  |     |
|        | N: 28.740  | E: 34.490   | ELE:-2.050  | CM: |
| PN:105 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:305.352 | VA: 93.192  | SD: 40.940  |     |
|        | N: 23.790  | E: -33.240  | ELE:2.625   | CM: |
| PN:106 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:281.283 | VA: 89.096  | SD: 96.130  |     |
|        | N: 19.120  | E: -94.200  | ELE:6.400   | CM: |
| PN:107 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:275.183 | VA: 88.094  | SD: 155.640 |     |
|        | N: 14.390  | E: -154.900 | ELE:10.000  | CM: |
| PN:108 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:272.234 | VA: 87.431  | SD: 221.130 |     |
|        | N: 9.230   | E: -220.760 | ELE:13.800  | CM: |
| PN:109 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:270.352 | VA: 87.315  | SD: 304.140 |     |
|        | N: 3.120   | E: -303.840 | ELE:18.105  | CM: |
| PN:110 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:269.211 | VA: 87.252  | SD: 404.970 |     |
|        | N: -4.580  | E: -404.530 | ELE:23.220  | CM: |
| PN:111 | SH:0.600   | Pcode:EA2   | PD: EA2     |     |
|        | HA:268.441 | VA: 87.263  | SD: 490.480 |     |
|        | N: -10.810 | E: -489.870 | ELE:26.900  | CM: |
| PN:112 | SH:0.600   | Pcode:EA1   | PD: EA1     |     |
|        | HA:265.512 | VA: 87.264  | SD: 485.880 |     |

|        |                                                    |                                                       |                                                    |     |
|--------|----------------------------------------------------|-------------------------------------------------------|----------------------------------------------------|-----|
| PN:113 | N: -35.070<br>SH:0.600<br>HA:265.525<br>N: -29.860 | E: -484.120<br>Pcode:EA1<br>VA: 87.256<br>E: -414.570 | ELE:26.660<br>PD: EA1<br>SD: 416.060<br>ELE:23.645 | CM: |
| PN:114 | SH:0.600<br>HA:265.571<br>N: -23.560               | Pcode:EA1<br>VA: 87.291<br>E: -333.020                | PD: EA1<br>SD: 334.180<br>ELE:19.655               | CM: |
| PN:115 | SH:0.600<br>HA:266.055<br>N: -15.990               | Pcode:EA1<br>VA: 87.404<br>E: -234.440                | PD: EA1<br>SD: 235.180<br>ELE:14.535               | CM: |
| PN:116 | SH:0.600<br>HA:266.200<br>N: -9.770                | Pcode:EA1<br>VA: 88.092<br>E: -152.500                | PD: EA1<br>SD: 152.890<br>ELE:9.920                | CM: |
| PN:117 | SH:0.600<br>HA:266.404<br>N: -4.080                | Pcode:EA1<br>VA: 90.012<br>E: -70.180                 | PD: EA1<br>SD: 70.300<br>ELE:4.975                 | CM: |
| PN:118 | SH:0.600<br>HA:82.134<br>N: 3.440                  | Pcode:EA1<br>VA: 104.103<br>E: 25.230                 | PD: EA1<br>SD: 26.260<br>ELE:-1.430                | CM: |
| PN:119 | SH:0.600<br>HA:85.105<br>N: 16.930                 | Pcode:EA1<br>VA: 94.473<br>E: 200.760                 | PD: EA1<br>SD: 202.170<br>ELE:-11.885              | CM: |
| PN:120 | SH:0.600<br>HA:81.432<br>N: 29.360                 | Pcode:PAVM1<br>VA: 94.405<br>E: 201.810               | PD: PAVM1<br>SD: 204.620<br>ELE:-11.695            | CM: |
| PN:121 | SH:0.600<br>HA:80.450<br>N: 26.340                 | Pcode:PAVM1<br>VA: 94.595<br>E: 161.720               | PD: PAVM1<br>SD: 164.480<br>ELE:-9.330             | CM: |
| PN:122 | SH:0.600<br>HA:77.054<br>N: 20.960                 | Pcode:PAVM1<br>VA: 96.165<br>E: 91.450                | PD: PAVM1<br>SD: 94.380<br>ELE:-5.325              | CM: |
| PN:123 | SH:0.600<br>HA:52.046<br>N: 15.490                 | Pcode:PAVM1<br>VA: 102.526<br>E: 19.890               | PD: PAVM1<br>SD: 25.860<br>ELE:-0.765              | CM: |
| PN:124 | SH:0.600<br>HA:279.571<br>N: 9.790                 | Pcode:PAVM1<br>VA: 90.373<br>E: -55.800               | PD: PAVM1<br>SD: 56.650<br>ELE:4.385               | CM: |
| PN:125 | SH:0.600<br>HA:271.572<br>N: 4.340                 | Pcode:PAVM1<br>VA: 88.214<br>E: -126.890              | PD: PAVM1<br>SD: 127.010<br>ELE:8.635              | CM: |
| PN:126 | SH:0.600<br>HA:269.251<br>N: -2.150                | Pcode:PAVM1<br>VA: 87.403<br>E: -212.300              | PD: PAVM1<br>SD: 212.490<br>ELE:13.625             | CM: |
| PN:127 | SH:0.600<br>HA:268.096<br>N: -10.100               | Pcode:PAVM1<br>VA: 87.273<br>E: -315.470              | PD: PAVM1<br>SD: 315.950<br>ELE:19.005             | CM: |
| PN:128 | SH:0.600<br>HA:267.380<br>N: -16.560               | Pcode:PAVM1<br>VA: 87.232<br>E: -400.700              | PD: PAVM1<br>SD: 401.460<br>ELE:23.290             | CM: |
| PN:129 | SH:0.600<br>HA:267.211<br>N: -21.490               | Pcode:PAVM1<br>VA: 87.231<br>E: -464.790              | PD: PAVM1<br>SD: 465.770<br>ELE:26.235             | CM: |
| PN:130 | SH:0.600<br>HA:265.152<br>N: -38.560               | Pcode:ECA1<br>VA: 87.276<br>E: -464.630               | PD: ECA1<br>SD: 466.680<br>ELE:25.635              | CM: |
| PN:131 | SH:0.600<br>HA:265.113                             | Pcode:ECA1<br>VA: 87.283                              | PD: ECA1<br>SD: 400.910                            |     |

|        |                                                 |                                                      |                                                      |         |
|--------|-------------------------------------------------|------------------------------------------------------|------------------------------------------------------|---------|
| PN:151 | N: -2.930<br>SH:5.800<br>HA:92.382<br>N: -5.620 | E: 121.160<br>Pcode:VEH1<br>VA: 94.464<br>E: 121.880 | ELE:-9.815<br>PD: VEH1<br>SD: 122.430<br>ELE:-10.395 | CM:     |
| PN:152 | SH:5.800<br>HA:96.471<br>N: -14.330             | Pcode:VEH1<br>VA: 95.242<br>E: 120.460               | PD: VEH1<br>SD: 121.850<br>ELE:-11.675               | CM:     |
| PN:153 | SH:5.800<br>HA:97.170<br>N: -15.280             | Pcode:VEH1<br>VA: 95.362<br>E: 119.540               | PD: VEH1<br>SD: 121.090<br>ELE:-12.025               | CM:AXLE |
| PN:154 | SH:5.800<br>HA:97.293<br>N: -15.460             | Pcode:VEH1<br>VA: 95.412<br>E: 117.600               | PD: VEH1<br>SD: 119.200<br>ELE:-12.015               | CM:     |
| PN:155 | SH:5.800<br>HA:96.521<br>N: -14.030             | Pcode:VEH1<br>VA: 95.345<br>E: 116.460               | PD: VEH1<br>SD: 117.860<br>ELE:-11.665               | CM:     |
| PN:156 | SH:5.800<br>HA:96.251<br>N: -13.000             | Pcode:VEH1<br>VA: 95.364<br>E: 115.530               | PD: VEH1<br>SD: 116.820<br>ELE:-11.620               | CM:     |
| PN:157 | SH:5.800<br>HA:95.321<br>N: -11.190             | Pcode:VEH1<br>VA: 95.243<br>E: 115.460               | PD: VEH1<br>SD: 116.520<br>ELE:-11.180               | CM:AXLE |
| PN:158 | SH:5.800<br>HA:92.343<br>N: -5.220              | Pcode:VEH1<br>VA: 94.463<br>E: 116.010               | PD: VEH1<br>SD: 116.530<br>ELE:-9.900                | CM:     |
| PN:159 | SH:5.800<br>HA:266.000<br>N: -18.870            | Pcode:XYZ2<br>VA: 86.301<br>E: -269.900              | PD: XYZ2<br>SD: 271.070<br>ELE:16.340                | CM:     |
| PN:160 | SH:5.800<br>HA:264.182<br>N: -18.520            | Pcode:TM1<br>VA: 86.281<br>E: -185.680               | PD: TM1<br>SD: 186.960<br>ELE:11.310                 | CM:     |
| PN:161 | SH:5.800<br>HA:264.075<br>N: -17.380            | Pcode:TM1<br>VA: 86.300<br>E: -169.050               | PD: TM1<br>SD: 170.260<br>ELE:10.190                 | CM:     |
| PN:162 | SH:5.800<br>HA:263.531<br>N: -16.270            | Pcode:TM1<br>VA: 86.302<br>E: -151.880               | PD: TM1<br>SD: 153.030<br>ELE:9.130                  | CM:     |
| PN:163 | SH:5.800<br>HA:262.565<br>N: -15.690            | Pcode:TM1<br>VA: 86.375<br>E: -126.830               | PD: TM1<br>SD: 128.010<br>ELE:7.325                  | CM:     |
| PN:164 | SH:5.800<br>HA:260.491<br>N: -15.130            | Pcode:TM1<br>VA: 86.576<br>E: -93.640                | PD: TM1<br>SD: 94.990<br>ELE:4.830                   | CM:     |
| PN:165 | SH:5.800<br>HA:258.521<br>N: -15.270            | Pcode:TM1<br>VA: 87.001<br>E: -77.600                | PD: TM1<br>SD: 79.190<br>ELE:3.940                   | CM:     |
| PN:166 | SH:5.800<br>HA:258.342<br>N: -15.010            | Pcode:TM1<br>VA: 86.333<br>E: -74.250                | PD: TM1<br>SD: 75.890<br>ELE:4.355                   | CM:     |
| PN:167 | SH:5.800<br>HA:229.505<br>N: -12.330            | Pcode:TM2<br>VA: 92.361<br>E: -14.620                | PD: TM2<br>SD: 19.150<br>ELE:-1.070                  | CM:     |
| PN:168 | SH:5.800<br>HA:122.282<br>N: -12.700            | Pcode:TM2<br>VA: 99.254<br>E: 19.950                 | PD: TM2<br>SD: 23.980<br>ELE:-4.130                  | CM:     |
| PN:169 | SH:5.800<br>HA:107.046                          | Pcode:TM2<br>VA: 97.304                              | PD: TM2<br>SD: 52.640                                |         |



|        |            |             |              |     |
|--------|------------|-------------|--------------|-----|
|        | N: -15.330 | E: 49.890   | ELE:-7.080   | CM: |
| PN:170 | SH:5.800   | Pcode:TM2   | PD: TM2      |     |
|        | HA:104.533 | VA: 97.144  | SD: 67.930   |     |
|        | N: -17.320 | E: 65.130   | ELE:-8.765   | CM: |
| PN:171 | SH:5.800   | Pcode:TM3   | PD: TM3      |     |
|        | HA:172.540 | VA: 101.024 | SD: 16.330   |     |
|        | N: -15.900 | E: 1.980    | ELE:-3.330   | CM: |
| PN:172 | SH:5.800   | Pcode:TM3   | PD: TM3      |     |
|        | HA:125.215 | VA: 100.104 | SD: 31.620   |     |
|        | N: -18.010 | E: 25.380   | ELE:-5.785   | CM: |
| PN:173 | SH:5.800   | Pcode:TM3   | PD: TM3      |     |
|        | HA:112.383 | VA: 98.380  | SD: 49.740   |     |
|        | N: -18.930 | E: 45.390   | ELE:-7.670   | CM: |
| PN:174 | SH:5.800   | Pcode:TM3   | PD: TM3      |     |
|        | HA:109.162 | VA: 97.395  | SD: 64.600   |     |
|        | N: -21.130 | E: 60.430   | ELE:-8.815   | CM: |
| PN:175 | SH:5.800   | Pcode:XYZ1  | PD: XYZ1     |     |
|        | HA:106.446 | VA: 97.340  | SD: 71.100   |     |
|        | N: -20.310 | E: 67.490   | ELE:-9.565   | CM: |
| PN:176 | SH:5.800   | Pcode:DTRE1 | PD: DTRE1    |     |
|        | HA:102.305 | VA: 95.455  | SD: 118.110  |     |
|        | N: -25.460 | E: 114.720  | ELE:-12.065  | CM: |
| PN:177 | SH:0.600   | Pcode:CP2   | PD: BACKSITE |     |
|        | HA:0.000   | VA: 93.061  | SD: 52.010   |     |
|        | N: 51.930  | E: 0.000    | ELE:2.185    | CM: |

## WISCONSIN STATE PATROL DATA COLLECTION REPORT

Prj/Incident: (b) (6) Time: 11.3607  
 TS Operator: WDT Temp: 48.0  
 Survey Date: 2006.1106 Pressure: 29.00

OS: 1 IH: 4.950  
 N: 0.000 Pcode:CP1  
 E: 0.000 PD: OS  
 ELE: 0.000

BS: 2 SH: 5.600 HA: 0.004  
 N: 86.060 Pcode:CP2 VT: 88.405  
 E: 0.020 PD: BS DS: 86.080  
 ELE: 1.330

|        |            |            |             |        |
|--------|------------|------------|-------------|--------|
| PN:201 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:348.426 | VA: 84.222 | SD: 19.420  |        |
|        | N: 18.960  | E: -3.780  | ELE:1.255   | CM:RFT |
| PN:202 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:349.184 | VA: 84.401 | SD: 19.860  |        |
|        | N: 19.430  | E: -3.670  | ELE:1.195   | CM:    |
| PN:203 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:348.526 | VA: 87.546 | SD: 22.310  |        |
|        | N: 21.880  | E: -4.300  | ELE:0.160   | CM:    |
| PN:204 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:348.493 | VA: 88.082 | SD: 25.980  |        |
|        | N: 25.480  | E: -5.030  | ELE:0.195   | CM:RRT |
| PN:205 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:349.212 | VA: 88.076 | SD: 27.370  |        |
|        | N: 26.890  | E: -5.050  | ELE:0.240   | CM:    |
| PN:206 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:349.335 | VA: 88.081 | SD: 28.120  |        |
|        | N: 27.640  | E: -5.090  | ELE:0.265   | CM:    |
| PN:207 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:349.554 | VA: 88.081 | SD: 28.550  |        |
|        | N: 28.100  | E: -4.990  | ELE:0.280   | CM:    |
| PN:208 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:350.291 | VA: 88.085 | SD: 28.820  |        |
|        | N: 28.410  | E: -4.760  | ELE:0.280   | CM:    |
| PN:209 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:351.371 | VA: 88.071 | SD: 29.050  |        |
|        | N: 28.720  | E: -4.230  | ELE:0.305   | CM:    |
| PN:210 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:353.136 | VA: 88.042 | SD: 29.240  |        |
|        | N: 29.020  | E: -3.440  | ELE:0.335   | CM:    |
| PN:211 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:354.294 | VA: 88.025 | SD: 29.300  |        |
|        | N: 29.150  | E: -2.810  | ELE:0.350   | CM:    |
| PN:212 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:355.461 | VA: 88.032 | SD: 29.350  |        |
|        | N: 29.250  | E: -2.160  | ELE:0.345   | CM:    |
| PN:213 | SH:5.600   | Pcode:VEH2 | PD: PROFILE |        |
|        | HA:357.273 | VA: 88.031 | SD: 29.310  |        |

|        |            |             |             |        |
|--------|------------|-------------|-------------|--------|
|        | N: 29.270  | E: -1.300   | ELE:0.345   | CM:    |
| PN:214 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:358.194 | VA: 88.085  | SD: 29.220  |        |
|        | N: 29.190  | E: -0.850   | ELE:0.295   | CM:    |
| PN:215 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:359.000 | VA: 88.084  | SD: 29.050  |        |
|        | N: 29.030  | E: -0.510   | ELE:0.290   | CM:    |
| PN:216 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:359.424 | VA: 88.093  | SD: 28.570  |        |
|        | N: 28.560  | E: -0.140   | ELE:0.270   | CM:    |
| PN:217 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:0.182   | VA: 88.115  | SD: 27.780  |        |
|        | N: 27.770  | E: 0.150    | ELE:0.225   | CM:    |
| PN:218 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:1.165   | VA: 88.102  | SD: 26.540  |        |
|        | N: 26.520  | E: 0.590    | ELE:0.195   | CM:LRT |
| PN:219 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:3.211   | VA: 87.582  | SD: 22.970  |        |
|        | N: 22.920  | E: 1.340    | ELE:0.160   | CM:    |
| PN:220 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:6.055   | VA: 87.502  | SD: 19.200  |        |
|        | N: 19.080  | E: 2.040    | ELE:0.075   | CM:    |
| PN:221 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:5.323   | VA: 87.481  | SD: 17.850  |        |
|        | N: 17.750  | E: 1.720    | ELE:0.035   | CM:    |
| PN:222 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:5.334   | VA: 87.481  | SD: 17.860  |        |
|        | N: 17.760  | E: 1.730    | ELE:0.035   | CM:LFT |
| PN:223 | SH:5.600   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:3.183   | VA: 87.283  | SD: 16.390  |        |
|        | N: 16.340  | E: 0.940    | ELE:0.070   | CM:    |
| PN:224 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:1.585   | VA: 99.413  | SD: 16.360  |        |
|        | N: 16.120  | E: 0.560    | ELE:2.195   | CM:    |
| PN:225 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:358.115 | VA: 102.441 | SD: 16.330  |        |
|        | N: 15.920  | E: -0.500   | ELE:1.350   | CM:    |
| PN:226 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:357.030 | VA: 102.254 | SD: 16.180  |        |
|        | N: 15.780  | E: -0.810   | ELE:1.465   | CM:    |
| PN:227 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:355.492 | VA: 102.481 | SD: 16.490  |        |
|        | N: 16.040  | E: -1.170   | ELE:1.295   | CM:    |
| PN:228 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:355.073 | VA: 99.532  | SD: 17.860  |        |
|        | N: 17.530  | E: -1.500   | ELE:1.880   | CM:    |
| PN:229 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:354.355 | VA: 99.532  | SD: 18.480  |        |
|        | N: 18.130  | E: -1.710   | ELE:1.775   | CM:    |
| PN:230 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:354.005 | VA: 99.180  | SD: 18.360  |        |
|        | N: 18.020  | E: -1.890   | ELE:1.985   | CM:    |
| PN:231 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:352.561 | VA: 99.243  | SD: 18.330  |        |
|        | N: 17.950  | E: -2.220   | ELE:1.955   | CM:    |
| PN:232 | SH:0.000   | Pcode:VEH2  | PD: PROFILE |        |
|        | HA:352.156 | VA: 99.435  | SD: 18.010  |        |

|        |                                     |                                       |                                        |     |
|--------|-------------------------------------|---------------------------------------|----------------------------------------|-----|
| PN:233 | N: 17.590<br>SH:0.000<br>HA:351.042 | E: -2.390<br>Pcode:VEH2<br>VA: 99.425 | ELE:1.905<br>PD: PROFILE<br>SD: 17.910 | CM: |
| PN:234 | N: 17.440<br>SH:0.000<br>HA:350.021 | E: -2.740<br>Pcode:VEH2<br>VA: 98.125 | ELE:1.925<br>PD: PROFILE<br>SD: 18.480 | CM: |
| PN:235 | N: 18.020<br>SH:0.000<br>HA:349.154 | E: -3.170<br>Pcode:VEH2<br>VA: 98.172 | ELE:2.310<br>PD: PROFILE<br>SD: 18.520 | CM: |
| PN:236 | N: 18.010<br>SH:0.000<br>HA:348.285 | E: -3.420<br>Pcode:VEH2<br>VA: 98.040 | ELE:2.280<br>PD: PROFILE<br>SD: 18.470 | CM: |
| PN:237 | N: 17.920<br>SH:0.000<br>HA:348.254 | E: -3.650<br>Pcode:VEH2<br>VA: 98.040 | ELE:2.355<br>PD: PROFILE<br>SD: 18.470 | CM: |
| PN:238 | N: 17.910<br>SH:0.000<br>HA:347.055 | E: -3.670<br>Pcode:VEH2<br>VA: 98.325 | ELE:2.360<br>PD: PROFILE<br>SD: 18.030 | CM: |
| PN:239 | N: 17.380<br>SH:0.000<br>HA:346.211 | E: -3.980<br>Pcode:VEH2<br>VA: 98.175 | ELE:2.270<br>PD: PROFILE<br>SD: 18.060 | CM: |
| PN:240 | N: 17.360<br>SH:5.600<br>HA:345.185 | E: -4.220<br>Pcode:VEH2<br>VA: 87.384 | ELE:2.345<br>PD: PROFILE<br>SD: 18.910 | CM: |
| PN:241 | N: 18.270<br>SH:5.600<br>HA:348.441 | E: -4.790<br>Pcode:VEH2<br>VA: 83.595 | ELE:0.125<br>PD: PROFILE<br>SD: 19.410 | CM: |
|        | N: 18.930                           | E: -3.770                             | ELE:1.380                              | CM: |











TA000093379

































