


EWR D&I ANNOTATION

FAN-000001L091001DP160-1567

Artemis # : 000001L091001DP160**Record Created Date :** 04/15/2010**Printed Date :** 04/16/2010**Description :**

DI09-066 SEQUENCE ID 160 GM INJURY GM WAS CONTACTED BY A CUSTOMER THAT STATES THAT THEY EXITED FROM AN INTERSTATE AT 45 MPH AND AS THEY BRAKED FOR A STOP LIGHT, THE VEHICLE BEGAN TO VIBRATE. AS A RESULT, SHE DID NOT STOP BEFORE REAR ENDING A SEDAN. THE DRIVER OF THE HHR RECEIVED MINOR INJURIES. THE OWNER WAS GM TO INVESTIGATE THE INCIDENT. THE HHR WAS TAKEN TO A LOCAL DEALER WHERE THE FRONT ROTORS WERE RESURFACED PER A TSB. THIS REPAIR HAD BEEN DONE PREVIOUSLY TO THIS VEHICLE ALSO. ACCORDING TO THE LOG, THE CUSTOMER HAS NOT HAD ANY PROBLEM SINCE. THERE ARE TSBS ON THE ISSUE AND MANY VOQS, BUT SINCE THE ISSUE GETS WORSE OVER TIME AND DOESN'T COME ON SUDDENLY (IT GIVES PLENTY OF WARNING) THE AGENCY BELIEVES THAT IT DOES NOT POSE A SAFETY RISK. *JN

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 4, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-066

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 2, 17, 20, 75, 76, 79, 87, 98, 103, 122, 124, 126, 133, 139, 147, 150, 157, 159, 160, 164, 179, 186, 196, 203, 204, 205, 209, 216, 254, 257, 266, 268, 282, 283, 296, 325, 331, 339, 354, 355, 357, 358, 374, 380, 396, 407, 432, 435, 436, 439, 440, 456, 457, 462, 469, 471, 504, 507, 511	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 2, 2009**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Josh Neff at (202) 366-0698 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS COMPANY
Global Interior and Safety Center

14 October 2009

OCT 15 2009

OCT 15 2009

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-066

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 4th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2009.

GM's response is comprised of 65 disks for the incidents that are the subject of DI09-066. Sequence ID number 457, is a NISM (Not In Suit Matters) that originated in China and will be submitted as soon as the documents are located.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 274020230 - 671278 and 2008 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 274020230 - 671278_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-066
2 274020230-671278
2008 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 2 274020230 - 671278_01_001 - is the first document responsive to Inquiry no. 1.
 2 274020230 - 671278_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(1 Vehicle from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	UNKNOWN	NISM
17	3G5DA03E25S [REDACTED]	NISM
20	3G5DA03L97S [REDACTED]	NISM
75	KL1TG52655B [REDACTED]	NISM
76	KL1TD52685B [REDACTED]	NISM
79	KL1TD56677B [REDACTED]	NISM
87	KL1TD56EX9B [REDACTED]	NISM
98	1G1AZ55F267 [REDACTED]	PAR
103	1G1AK55F067 [REDACTED]	NISM
122	1G1AL58F887 [REDACTED]	NISM
124	1G1AL58F887 [REDACTED]	NISM
126	1G1AM18BX87 [REDACTED]	NISM
133	1G1AT58H497 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
139	1GCDS49E288	NISM
147	2CNDL73F866	NISM
150	2CNDL63F166	PAR
157	1GBJG316481	RUMOR
159	3GNDA23D96S	NISM
160	3GNDA23DX7S	NISM
164	3GNDA13D18S	NISM
179	2G1WF52E359	NISM
186	2G1WT58K879	NISM
196	2G1WB57K291	NISM
203	1G1ZU57NX7F	NISM
204	1G1ZU57N77F	NISM
205	1G1ZT58F57F	NISM
209	1G1ZG57BX8F	NISM
216	2G1WM15K069	NISM
254	2GCEK133971	NISM
257	2GCEK19J071	PAR
266	2GCEK19JX81	NISM
268	2GCEK13C181	NISM
282	1GCHK29D87E	NISM
283	1GCHK53679F	LIT
296	1GNFK16358R	NISM
325	1GNDT13S552	NISM
331	1GNDT13S772	NISM
339	1GNDT13S882	PAR
354	1GKEV33798J	NISM
355	1GKER23738J	NISM
357	1GKEV33748J	NISM
358	1GKEV33748J	NISM
374	1GKDT13S862	NISM
380	1GKDT13S772	NISM
396	3GTEC13047G	NISM
407	1GTHK23668F	NISM
432	1G2ZH57N284	NISM
435	1G2ZF57B084	NISM
436	1G2ZH57NX84	NISM
439	1G2ZH57N394	NISM
440	1G2ZH57N094	NISM
456	2G2WP552281	NISM
457	UNKNOWN	NISM
462	1G2MB33B76Y	NISM
469	YS3FD79Y856	NISM
471	YS3FD79Y376	NISM
504	5GZCZ53466S	NISM
507	5GZCZ33D36S	PAR
511	3GSDL73768S	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in dark ink, appearing to read 'G. Kent', with a long, sweeping horizontal flourish extending to the right.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 65 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run Jpegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5, F6, F7, and F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

982.2(b)(1)

FOR COUNTY USE ONLY

ATTESTED BY PARTY OR PARTY'S ATTORNEY, and by the court, and without
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE (909) 469-5127 FAX (909) 469-5126
 ATTORNEY FOR PLAINTIFF'S

NOTICE: THIS CASE IS A COMPLEX CASE UNDER RULE 1800 OF THE CALIFORNIA RULES OF COURT, AND THE SUPERIOR COURT FOR THE STATE OF CALIFORNIA

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET

Complex Case Designation
☐ Counter ☐ Joinder
☐ Limited ☒ Unlimited
 Filed with first appearance by defendant (Cal. Rules of Court, rule 1811)

SLIDE NUMBER: _____
 ASSIGNED JUDGE: _____

Please complete all five (5) items below

1. Check one box below for the case type that best describes this case

☒ Auto Tort
☐ Auto (22)
☐ Other PFDWD (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Asbestos (24)
☐ Product Liability (24)
☐ Medical Malpractice (45)
☐ Other PFDWD (23)
☐ Non-PFDWD (Other) Tort
☐ Business/contract/business practice (37)
☐ Other torts (e.g., discrimination, false arrest) (50)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PFDWD tort (26)
☐ Employment
☐ Wrongful termination (36)

☐ Other employment (15)
☐ Contract
☐ Breach of contract/warranty (26)
☐ Collection (e.g., money owed, open book accounts) (39)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/reverse condemnation (14)
☐ Wrongful eviction (32)
☐ Other real property (e.g., quiet title) (28)
☐ Unlawful Detainer
☐ Commercial (21)
☐ Residential (32)
☐ Drugs (34)
☐ Judicial Review
☐ Asset forfeiture (56)
☐ Petition for writ of habeas corpus (11)

☐ Will of intestate (22)
☐ Other judicial review (31)
☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1808 - 1812)
☐ Arbitration/Trade regulation (33)
☐ Construction defect (10)
☐ Claims limitation statute (40)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.

a. ☒ Large number of separately represented parties. d. ☒ Large number of issues that will be time-consuming to resolve. e. ☐ Substantial post-trial issues.

3. ☒ Substantial amount of documentary evidence. f. ☐ Substantial post-trial issues.

4. Type of remedies sought (check all that apply):
 a. ☒ monetary b. ☐ nonmonetary: declaratory or injunctive relief c. ☐ other

5. Number of causes of action (specify): FIVE

6. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/B# 147836
 (this is next name)

NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Codes) (Cal. Rules of Court, rule 1800).
 • File this cover sheet in addition to any cover sheet required by local court rule.
 • If this case is complex under rule 1800 et seq. of the California Rules of Court, you must enter parties to the action or proceeding.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

From Plaintiff's Handbook
 982.2(b)(1) (Rev. January 1, 2003)

CIVIL CASE COVER SHEET

EXIF Image Information...
 Preferences...
 Ctrl+R

Step 7: Next File
(Image)

Step 7: Next page

Step 8: Scale
Image

Step 7: Image Properties

DI09-066
160 272742397 – 668207
2007 CHEVROLET HHR

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. 71-704613121	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Brakes - General	Sub-Area	Initiate PAR- Collision
Address	City Deland	Involved Dir	Starting Chevrolet-Cadillac, Utc	Safety	Yes
State FL ZipCd	Con Acct	Source	Phone	Updated	3/9/2009 05:22:02 PM
Serial #/VIN 3GND0A23DX7S	Model Year 2007	Priority	Esc to T2 - License #	Owner	RODRIGOS
Make Chevrolet	Warr. Start 05/31/2007	Status	Open	Opened	2/23/2009 04:52:42 PM
Model HHR	Mileage 35004	Sub-Status	Satisfied	Closed	
Abstract (FL) Brakes Caused Accident					
Customer Description	*** BRC PAR CASE. DO NOT ASSUME. FORWARD ALL INQUIRIES TO JOSE RODRIGUEZ EXT 31103 ***				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries #	Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	2/17/2009 08:28:00 AM	N	1	1	Asphalt	Dry	N/A	10452159
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5' 6"		No				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Sonia	Murray	(386) 738-4805	State Farm					
Incident Loc	101 C exit on Interstate 4 in Sanford FL				Incident Desc	Cust sts that on 2-17-09. She was driving the veh at about 45mph. Sts that she was exiting off an intersection. Sts that there was a red light ahead of her. She pressed the brakes and then the veh started vibrating. Cust sts that the veh did not stop and she rear ended a Honda Accord.		
Component	Brakes Failed				Damage Desc	Damaged the front end of customer's veh and the rear end of the other veh		
Vehicle Loc	Home				Add'l Info			
Emgcy Svc Names	Cemanal County Sheriff dept				Maint Loc	Independent shop or Bill Haard		

PAR Detail

Collision	Y	Non Collision	Property Damage	Y	Thermal Evt	N	Spec Equip	n/a
Vehicle Speed	45	Weather Condition	dry and clear		Prop Owner	unknown	Property Type	Honda Accord
Last Service Date		Loc Last Service			Property Location	unknown	Prop Est Repair Cost	
Veh Est Repair Cost		Spec Equip Installer	n/a		Prop Damage Description	rear end damage, customers ins is fixing veh		
Primary Veh Use	Personal	Inspection Type			Inspected By	Inspection Not Performed	Inspection Date/Time	
Veh Damage Description	frontal damages				Explain Other	n/a		

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelt
Injury Description			Medical Rat#	Treatment Location		Treated By
Broken tooth, neck pain			n/a	n/a		n/a
Street Address			City	State	Zip Code	
			Deland	FL		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 05:12:58 PM	RODRUJOS	RODRUJOS	BRC PAR	ESIS - Injuries	Done	3/9/2009 05:13:14 PM	Esis case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Case was sent to ESIS.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 05:12:39 PM	RODRUJOS	RODRUJOS	Scheduled Follow-up		Scheduled Aftam		71-704613121 Check on ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 05:12:14 PM	RODRUJOS	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Assigned to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Injuries, property damages, insurance involved.

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 04:53:41 PM	RODRIGOS	RODRIGOS	Inbound Call Customer	Service Request Update	Done	3/9/2009 05:11:58 PM	Cust called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts that on 2-17-09, She was driving the veh at about 45mph. Sts that she was exiting off an intersection. Sts that there was a red light ahead of her. She pressed the brakes and then the veh started vibrating. Cust sts that the veh did not stop and she rear ended a Honda Accord. There was damages to both vehicle. Cust had neck injury and broke a tooth. The other drivers did not claim injuries.

Cust sts that her insurance co, is fixing the Honda Accord, they have not fixed her veh. The dlr checked her brakes on her veh.

Cust seeks to have GM Investigate what happened.

Crs advised that the case will go to ESIS. Advised that they will be in contact in the next 7-10 business days.

Cust understood.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 03:23:00 PM	RODRIGOS	RODRIGOS	Scheduled Follow-up		Done	3/9/2009 04:53:38 PM	71-704613121 final attempt
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cancelled owner called in.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/8/2009 03:21:08 PM	RODRIGOS	RODRIGOS	Outbound Call Third Party	Received No Answer	Done	3/8/2009 03:22:57 PM	called father
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs called. no one answered the phone. Machine was not set up for crs to leave a voicemail.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/8/2009 02:34:31 PM	RODRIGOS	RODRIGOS	Scheduled Follow-up		Done	3/8/2009 03:21:03 PM	71-704513121 call cust
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Closed called early.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/8/2009 02:33:15 PM	RODRIGOS	RODRIGOS	Outbound Call Customer	Received Busy Signal	Done	3/8/2009 02:34:26 PM	Called Driver of Veh
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs called customer. no one answered. machine did not take voicemail.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/8/2009 02:28:48 PM	RODRIGOS	RODRIGOS	Outbound Call Third Party	Received No Answer	Done	3/8/2009 02:31:23 PM	Called cust back
Contact Last Name	Contact First Name	Account	BAC Code				

Comments:

No one answered. Csa was unable to leave a voicemail, since the voicemail machine was not set up.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/6/2009 06:20:06 PM	RODRIGOS	RODRIGOS	Inbound Call Third Party	Voice Mail Received	Done	3/6/2009 06:24:42 PM	Customers father called in
Contact Last Name	Contact First Name	Account	BAC Code				

Comments:

Cust sts that he is calling on behalf on his daughter

Seeks call back at Cell #

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/5/2009 12:18:27 PM	RODRIGOS	RODRIGOS	Ownership Changed	Ownership Escalated to BRC	Done	3/5/2009 12:18:27 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments:

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/5/2009 12:16:11 PM	RODRUJOS	RODRUJOS	Scheduled Follow-up		Done	3/5/2009 12:12:22 PM	71-704613121 do initial contact
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Closed made call early.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:57 PM	KINZERTH	RODRUJOS	Ownership Changed		Done	3/4/2009 02:29:57 PM	Service Request Ownership has changed FROM: BENTIVLE TO: RODRUJOS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:37 PM	KINZERTH	RODRUJOS	BRC PAR	Initial Contact- AVM	Done	3/5/2009 12:13:52 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DVM Steven Giammalvo 404082 6130

Crs advised that on 2-17-09, Cust was driving the vehicle. She ended up hitting another vehicle because the brakes failed.

Crs advised case is going to esla.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:27 PM	KINZERTH	RODRIGOS	BRC PAR	Initial Contact- Dealer	Done	3/5/2009 12:03:34 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

BAC # 242070
STARLING CHEVROLET-CADILLAC, LLC
2800 S HWY 17 S2
DELAND FL 32720-8682
388-734-2661

left voicemail
Svc Mgr Jeff Laberge

Crs advised that cust sts that she was in an accident on 2-17-09, due to Brakes not working properly.

Crs seeks information related to allegation. provided contact information.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:18 PM	KINZERTH	RODRIGOS	BRC PAR	Initial Contact- Phone	Done	3/5/2009 12:19:31 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts that she is at work at this time. she will call back on her brake.

Crs provided cust contact information.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:11 PM	KINZERTH	RODRJOS	BRC PAR	Acknowledgement	Done	3/5/2009 11:10:51 AM	Called
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							

no one answered. Machine did not take voicemails.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:29:04 PM	KINZERTH	RODRJOS	Notify CRM		Done	3/4/2009 03:14:01 PM	File Assigned
Contact Last Name	Contact First Name		Account			BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-type	Status	Completed	Description
3/4/2009 02:28:54 PM	KINZERTH	RODRJOS	Research		Done	3/5/2009 11:02:36 AM	Research VIN
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
3GNDA23DX7S							

3GNDA23DX7S

08016 HEAD IMPACT PROTECTION - INCREASED PROTECTION

08157 INSTRUMENT PANEL STORAGE BIN DOOR COMPLIANCE - ADD REINFORCEMENT BRACKET

No other related cases

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 02:28:34 PM	KINZERTH	RODRUOS	BRC PAR	Case Assigned	Done	3/5/2009 10:58:57 AM	Assigned to Jose Rodriguez x31103
Contact Last Name	Contact First Name		Account	BAC Code			

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 01:52:54 PM	KINZERTH	BENTIVLE	SR Opened		Done	3/4/2009 01:52:54 PM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name	Contact First Name		Account	BAC Code			

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 01:52:52 PM	KINZERTH	BENTIVLE	SR Closed - Satisfied		Done	3/4/2009 01:52:52 PM	Service Request has been Closed Satisfied.
Contact Last Name	Contact First Name		Account	BAC Code			

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 10:30:41 AM	BENTIVLE	BENTIVLE	Outbound Call Customer		Done	3/4/2009 10:31:51 AM	Called cusotmer
Contact Last Name	Contact First Name		Account	BAC Code			

Comments

Cust sts I been involved in an accident because of my brakes and I hit a womans car while exiting the Interstate

Crs adv followed procedures to fill BRC form for Pre Par

Leo Benti CAC/ba/L2/Tier2

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 10:29:05 AM	BENTIVLE	KINZERTH	Escalation	Initiate PAR	Done	3/4/2009 01:52:48 PM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 09:50:01 AM	BENTIVLE	BENTIVLE	Outbound Call Dealer	Made Contact	Done	3/4/2009 09:54:37 AM	Jeff Laberge Svc Mgr
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Jeff Laberge Svc Mgr

Dir sts: we took care of the veh, the rotors whewre refinished and we installed the new shoes as the TSB says we water tested the sunroof abou this leaks and we could not find the leaks never heard back from the customer

Leo Betni CAC/BA/L2/Tier2

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 11:44:43 AM	MURPHYDA	BENTIVLE	Notify CRM	Customer Called	Done	3/3/2009 04:38:17 PM	cust left me message
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 11:43:34 AM	MURPHYDA	MURPHYDA	Inbound Call Customer	Voice Mail Received	Done	3/3/2009 11:44:40 AM	vm message
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Voice Mail Received From

Message:
sr 71-704613121

we have not received call from a supervisor

time stamp 1115 am 3/3/2009

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2009 03:39:59 PM	BENTIVLE	BENTIVLE	Scheduled Outbound Call Cust	Cancelled	Done	3/4/2009 10:31:59 AM	Call Customer
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/2/2009 03:39:34 PM	BENTIVLE	BENTIVLE	Outbound Call Customer	Left Message	Done	3/2/2009 03:40:28 PM	]Left Message
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Left Message

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/26/2009 12:58:53 PM	BENTIVLE	BENTIVLE	Scheduled Outbound Call Cust		Done	3/2/2009 03:40:21 PM	call Customer
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/26/2009 12:56:37 PM	BENTIVLE	BENTIVLE	Outbound Call Customer	Left Message	Done	2/26/2009 01:13:56 PM	Left message
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Left Message							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/25/2009 12:44:39 PM	BENTIVLE	BENTIVLE	Scheduled Outbound Call	Cust	Done	2/26/2009 12:57:17 PM	Call Customer
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/25/2009 12:44:14 PM	BENTIVLE	BENTIVLE	Outbound Call Customer	Received No Answer	Done	2/25/2009 12:45:10 PM	VM not being set up yet
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
VM not being set up yet							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:25:58 PM	MURPHYDA	BENTIVLE	Dealer Notification	Action Required	Done	2/24/2009 02:25:58 PM	Dir Notify on T2 Escalation
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
This is to notify you that this case was sent to your District Specialist (Tier 2) CRS. They may reach out to you shortly to discuss the customer's concerns. If possible, you may want to reach out to the customer to attempt to resolve.							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:25:58 PM	MURPHYDA	BENTIVLE	Ownership Changed		Done	2/24/2009 02:25:58 PM	Service Request Ownership has changed FROM: MURPHYDA TO: BENTIVLE
Contact Last Name	Contact First Name		Account		BAC Code		
[REDACTED]							
Comments							
[REDACTED]							
Confidential Comments							
[REDACTED]							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:25:58 PM	MURPHYDA	BENTIVLE	T2 Initial Acknowledgement		Done	2/25/2009 12:45:06 PM	Initial Customer Contact after escalation
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:23:40 PM	MURPHYDA	MURPHYDA	Outbound Call Customer	Received No Answer	Done	2/24/2009 02:25:55 PM	escalation to district
Contact Last Name	Contact First Name		Account		BAC Code		
Comments							
calling father at [REDACTED] no answer no voice mail box set up							
dave murphy st/ cac t1							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:14:15 PM	MURPHYDA	MURPHYDA	Outbound Call Customer	Made Contact	Done	2/24/2009 02:23:39 PM	escalation to district specialist
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

btto number was a wrong number for father

calling daytime #

crs sts

dave murphy calling from Chevy customer service

your father contact number came up as a wrong number.

problems calling dir no answer

i will call your father too

the file is being escalated to district specialist

to try and contact dir

cust sts

my father number is

the dir number i have is

i would appreciate any help you can give me

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:08:31 PM	MURPHYDA	MURPHYDA	Other	Reason for Escalation	Done	2/24/2009 02:14:14 PM	district special
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

father calling on daughters vehicle

unable to contact dir after 4 calls over 2 days
no answer in service then bounces back toivr menu no live answer,

denied warranty coverage for interior blind cover for sunroof which was water stained from a leak in sunroof.

looking for a print out of service history and tsb on brake issue
SERVICE BULLETIN ON FRONT BRAKES

REAR ENDED SOMEONE BECAUSE BRAKE WOULD NOT STOP-BRAKES VIBRATED
POLICE CALLED -NO INJURIES
BRAKES DID NOT WORK

PLASTIC SHOCKS were installed as per tsb.
ARE WHOLE FAMILY IS GM AND OWN 35 VEHICLES.
VEH WAS PICKED UP THURSDAY NIGHT
DLR CALLED THIS AFTERNOON AND CHEVY IS REFUSING TO REPLACE INTERIOR SUNCOVER WHICH HAS WATER STAINED
STARLING S/A CEO(LADY)
INSURANCE REQUESTED TSB ON BRAKES
ROTORS 3 TIMES IN 31000 MILES
I DONT KNOW THE MILEAGE

cust mentioned this was a small dir

dave murphy stj cac t1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 02:01:03 PM	MURPHYDA	MURPHYDA	Outbound Call Dealer	Made Contact	Done	2/24/2009 02:03:34 PM	4th attempt calling dir
Contact Last Name		Contact First Name	Account		BAC Code		

Comments

4th attempt

no answer at dir
keeps looping through menu
disconnected

dave murphy stj cac t1

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 11:09:18 AM	MURPHYDA	MURPHYDA	Scheduled Outbound Call	Dir	Done	2/24/2009 02:12:17 PM	diagnosis
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

3rd call attempt
ask service dept about F ABOUT BRAKE CONCERNS, SUNROOF/WATER STAIN, TSB COPY ON BRAKES.

DAVE MURPHY STJ CAC T1

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/24/2009 11:05:40 AM	MURPHYDA	MURPHYDA	Outbound Call Dealer	Received No Answer	Done	2/24/2009 11:09:08 AM	diagnosis
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

crs sts
line keeps looping between service dept and selction menu
2nd call in 2 days
no voice mail to leave message

DAVE MURPHY STJ CAC T1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/23/2009 04:58:50 PM	MURPHYDA	MURPHYDA	Scheduled Outbound Call	Dir	Done	2/24/2009 11:05:39 AM	DIAGOSIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CALL DLR AND INQUIRE OF ABOUT BRAKE CONCERNS, SUNROOFWATER STAIN, TSB COPY ON BRAKES.

DAVE MURPHY STJ CAC T1

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/23/2009 04:55:30 PM	MURPHYDA	MURPHYDA	Scheduled Outbound Call	Cust	Done	2/24/2009 02:12:29 PM	DIAGNOSIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CALL CUST AFTER RESEARCHING ISSUE WITH BRAKES AND SUNROOF BLIND

DAVE MURPHY STJ CAC T1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/23/2009 04:53:30 PM	MURPHYDA	MURPHYDA	Inbound Call	Customer	Done	2/23/2009 05:02:02 PM	FRONT BRAKE ISSUES AND SUNROOF SUN BLIND
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Customer States:

CALL -FATHER CALLING ON DAUGHTERS

BRAKES REPAIRED - 3 TIMES
SUNROOF 2 TIMES
DLR IS REFUSING TO REPLACE INSIDE LID
WATER DAMAGE
SERVICE BULLETIN ON FRONT BRAKES

REAR ENDED SOMEONE BECAUSE BRAKE WOULD NOT STOP-BRAKED VIBRATED
POLICE CALLED
NO INJURIES
BRAKES DID NOT WORK
NEXT CHEVY DLR - TURNED ROTORS, INSTALLED PLASTIC SHIED'S.
LOST 30 PER CENT OF ROTORS
ARE WHOLE FAMILY IS GM AND OWN 35 VEHICLES.
VEH WAS PICKED UP THURSDAY NIGHT
DLR CALLED THIS AFTERNOON AND CHEVY IS REFUSING TO REPLACE INTERIOR SUNCOVER WHICH HAS WATER STAINED
STARLING S/A CEO(LADY)
INSURANCE REQUESTED TSB ON BRAKES
ROTORS 3 TIMES IN 31000 MILES
I DONT KNOW THE MILEAGE

BACH: 242070
Incorporated Name: STARLING CHEVROLET-CADILLAC, LLC
3GND23DX75

CALLED DLR FOR VIN- NO ANSWER IN SERVICE - 3TIMES

ON HOLD WITH CUST FOR MOST OF CALL WHILE HE TRIED TO FIND VIN

CRS ADV
WILL RESEARCH FURTHER AND CALL FATHER BACK TOMORROW EVENING

DAVE MURPHY STJ CAC T1

Customer Seeks:
CRS Advised:

Service Request Detail

UCC Information

UCC Code	Symptom	Description
C44	Leaks Water	Body - Sunroof / T-Top / Removable Top/ Tonneau Cover
H01	Inoperative	Brakes - General

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	3GNDA23DX7S
-------	-------------

VEHICLE INFORMATION

Merchandising Model :		1AS46 -2007 CHEVROLET HHR LT		Warranty Start Date :		05/31/2007	
BARS Order Type :		70 - RETAIL - STOCK					
Delivering Dealer :		BILL HEARD CHEVROLET 127 N OREGON ST SANFORD , FL 32771-8578 (407) 321-7800		Selling Source :		13 - CHEVROLET	
				Site Code :		26428	
				Business Associate Code :		160156	
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	08016	HEAD IMPACT PROTECTION - INCREASED PROTECTION	N/A	Closed
RC	08157	INSTRUMENT PANEL STORAGE BIN DOOR COMPLIANCE - ADD REINFORCEMENT BRACKET	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

OnStar Equipped	No	OnStar Status	N/A	Refer to Help page for details or go to OnStar Online Enrollment (located on the "OnStar" tab in GM InfoNET) or (888)ONSTAR1 (888) 667-8271.		
XM Equipped	Yes	XM Radio ID	WWV6T044	XM Status	Inactive	Refer to Help page for details or: www.xmradio.gm.ca or Dealer Hotline 1.877.GET.XMST (1-877-438-9677).

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	05/31/2007	6 miles	05/31/2010	36006 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	05/31/2007	6 miles	05/31/2013	100006 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	05/31/2007	6 miles	05/31/2015	80006 miles

60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	05/31/2007	6 miles	05/31/2012	100006 miles
36/36000 FEDERAL EMISSION	05/31/2007	6 miles	05/31/2010	36006 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
02/18/2009	041911	#	C7295 - LATCH, REAR SEAT CUSHION - RIGHT - REPLACE	34524 miles
02/18/2009	041911	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	34524 miles
02/18/2009	041911	#	N3360 - SUNROOF WINDOW MOTOR REPLACEMENT	34524 miles
02/18/2009	041911	#	V1786 - 08016 - INSTALL ENERGY ABSORBING DEVICES	34524 miles
02/18/2009	041911	#	V1865 - 08157 - INSPECT STORAGE BIN & INSTALL REINFORCEMENT LATCH	34524 miles
07/02/2008	397729	#	H0122 - FRONT BRAKE ROTOR REFINISHING	21788 miles
12/07/2007	379249	#	H0122 - FRONT BRAKE ROTOR REFINISHING	11045 miles
12/07/2007	379249	#	B2800 - LOCATOR, DRIVE CABLE AND/OR MICRO SWITCH - REPLACE	11045 miles
07/25/2007	362574	I	Z6998 - PDI ADDS	373 miles
04/23/2007	A23435	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	3GNDA23DX7S
-------	-------------

CLAIM HISTORY

Repair Order Date :		02/18/2009		Repair Order Number :		041911		Odometer Reading :		34524 miles	
Served By :		STARLING CHEVROLET-CADILLAC, LLC PO BOX 609 DELAND, FL 32721-0609 (386) 734-2661				Selling Source :		13 - CHEVROLET			
						Site Code :		26453			
						Business Associate Code :		242070			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
03/10/2009	985	01	#	C7295 - LATCH, REAR SEAT CUSHION - RIGHT - REPLACE		22733906 - COVER	N/A	N/A	\$ 50.94	N	
03/06/2009	984	01	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE		22731037 - PAD KIT	N/A	N/A	\$ 246.39	N	
03/06/2009	984	02	#	N3360 - SUNROOF WINDOW MOTOR REPLACEMENT		15907357 - ACTUATOR	E	N/A	\$ 312.77	N	
03/06/2009	984	04	#	V1786 - 08016 - INSTALL ENERGY ABSORBING DEVICES		19206742 - ABSORBER	N/A	N/A	\$ 46.65	N	
03/06/2009	984	05	#	V1865 - 08157 - INSPECT STORAGE BIN & INSTALL REINFORCEMENT LATCH		N/A	N/A	N/A	\$ 16.67	N	

Repair Order Date :		07/02/2008		Repair Order Number :		397729		Odometer Reading :		21788 miles	
Served By :	BILL HEARD CHEVROLET 127 N OREGON ST SANFORD, FL 32771-8578 (407) 321-7800					Selling Source :		13 - CHEVROLET			
						Site Code :		26428			
						Business Associate Code :		160156			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
				H0122 - FRONT							

http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=3GNDA2... 3/10/2009

07/25/2008	920	01	#	BRAKE ROTOR REFINISHING	N/A	WB	N/A	\$ 147.01	Y
------------	-----	----	---	----------------------------	-----	----	-----	-----------	---

Repair Order Date :		12/07/2007		Repair Order Number :		379249		Odometer Reading :		11045 miles	
Serviced By :		BILL HEARD CHEVROLET 127 N OREGON ST SANFORD, FL 32771-8578 (407) 321-7800				Selling Source :		13 - CHEVROLET			
						Site Code :		26428			
						Business Associate Code :		160156			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
12/18/2007	857	01	#	H0122 - FRONT BRAKE ROTOR REFINISHING		N/A		N/A	N/A	\$ 142.61	N
12/18/2007	857	02	#	B2800 - LOCATOR, DRIVE CABLE AND/OR MICRO SWITCH - REPLACE		N/A		E	N/A	\$ 277.31	N

Repair Order Date :		07/25/2007		Repair Order Number :		362574		Odometer Reading :		373 miles	
Serviced By :		BILL HEARD CHEVROLET 127 N OREGON ST SANFORD, FL 32771-8578 (407) 321-7800				Selling Source :		13 - CHEVROLET			
						Site Code :		26428			
						Business Associate Code :		160156			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/03/2007	818	01	I	Z6998 - PDI ADDS		N/A		N/A	N/A	\$ 39.62	N

Repair Order Date :		04/23/2007		Repair Order Number :		A23435		Odometer Reading :		0 miles	
Serviced By :	BILL HEARD CHEVROLET 127 N OREGON ST SANFORD, FL 32771-8578 (407) 321-7800					Selling Source :		13 - CHEVROLET			
						Site Code :		26428			
						Business Associate Code :		160156			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
04/27/2007	790	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 103.00	N

CHECK HISTORY

Vehicle Has No Associated Check History.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	3GNDA23DX7S
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AS46 -2007 CHEVROLET HHR LT		
Gross Vehicle Weight Rating :	1925 kg (4245 lb)	Order Number :	KWFS1X
Build Date :	04/23/2007	Build Plant :	37SA

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AL0 - SENSOR INDICATOR,FRT PASS/CHILD	AP3 - REMOTE STARTER SYSTEM
AP9 - CARGO CONVENIENCE NET	AR9 - FRONT BUCKET SEATS,DELUXE
AT8 - RESTRAINT CHILD PROVISIONS	B36 - CARGO MAT, CARPETED, REAR
B50 - PREMIUM CARPETED FLOOR MATS ***DEALER INSTALLED***	B57 - BRIGHT CHROME APPEARANCE PKG: *BRIGHT CHROME GRILLE *BRIGHT CHROME O/S MIRRORS *BRT CHROME LIFTGATE APPLIQUE *BRIGHT CHROME DOOR HANDLE *ROOF RAILS WHEN PURCHASED
CF5 - POWER SUNROOF	C2Y - GVW RATING 4,240 LBS
C67 - AIR CONDITIONING	DG7 - MIRROR,O/S ELECT REMOTE CNTRL
DNR - DEALER INSTALLED EQUIPMENT	DT4 - ASHTRAY AND LIGHTER
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - 50-STATE EMISSIONS
FX2 - 3.91 AXLE RATIO	IP2 - INTERIOR DESIGN (P2)
J41 - PWR BRAKE SYSTEM	KA1 - HEATED DRIVER SEAT
L61 - 4 CYL 2.2L MFI DOHC	MN5 - 4 SPD AUTO TRANSMISSION, HMD
MX0 - TRANSMISSION, 4 SPD AUTOMATIC W/REMOTE START	NP5 - LEATHER WRAPPED STEERING WHEEL
NT7 - FEDERAL EMISSION SYSTEM TIER 2	PCJ - SUN AND FUN EDITION PACKAGE: * POWER SUNROOF * XM SATELLITE RADIO - SERVICE FEE EXTRA 1ST 3 MONTHS INCL. * AUDIO SYSTEM,HIGH PERFORMANCE WITH 7 PIONEER SPEAKERS * REAR SPOILER (DEALER INSTALLED)
QDB - TIRE, P215/55R16-91S BW ST AL2	QG9 - WHEELS, 16" ALUMINUM, MACHINE FACED

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=3GNDA2...> 3/10/2009

R6K	R6N - ONSTAR IDENTIFIER PR/VI
R6P - PREMIUM PAINT	R9L - SPRING WHOLESALE FLOORPLAN PLUS
R9N - LEATHER TRIM INCLUDES: *SEATS, FRONT BUCKET, LEATHER SURFACES *DRIVER & FRONT PASSENGER HEATED SEATS *LEATHER WRAPPED STEERING WHEEL *STEERING WHEEL RADIO CONTROLS *LEATHER WRAPPED SHIFT KNOB	SAL - RAMOS ARIZPE, MEXICO PLANT CODE
SLM - STOCK ORDERS	T43 - REAR SPOILER ***DEALER INSTALLED***
UQ3 - AUDIO SYSTEM HIGH PERFORMANCE WITH 7 PIONEER SPEAKERS	US8 - AM/FM STEREO, CD PLAYER, MP3 PLAYER, W/AUX INPUT JACK (REPLACES STD/OPT RADIO)
U2K - XM SATELLITE RADIO-SERVICE FEE EXTRA.1ST 3MONTHS INCL	VK3 - FRONT LICENSE PLATE BRACKET
VT7 - OWNERS MANUAL ENGLISH	VY7 - LEATHER WRAPPED SHIFT KNOB
V73 - STATEMENT OF VEHICLE CERT.- U.S./CANADA	1LT - LT PACKAGE
ISZ - SUN AND FUN EDITION PACKAGE DISCOUNT	14I - GRAY INTERIOR TRIM
142 - GRAY INTERIOR TRIM	6AE - FRONT SPRING
63U - SPORT RED METALLIC	7AE - FRONT SPRING

© 1998-2005 General Motors Corporation. All Rights Reserved.