


EWR D&I ANNOTATION



FAN-000001L092001DP85-2448

Artemis # : 000001L092001DP85**Record Created Date :** 06/11/2010**Printed Date :** 06/14/2010

Description : DI09-096. SEQ ID 85. 2009 Q2. DRIVER OF A 2006 CHEVY COBALT STATES THAT HE WAS TRYING TO AVOID A CAR THAT MADE AN ILLEGAL TURN WHICH RESULTED IN A COLLISION WITH A CAR THAT WAS AT A STOP SIGN. DRIVER SIDE FRONT WAS HIT AND RADIATOR DAMAGED. NO POLICE REPORT GIVEN. DRIVER ALLEGES AIR BAGS DID NOT DEPLOY AND SHOULD HAVE. SEARCHED 2005-2006. VOQ-27. PURSUIT-1. TSB-0. RECALLS-0. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-096

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 3, 7, 15, 39, 63, 78, 81, 82, 85, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 98, 100, 101, 103, 105, 106, 107, 108, 109, 110, 131, 137, 145, 146, 148, 149, 158, 167, 168, 178, 209, 216, 219, 231, 243, 253, 254, 255, 256, 257, 258, 259, 261, 263, 264, 266, 270, 271, 276, 281, 282, 288, 289, 290, 291, 292, 293, 297, 299, 300, 311, 312, 327, 338, 339, 341, 343, 344, 345, 346, 348, 349, 351, 352, 354, 370, 382, 390, 391	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

12660

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 22, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

11 February 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-096

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2009.

GM's response is comprised of 88 disks for the incidents that are the subject of DI09-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 3 18605620-675350 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 3 18605620-675350_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI09-096
3 18605620-675350
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 3 18605620-675350 **_01_001** - is the first document responsive to Inquiry no. 1.
3 18605620-675350 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(88 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
3	5GAER23D69J [REDACTED]	NISM
7	UNKNOWN [REDACTED]	NISM
15	5GADS13S142 [REDACTED]	NISM
39	1G6DU57V090 [REDACTED]	LIT
63	UNKNOWN [REDACTED]	NISM
78	1G1AL52F957 [REDACTED]	NISM
81	1G1AK52F257 [REDACTED]	NISM
82	1G1AK55F167 [REDACTED]	NISM
85	1G1AK15F467 [REDACTED]	NISM
87	1G1AK55F267 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
88	1G1AM15B367	NISM
89	1G1AL15FX67	NISM
90	1G1AK15F367	NISM
91	1G1AL58F977	NISM
92	1G1AK15F077	NISM
93	1G1AK55F577	NISM
94	1G1AK15F477	NISM
95	1G1AK55F577	LIT
96	1G1AK15F077	NISM
98	1G1AK58FX77	NISM
100	1G1AK55FX77	NISM
101	1G1AK15F477	NISM
103	1G1AK18F887	NISM
105	1G1AL58F287	NISM
106	1G1AK18F187	NISM
107	1G1AL58F987	NISM
108	1G1AK58F987	NISM
109	1G1AL58F987	NISM
110	1G1AT58H097	NISM
131	3GNDA23P76S	NISM
137	3GNDA13D48S	NISM
145	2G1WF52E049	NISM
146	2G1WF52E249	NISM
148	2G1WH52K049	NISM
149	2G1WH52K049	NISM
158	2G1WT58N279	NISM
167	2G1WT57K791	NISM
168	2G1WC57M591	NISM
178	1G1ZG57B39F	NISM
209	1GCEK24009Z	NISM
216	1GCHK29K57E	NISM
219	1GBJC34K78E	NISM
231	1GNFC16047J	NISM
243	1GNFK33059R	NISM
253	1GNDS13S642	NISM
254	1GNDT13S052	NISM
255	1GNDT13S052	NISM
256	1GNDS13SX52	NISM
257	1GNDT13S852	NISM
258	1GNDT13S052	NISM
259	1GNDT13S352	NISM
251	1GNDT13S662	NISM
263	1GNDT13S682	NISM
264	1GNDT13S882	NISM
266	1GNDS33S892	NISM
270	1GNES16S866	NISM
271	1GNEV23D29S	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
276	1GNDU03E64D [REDACTED]	NISM
281	1GKEV23D59J [REDACTED]	NISM
282	1GKEV23D99J [REDACTED]	NISM
288	UNKNOWN	NISM
289	1GKDS13S442 [REDACTED]	NISM
290	1GKDT13S442 [REDACTED]	NISM
291	1GKDT13S552 [REDACTED]	NISM
292	1GKDS13S962 [REDACTED]	NISM
293	1GKDS13S462 [REDACTED]	NISM
297	1GKET16S956 [REDACTED]	NISM
299	1GKES12S046 [REDACTED]	NISM
300	1GKES12S956 [REDACTED]	NISM
311	3GTEC13C48G [REDACTED]	NISM
312	3GTEK13378G [REDACTED]	NISM
327	5GTDN136568 [REDACTED]	NISM
338	1G2ZF55B264 [REDACTED]	NISM
339	1G2ZF55B064 [REDACTED]	NISM
341	1G2ZG558364 [REDACTED]	NISM
343	1G2ZH18N374 [REDACTED]	NISM
344	1G2ZG58B574 [REDACTED]	NISM
345	1G2ZH57N584 [REDACTED]	NISM
346	1G2ZG57B384 [REDACTED]	NISM
348	1G2ZH57N684 [REDACTED]	NISM
349	1G2ZF57B584 [REDACTED]	NISM
351	1G2ZJ57B494 [REDACTED]	NISM
352	1G2ZH36N994 [REDACTED]	NISM
354	6G2EC57Y19L [REDACTED]	NISM
370	2G2WP552881 [REDACTED]	NISM
382	5S3ET13S662 [REDACTED]	NISM
390	5GZER13737J [REDACTED]	NISM
391	5GZEV23748J [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Kent', with a stylized flourish at the end.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 88 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI09-096
85 278517345 – 671459
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR - Collision
Address	City Palm Coast	Involved Dir	Jon Hall Chevrolet, Inc.	Safety	Yes
State FL ZipCd	Con Acct	Source	Phone	Updated	5/12/2009 05:08:23 PM
Serial #/VIN 1G1AK15F467	Model Year 2006	Priority	Medium License # CHEVROL	Owner	SANCHERI
Make Chevrolet	Warr. Start 07/01/2006	Status	Open	Opened	5/11/2009 10:23:39 AM
Model Cobalt	Mileage 75000	Sub-Status		Closed	
Abstract Airbags did not deploy in accident					
Customer Description ***This is a BRC PAR Case. Please do not assume. Forward any Inquiries to Rita Sanchez at ext.31227 ***					

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	5/9/2009 04:00:00 PM	Y	2	1	Asphalt	Dry	unknown	unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'4"		none				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unknown	Terry	(904) 461-5400	state Farm Insurance					
Incident Loc	pine lakes parkway Palm Coast, FL	Incident Desc	was avoiding a car that made an illegal turn and skidded into a car that was at a stop sign. driver side front was hit and radiator damaged as well. veh was at 40mph and airbag did not deploy					
Component	Airbag	Damage Desc	damage on front of veh. damage reached radiator					
Vehicle Loc	at collision shop. J and J autoshop	Add'l Info	customer has acquired an attorney. New Land					
Emergency Svc Names		Maint Loc	john hall					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	na
Vehicle Speed	40	Weather Condition	clear	Prop Owner	na	Property Type	na	
Last Service Date		Loc Last Service		Property Location	na	Prop Est Repair Cost		
Veh Est Repair Cost		Spec Equip Installer	na	Prop Damage Description	na			
Primary Veh Use	Personal	Inspection Type		Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	front end damage	Explain Other	n/a					

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		03/31/67	Non-occupant of vehicle		Driver	Seatbelt was on
Injury Description		Medical Rpt#		Treatment Location		Treated By
-back injury, pinched nerve, constant headaches,				none		none
Street Address		City	State	Zip Code		
		Palm Coast	FL			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 05:09:23 PM	RODRIGOS	ESISBIQU	Escalation	ESIS - Atty Involvement	In Progress		Assigned to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
John Brennan Newland Attorney's 20 N Orange Ave, Ste 1600 Orlando, FL 32801-4624 407-420-1212							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 04:26:27 PM	KINZERTH	RODRIGOS	Notify CRM		Done	5/12/2009 05:09:21 PM	ESIS - Injuries
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Received And Assigned to ESIS							
Jose Rodriguez ATX PAR							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 04:14:04 PM	SANCHER	SANCHER	Scheduled Follow-up		Scheduled Alarm		tu ESis Pick up
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 04:11:08 PM	SANCHERI	KINZERTH	BRC PAR	ESIS- Injuries	Done	5/12/2009 04:26:25 PM	ESIS- Injuries
Contact Last Name		Contact First Name		Account	BAC Code		

Comments
ESIS- Injuries

*constant headaches
* attorney involvement

John Brennan
Newland Attorney's
20 N Orange Ave, Ste 1500
Orlando, FL 32801-4624
407-420-1212

Rita Sanchez/ATX/PAR
Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 04:07:17 PM	SANCHERI	SANCHERI	Ownership Changed	Ownership Escalated to BRC	Done	5/12/2009 04:07:17 PM	Ownership Escalated to BRC
Contact Last Name		Contact First Name		Account	BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:50 AM	KINZERTH	SANCHERI	Ownership Changed		Done	5/12/2009 08:38:50 AM	Service Request Ownership has changed FROM: GROMGLPA TO: SANCHERI
Contact Last Name		Contact First Name		Account	BAC Code		

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:33 AM	KINZERTH	SANCHERI	BRC PAR	Initial Contact- AVM	Done	5/12/2009 04:10:59 PM	Called DVM is Steve Giamalvo
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

This is Rita Sanchez calling from gm par dept.

Customer:

Service Request: 71-723567819

Vehicle Information: 06 cobalt

Last 8 of the VIN: 67

Involved Dealership: jon hall

Nature of allegation: non deployment

CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-866-790-5600 X 31227 If not then this is an FYI to let you know what is going on in your district.

Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:24 AM	KINZERTH	SANCHERI	BRC PAR	Initial Contact- Dealer	Done	5/12/2009 04:08:23 PM	Called Jon Hall Chevrolet, Inc. (386) 255-4444
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Spoke with: Service Manager - Dawn

CRS adv: Calling on regards to an claim that was called in by an cust by the names of Syndie Gigliello -. They have an 06 cobalt -. Calling to make dir aware of allegation and checking to see what dir knows of allegation non deploy

Dir sts: the vehicle is not here and no history

CRS Adv: Due to the allegation file will be forwarded to ESIS and will be incontact with cust on this concern.

DVM is Steve Giamalvo

Rita Sanchez/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:16 AM	KINZERTH	SANCHERI	BRC PAR	Initial Contact- Phone	Done	5/12/2009 04:02:49 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

cust sts my wife was avoiding a car that made an illegal turn and skidded into a car that wat a stop sign. driver side front was hit and radiator damaged as well. veh was at 40mph and airbag did not deploy, we have an attorney but my wife has the information , you would have to call her at [REDACTED] and she was injured and is still having headaches

crs sts well i am sorry she had to experience this but what i will do is contact her and get some further information

crs called wife at [REDACTED]

cust sts her attorney name is John Brennan From Newland Attorneys 407-4201212

crs sts thanks

Rita SanchezATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:08 AM	KINZERTH	SANCHERI	BRC PAR	Acknowledgement	Done	5/12/2009 03:44:48 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

See Initial Contact

Rita Sanchez/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:38:00 AM	KINZERTH	SANCHERI	Notify CRM		Done	5/12/2009 03:43:36 PM	File Assigned
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:37:53 AM	KINZERTH	SANCHER	Research		Done	5/12/2009 03:43:32 PM	Research VIN 1G1AK15F467
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Performed VIN Scan
GMVIS: - Found No Open Recalls

VIN: - Found No Duplicate File

SVC History: No Service History Related to Allegation

Rita Sanchez/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:37:30 AM	KINZERTH	SANCHER	BRC PAR	Case Assigned	Done	5/12/2009 03:42:16 PM	Assigned to Rita Sanchez x31227
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:37:22 AM	KINZERTH	GROMGLPA	SR Opened		Done	5/12/2009 08:37:22 AM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2009 08:37:16 AM	KINZERTH	GROMGLPA	SR Closed - Satisfied		Done	5/12/2009 08:37:20 AM	Service Request has been Closed Satisfied.
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/11/2009 10:48:18 AM	GROMGLPA	KINZERTH	Escalation	Initiate PAR	Done	5/12/2009 08:37:13 AM	Assigning file to PAR queue
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

-advised cust that someone from the PAR team will be calling cust w/in 2-5 business days

Paul Peters/CACT1/Mia/LVL 1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/11/2009 10:23:49 AM	GROMGLPA	GROMGLPA	Inbound Call Customer	Complex Request	Done	5/11/2009 10:48:16 AM	Recall Inquiry
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
husband calling

CUST STS:

2006 Chevy Cobalt
-airbag didn't deploy during wife's accident
-veh was at 40 mph
-another veh made an illegal turn and wife's car skidded onto another veh
-wife was avoiding a car that made an illegal turn and skidded into a car that was in a stop sign. -driver side front was hit and radiator damaged as well. veh was at 40mph and airbag did not deploy
-calling to check if veh had any recalls. wants to find out why airbags didn't deploy

CUST SKS:

-asst

CRS ADVSD:

-checked gmvis, no recalls on veh
-will gather necessary info
-will be forwarding case to product allegation team
-provided SR#
-advsd cust to expect a call from PAR team w/in 2-5 business days

Paul Peters/CACT1/Mia/LVL 1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) -
[Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK15F467
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK37 -2006 COBALT 2-DOOR LS COUPE		Warranty Start Date :	07/01/2006			
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	JON HALL CHEVROLET, INC. PO BOX 751 DAYTONA BEACH , FL 32115-0751 (386) 255-4444		Selling Source :	13 - CHEVROLET			
			Site Code :	26462			
			Business Associate Code :	114760			
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns
--

SERVICE INFORMATIONAL ITEMS

Type	Number	Description	Posted Date	Status
EI	09110	SIR/AIRBAG LIGHT ILLUMINATED, DTC B0081 SET(REF. TSB 09-09-41-003)	05/05/2009	See Bulletin

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	07/01/2006	78 miles	07/01/2009	36078 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	07/01/2006	78 miles	07/01/2012	100078 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	07/01/2006	78 miles	07/01/2014	80078 miles
36/36000 FEDERAL EMISSION	07/01/2006	78 miles	07/01/2009	36078 miles
60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	07/01/2006	78 miles	07/01/2011	60078 miles

CLAIM HISTORY

--	--	--	--	--

<http://98.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AK15F46...> 5/13/2009

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
01/11/2007	J24132	#	Z2081 - ROADSIDE SERVICE (LOCKOUT)	18000 miles
10/04/2006	164593	#	N6624 - OCCUPANT SAFETY WIRING AND/OR CONNECTOR REPAIR OR REPLACEMENT	10938 miles
05/22/2006	A71476	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK15F467 [REDACTED]
-------	------------------------

CLAIM HISTORY

Repair Order Date : 01/11/2007		Repair Order Number : J24132		Odometer Reading : 18000 miles					
Serviced By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117			Selling Source : 13 - CHEVROLET					
				Site Code : 34415					
				Business Associate Code : 207453					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
01/19/2007	762	01	#	Z2081 - ROADSIDE SERVICE (LOCKOUT)	N/A	C	N/A	\$ 46.92	N

Repair Order Date : 10/04/2006		Repair Order Number : 164593		Odometer Reading : 10938 miles					
Serviced By :	TOM GIBBS CHEVROLET, INC. 5850 E HWY 100 PALM COAST, FL 32164-2446 (386) 437-3314			Selling Source : 13 - CHEVROLET					
				Site Code : 26204					
				Business Associate Code : 114729					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
10/06/2006	732	01	#	N6624 - OCCUPANT SAFETY WIRING AND/OR CONNECTOR REPAIR OR REPLACEMENT	N/A	E	N/A	\$ 102.09	N

Repair Order Date : 05/22/2006		Repair Order Number : A71476		Odometer Reading : 0 miles					
Serviced By :	NIMNIGHT CHEVROLET COMPANY PO BOX 14000 JACKSONVILLE, FL 32238-1000 (904) 387-4041			Selling Source : 13 - CHEVROLET					
				Site Code : 26358					
				Business Associate Code : 114752					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=1G1AK15...> 5/13/2009

05/26/2006	694	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	N/A	N/A	N/A	\$ 97.50	N
------------	-----	----	---	---	-----	-----	-----	----------	---

CHECK HISTORY**Vehicle Has No Associated Check History.**

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	1G1AK15F467
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK37 -2006 COBALT 2-DOOR LS COUPE		
Gross Vehicle Weight Rating :	1676 kg (3696 lb)	Order Number :	KCKM72
Build Date :	05/22/2006	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
B34 - FLOOR MATS	B35 - REAR FLOOR MATS
B84 - BODY COLOR BODYSIDE MOLDINGS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - POWER DISC FRONT BRAKES
K34 - CRUISE CONTROL	K64 - 115 AMP GENERATOR
LOD - ASSEMBLY PLANT - LORDSTOWN,OHIO	L61 - 2.2L DOHC 4 CYL ENGINE
MN5 - 4 SPEED AUTO TRANSMISSION	MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE
NT7 - FEDERAL EMISSION TIER 2	N46 - 4 SPOKE STEERING WHEEL
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
R6P - PREMIUM PAINT	R8K - *****
SLM - STOCK ORDERS	UN0 - AM/FM STEREO W/CD & RDS
UQ4 - BASE SPEAKER SYSTEM	VK3 - FRONT LICENSE PLATE MOUNT
V73 - STATEMENT OF VEHICLE CERT.- U.S./CANADA	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	14B - GRAY
14I - GRAY	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK15...> 5/13/2009

9AA - REAR SPRING	95U - ULTRA SILVER METALLIC
-------------------	-----------------------------

© 1998-2005 General Motors Corporation. All Rights Reserved.