

EWR D&I ANNOTATION



FAN-000001L092001DP98-9944

Artemis # : 000001L092001DP98

Record Created Date :

Printed Date : 06/22/2010

Description :

DI09-096. SEQ ID 98. 2009 Q2. DRIVER OF A 2007 CHEVY COBALT WENT OFF THE ROAD AND OVER CORRECTED. VEHICLE SPUN AND FLIPPED OVER. AIR BAGS DID NOT DEPLOY AND CUSTOMER ALLEGES THEY SHOULD HAVE. NO POLICE REPORT GIVEN. VOQ-37. PURSUIT-0 (1 FOR 2006). TSB-0. RECALLS-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-096

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 3, 7, 15, 39, 63, 78, 81, 82, 85, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 98, 100, 101, 103, 105, 106, 107, 108, 109, 110, 131, 137, 145, 146, 148, 149, 158, 167, 168, 178, 209, 216, 219, 231, 243, 253, 254, 255, 256, 257, 258, 259, 261, 263, 264, 266, 270, 271, 276, 281, 282, 288, 289, 290, 291, 292, 293, 297, 299, 300, 311, 312, 327, 338, 339, 341, 343, 344, 345, 346, 348, 349, 351, 352, 354, 370, 382, 390, 391	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

126800

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 22, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in cursive script that reads "Christina Morgan".

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement

11 February 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-096

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2009.

GM's response is comprised of 88 disks for the incidents that are the subject of DI09-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 3 18605620-675350 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 3 18605620-675350_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI09-096
3 18605620-675350
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 3 18605620-675350 **_01_001** - is the first document responsive to Inquiry no. 1.
- 3 18605620-675350 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(88 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
3	5GAER23D69J [REDACTED]	NISM
7	UNKNOWN	NISM
15	5GADS13S142 [REDACTED]	NISM
39	1G6DU57V090 [REDACTED]	LIT
63	UNKNOWN	NISM
78	1G1AL52F957 [REDACTED]	NISM
81	1G1AK52F257 [REDACTED]	NISM
82	1G1AK55F167 [REDACTED]	NISM
85	1G1AK15F467 [REDACTED]	NISM
87	1G1AK55F267 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
88	1G1AM15B367	NISM
89	1G1AL15FX67	NISM
90	1G1AK15F367	NISM
91	1G1AL58F977	NISM
92	1G1AK15F077	NISM
93	1G1AK55F577	NISM
94	1G1AK15F477	NISM
95	1G1AK55F577	LIT
96	1G1AK15F077	NISM
98	1G1AK58FX77	NISM
100	1G1AK55FX77	NISM
101	1G1AK15F477	NISM
103	1G1AK18F887	NISM
105	1G1AL58F287	NISM
106	1G1AK18F187	NISM
107	1G1AL58F987	NISM
108	1G1AK58F987	NISM
109	1G1AL58F987	NISM
110	1G1AT58H097	NISM
131	3GNDA23P76S	NISM
137	3GNDA13D48S	NISM
145	2G1WF52E049	NISM
146	2G1WF52E249	NISM
148	2G1WH52K049	NISM
149	2G1WH52K049	NISM
158	2G1WT58N279	NISM
167	2G1WT57K791	NISM
168	2G1WC57M591	NISM
178	1G1ZG57B39F	NISM
209	1GCEK24009Z	NISM
216	1GCHK29K57E	NISM
219	1GBJC34K78E	NISM
231	1GNFC16047J	NISM
243	1GNFK33059R	NISM
253	1GNDS13S642	NISM
254	1GNDT13S052	NISM
255	1GNDT13S052	NISM
256	1GNDS13SX52	NISM
257	1GNDT13S852	NISM
258	1GNDT13S052	NISM
259	1GNDT13S352	NISM
251	1GNDT13S662	NISM
263	1GNDT13S682	NISM
264	1GNDT13S882	NISM
266	1GNDS33S892	NISM
270	1GNES16S866	NISM
271	1GNEV23D29S	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
276	1GNDU03E64D1 [REDACTED]	NISM
281	1GKEV23D59J [REDACTED]	NISM
282	1GKEV23D99J [REDACTED]	NISM
288	UNKNOWN	NISM
289	1GKDS13S442 [REDACTED]	NISM
290	1GKDT13S442 [REDACTED]	NISM
291	1GKDT13S552 [REDACTED]	NISM
292	1GKDS13S962 [REDACTED]	NISM
293	1GKDS13S462 [REDACTED]	NISM
297	1GKET16S956 [REDACTED]	NISM
299	1GKES12S046 [REDACTED]	NISM
300	1GKES12S956 [REDACTED]	NISM
311	3GTEC13C48G [REDACTED]	NISM
312	3GTEK13378G [REDACTED]	NISM
327	5GTDN136568 [REDACTED]	NISM
338	1G2ZF55B264 [REDACTED]	NISM
339	1G2ZF55B064 [REDACTED]	NISM
341	1G2ZG558364 [REDACTED]	NISM
343	1G2ZH18N374 [REDACTED]	NISM
344	1G2ZG58B574 [REDACTED]	NISM
345	1G2ZH57N584 [REDACTED]	NISM
346	1G2ZG57B384 [REDACTED]	NISM
348	1G2ZH57N684 [REDACTED]	NISM
349	1G2ZF57B584 [REDACTED]	NISM
351	1G2ZJ57B494 [REDACTED]	NISM
352	1G2ZH36N994 [REDACTED]	NISM
354	6G2EC57Y19L [REDACTED]	NISM
370	2G2WP552881 [REDACTED]	NISM
382	5S3ET13S662 [REDACTED]	NISM
390	5GZER13737J [REDACTED]	NISM
391	5GZEV23748J [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Kent', with a stylized flourish at the end.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 88 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI09-096
98 278516878 – 670515
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Documents. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address	City Oakwood	Involved Dir		Safety	Yes
State GA ZipCd	Con Acct	Source	Phone	Updated	4/29/2009 01:00:34 PM
Serial #/VIN 1G1AK58FX77	Model Year 2007	Priority	Medium License #	Owner	STEWARDE
Make Chevrolet	Warr. Start 01/16/2007	Status	Open	Opened	4/27/2009 05:46:13 PM
Model Cobalt	Mileage 24000	Sub-Status	Dissatisfied	Closed	
Abstract (ESIS) Air Bag - (SIR) - Driver Front (non deployment)					
Customer Description	This is a BRC PAR File. Please do not Assume. Forward all Inquiries to Debbie Stewart @ ext 31117				

Pre-PAR

PAR Modifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	3/26/2009 11:30:54 AM	Y	0	1	Concrete	Wet	None	unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
				none				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Stuckey	Andy	(180) 064-1884	Geico Insurance					
Incident Loc	near Bethel Rd., Gainesville, GA	Incident Desc	It was raining and road was wet. went off the road on a curve to the right and over compensated to left to avoid hitting a mailbox. Vehicle spun around and flipped over hitting a ditch and was knocked out					
Component	air bags	Damage Desc	passenger side crushed, driver's seat was twisted, hood and top of vehicle crushed					
Vehicle Loc	with insurance company	Add'l Info	Customer injuries - knee					
Emrgy Svc Names	Georgia State Patrol and ambulance from NE Georgia Medical Center in Gainesville, GA	Maint Loc	Walmart					

PAR Detail

Collision	Y	Non Collision	Property Damage	Y	Thermal Evt	N	Spec Equip	None
Vehicle Speed	30	Weather Condition	raining	Prop Owner	unknown	Property Type	mailbox	
Last Service Date	3/11/2009	Loc Last Service	Midas	Property Location	unknown	Prop Est Repair Cost		
Veh Est Repair Cost	\$10,000.00	Spec Equip Installer	N/A	Prop Damage Description	vehicle ran over mailbox and crushed it			
Primary Veh Use	Personal	Inspection Type		Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	passenger side crushed, driver's seat was twisted, hood and top of vehicle crushed			Explain Other	n/a			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	shoulder and lap belts
Injury Description		Medical Rot#	Treatment Location		Treated By	
concussion, right knee bruised and cartilage, tendons and ligaments torn, numbness in right arm and leg sore shoulder and back		unknown	NE Georgia Medical Center in Gainesville, GA		Dr. Cacenard Dr. Munn	
Street Address		City	State	Zip Code		
		Oakwood	GA			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 03:25:02 PM	RODRIGOS	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Assigned to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

injuries

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 02:43:25 PM	STEWARDE	STEWARDE	Scheduled Follow-up		Scheduled Alarm		ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Action Plan: Check to see if ESIS has picked up file.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 01:33:08 PM	KINZERTH	RODRIGOS	Notify CRM		Done	4/29/2009 03:25:00 PM	ESIS - Injuries
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Received And Assigned to ESIS

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 01:08:33 PM	STEWARDE	KINZERTH	BRC PAR	ESIS- Injuries	Done	4/29/2009 01:33:07 PM	Escalating to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Received and assigned for ESIS escalation
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 01:07:32 PM	STEWARDE	STEWARDE	BRC PAR	ESIS- Injuries	Done	4/29/2009 01:08:27 PM	Escalation to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Escalating to ESIS.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 12:21:06 PM	STEWARDE	STEWARDE	BRC PAR	Initial Contact- Phone	Done	4/29/2009 01:05:32 PM	Update
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS adv: I would like to review the information given to the previous agent and I have a few more questions.

Cus sts: It was raining and road was wet. Went off the road on a curve to the right and over compensated to left to avoid hitting a mailbox. Vehicle spun around and flipped over hitting a ditch and was knocked out
has to have knee surgery 5/4/09
Geico only covers \$10,000 on vehicle and \$1000

ambulance to hospital, released that evening but went back in several days because of concussion symptoms, bumps on back of head, right knee bruised and cartilage, tendons and ligaments torn, will be having surgery, numbness in right arm and leg
sore shoulder and back, going to neurologist for that

Crs Adv: I will be sending your file to our central claims office for further handling. Someone will be in contact w/ you w/ 7-10 business days. If you haven't heard from someone by the end of the 2 weeks please give me a call back and by that time I should have the info of the new agent that will be handling your file which I can release to you at that time.

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 11:17:40 AM	RODRIGOS	STEWARDE	Notify CRM		Done	4/29/2009 01:05:46 PM	returned
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Returned for completion

* Please make sure that in the initial contact you document a summary of the incident and what happened.

* on the pre par the component needs to be whatever the customer is alleging to be defective.

*Please add the Suffix to the contact information.

Resubmit once it has been corrected

Jose Rodriguez-ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 10:55:27 AM	KINZERTH	RODRIGOS	Notify CRM		Done	4/29/2009 11:17:38 AM	ESIS - Injuries
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Returned for completion

* Please make sure that in the initial contact you document a summary of the incident and what happened.

* on the pre par the component needs to be whatever the customer is alleging to be defective.

*Please add the Suffix to the contact information.

Resubmit once it has been corrected

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 10:34:25 AM	STEWARDE	KINZERTH	BRC PAR	ESIS- Injuries	Done	4/29/2009 10:55:26 AM	Escalation to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Received and assigned for ESIS escalation
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 10:32:37 AM	STEWARDE	STEWARDE	BRC PAR	ESIS- Injuries	Done	4/29/2009 10:34:21 AM	Escalation to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 09:48:41 AM	STEWARDE	STEWARDE	Outbound Call Customer	Made Contact	Done	4/29/2009 10:01:24 AM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS adv: I was reviewing your case and wanted to verify that you did indeed have a concussion.

Cus sts: Yes

CRS adv: I will be sending your file to our central claims office for further handling. Someone will be in contact w/ you w/in 7-10 business days. If you haven't heard from someone by the end of the 2 weeks please give me a call back and by that time I should have the info of the new agent that will be handling your file which I can release to you at that time. I will not be requesting an inspection at this time.

Debbie Stewart/PARATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:54:05 AM	STEWARDE	STEWARDE	Outbound Call Customer	Made Contact	Done	4/29/2009 09:47:12 AM	called
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Crs Adv: This is Debbie Stewart calling from the GM Product Allegation Dept. I have received your file and do require further information. Do you have a moment to speak to me?

Cust sts: Yes

Continued in Initial

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:35:42 AM	STEWARDE	STEWARDE	Ownership Changed	Ownership Escalated to BRC	Done	4/29/2009 08:35:42 AM	Ownership Escalated to BRC
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:29:08 AM	KINZERTH	STEWARDE	Ownership Changed		Done	4/29/2009 08:29:08 AM	Service Request Ownership has changed FROM: ABELLAHE TO: STEWARDE
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:50 AM	KINZERTH	STEWARDE	BRC PAR	Initial Contact- AVM	Done	4/29/2009 08:49:42 AM	Called Savage Wade @ 404-08 6139
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DVM Name: Wade Savage
Node/Mailbox: 404-08 6139
This is Debbie Stewart calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.
The request number is: 71-720200476
The Customer's name is: [REDACTED]
The dealer involved is: none
Located in:
The vehicle is a: 2007 Chevrolet Cobalt
With current mileage: 24,000
The last 8 digits of the VIN# are: 77 [REDACTED]
This involves: Cus alleges the front air bag did not deploy in a rollover
We will be fully investigating this incident. This message is for informational purposes only, however if you do have any questions please feel free to give me a call at 866-790-5600 x31117.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:42 AM	KINZERTH	STEWARDE	BRC PAR	Initial Contact- Dealer	Done	4/29/2009 08:53:04 AM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

No record of vehicle at dealer since purchase.

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:33 AM	KINZERTH	STEWARDE	BRC PAR	Initial Contact- Phone	Done	4/29/2009 10:04:02 AM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS adv: I would like to review the information given to the previous agent and I have a few more questions.

Cus sts:

has to have knee surgery 5/4/09

Geico only covers \$10,000 on vehicle and \$1000

ambulance to hospital, released that evening but went back in several days because of concussion symptoms, bumps on back of head, right knee bruised and cartilage, tendons and ligaments torn, will be having surgery, numbness in right arm and leg
sore shoulder and back, going to neurologist for that

CRS Adv: I will be sending your file to our central claims office for further handling. Someone will be in contact w/ you w/in 7-10 business days. If you haven't heard from someone by the end of the 2 weeks please give me a call back and by that time I should have the info of the new agent that will be handling your file which I can release to you at that time.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:25 AM	KINZERTH	STEWARDE	BRC PAR	Acknowledgement	Done	4/29/2009 08:56:33 AM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Adv: This is Debbie Stewart calling from the GM Product Allegation Dept. I have received your file and do require further information. Do you have a moment to speak to me?

Cust sts: Yes

Continued in Initial

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:17 AM	KINZERTH	STEWARDE	Notify CRM		Done	4/29/2009 08:30:56 AM	File Assigned
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:28:09 AM	KINZERTH	STEWARDE	Research		Done	4/29/2009 08:40:42 AM	Research VIN
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

No open recalls.
No other related files.
No related repairs.

Vehicle build:
AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR
ASF - HEAD CURTAIN SIDE AIRBAGS, FRONT/REAR

Research complete.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/29/2009 08:27:48 AM	KINZERTH	STEWARDE	BRC PAR	Case Assigned	Done	4/29/2009 08:30:38 AM	Assigned to Deborah Stewart x31117
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Received.

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/28/2009 11:35:23 AM	SALAZAJU	SALAZAJU	Information Station	Name/Address Change	Done	4/28/2009 11:35:58 AM	Customer Update
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Info Station -

71-720200476

1G1AK58FX77

old address-

Park City, IL
old tel#-

new address-

Oakwood GA
new tel#-

Juan Salazar/info station/atx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/28/2009 11:23:29 AM	KINZERTH	ABELLAHE	SR Opened		Done	4/28/2009 11:23:29 AM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/28/2009 11:23:28 AM	KINZERTH	ABELLAHE	SR Closed - Satisfied		Done	4/28/2009 11:23:28 AM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/28/2009 10:31:51 AM	ABELLAHE	ABELLAHE	Outbound Call Third Party	Info Station/KBA	Done	4/28/2009 11:23:24 AM	researching with info station
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Contacting Information Station
Document ID : d_1009805
Internal Transfer Number: 72431

crs adv- associate vin to cust name as the new owner of the veh

SR 71-720200476

name-
yr/make-2007 COBALT 4-DOOR LS SEDAN
vin- 1G1AK58FX77

old address-

Park City, IL
old tel#-

new address-

Oakwood, GA
new tel#-

Anette Richards MLA/CAC T1/Emp Lvl 1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/27/2009 08:15:12 PM	ABELLAHE	KINZERTH	Escalation	Initiate PAR	Done	4/28/2009 11:23:16 AM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days."

Anette Richards/MAN/CAC T1/Emp Lvl 1

Received in PAR

Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/27/2009 05:57:03 PM	ABELLAHE	ABELLAHE	Inbound Call Customer	Complex Request	Done	4/28/2009 10:31:23 AM	Pre PAR
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

cust sts- calling to file a complaint abt the airbags that did not deploy causing multiple injuries to her

- she needed knee operation
- veh traction concern
- was heading home, was raining
- went off road at curve
- tried to avoid the mailbox
- veh flipped at fell off ditch
- she was knocked unconscious
- veh totalled by insurance
- was told to contact GM so that a rep could look at the veh
- veh still with insurance company but they are moving the veh to a location in Snowville GA
- contact Andy Stuckey (insurance company rep) for more info

Owner Specific:

Orig owner? n
Primary driver? y
Personal or business use? personal
Veh Specific:
Where purchased? Carmax/ WI
/ 2 yrs ago in Jan / 13,000
Current approx mlg? 24,000 miles
Ext Svc Plan? n

cust sks- report incident and file complaint

crs adv- doc concern and gave SR

- will update cust address since cust moved
- will get all information necessary to endorse to PAR
- advised that a person from the PAR Department will contact the customer within 2 business days."

Anette Richards/MAN/CAC T1/Emp Lvl 1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front
C49	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Side -Side Impact
S97	Insurance Company	Referred Customer to CAC

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

[Help](#)

VIN :	1G1AK58FX77
-------	-------------

VEHICLE INFORMATION

GENERAL INFORMATION											
Merchandising Model :		1AK69 -2007 COBALT 4-DOOR LS SEDAN			Warranty Start Date :		01/16/2007				
BARS Order Type :		70 - RETAIL - STOCK									
Delivering Dealer :		KENOSHA CHEVROLET 8200 120TH AVE KENOSHA , WI 53142-7334 (262) 857-4827			Selling Source :		13 - CHEVROLET				
					Site Code :		47005				
					Business Associate Code:		164674				
Service Contract :		Yes	Branded Title :		No	Warranty Block :		No	PDI Status :		Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	01/16/2007	7 miles	01/16/2010	36007 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	01/16/2007	7 miles	01/16/2013	100007 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	01/16/2007	7 miles	01/16/2015	80007 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	01/16/2007	7 miles	01/16/2012	100007 miles
36/36000 FEDERAL EMISSION	01/16/2007	7 miles	01/16/2010	36007 miles

CLAIM HISTORY

R.O Date	R.O	Type	Labor Operation	Odometer
----------	-----	------	-----------------	----------

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AK58FX...> 4/30/2009

	Number			Reading
10/25/2006	A98827	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK58FX77 [REDACTED]
-------	------------------------

CLAIM HISTORY

Repair Order Date :		10/25/2006	Repair Order Number :		A98827	Odometer Reading :		0 miles		
Serviced By :	KENOSHA CHEVROLET 8200 120TH AVE KENOSHA, WI 53142-7334 (262) 857-4827					Selling Source :		13 - CHEVROLET		
						Site Code :		47005		
						Business Associate Code :		164674		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments	
10/31/2006	739	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	N/A	N/A	N/A	\$ 95.54	N	

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=1G1AK58... 4/30/2009

GM Vehicle Inquiry System

Vehicle Build

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

[Help](#)

VIN	1G1AK58FX77
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK69 -2007 COBALT 4-DOOR LS SEDAN		
Gross Vehicle Weight Rating :	1685 kg (3715 lb)	Order Number :	KMVPK9
Build Date :	10/25/2006	Build Plant :	177A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRt PASS/CHILD PRESENCE DETECTOR
AR9 - DELUXE FRONT BUCKET SEAT	ASF - HEAD CURTAIN SIDE AIRBAGS, FRONT/REAR
AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	D36 - MIRROR I/S R/V TILT
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - FEDERAL EMISSIONS
FR6 - 3.84 FINAL DRIVE TRANSAXLE RATIO	IPB - INTERIOR TRIM DESIGN
JM4 - ANTILOCK BRAKE SYSTEM	K64 - 115 AMP GENERATOR
LOD - ASSEMBLY PLANT - LORDSTOWN,OHIO	L61 - ENGINE, 2.2L DOHC 4V ECOTEC
MM5 - 5-SPEED MANUAL TRANSMISSION	M86 - MANUAL 5 SPEED TRANSMISSION
NT7 - FEDERAL EMISSION TIER 2	N45 - 3 SPOKE STEERING WHEEL
PCW - ENHANCED SAFETY PACKAGE *HEAD CURTAIN SIDE AIRBAGS, FRONT/REAR *ANTILOCK BRAKE SYSTEM	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6K
R6P - PREMIUM PAINT	R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS
SLM - STOCK ORDERS	T43 - REAR SPOILER
UQ4 - BASE SPEAKER SYSTEM	US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER (REPLACES STD/OPT RADIO)

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK58...> 4/30/2009

VK3 - FRONT LICENSE PLATE BRACKET	VT7 - OWNERS MANUAL ENGLISH
V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	14B - GRAY
14I - GRAY	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	95U - ULTRA SILVER METALLIC

© 1998-2005 General Motors Corporation. All Rights Reserved.

CDR File Information

User Entered VIN	1G1AK58FX77
User	RYAN JAHR ESIS/GM
Case Number	670515
EDR Data Imaging Date	Thursday, June 4 2009
Crash Date	Wednesday, March 25 2009
Filename	1G1AK58FX77 ACMMARTINEZ.CDR
Saved on	Thursday, June 4 2009 at 10:55:47 AM
Collected with CDR version	Crash Data Retrieval Tool 3.2
Reported with CDR version	Crash Data Retrieval Tool 3.2
EDR Device Type	airbag control module
Event(s) recovered	None

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```

$01 08 00 00 00 00 00 00
$02 30 00 00 00 00 00 00
$03 00 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 03 0A 00 00
$07 00 20 00 00 00 00 00
$08 00 00 00 00 00 00 00
$09 00 00 00 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 0F 0F 03 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 00 00 00 00 00 00 00
$11 00 00 00 00 00 00 00
$12 00 00 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 00 00 00 00 00 00 00
$18 00 00 00 00 00 00 00
$19 00 00 00 00 00 00 00
$1B 3F 30 00 67 00 7A 00
$1C 3F 30 00 62 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 28 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 93 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 12 5D 00 00
$2F 00 FE 12 5D 00 00 00
$30 9D 00 00 00 00 00 00
$31 FF FF FF FF FF 80 00
$32 F8 80 FF 80 00 00 00
$33 FF FF FF FF FF 80 00
$34 FF FF FF FF FF 80 00
$35 FF FF FF FF FF 80 00
$36 FF FF FF FF FF 80 00
$37 F8 80 F8 0F 0F CA FE
$38 FF 80 C0 80 FF C0 FC
$39 FF FF FF FF FF 80 00
$3A FF FF FF FF FF 80 00
$3B 7F 0F 1F 1F 3F 00 00
$3C FF FF FF FF FF FF C0
$3D FF FF FF FF FF FF 00

```

```

$3E FF FF FF FF 00 00 00
$3F 00 00 F0 00 00 00 00
$40 E0 FF 00 00 00 00 00
$41 F8 F8 90 00 00 00 00
$42 80 FF FF FF FF 00 00
$43 FF FF FF 00 00 00 00
$44 FF FF FF FF FF FF 00
$45 FF FF FF FF FF FF 00
$46 FF FF FF FF FF FF 00
$47 FF FF FF FF FF FF 00
$48 FF FF FF FF FF FF 00
$49 FF FF FF FF FF FF 00
$4A FF FF FF FF FF FF 00
$4B FF FF FF FF FF FF 00
$4C FF FF FF FF FF FF 00
$4D FF FF FF FF FF FF 00
$4E FF FF FF FF FF FF 00
$4F FF FF FF FF FF FF 00
$50 FF FF FF FF FF FF 00
$51 F0 00 00 F0 00 00 00
$52 81 FF FF FF 00 00 00
$53 FF FF FF 00 00 00 00
$54 82 FF FF 00 00 00 00
$55 FF FF FF FF FF FF 00
$67 A0 FF 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 32 39 34 39 52 36 32 30 36 31 34 48 48 43
$02 41 0A 99 B3
$03 41 54 32 39 34 39 52 36 32 32 34 31 34 4E 44 46
$04 41 0A 99 B3
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 32 34 39 33 45 43 36 48
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 06 32 37 39 39 4A 45 55
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A
$22 39 14
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

\$26 32 41 FA FA FA FA FA
\$40 00 00
\$41 3F 30 00 62 00 1A
\$42 D0 C4
\$43 00 00 8E 80
\$44 C6 00 00 FC C0 C0
\$45 07 01 07 01 05 01
\$46 FF 1B 1B 64 28
\$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
\$48 18 08 08
\$B0 58
\$B1 FD FE 00
\$B2 FF FF FF FF FF
\$B4 41 53 33 39 31 34 32 32 30 36 32 55 20 20 20 20
\$B7 50 AA 04 0F 07
\$B8 43 48 70 02 09
\$C1 30 46 30 37
\$CA 30 46 30 37
\$CB 01 89 6E 6A
\$CC 01 89 6E 6A
\$D1 00 00
\$DB 00 00
\$DC 00 00

Comments

CONNECTION: DLC VEHICLE HAS POWER

MILEAGE: 24735

LAMP TEST: NO KEY FOR VEHICLE

LOCATION: IAA LOGANVILLE GA

PRESENT: RYAN JAHR ESIS/GM

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.