


EWR D&I ANNOTATION



FAN-000001L093001DP171-9156

Artemis # : 000001L093001DP171**Record Created Date :** 09/21/2010**Printed Date :** 09/23/2010**Description :**

DI10-006 SEQUENCE ID 171 A SERVICE REQUEST DETAIL REPORT FROM GM DETAILS A CUSTOMER COMPLAINT OF AIRBAG NON-DEPLOYMENT ON A 2007 CHEVROLET HHR. THE VEHICLE WAS INVOLVED IN A TWO CAR COLLISION THAT RESULTED IN INJURIES TO BOTH OCCUPANTS AND SERIOUS DAMAGE TO THE VEHICLE. THE CALLER STATES THAT HIS WIFE WAS DRIVING WHEN A VEHICLE ENTERED HER LANE. SHE SWERVED TO AVOID A HEAD ON COLLISION AND IN THE PROCESS STRUCK A DIFFERENT VEHICLE. NO SPECIFICS ARE GIVEN REGARDING THIS COLLISION. NONE OF THE AIRBAGS IN THE HHR DEPLOYED; BOTH THE DRIVER AND PASSENGER WERE INJURED AND TAKEN TO THE EMERGENCY ROOM. THE DRIVER SUFFERED FROM A CHEST AND HEAD CONTUSION AND HEAD TRAUMA. THE PASSENGER WAS TREATED FOR HEAD TRAUMA, AND BRUISING OF THE RIGHT HIP. THE PASSENGER ALSO BIT HER TONGUE AND HIT HER CHIN. THE DAMAGE TO THE HHR WAS ENOUGH TO DECLARE IT TOTALED. THE FRONT END WAS SMASHED, THE FRAME BENT, AND SOME OF THE MOTOR MOUNTS WERE BROKEN. ALSO PROVIDED IS A LETTER FROM GM TO THE VEHICLE'S OWNER REJECTING A REQUEST FOR DAMAGES. THE VEHICLE WAS INSPECTED AND AN EDR REPORT IS PROVIDED. THE MAX SDM RECORDED VELOCITY CHANGE IS LISTED AS 23.73MPH. THERE ARE TWO VOQS REGARDING AIRBAG NON-DEPLOYMENT IN COLLISIONS. NO APPLICABLE RECALLS WERE FOUND. THERE ARE TWO AIRBAG RELATED TSBS FOR THIS VEHICLE. THESE BOTH ADDRESS AIRBAG WARNING LIGHTS, ONE POSSIBLY DUE TO A LOOSE CONNECTION THE OTHER REGARDING THE PASSENGER AIRBAG SUPPRESSION. THERE IS NO INDICATION OF AN AIRBAG WARNING LIGHT PRIOR TO OR DURING THIS COLLISION. THERE ARE SEVERAL FIELD REPORTS REGARDING AIRBAG NON-DEPLOYMENT. *RC

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

July 6, 2010

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-006

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 6, 12, 13, 14, 15, 16, 17, 46, 47, 50, 60, 61, 93, 103, 105, 106, 115, 119, 129, 132, 135, 147, 161, 171, 185, 186, 187, 188, 189, 190, 192, 193, 194, 215, 231, 239, 242, 271, 278, 281, 297, 321, 326, 342, 344, 349, 350, 352, 355, 375, 384, 386, 450, 451, 452, 462, 467, 471, 478, 495	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **August 6, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

AUG 18 2010

August 17, 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-006

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated July 6th, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2009.

GM's response is comprised of 62 disks for the incidents that are the subject of DI10-006.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 48649735-678866 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 48649735-678866_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-006
6 48649735-678866
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 6 48649735-678866 **_01_001** - is the first document responsive to Inquiry no. 1.
 6 48649735-678866 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-006, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(60 Vehicles from the Light Vehicle Template)			
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)		TYPE
6	5GAER23D19J		NISM
12	1G4HD57267U		NISM
13	1G4HD57287U		NISM
14	1G4HE57Y48U		NISM
15	1G4HD57278U		NISM
16	1G4HD57218U		NISM
17	1G4HD57248U		NISM
46	1G6DT57V380		NISM
47	1G6DF577880		NISM
50	1G6DS57V890		NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
60	1G6KD57Y17U [REDACTED]	NISM
61	1G6KD57947U [REDACTED]	NISM
93	KL1TJ58Y05B [REDACTED]	NISM
103	KL1TD66E09B [REDACTED]	NISM
105	KL1TD56E19B [REDACTED]	NISM
106	2G1FC1EV0A9 [REDACTED]	NISM
115	1G1AK55F267 [REDACTED]	PAR
119	1G1AK15F967 [REDACTED]	NISM
129	1G1AK55F677 [REDACTED]	NISM
132	1G1AK58F887 [REDACTED]	NISM
135	1G1AM58B187 [REDACTED]	NISM
147	1G1YY26W185 [REDACTED]	LIT
161	2CNFLGEYXA6 [REDACTED]	NISM
171	3GNDA13D57S [REDACTED]	NISM
185	2G1WF52E349 [REDACTED]	NISM
186	2G1WF52E659 [REDACTED]	NISM
187	2G1WH52K359 [REDACTED]	NISM
188	2G1WF52E859 [REDACTED]	NISM
189	2G1WF52E659 [REDACTED]	NISM
190	2G1WF52E359 [REDACTED]	NISM
192	2G1WC581469 [REDACTED]	NISM
193	2G1WB58K669 [REDACTED]	NISM
194	2G1WB58K069 [REDACTED]	NISM
215	2G1WB5ENXA1 [REDACTED]	NISM
231	1G1ZG57BX84 [REDACTED]	NISM
239	1G1ZH57B69F [REDACTED]	NISM
242	1G1ZK57749F [REDACTED]	NISM
271	2GCEK19T541 [REDACTED]	NISM
278	1GCEK19C47Z [REDACTED]	NISM
281	2GCEK19J171 [REDACTED]	NISM
297	1GCHK73K79F [REDACTED]	NISM
321	1GNEC13T75R [REDACTED]	LIT
326	2CNBJ13C036 [REDACTED]	NISM
342	1GNDT13S142 [REDACTED]	NISM
344	1GNDT13S042 [REDACTED]	NISM
349	1GNDT13S852 [REDACTED]	NISM
350	1GNDT13S352 [REDACTED]	NISM
352	1GNDT13S362 [REDACTED]	NISM
355	1GNDS13SX62 [REDACTED]	NISM
375	1GNDV23178D [REDACTED]	PAR
384	1GKER137X8J [REDACTED]	NISM
386	1GTDS43E888 [REDACTED]	LIT
450	1G2AL18H797 [REDACTED]	NISM
451	1G2AS18H197 [REDACTED]	NISM
452	1G2AS18H297 [REDACTED]	NISM
462	1G2ZH57N784 [REDACTED]	NISM
467	1G2ZG57N994 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
471	1G2ZM577194 [REDACTED]	PAR
478	2G2WP552061 [REDACTED]	LIT
495	1G8ZS57B49F [REDACTED]	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 62 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI10-006
171 283702195 – 677229
2007 CHEVROLET HHR

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. 71-749059263	Ref No.	Goodwill No Goodwill Offered	BRC Type PAR
Account	Site	GW SubType	Bus. Unit BRC
Last Name	First Name	Approval Not Initiated	Area PAR
Daytime #	Evening #	UCC Restraints - (SIR) - Driver Front	Sub-Area Initiate PAR- Injury
Address	City San Antonio	Involved Dir	Safety Yes
State TX ZipCd	Con Acct	Source Phone	Updated 8/12/2009 06:37:01 PM
Serial #/VIN 3GNDA13D57S	Model Year 2007	Priority Medium License # CHEVROL	Owner GARCIAJR
Make Chevrolet	Warr. Start 10/27/2006	Status Open	Opened 8/11/2009 07:30:24 PM
Model HHR	Mileage 25000	Sub-Status Dissatisfied	Closed
Abstract Non-deployment - 07 Chevrolet HHR			
Customer Description This is a BRC PAR Case. Do not assume case. Forward any inquiries to Joe Garcia at ext 11291.			

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	8/7/2009 03:37:28 PM	Y	1		Concrete	Dry		
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'5"		Glasses				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
N/A	N/A	(800) 861-8380	Gayco Insurance Co.					
Incident Loc	Residential street in San Antonio, TX				Incident Desc	wife with my daughter was driving veh last Friday when another veh drove in her lane; to prevent head on collision, she swerved the veh and hit another car		
Component	Both Frontal Airbags				Damage Desc	Veh was totalled		
Vehicle Loc	At the body shop of Caliber Collision				Add'l Info	N/A		
Emgcy Svc Names	N/A				Maint Loc	N/A		

PAR Detail

Collision	Y	Non Collision		Property Damage	N	Thermal Evt	N	Spec Equip	none
Vehicle Speed	45	Weather Condition	clear	Prop Owner	n/a	Property Type	n/a	Prop Est Repair Cost	\$0.00
Last Service Date		Loc Last Service		Property Location	n/a	Prop Damage Description	n/a	Inspected By	Inspection Not Performed
Veh Est Repair Cost	\$0.00	Spec Equip Installer	n/a	Inspected By	Inspection Not Performed	Inspection Date/Time			
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Explain Other	being sent to ESIS				
Veh Damage Description frt end dmg smashed in, frame bent, motor mounts broken - totalled									

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelts
Injury Description			Medical Rpt#		Treatment Location	Treated By
Chest and head contusion and head trauma			unk		Santa Rosa Hospital in West Hills	ER doctor
Street Address			City		State	Zip Code

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	Seatbelts
Injury Description			Medical Rpt#		Treatment Location	Treated By
Head trauma / blood spot in the head - rt injury injury and bruising to rt hip, hit chin and bit tongue			unk		Santa Rosa Hospital in West Hills and then transferred to another hospital	ER doctor
Street Address			City		State	Zip Code

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 06:50:30 PM	GARCIAJR	GARCIAJR	Scheduled Follow-up		Scheduled Alarm		waiting for ESIS to pick up

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 06:47:44 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Chest and head contusion and head trauma
- Head trauma / blood spot in the head - rt injury injury and bruising to rt hip, hit chin and bit tongue

Joe G/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 03:26:25 PM	GARCIAJR	GARCIAJR	Ownership Changed	Ownership Escalated to BRC	Done	8/12/2009 03:26:25 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:07:43 AM	KINZERTH	GARCIAJR	Ownership Changed		Done	8/12/2009 10:07:43 AM	Service Request Ownership has changed FROM: LOPEZKA TO: GARCIAJR

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:07:24 AM	KINZERTH	GARCIAJR	BRC PAR	Initial Contact- AVM	Done	8/12/2009 04:01:04 PM	I/m for DVM, Chard Christense

Contact Last Name	Contact First Name	Account	BAC Code

Comments

DCM: Chad Christensen
Node: 972075
Mailbox: 8091

Calling to provide heads-up/FYI on cust's product allegation case.

Joe G/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:07:13 AM	KINZERTH	GARCIAJR	BRC PAR	Initial Contact- Dealer	Done	8/12/2009 04:10:25 PM	Vara Chevrolet (l/m for svc dept)
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Called dlr @ (210) 924-2000.

Calling to get any details that may be related to cust's product allegation case.

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:07:03 AM	KINZERTH	GARCIAJR	BRC PAR	Initial Contact- Phone	Done	8/12/2009 06:44:23 PM	made initial ct w/cust
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Called daytime phone #.

Crm stated calling to f/u w/cust re the product allegation case, understand that veh was involved in a collision where the airbags did not deploy.

Cust stated that is correct, was going approx 45 mph when had to swerve to avoid a veh but hit another veh in the frt. Cust stated the veh was totaled and his wife and stepdaughter suffered injuries that required hospitalization.

Crm verifd pre-par & par detail screen info.

Crm also advised that will need to refer this file to our central claim dept, they will f/u w/cust w/in 7-10 business days.

Cust stated that is fine.

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:55 AM	KINZERTH	GARCIAJR	BRC PAR	Acknowledgement	Done	8/12/2009 06:35:04 PM	acknowledgement made
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

see initial ct w/cust

Joe G/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:47 AM	KINZERTH	GARCIAJR	Notify CRM		Done	8/12/2009 01:53:05 PM	File Assigned
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:38 AM	KINZERTH	GARCIAJR	Research		Done	8/12/2009 01:55:49 PM	Research VIN
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Summary:

Repairs - no related repairs

Recalls - 08016 HEAD IMPACT PROTECTION - INCREASED PROTECTION, not related to allegation

SR's - no other files for this veh

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:22 AM	KINZERTH	GARCIAJR	BRC PAR	Case Assigned	Done	8/12/2009 01:53:01 PM	Assigned to Joe Garcia x1 1291
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:14 AM	KINZERTH	LOPEZKA	SR Opened		Done	8/12/2009 10:06:14 AM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2009 10:06:13 AM	KINZERTH	LOPEZKA	SR Closed - Satisfied		Done	8/12/2009 10:06:13 AM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/11/2009 07:43:22 PM	LOPEZKA	KINZERTH	Escalation	Initiate PAR	Done	8/12/2009 10:06:09 AM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

CRS advised that a person from the PAR Department will contact the customer within 5* business days

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/11/2009 07:36:54 PM	LOPEZKA	LOPEZKA	SmartScript	SmartScript Finished	Done	8/11/2009 07:36:54 PM	CAC SmartScript - Tier 1
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

The CAC Tier 1 SmartScript was finished by LOPEZKA

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/11/2009 07:36:54 PM	LOPEZKA	LOPEZKA	SmartScript	SmartScript Decision	Done	8/11/2009 07:37:05 PM	CAC SmartScript - Tier 1 - Decision
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Complete the Pre-PAR form in Siebel and escalate to PAR. CRS Notes: (1)Refer to Service Center for process.

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/11/2009 07:36:48 PM	LOPEZKA	LOPEZKA	Inbound Call Customer	Complex Request	Done	8/11/2009 07:37:01 PM	Inbound Call from Customer - SmartScript
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CUST STS:

=wife with my daughter was driving veh last Friday when another veh drove in her lane; to prevent head on collision, she swerved the veh and hit another car
=both frontal airbags did not deploy and both my wife and daughter had a head trauma
=2007 HHR with 25000 miles
=veh is about to be totalled by the insurance company; veh's currently at the body shop of Caliber Collision

CUST SKS:

=assistance

CRS ADV:

=apologized
=gathered pertinent info
=CRS advised that a person from the PAR Department will contact the customer within 5* business days

CUST STS:

=ok, thanks

Karen Lopez/Man/CAC T1/Lvl 1

Cust has PAR situation.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/11/2009 07:31:19 PM	LOPEZKA	LOPEZKA	SmartScript	SmartScript Started	Done	8/11/2009 07:31:19 PM	CAC SmartScript - Tier 1
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

The CAC Tier 1 SmartScript was started by LOPEZKA

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front

GM Vehicle Inquiry System

Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

[Help](#)

VIN :	3GNDA13D57S
-------	-------------

VEHICLE INFORMATION

VEHICLE INFORMATION										
Merchandising Model :		1AT46 -2007 CHEVROLET HHR LS			Warranty Start Date :		10/27/2006			
BARS Order Type :		50 - FLEET								
Delivering Dealer :		WALDEN FLEET GROUP 500 FORD RD MINNEAPOLIS , MN 55426-1134 (952) 944-7885			Selling Source :		13 - CHEVROLET			
					Site Code :		04684			
					Business Associate Code :		111571			
Service Contract :		No	Branded Title :		No	Warranty Block :		No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	08016	HEAD IMPACT PROTECTION - INCREASED PROTECTION	03/25/2008	Open
RC	08157	INSTRUMENT PANEL STORAGE BIN DOOR COMPLIANCE - ADD REINFORCEMENT BRACKET	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	10/27/2006	10 miles	10/27/2009	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	10/27/2006	10 miles	10/27/2012	100010 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	10/27/2006	10 miles	10/27/2011	100010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	10/27/2006	10 miles	10/27/2014	80010 miles
36/36000 FEDERAL EMISSION	10/27/2006	10 miles	10/27/2009	36010 miles

CLAIM HISTORY

--	--	--	--

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=3GNDA13D5...> 8/13/2009

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
12/10/2007	016579	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	9490 miles
11/26/2007	002408	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	10 milcs
09/26/2007	011691	#	E7700 - SHAFT, STEERING INTERMEDIATE - REPLACE	5852 miles
09/26/2007	011691	#	E2020 - WHEEL ALIGNMENT MEASUREMENT	5852 miles
09/26/2007	011691	#	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMEN	5852 miles
07/31/2007	007636	#	E7680 - STEERING COLUMN REPLACEMENT	3569 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) -
[Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	3GNDA13D57S [REDACTED]
--------------	------------------------

CLAIM HISTORY

Repair Order Date :		12/10/2007		Repair Order Number :		016579		Odometer Reading :		9490 miles	
Serviced By :	VARA CHEVROLET PO BOX 240850 SAN ANTONIO, TX 78224-0850 (210) 924-2000					Selling Source :		13 - CHEVROLET			
						Site Code :		30443			
						Business Associate Code :		114907			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments		
01/08/2008	863	01	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	N/A	N/A	N/A	\$ 65.82	N		

Repair Order Date :		11/26/2007		Repair Order Number :		002408		Odometer Reading :		10 miles	
Serviced By :	JIM DUNWORTH INC. 8927 INTERNATIONAL/AIRPORT SECURITY PARKING SAN ANTONIO, TX 78216					Selling Source :		13 - CHEVROLET			
						Site Code :		48795			
						Business Associate Code :		228833			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments		
11/30/2007	852	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	N/A	N/A	N/A	\$ 56.58	N		

Repair Order Date :		09/26/2007		Repair Order Number :		011691		Odometer Reading :		5852 miles	
Serviced By :	VARA CHEVROLET PO BOX 240850 SAN ANTONIO, TX 78224-0850 (210) 924-2000					Selling Source :		13 - CHEVROLET			
						Site Code :		30443			
						Business Associate Code :		114907			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments		
				E7700 - SHAFT,							

http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=3GNDA1... 8/13/2009

10/02/2007	835	01	#	STEERING INTERMEDIATE - REPLACE	22730246 - SHAFT KIT	B	N/A	\$ 142.43	N
10/02/2007	835	02	#	E2020 - WHEEL ALIGNMENT MEASUREMENT	N/A	N/A	N/A	\$ 51.19	N
10/02/2007	835	03	#	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMEN	N/A	N/A	N/A	\$ 87.76	N

Repair Order Date :		07/31/2007		Repair Order Number :		007636		Odometer Reading :		3569 miles	
Serviced By :		VARA CHEVROLET PO BOX 240850 SAN ANTONIO, TX 78224-0850 (210) 924-2000				Selling Source :			13 - CHEVROLET		
						Site Code :			30443		
						Business Associate Code :			114907		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/10/2007	820	01	#	E7680 - STEERING COLUMN REPLACEMENT		15806195 - COLUMN KI		N/A	N/A	\$ 745.44	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System

Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	3GNDA13D57S
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AT46 -2007 CHEVROLET HHR LS		
Gross Vehicle Weight Rating :	1925 kg (4245 lb)	Order Number :	KJNJQW
Build Date :	10/26/2006	Build Plant :	37SA

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AL0 - SENSOR INDICATOR,FRT PASS/CHILD	AR9 - FRONT BUCKET SEATS,DELUXE
AT8 - RESTRAINT CHILD PROVISIONS	AXP - MPV VIN IDENT POSITION
B8T - GM PRODUCTION WEEK #44	CAP - COMPETITIVE ASSISTANCE PROGRAM
C2Y - GVW RATING 4,240 LBS	C67 - AIR CONDITIONING
D22 - MIRROR,O/S ELECT REMOTE CNTRL	E2C - ORDER TO DELIVERY - EXPEDITE
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - 50-STATE EMISSIONS
FLT - FLEET PROCESSING OPTION	FX2 - 3.91 AXLE RATIO
IPB - TRIM INTERIOR DESIGN (PB)	J41 - PWR BRAKE SYSTEM
L61 - 4 CYL 2.2L MFI DOHC	MN5 - 4 SPD AUTO TRANSMISSION, HMD
MX0 - TRANSMISSION, 4 SPD AUTOMATIC	NT7 - FEDERAL EMISSION SYSTEM TIER 2
N24 - STEERING WHEEL, 3 SPOKE	QB5 - 16" X 6.5" WHEELS
QDB - TIRE, P215/55R16-91S BW ST AL2	R6F - IDENTIFY B CODE USERS
R6K	R6P - PREMIUM PAINT
R9N - LEATHER SEAT TRIM	SAL - RAMOS ARIZPE, MEXICO PLANT CODE
UW5 - 6 SPEAKER SYSTEM	U1C - AM/FM STEREO RADIO/COMPACT DISC ELECTRONICALLY TUNED AM/FM STEREO RADIO W/SEEK,TONE SELECT, COMPACT DISC PLAYER, DIGITAL CLOCK AND 4 SPEAKERS
VK3 - FRONT LICENSE PLATE BRACKET	VQ2 - FLEET ORDERING AND ASSISTANCE
VT7 - OWNERS MANUAL ENGLISH	V2G - FULL FUEL FILL CREDIT
V73 - STATEMENT OF VEHICLE CERT.-	

http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=3GNDA1... 8/13/2009

U.S. /CANADA	1LS - LS PACKAGE
1SZ - SUN AND FUN EDITION PACKAGE DISCOUNT	14B - GRAY CLOTH
14I - GRAY INTERIOR TRIM	2K1 - FLT-JIM DUNWORTH INC
6AE - FRONT SPRING	67U - SILVERSTONE METALLIC
7AE - FRONT SPRING	

© 2009 General Motors. All Rights Reserved.

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Yvette Young
Claims Administrator

November 30, 2009

[REDACTED]
San Antonio TX [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: 677229
Our Client: General Motors LLC
Date/Event: 8/7/09
Vehicle: 2007 Chevrolet HHR
VIN: 3GNDA13D57S [REDACTED]

Dear [REDACTED]

This will confirm that we have completed our review of your claim regarding your Chevrolet HHR. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Yvette Young
Claims Administrator

CDR File Information

User Entered VIN	3GNDA13D57S
User	Ronald R Marquis
Case Number	677229
EDR Data Imaging Date	Monday, September 28 2009
Crash Date	Friday, August 7 2009
Filename	3GNDA13D57S ACM.CDR
Saved on	Monday, September 28 2009 at 10:22:26 AM
Collected with CDR version	Crash Data Retrieval Tool 3.3
Reported with CDR version	Crash Data Retrieval Tool 3.3
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

-Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

-Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.

-The Belt Switch Circuit is wired directly to the SDM.

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**NDA13D*7*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Fourth Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	77
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	35	35	35	37	39
Engine Speed (RPM)	1088	1728	2368	2496	2496
Percent Throttle	11	30	39	41	41
Accelerator Pedal Position (percent)	0	7	14	17	15
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	3833
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	2989
Ignition Cycles At Event	3826
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	BUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Not Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	23.73
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	170
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-1.36	-2.71	-4.07	-5.42	-8.13	-10.85	-12.88	-14.91	-16.95	-18.98	-21.01	-22.37	-23.05	-23.05	-23.05
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-23.05	-23.72	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	-0.68	-0.68	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 00 00 00 00 52 00 00
$02 30 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 00 0A 36 33
$07 00 09 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 8D 8D 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 01 0F 00 00 00
$0C 80 00 80 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F A2 00 00 00 00 00 00
$10 47 4E 44 41 31 33 44
$11 35 37 53 35 36 38 31
$12 36 31 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 03 03 02 02 00 00 00
$18 02 02 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 01 00 00 4F 00 01 00
$1F 33 C1 00 00 00 23 00
$20 40 00 00 00 00 00 00
$21 FF FF 00 00 50 00 00
$22 00 8D 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 80 00 9E 00 07 00 00
$2F 00 FE 0E F9 07 00 00
$30 9D 00 00 00 00 00 00
$31 26 2C 24 12 00 00 00
$32 00 00 00 00 00 00 00
$33 69 69 64 4D 1D 00 00
$34 27 27 25 1B 11 00 00
$35 3E 3B 39 39 39 00 00
$36 00 00 00 00 00 00 00
$37 00 00 00 04 04 00 E2
$38 82 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 4E 44 41 31 33 44 00
```

```

$3E 37 56 81 61 00 00 00
$3F 00 00 90 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 0B AD 00 00
$43 FE 0E F2 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 FE 00 FC 00 FA 00
$48 00 F8 00 F4 00 F0 00
$49 FF ED FF EA FF E7 00
$4A FF E4 FF E1 FF DF 00
$4B FF DE FF DE FF DE 00
$4C FF DE FF DD 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 F0 00 00 00 00 00 00
$52 01 00 00 00 00 00 00
$53 11 04 CA 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 36 37 35 37 52 36 32 32 33 32 37 32 36 4E
$0E 01 5A A1 55
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 37 34 33 34 56 31 06 32 36 38 38 59 5A 4D
$14 01 5A 8B E0
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 3F F5 91 9A
$22 36 33
$23 FA FA FA FA FA FA FA
$24 FA FA FA FA FA FA FA
$25 FA FA FA FA FA FA FA

```

\$26 FA FA FA FA FA FA FA
\$40 00 00
\$41 3F 00 00 02 00 1A
\$42 D0 C2
\$43 00 00 8E 80
\$44 C2 00 00 FC C0 C0
\$45 07 01 07 01 05 01
\$46 55 0E 0E 64 64
\$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
\$48 18 08 08
\$B0 58
\$B1 FD FE 00
\$B2 FF FF FF FF FF
\$B4 41 53 33 36 33 33 32 32 31 31 30 37 20 20 20 20
\$B7 50 AA 04 0F 07
\$B8 43 54 69 03 18
\$C1 30 46 30 37
\$CA 30 46 30 37
\$CB 01 89 6D 51
\$CC 01 89 6D 51
\$D1 00 00
\$DB 00 00
\$DC 00 00

Comments

Download performed at IIA, 10475, Somerset Road, San Antonio, TX

Download via dlc

No One Present at download

Power supply for download via vehicle own Power supply

Milage: 34878

Airbag light 34878 one and remained solid

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.