


EWR D&I ANNOTATION



FAN-000001L101001DP125-2979

Artemis # : 000001L101001DP125**Record Created Date :** 01/05/2011**Printed Date :** 01/05/2011**Description :**

DI10-062 SEQUENCE 125 GENERAL MOTORS 1 INJURY 2006 CHEVROLET COBALT A SINGLE VEHICLE CRASH OCCURRED IN A CALIFORNIA PARKING LOT. THE DRIVER WAS PICKING UP A FRIEND AND WAITING IN THE PARKING LOT FOR HER TO COME OUT. ONCE THE PASSENGER ENTERED THE VEHICLE THE DRIVER RELEASED THE BRAKE AND SHIFTED THE GEAR INTO DRIVE. THE VEHICLE EXPERIENCED SUDDEN ACCELERATION. THE DRIVER LOST CONTROL OF THE CAR AND STRUCK THE SIDE OF A BUILDING. THE SHORT DISTANCE THE VEHICLE TRAVELED IT DAMAGED A TREE AND SOME CHAIRS INSIDE THE BUILDING. THE DRIVER DID NOT SUSTAIN ANY INJURIES BUT THE PASSENGER HAD 2 BROKEN ARMS. THE INSURANCE COMPANY TOTALED THE CAR. NO SIMILAR FIELD REPORTS, VOQS, OR TSBS. *AA



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 16, 2010

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-062

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 16, 34, 38, 53, 67, 77, 91, 94, 113, 114, 125, 151, 167, 172, 173, 183, 195, 196, 208, 217, 225, 231, 253, 261, 267, 268, 285, 286, 293, 320, 323, 357, 365, 409, 410, 451, 506, 516, 539, 540, 585	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the

information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 15, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

October 13, 2010

OCT 15 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-062

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 16, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2010.

GM's response is comprised of 41 disks for the incidents that are the subject of DI10-062.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 16 298093428-690125 and 2005 BUICK RAINIER. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 16 298093428-690125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-062
16 298093428-690125
2005 BUICK RAINIER

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

16 298093428-690125_01_001- is the first document responsive to Inquiry no.1.
 16 298093428-690125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-062, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(41 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
16	5GADT13S552 [REDACTED]	NISM
34	1G6DP577760 [REDACTED]	NISM
38	1G6DP57V680 [REDACTED]	NISM
53	1GYFK43569R [REDACTED]	NISM
67	1G6DK67V490 [REDACTED]	NISM
77	KL1TD52695B [REDACTED]	LIT
91	2G1FK1EJ3A9 [REDACTED]	NISM
94	2G1FB1EV4A9 [REDACTED]	NISM
113	1G1AM58B367 [REDACTED]	NISM
114	1G1AK55F667 [REDACTED]	NISM
125	1G1AK55F767 [REDACTED]	PAR
151	1G1AL55FX77 [REDACTED]	NISM
167	1G1AL58F787 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
172	1G1AT58H497 [REDACTED]	NISM
173	1G1AT58H797 [REDACTED]	NISM
183	1G1AG1FX3A7 [REDACTED]	NISM
195	1GCDT19E898 [REDACTED]	NISM
196	1G1YY32G935 [REDACTED]	NISM
208	2CNDL13F576 [REDACTED]	PAR
217	1GCFG15X481 [REDACTED]	NISM
225	3GNCA33D28S [REDACTED]	NISM
231	3GNBABDB4AS [REDACTED]	NISM
253	2G1WB55K379 [REDACTED]	NISM
261	2G1WB58K789 [REDACTED]	NISM
267	2G1WT57K491 [REDACTED]	NISM
268	2G1WC57M091 [REDACTED]	NISM
285	1G1ZH57B384 [REDACTED]	NISM
286	1G1ZJ57B28F [REDACTED]	LIT
293	1G1ZH57B39F [REDACTED]	NISM
320	1GCEC19X17Z [REDACTED]	NISM
323	3GCEC13J48G [REDACTED]	NISM
357	1GNFK13J57J [REDACTED]	NISM
365	1GNFK13559R [REDACTED]	NISM
409	1GNEV23D19S [REDACTED]	NISM
410	1GNLRHED5AS [REDACTED]	NISM
451	1GTEK19047Z [REDACTED]	NISM
506	1G2ZG57B994 [REDACTED]	NISM
516	1G2NW52EX2M [REDACTED]	NISM
539	5Y2SP67019Z [REDACTED]	NISM
540	5Y2SM67079Z [REDACTED]	PAR
585	5GZCZ53477S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.


GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read "M. Carmen Benavides". The signature is fluid and cursive, with the first name "M." and last name "Benavides" clearly distinguishable.

M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 41 Disks
Attachment A

Attachment A


Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.




Selected Death Incidents from the
 3rd Quarter 2004
 For Reporting Category: Light Vehicles


(c) Vallen-Systeme GmbH, www.vallen.de/freeware



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI10-062
125 299569497 – 71-801365697
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Documents. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. [REDACTED]	Ref No. [REDACTED]	Goodwill	No Goodwill Offered	BRC Type	PAR
Account [REDACTED]	Site [REDACTED]	GW SubType		Bus. Unit	BRC
Last Name [REDACTED]	First Name [REDACTED]	Approval	Not Initiated	Area	PAR
Daytime # [REDACTED]	Evening # [REDACTED]	UCC	Engine - Throttle Linkage/Pedal	Sub-Area	Initiate PAR- Injury
Address [REDACTED]	City Downey	Involved Dir		Safety	Yes
State CA ZipCd [REDACTED]	Con Acct	Source	Email	Updated	2/15/2010 12:12:52 PM
Serial #/VIN 1G1AK55F767 [REDACTED]	Model Year 2006	Priority	Medium License #	Owner	KINZERTH
Make Chevrolet	Warr. Start 09/08/2005	Status	Open	Opened	2/8/2010 06:07:08 AM
Model Cobalt	Mileage 60000	Sub-Status	Satisfied	Closed	
Abstract Unwanted Acceleration - Collision w/Injuries					
Customer Description This is a BRC-PAR case / do not assume / forward all inquiries to Thaddeus Kinzer x41039					

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	12/30/2009 02:30:00	Y	0	1	Concrete	Dry	n/a	unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
[REDACTED]	[REDACTED]	5'2"	[REDACTED]	None				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
NA	NA	(800) 920-5798	Auto Club of California					
Incident Loc	parking lot of YMCA Bldg, Downey Ave, Downey CA				Incident Desc	- my car was stopped with the gear in Park and my foot on the brakes		
Component	gas pedal - unwanted acceleration				Damage Desc	car totalled		
Vehicle Loc	customer's driveway				Add'l Info	n/a		
Emgcy Svc Names	Downing Police Department				Maint Loc	independent		

PAR Detail

Collision	Y	Non Collision	N	Property Damage	Y	Thermal Evt	N	Spec Equip	None	
Vehicle Speed	0			Weather Condition	clear			Prop Owner	YMCA	Property Type side of building
Last Service Date				Loc Last Service				Property Location	Downing YMCA	Prop Est Repair Cost
Veh Est Repair Cost				Spec Equip Installer	n/a			Prop Damage Description	damage to side of building where vehicle hit - was covered by insurance	
Primary Veh Use	Personal			Inspection Type	Accelerator/Throttle Systems			Inspected By	Inspection Not Performed	Inspection Date/Time
Veh Damage Description	front end crushed in							Explain Other	file forwarded to ESIS	

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	Seatbelt
Injury Description	Medical Rpt#	Treatment Location	Treated By			
2 broken arms	unknown	Kaiser Hospital, Downey CA	ER doctor			
Street Address	City	State	Zip Code			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 12:11:06 PM	MARTIRAM	ESISBIQU	Escalation	ESIS - Injuries	In Progress		ESIS - Injuries
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Injuries	2 broken arms						

Ramiro/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 11:19:28 AM	KINZERTH	KINZERTH	Scheduled Follow-up		Scheduled Alarm		ESIS
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 11:18:23 AM	KINZERTH	MARTIRAM	Notify CRM		Done	2/15/2010 12:09:04 PM	ESIS - Injuries & Property Damage
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Customer claims unwanted acceleration resulted in collision							
Customer's front passenger was treated for injuries - 2 broken arms							
Property damage consists of damage to the building that customer's vehicle struck							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 10:25:54 AM	KINZERTH	KINZERTH	Ownership Changed	Ownership Escalated to BRC	Done	2/15/2010 10:25:55 AM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:32:21 AM	MARTIRAM	KINZERTH	Ownership Changed		Done	2/15/2010 09:32:21 AM	Service Request Ownership has changed FROM: LAGDAMCL TO: KINZERTH

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:54 AM	MARTIRAM	KINZERTH	BRC PAR	Initial Contact- AVM	Done	2/15/2010 11:18:22 AM	DVM Name Paul Byrne

Contact Last Name	Contact First Name	Account	BAC Code

Comments

The request number is [REDACTED]
The customer's name is [REDACTED]
The vehicle is a (year / make / model) 2005 Chevrolet Cobalt
The last 8 of the VIN are 67 [REDACTED]
The concern involved is Customer claims unwanted acceleration resulted in collision

Thaddeus Kinzer/PAJ/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:52 AM	MARTIRAM	KINZERTH	BRC PAR	Initial Contact- Dealer	Done	2/15/2010 10:26:28 AM	No initial contact required - vehicle has not been to dealer in two years
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
No initial contact required - vehicle has not been to dealer in two years							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:48 AM	MARTIRAM	KINZERTH	BRC PAR	Initial Contact- Phone	Done	2/15/2010 11:14:22 AM	Called
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Spoke with customer							

- * Customer claims unwanted acceleration caused collision
- * Verified pre-par and completed par detail interview
- * Customer states that vehicle was stopped in parking spot, when she took her foot off the brakes and shifted vehicle into drive the vehicle accelerated on its own and she could not control it, vehicle struck side of a building
- * Customer states she was uninjured however her front passenger's arms were both broken - customer does not have address or phone number for her friend available
- * Side of the building that vehicle struck was damaged - customer does not have specific address or repair cost available
- * Customer's insurance covered the medical expenses and property damage but did not cover her vehicle
- * Vehicle is currently at customer's home address, no repairs or repair estimate
- * Advised customer file would be forwarded to ESIS
- * Provided contact information

Thaddeus Kinzer/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:40 AM	MARTIRAM	KINZERTH	BRC PAR	Acknowledgement	Done	2/15/2010 11:00:53 AM	Called
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Initial completed during acknowledgment							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:35 AM	MARTIRAM	KINZERTH	Notify CRM		Done	2/15/2010 09:42:00 AM	File Assigned

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:29 AM	MARTIRAM	KINZERTH	Research		Done	2/15/2010 09:45:13 AM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Open Recalls:None
Related Repairs:None
Previous SRs:None

Thaddeus Kinzer/PAJ/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:30:05 AM	MARTIRAM	KINZERTH	BRC PAR	Case Assigned	Done	2/15/2010 09:42:15 AM	Assigned to Thaddeus Kinzer x41039

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:29:57 AM	MARTIRAM	LAGDAMCL	SR Opened		Done	2/15/2010 09:29:58 AM	SR in Status of Closed has been Re-Opened by MARTIRAM

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 09:29:56 AM	MARTIRAM	LAGDAMCL	SR Closed - Dissatisfied		Done	2/15/2010 09:29:56 AM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 08:14:02 AM	LAGDAMCL	LAGDAMCL	Scheduled Outbound Call Cust	Follow-up Attempt	Done	2/15/2010 08:56:34 AM	SOCC f/u

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

notify as per Pre-PAR: that a person from the PAR Department will contact the customer within 2 business days.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/15/2010 08:12:03 AM	LAGDAMCL	MARTIRAM	Escalation	Initiate PAR	Done	2/15/2010 09:29:53 AM	Assigning activity to PAR QUEUE

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/12/2010 10:19:09 AM	AGUILOMA	LAGDAMCL	Scheduled Follow-up		Done	2/15/2010 08:06:18 AM	3 IBCC activities still in progress

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/11/2010 02:18:17 AM	LAGDAMCL	LAGDAMCL	Inbound Call Customer	Voice Mail Received	Done	2/15/2010 08:05:13 AM	Cust vmmsg yest 02/10/10 0347 pm fr 28008
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Cust sts:

re SR...; called this am... (reiterates insurance info)...; tried the other #8667905702, but 42783 is wrong in that #...

- Clinton Lagdameo / MAN/ CAC T1/ Email/L1

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/11/2010 02:18:13 AM	LAGDAMCL	LAGDAMCL	Inbound Call Customer	Voice Mail Received	Done	2/15/2010 08:05:58 AM	Cust vmmsg yest 02/10/10 1158 am fr 28056
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Cust sts:

re SR...; forgot to give cel # ... (reiterates insurance info)

- Clinton Lagdameo / MAN/ CAC T1/ Email/L1

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/11/2010 02:17:46 AM	LAGDAMCL	LAGDAMCL	Inbound Call Customer	Voice Mail Received	Done	2/15/2010 08:05:46 AM	Cust vmmsg yest 02/10/10 1154 am fr 28002
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Cust sts:

re SR...; giving policy # fr insurance co Automobile Club; # 8009205798

- Clinton Lagdameo / MAN/ CAC T1/ Email/L1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/10/2010 02:00:48 PM	ESGUERPA	LAGDAMCL	Notify CRM		Done	2/11/2010 02:17:45 AM	performed cb
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

please see previous activity. thank you.

PaulEsguerra/TIER1/email/MANILA/Lv1Emp

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/10/2010 02:00:33 PM	ESGUERPA	ESGUERPA	Outbound Call Customer	Left Message	Done	2/10/2010 02:00:47 PM	customer information
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

left voicemail: adv cust we need information about her insurance company. left message. and contact info

PaulEsguerra/TIER1/email/MANILA/Lv1Emp

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/10/2010 08:07:15 AM	LAGDAMCL	ESGUERPA	Scheduled Outbound Call Cust	Follow-up Attempt	Done	2/10/2010 02:00:31 PM	SOCC fu
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

**Re-ENDORSING TO ACRS: PST

> Conclude PRE-PAR; obtain insurance information

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/9/2010 04:46:08 PM	FLOJORA	LAGDAMCL	Notify CRM	Other	Done	2/10/2010 08:05:52 AM	callback done
Contact Last Name		Contact First Name		Account		BAC Code	
[REDACTED]		[REDACTED]		[REDACTED]		[REDACTED]	
Comments							
- please see previous Outbound Call Customer activity							
- cust will call you in the morning for all required info about the insurance company (if not, you may call her at her home phone anytime)							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/9/2010 03:54:45 PM	FLOJORA	FLOJORA	Outbound Call Customer	Made Contact	Done	2/9/2010 04:46:06 PM	Alleged product allegation-unwanted acceleration
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Cust sts:							
- have had 2 incidents wth this car							
- first was when I parked it outside the church, when I came back, the car wasnt in the place where I left it, instead moved a few feet and ended up in a flower box							
- the second timne was a serious accident							
- was waiting for my friend to come out from the YMCA Bldg, had the gear at Park							
- when she got inside the car, took the gear out of Park and put in into Drive, suddenly without even touching the gas pedal, the car suddenly surged forward and hit the wall of an apartment house 150 ft away, luckily no one was inside, but it left my friend with 2 broken arms, I was unhurt							
- car was totalled, remembered that there were police and paramedics							
- bought the car used about a year and ahalg ago with 41000 miles,							
- dont have info about my insurance with the Auto Clun of California (will call Clinton tomorrow in the morning), they covered my friend's hospital bills but not the car							
Cuiat sks:							
- would like to get this incident investigated, dont want this to happen to someone else							
CRS adv:							
- will be forwarding this info to Clinton, and as soon as he completes all required documentation, will be forwarding said case file to PAR							
RamonFlojo/Mia/CAC-T1/Lv1Emp							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/9/2010 03:50:11 PM	FLOJORA	FLOJORA	Outbound Call Customer	Received No Answer	Done	2/9/2010 03:54:44 PM	f/u. [REDACTED]
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts: (female on the other line)
- am sorry she is not in this classroom

Action Plan:

- wasnt able to leave any message
- will call cust using other phone number

RamonFlojo/Mia/CAC-T1/Lvl1Emp

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/9/2010 04:45:21 AM	LAGDAMCL	LAGDAMCL	Scheduled Outbound Call Cust	Follow-up Attempt	Done	2/9/2010 03:53:05 PM	SOCC f/u 2nd attempt
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Re-ENDORSING TO ACRS; PST

> CONDUCT PRE-PAR...

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/9/2010 04:43:21 AM	LAGDAMCL	LAGDAMCL	Inbound Call Customer	Voice Mail Received	Done	2/9/2010 04:44:36 AM	Cust vmag yest 02/09/10 0207pm fr 28006
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts: [REDACTED] expecting call; will be here rest of the day & tom; hope u call me...

- Clinton Lagdameo / MAN/ CAC T1/ Email/L1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/8/2010 02:07:13 PM	CRUZAL	LAGDAMCL	Notify CRM	Other	Done	2/9/2010 04:43:18 AM	callback done
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/8/2010 02:06:34 PM	CRUZAL	CRUZAL	Outbound Call Customer	Received No Answer	Done	2/8/2010 02:07:12 PM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

no answer

can't leave VM.

Alex CAC/SURVEY /White Mail / Tier 1 MLA LVL 1 ext 42731

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/8/2010 06:09:52 AM	LAGDAMCL	LAGDAMCL	Scheduled Outbound Call Cust	Initial Attempt	Done	2/8/2010 02:04:58 PM	SOCC initial contact
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

ENDORISING TO ACRS; PST

> CONDUCT PRE-PAR...

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/8/2010 06:09:17 AM	LAGDAMCL	LAGDAMCL	Email - Outbound		Done	2/8/2010 06:09:51 AM	RE: Cobalt 2006
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request:
Customer Relationship Specialist: Clinton

Dear [REDACTED]

Thank you for contacting the Chevrolet Customer Assistance Center. We appreciate you taking the time to write us about the resulting accident of your 2006 Chevrolet Cobalt after an unwanted acceleration coming from park.

Based on the nature of your concern, it is apparent that contacting you by phone would allow me a better opportunity to assist you and ensure that I respond to your inquiry to your complete satisfaction. Since you included your phone number in your e-mail, I will be contacting you today, February 8, 2010, between the hours of 9:00 a.m. and 11:00 a.m., Pacific Time (12:00 p.m. and 2:00 p.m., Eastern Time) with hopes that we could resolve this in a timely manner.

If this is not a good time to contact you or if you'd prefer to contact me sooner, please do not hesitate to call me at 1-866-760-5700, extension 42783. I am in the office Monday through Friday from 8:00 a.m. to 11:00 a.m., Eastern Time and would be happy to assist you. If my hours are inconvenient for you, please reply to this e-mail with a date and time that I may contact you, or call our Chevrolet Customer Assistance Center at 1-800-222-1020. Customer Relationship Specialists are available Monday through Saturday from 8:00 a.m. to 9:00 p.m., Eastern Time.

For more information regarding the maintenance and care of your vehicle, please visit <http://www.gmownercenter.com>. This fr...

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/6/2010 09:02:03 AM		LAGDAMCL	Email - Inbound		Done	2/8/2010 06:09:42 AM	Cobalt 2006
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

On December 30,2009 I was involved in a serious car accident.My car was stopped with the gear in Paek and my foot on thr break. When I was ready to move forward I shifted to Drive and removed my foot from the break.At that moment the car speed forward at am uncontrollable speed, I was unable to stop it. I was only stopped by crashing into a wall.
Since I dont have Collision insurance my insurance company woud not pay to find out what happened to the car.
I still have the car parked in my drive way! I NEED HELP.I would likr to have someone who specializes on such problems to come and check the vehide. I dont want this to happen to someone else.

Thank you for your attention

Dpwney, Ca.

Telf

E Mail:

Confidential Comments

UCC Information

UCC Code	Symptom	Description
J42	Unwanted Acceleration	Engine - Throttle Linkage/Pedal

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F767
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN	Warranty Start Date :	09/08/2005
BARS Order Type :	50 - FLEET		
Delivering Dealer :	POWER CHEVROLET LONG BEACH 110 SE 6TH STREET 26TH FLOOR FORT LAUDERDALE , FL 33301-5000 (562) 420-4200	Selling Source :	13 - CHEVROLET
		Site Code :	20036
		Business Associate Code :	114546
Service Contract :	No	Branded Title :	No
Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	07132	SERVICE UPDATE-INV/CUST-OBD SYS IMPROVE-REPROG PCM-EXP W/8YR/80K MILE ECM WARR	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	09/08/2005	10 miles	09/08/2008	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	09/08/2005	10 miles	09/08/2011	100010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	09/08/2005	10 miles	09/08/2013	80010 miles
96/100000 CALIFORNIA SELECT COMPONENT	09/08/2005	10 miles	09/08/2013	100010 miles
36/50000 CALIFORNIA EMISSIONS	09/08/2005	10 miles	09/08/2008	50010 miles
60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	09/08/2005	10 miles	09/08/2010	60010 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
12/27/2007	460102	#	V1629 - 07132 REPROGRAM ENGINE CONTROL MODULE (ECM)	46512 miles
01/05/2007	J09719	#	Z2084 - ROADSIDE SERVICE (FLAT TIRE)	28000 miles
11/06/2006	027848	#	E7200 - IGNITION LOCK CYLINDER REPLACEMENT	23998 miles
11/04/2006	H54436	#	Z2080 - ROADSIDE SERVICE (TOWING)	24000 miles
10/26/2006	027214	#	E7200 - IGNITION LOCK CYLINDER REPLACEMENT	23636 miles
10/26/2006	027214	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)	23636 miles
10/24/2006	027048	#	J0990 - OIL PAN DRAIN PLUG REPLACEMENT	23607 miles
06/19/2006	016626	#	J3100 - RADIATOR REPLACEMENT	20752 miles
06/19/2006	016626	F	Z7200 - CORPORATE PARTS RETURN REIMBURSEMENT	20752 miles
06/19/2006	016673	#	J0518 - HEAD, CYLINDER - REPLACE	20760 miles
06/13/2006	016201	#	J3080 - RADIATOR RECONDITIONING	20751 miles
09/07/2005	A53636	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F767 [REDACTED]
-------	------------------------

CLAIM HISTORY

Repair Order Date :		12/27/2007		Repair Order Number :		460102		Odometer Reading :		46512 miles	
Served By :	SELMAN CHEVROLET COMPANY PO BOX 31 ORANGE, CA 92856-9031 (714) 633-3521					Selling Source :		13 - CHEVROLET			
						Site Code :		20466			
						Business Associate Code :		114576			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
01/04/2008	862	01	#	V1629 - 07132 REPROGRAM ENGINE CONTROL MODULE (ECM)		N/A		N/A	N/A	\$ 32.29	N

Repair Order Date :		01/05/2007		Repair Order Number :		J09719		Odometer Reading :		28000 miles	
Served By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117					Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
01/12/2007	760	01	#	Z2084 - ROADSIDE SERVICE (FLAT TIRE)		N/A		C	N/A	\$ 42.75	N

Repair Order Date :		11/06/2006		Repair Order Number :		027848		Odometer Reading :		23998 miles	
Served By :	MAURICE J. SOPP AND SON PO BOX 311 BELL, CA 90201-0311 (323) 562-8600					Selling Source :			13 - CHEVROLET		
						Site Code :			20039		
						Business Associate Code :			114547		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
				E7200 - IGNITION		15825311 -					

11/21/2006	745	01	#	LOCK CYLINDER REPLACEMENT	CYLINDER	BP	N/A	\$ 144.20	Y
------------	-----	----	---	---------------------------	----------	----	-----	-----------	---

Repair Order Date :		11/04/2006		Repair Order Number :		H54436		Odometer Reading :		24000 miles	
Served By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117					Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
11/10/2006	742	01	#	Z2080 - ROADSIDE SERVICE (TOWING)		N/A		C	N/A	\$ 58.94	N

Repair Order Date :		10/26/2006		Repair Order Number :		027214		Odometer Reading :		23636 miles	
Served By :		MAURICE J. SOPP AND SON PO BOX 311 BELL, CA 90201-0311 (323) 562-8600				Selling Source :		13 - CHEVROLET			
						Site Code :		20039			
						Business Associate Code :		114547			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
11/03/2006	740	01	#	E7200 - IGNITION LOCK CYLINDER REPLACEMENT		15825311 - CYLINDER		B	N/A	\$ 116.75	N
11/03/2006	740	02	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)		N/A		N/A	N/A	\$ 3.79	N

Repair Order Date :		10/24/2006		Repair Order Number :		027048		Odometer Reading :		23607 miles	
Serviced By :	MAURICE J. SOPP AND SON PO BOX 311 BELL, CA 90201-0311 (323) 562-8600					Selling Source :		13 - CHEVROLET			
						Site Code :		20039			
						Business Associate Code :		114547			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
11/03/2006	740	01	#	J0990 - OIL PAN DRAIN PLUG REPLACEMENT		11515757 - BOLT		N/A	N/A	\$ 28.00	Y

Repair Order Date :		06/19/2006	Repair Order Number :	016626	Odometer Reading :	20752 miles
Served	MAURICE J. SOPP AND SON			Selling Source :	13 - CHEVROLET	

By :		PO BOX 311 BELL, CA 90201-0311 (323) 562-8600				Site Code :		20039	
						Business Associate Code :		114547	
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
07/14/2006	708	01	F	Z7200 - CORPORATE PARTS RETURN REIMBURSEMENT	N/A	N/A	N/A	\$ 15.92	Y
06/30/2006	704	01	#	J3100 - RADIATOR REPLACEMENT	22731217 - RADIATOR	B	N/A	\$ 426.21	N

Repair Order Date :		06/19/2006		Repair Order Number :		016673		Odometer Reading :		20760 miles	
Served By :		MAURICE J. SOPP AND SON PO BOX 311 BELL, CA 90201-0311 (323) 562-8600				Selling Source :			13 - CHEVROLET		
						Site Code :			20039		
						Business Associate Code :			114547		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/25/2006	720	01	#	J0518 - HEAD, CYLINDER - REPLACE		12591860 - HEAD		N/A	N/A	\$ 1604.05	N

Repair Order Date :		06/13/2006		Repair Order Number :		016201		Odometer Reading :		20751 miles	
Served By :		MAURICE J. SOPP AND SON PO BOX 311 BELL, CA 90201-0311 (323) 562-8600				Selling Source :			13 - CHEVROLET		
						Site Code :			20039		
						Business Associate Code :			114547		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
06/27/2006	703	01	#	J3080 - RADIATOR RECONDITIONING		22731217 - RADIATOR		P	N/A	\$ 443.55	Y

Repair Order Date :		09/07/2005		Repair Order Number :		A53636		Odometer Reading :		0 miles	
Serviced By :		POWER CHEVROLET LONG BEACH 110 SE 6TH STREET 26TH FLOOR FORT LAUDERDALE, FL 33301-5000 (562) 420-4200				Selling Source :			13 - CHEVROLET		
						Site Code :			20036		
						Business Associate Code :			114546		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
09/13/2005	621	01	I	Z7000 - PRE-DELIVERY		N/A		N/A	N/A	\$ 102.14	N

				INSPECTION - BASE TIME					
--	--	--	--	---------------------------	--	--	--	--	--

CHECK HISTORY**Vehicle Has No Associated Check History.**

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

Help

VIN	1G1AK55F767 [REDACTED]
-----	------------------------

VEHICLE BUILD

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN		
Gross Vehicle Weight Rating :	1708 kg (3766 lb)	Order Number :	JDKPRQ
Build Date :	09/07/2005	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
B0L - GM PRODUCTION WEEK #29	C1U - FLT-ENTERPRISE RENT A CAR
C67 - ELECT. FRONT AIR CONDITIONER	DC8 - MIRROR, O/S MANUAL FLDG, BLK
DT4 - ASHTRAY AND LIGHTER	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FLT - FLEET PROCESSING OPTION	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	JJK - SUSPENSION, REAR INSTALLED
J41 - POWER DISC FRONT BRAKES	K64 - 115 AMP GENERATOR
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	L61 - 2.2L DOHC 4 CYL ENGINE
MN5 - 4 SPEED AUTO TRANSMISSION	MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE
NU3 - EMISSIONS SYSTEM CALIFORNIA, SULEV	N46 - 4 SPOKE STEERING WHEEL
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
R6F - IDENTIFY B-CODE USERS	R6P - PREMIUM PAINT
R9U - GM ACCESS - AUTOBOOK IDENTIFIER	UN0 - AM/FM STEREO W/CD & RDS
UQ4 - BASE SPEAKER SYSTEM	VK3 - FRONT LICENSE PLATE MOUNT
VQ2 - FLEET ORDERING AND ASSISTANCE	VX7 - LONG TERM DAILY RENTAL PROGRAM
V2G - FULL FUEL FILL CREDIT	V73 - STATEMENT OF VEHICLE CERT.- U.S./CANADA
YF5 - CALIFORNIA EMISSIONS	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	15U - SANDSTONE METALLIC

52B - NEUTRAL	52I - GRAY
6AR - FRONT SPRING	7AR - FRONT SPRING
8AA - REAR SPRING	9AA - REAR SPRING

© 2009 General Motors. All Rights Reserved.

TRAFFIC COLLISION REPORT

CHP 555 CARS Page 1 (Rev 8/98) OPI 042

CONFIDENTIAL

Dissemination, distribution, or copying
of this document for unauthorized
purpose is prohibited and punishable!

Page 1 of 4

SPECIAL CONDITIONS PRIVATE PROPERTY		NUMBER PAIRED 2	HT & BLN FELONY	CITY DOWNEY	REPORTING DISTRICT DOWNEY	BEAT 6	LOCAL REPORT NUMBER (b) (6)
COLLISION OCCURRED ON:		MO DAY YEAR TIME (2400)		NOIC #		OFFICER I.D.	
MILEPOST INFORMATION:		12/30/2009 1124		1920		11033	
AT INTERSECTION WITH:		DAY OF WEEK WEDNESDAY		TOW AWAY ☒ YES ☐ NO		PHOTOGRAPHS BY: ☒ NONE	
OR:		STATE HWY REL ☐ YES ☒ NO					
LOCATION	PARTY 1 DRIVER'S LICENSE NUMBER	STATE	CLASS	SAFETY EQUIP.	VEH. YEAR	MAKE / MODEL / COLOR	LICENSE NUMBER
	1	CA	C	G	2006	CHEV COBALT GOL	CA
	DRIVER NAME (FIRST, MIDDLE, LAST)	OWNER'S NAME ☒ SAME AS DRIVER					
	PEDESTRIAN	OWNER'S ADDRESS ☒ SAME AS DRIVER					
PARKED VEHICLE	CITY / STATE / ZIP	DISPOSITION OF VEHICLE ON ORDERS OF: ☐ OFFICER ☒ DRIVER ☐ OTHER					
BI-CYCLIST	SEX HAIR EYES HEIGHT WEIGHT No BIRTHDATE Day Year RACE	AUTO CLUB					
OTHER	HOME PHONE BUSINESS PHONE	PRIOR MECH. DEFECTS ☒ NONE APP. ☐ REFER TO NARRATIVE					
INSURANCE CARRIER	POLICY NUMBER	VEHICLE IDENTIFICATION NUMBER:					
AAA		CHP USE ONLY VEHICLE TYPE 01 DESCRIBE VEHICLE DAMAGE SHADE IN DAMAGED AREA					
DIR OF TRAVEL ON STREET OR HIGHWAY	SPEED LIMIT	CA DOT TOPPSC MCMX					
W PRIVATE PROPERTY		CAL-T					
PARTY 2 DRIVER'S LICENSE NUMBER	STATE	CLASS	SAFETY	VEH. YEAR	MAKE / MODEL / COLOR	LICENSE NUMBER	STATE
2							
DRIVER NAME (FIRST, MIDDLE, LAST)	OWNER'S NAME ☐ SAME AS DRIVER						
PEDESTRIAN	OWNER'S ADDRESS ☐ SAME AS DRIVER						
PARKED VEHICLE	CITY / STATE / ZIP	DISPOSITION OF VEHICLE ON ORDERS OF: ☐ OFFICER ☐ DRIVER ☐ OTHER					
BI-CYCLIST	SEX HAIR EYES HEIGHT WEIGHT No BIRTHDATE Day Year RACE	PRIOR MECHANICAL DEFECTS ☐ NONE APP. ☐ REFER TO NARRATIVE					
OTHER	HOME PHONE BUSINESS PHONE	VEHICLE IDENTIFICATION NUMBER:					
INSURANCE CARRIER	POLICY NUMBER	CHP USE ONLY VEHICLE TYPE DESCRIBE VEHICLE DAMAGE SHADE IN DAMAGED AREA					
DIR OF TRAVEL ON STREET OR HIGHWAY	SPEED LIMIT	CA DOT TOPPSC MCMX					
CONFIDENTIAL		CAL-T					
PARTY 3 DRIVER'S LICENSE NUMBER	STATE	CLASS	SAFETY	VEH. YEAR	MAKE / MODEL / COLOR	LICENSE NUMBER	STATE
3							
DRIVER NAME (FIRST, MIDDLE, LAST)	OWNER'S NAME ☐ SAME AS DRIVER						
PEDESTRIAN	OWNER'S ADDRESS ☐ SAME AS DRIVER						
PARKED VEHICLE	CITY / STATE / ZIP	DISPOSITION OF VEHICLE ON ORDERS OF: ☐ OFFICER ☐ DRIVER ☐ OTHER					
BI-CYCLIST	SEX HAIR EYES HEIGHT WEIGHT No BIRTHDATE Day Year RACE	PRIOR MECHANICAL DEFECTS ☐ NONE APP. ☐ REFER TO NARRATIVE					
OTHER	HOME PHONE BUSINESS PHONE	VEHICLE IDENTIFICATION NUMBER:					
INSURANCE CARRIER	POLICY NUMBER	CHP USE ONLY VEHICLE TYPE DESCRIBE VEHICLE DAMAGE SHADE IN DAMAGED AREA					
DIR OF TRAVEL ON STREET OR HIGHWAY	SPEED LIMIT	CA DOT TOPPSC MCMX					
CAL-T							
PREPARED BY NAME	DISPATCH NOTIFIED	REVIEWER'S NAME					DATE REVIEWED
C MAHER 11033	☒ YES ☐ NO ☐ N/A	JMA					12-31-09

TA000107411

TA000107412

STATE OF CALIFORNIA
INJURED / WITNESSES / PASSENGERS
 CHP 555 CARS Page 3 (Rev 8/98) OPI 042

Page 3 of 4

DATE OF COLLISION (MO. DAY YEAR) 12/30/2009		TIME (2400) 1124		NCIC # 1920		OFFICER I.D. 11033		NUMBER (b) (6)									
WITNESS ONLY	PASSENGER ONLY	AGE	SEX	EXTENT OF INJURY (X ONE)				INJURED WAS (X ONE)				PARTY	SEAT	SAFETY EQUIP.	EJECTED		
				FATAL INJURY	SEVERE INJURY	OTHER VISIBLE INJURY	COMPLAINT OF PAIN	DRIVER	PASS.	YES	NO					YES	NO
☐	☐		F	☐	☐	☒	☐	☐	☒	☐	☐	☐	☐	☐	☐	☐	☐
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED] DOWNEY CA [REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY: DOWNEY FIRE PARAMEDICS																TAKEN TO: DOWNEY REGIONAL MEDICAL CENTER	
DESCRIBE INJURIES: COMPLAINT OF PAIN TO LEFT ARM, RIGHT ARM, AND LOWER LIP																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
#			78	F	☐	☐	☐	☒	☒	☐	☐	☐	☐	☐	☐	☐	0
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED] DOWNEY CA [REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY: DOWNEY FIRE PARAMEDICS																TAKEN TO: DOWNEY REGIONAL MEDICAL CENTER	
DESCRIBE INJURIES: COMPLAINT OF PAIN TO CHEST AND LOWER LIP																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
#					☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY:																TAKEN TO:	
DESCRIBE INJURIES:																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
#					☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY:																TAKEN TO:	
DESCRIBE INJURIES:																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
#					☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY:																TAKEN TO:	
DESCRIBE INJURIES:																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
#					☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	
NAME / D.O.B. / ADDRESS																TELEPHONE	
[REDACTED]																[REDACTED]	
(INJURED ONLY) TRANSPORTED BY:																TAKEN TO:	
DESCRIBE INJURIES:																	
☐ VICTIM OF VIOLENT CRIME NOTIFIED																	
PREPARER'S NAME: C MAHER																	
I.D. NUMBER: 11033				MO. DAY YEAR: 12/30/2009				REVIEWER'S NAME: [Signature]				MO. DAY YEAR: 12/31/09					

DATE OF INCIDENT	TIME	NCIC NUMBER	OFFICER I.D.	NUMBER
12/30/2009	1124	(b) (6)	11033	(b) (6)

1 **AOI #1 (P-1 VS WALL):**

2
3 WEST WALL OF THE SOUTH PARKING LOT OF [REDACTED]

4
5 **SKIDS:**

6
7 NONE

CONFIDENTIAL

Dissemination, distribution, or copying
of this document for unauthorized
purposes is prohibited and unlawful.

8
9 **STATEMENTS:**

10
11 AT THE SCENE OF THE COLLISION, I SPOKE WITH P-1 [REDACTED] P-1 TOLD ME
12 SHE HAD JUST PICKED UP HER FRIEND [REDACTED] IN THE SOUTH PARKING LOT OF
13 [REDACTED] P-1 PUT HER VEHICLE IN DRIVE AND STARTED MOVING
14 FORWARD. SHE ATTEMPTED TO STEP ON THE BRAKE PEDAL AND HER VEHICLE
15 ACCELERATED COLLIDING WITH THE WEST WALL OF THE PARKING LOT, AND THEN
16 INTO A TREE IN THE BACK YARD OF [REDACTED]

17
18 **INVESTIGATION AND OPINION:**

19
20 I OBSERVED MAJOR DAMAGE TO THE FRONT OF P-1'S VEHICLE. I OBSERVED THE
21 COMMON WALL BETWEEN [REDACTED] AND [REDACTED] HAD
22 BEEN KNOCKED DOWN AND P-1'S VEHICLE WAS AT REST AGAINST A TREE. I
23 OBSERVED MINOR DAMAGE TO THE TREE. I OBSERVED MINOR DAMAGE TO THE
24 GARAGE OF [REDACTED] I OBSERVED THREE METAL CHAIRS IN THE YARD
25 OF [REDACTED] WHICH HAD BEEN BROKEN BY P-1'S VEHICLE.

26
27 BASED ON THE DAMAGE AND THE STATEMENT, I DETERMINED THIS TO BE A VEHICLE
28 VERSUS A FIXED OBJECT TYPE COLLISION. DUE TO THE DAMAGE THE VEHICLE
29 SUSTAINED DURING THE COLLISION I WAS UNABLE TO DETERMINE IF THE BRAKES
30 WERE FUNCTIONING PROPERLY. THEREFORE I WAS UNABLE TO DETERMINE IF THE
31 CAUSE OF THIS COLLISION WAS FAULTY BRAKES OR DRIVER ERROR.

32
33 **ACTION TAKEN AND RECOMMENDED:**

34
35 THIS REPORT IS FOR DOCUMENTATION INSURANCE PURPOSES ONLY. NO FURTHER
36 ACTION IS REQUIRED AT THIS TIME.

PREPARED BY	I.D. NUMBER	DATE	REVIEWER'S NAME	DATE
C MAHER	11033	12/30/2009	JM	12-31-09

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Jemeia Price
Claims Administrator

May 11, 2010

[REDACTED]
Downey, CA [REDACTED]

RE: Claimant: [REDACTED]
 Our File No.: 685622
 Our Client: General Motors LLC
 Date/Event: 12/30/09
 Vehicle: 2006 Chevrolet Cobalt
 VIN: 1G1AK55F767 [REDACTED]

Dear [REDACTED],

This will confirm that we have completed our review of your claim regarding your 2006 Chevrolet Cobalt. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Enclosed please find a copy of the air bag data retrieved from the above vehicle.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Jemeia Price
Claims Administrator

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G1AK55F767
User	
Case Number	685622
EDR Data Imaging Date	Thursday, March 18 2010
Crash Date	Wednesday, December 30 2009
Filename	1G1AK55F767_ACM.CDR
Saved on	Thursday, March 18 2010 at 03:24:20 PM
Collected with CDR version	Crash Data Retrieval Tool 3.4
Reported with CDR version	Crash Data Retrieval Tool 3.4
EDR Device Type	airbag control module
Event(s) recovered	Deployment Non-Deployment

Comments

persons:
loc: claimants residence downey, ca
mileage: u/n

lamp: sir continuous

powered: portable battery thru main system

Recorded Crash Events
There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event can be overwritten by an event that has a greater SDM recorded vehicle velocity change.

Data Limitations

This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

- Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.
- Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.
- SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:
 - significant changes in the tire's rolling radius
 - final drive axle ratio changes
 - wheel lockup and wheel slip
- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r001

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**1AK55F*6*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	First Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	51
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	Invalid	Invalid
Cruise Control Resume Switch Active (If Equipped)	Invalid	Invalid
Cruise Control Set Switch Active (If Equipped)	Invalid	Invalid


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	7	12	17	24	32
Engine Speed (RPM)	1408	2752	3264	4288	5568
Percent Throttle	53	52	100	100	100
Accelerator Pedal Position (percent)	50	48	96	96	96
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s²)(If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Deployment

Ignition Cycles At Investigation	9459
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	9458
Ignition Cycles At Event	9459
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Not Suppressed
Automatic Passenger SIR Suppression System Validity Status at First Deployment Command	Valid
Automatic Passenger SIR Suppression System Status at First Deployment Command	Air Bag Not Suppressed
Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	52
Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	68
Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	52
Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	68
Time Between Events (sec)	N/A
Driver First Stage Deployment Loop Commanded	Yes
Driver Second Stage Deployment Loop Commanded	Yes
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	Yes
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	Yes
Passenger Second Stage Deployment Loop Commanded	Yes
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	Yes
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Driver 2nd Stage Deployment Loop Commanded for Disposal	No
Passenger 2nd Stage Deployment Loop Commanded for Disposal	No
Crash Record Locked	Yes
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes




Time (milliseconds)	-70	-60	-50	-40	-30	-20	-10	0	10	20	30	40	50	60	70
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	-1.36	-2.03	-3.39	-5.42	-8.81	-9.49	-11.52	-11.52	-11.52	-11.52	-11.52	-11.52
Time (milliseconds)	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-11.52	-11.52	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00




Time (milliseconds)	-70	-60	-50	-40	-30	-20	-10	0	10	20	30	40	50	60	70
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	-0.68	-0.68	-1.36	0.00	0.00	0.00	0.00	0.00	0.00	0.68
Time (milliseconds)	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220
SDM Lateral Axis Recorded Velocity Change (MPH)	0.68	0.68	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

System Status At Non-Deployment

Ignition Cycles At Investigation	9459
SIR Warning Lamp Status	ON
SIR Warning Lamp ON/OFF Time (seconds)	0
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	0
Ignition Cycles At Event	9459
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Invalid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Not Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	B0052
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	25.89
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	170
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	Yes
Vehicle Event Data (Pre-Crash) Associated With This Event	No
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-1.36	-4.07	-6.78	-10.17	-13.55	-16.94	-18.98	-21.01	-23.04	-23.72	-24.40	-25.07	-25.07	-25.75	-25.75
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-25.75	-25.75	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.68	1.36	0.68	0.68	0.68	1.36	1.36	1.36	2.03	2.03	2.03	2.03
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	2.03	2.71	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 00 00 00 00 57 00 00
$02 30 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 08 00 00 08 90 11
$07 00 08 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 8F 7E 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 40 00 00 00 00 00 00
$0F A0 00 00 00 00 00 00
$10 47 31 41 4B 35 35 46
$11 37 36 37 36 35 33 36
$12 33 36 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 07 07 07 07 00 00 00
$18 07 07 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 00 00 4F 00 01 00
$1F 33 C1 00 00 00 23 00
$20 40 00 00 00 00 00 00
$21 FF FF 00 00 50 00 00
$22 00 92 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 80 00 14 00 00 00 00
$2F 00 FE 24 F3 00 00 00
$30 9D 00 00 00 00 00 00
$31 F6 F6 F6 7A 80 00 00
$32 00 00 00 80 00 00 00
```

\$33 FE FE FE 85 87 00 00
\$34 57 43 33 2B 16 00 00
\$35 34 27 1B 13 0B 00 00
\$36 00 00 00 00 00 00 00
\$37 00 00 00 01 04 00 E2
\$38 65 00 40 00 03 C0 00
\$39 00 00 00 00 00 80 00
\$3A 00 00 00 00 00 80 00
\$3B 03 06 0C 00 00 00 00
\$3C 00 00 00 00 00 00 C0
\$3D 31 41 4B 35 35 46 00
\$3E 36 65 36 36 00 00 00
\$3F 00 00 90 00 00 00 00
\$40 80 A5 00 00 00 00 00
\$41 00 00 00 00 00 00 00
\$42 80 00 00 00 00 00 00
\$43 FE 24 F3 00 00 00 00
\$44 80 52 00 00 00 00 00
\$45 00 00 00 00 00 00 00
\$46 00 00 00 00 00 00 00
\$47 00 FE 00 FA 00 F6 00
\$48 01 F1 02 EC 01 E7 00
\$49 01 E4 01 E1 02 DE 00
\$4A 02 DD 02 DC 03 DB 00
\$4B 03 DB 03 DA 03 DA 00
\$4C 03 DA 04 DA 00 00 00
\$4D 00 00 00 00 00 00 00
\$4E 00 00 00 00 00 00 00
\$4F 00 00 00 00 00 00 00
\$50 00 00 00 00 00 00 00
\$51 D0 00 00 00 00 00 00
\$52 81 00 00 00 00 00 00
\$53 11 05 B4 00 00 00 00
\$54 00 00 00 00 00 00 00
\$55 00 00 00 00 00 00 00
\$67 A0 A5 00 00 00 00 00
\$68 D0 D0 00 00 00 00 00
\$69 00 FF F0 24 F2 00 00
\$6A FE 24 F3 00 00 00 00
\$6B 00 00 00 00 00 00 00
\$6C 00 00 00 00 00 00 00
\$6D 00 00 00 00 00 00 00
\$6E 00 00 00 00 00 00 00
\$6F 00 FE 00 FD FF FB 00
\$70 FF F8 FE F3 00 F2 00
\$71 00 EF 00 EF 00 EF 00
\$72 00 EF 00 EF 01 EF 00
\$73 01 EF 01 EF 00 00 00
\$74 00 00 00 00 00 00 00
\$75 00 00 00 00 00 00 00
\$76 00 00 00 00 00 00 00
\$77 00 00 00 00 00 00 00
\$78 D0 00 00 00 00 00 00
\$79 01 00 00 00 00 00 00
\$7A 02 00 00 00 00 00 00

```
$7B 1A 22 1A 22 00 00 FF

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 35 31 38 31 33 31 4D 53 42
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 05 32 32 38 35 57 44 4C
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 33 19 2A B4 E6 87 91 9A
$22 90 11
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 F0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1A 1A 64 64
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 39 30 31 31 32 31 31 4E 47 47 20 20 20 20
$B7 50 AA 04 0F 03
$B8 41 57 68 09 19
$C1 30 46 30 33
$CA 30 46 30 33
$CB 01 5A D1 33
$CC 01 5A D1 33
$D1 00 00
$DB 00 00
$DC 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.