


EWR D&I ANNOTATION



FAN-000001L103001DP618-4585

Artemis # : 000001L103001DP618**Record Created Date :** 04/22/2011**Printed Date :** 04/25/2011**Description :**

DI11-005. SEQ ID 618. 2010 Q3. WE RECEIVED A CALL LOG AND CRASH DATA FOR A 2007 SATURN ION. THE DRIVER WAS TRAVELLING ON A ROADWAY ABOUT 60MPH WHEN A VEHICLE ON THE RIGHT SIDE SHOULDER CAME INTO HIS LANE AND CUT HIM OFF. HE REAR ENDED THEM. THE DRIVER AND PASSENGER WERE WEARING THEIR SEATBELTS AND ARE WONDERING WHY THE BELTS DID NOT LOCK. THEY ALSO ALLEGE A NON-DEPLOYMENT OF THE AIRBAGS. THE FRONT END OF THE CAR WAS CRUSHED AND THE TWO OCCUPANTS SUFFERED MINOR INJURIES. THE MAXIMUM VELOCITY CHANGE DURING THE IMPACT WAS 8MPH. GM HAS DENIED ANY DEFECT. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DII11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
7	5GALRBED2AJ [REDACTED]	NISM
8	5GALRAEDXAJ [REDACTED]	NISM
19	1G4HD572X7U [REDACTED]	NISM
20	1G4HD57257U [REDACTED]	NISM
21	1G4HR57Y77U [REDACTED]	NISM
23	1G4HA5EM8AU [REDACTED]	NISM
24	1G4HC5EM3AU [REDACTED]	NISM
50	1G6DE5EG6A0 [REDACTED]	NISM
51	1G6DE5EY7B0 [REDACTED]	NISM
68	3GYFNFY9AS [REDACTED]	NISM
73	3GNEC12097G [REDACTED]	LIT
83	KL1TD66638B [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI11-005
618 316870364 – 697440
2007 SATURN ION

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name Sara	Approval	Not Initialed	Area	PAR
Daytime #	Evening #	UCC	Restraints - Seat Belt System /	Sub-Area	Inflate PAR- Injury
Address	City Fortless	Involved Dir	El Paso Saturn, Inc.	Safety	Yes
State TX ZipCd	Con Acct	Source	Phone	Updated	8/24/2010 05:02:43 PM
Serial #VIN 1G8AJ55F472	Model Year 2007	Priority	Medium License #	Owner	CUNNING1
Make Saturn	Warr. Start 09/07/2006	Status	Open	Opened	8/24/2010 04:12:38 PM
Model ION 2	Mileage 50800	Sub-Status	Dissatisfied	Closed	
Abstract Restraints - Seat Belt System / Buckles / Tether Anchor - Failed to Lock					
Customer Description Please Do Not Assume, This is a PAR File, Forward all Inquiries to Patrick at xt 31395					

Pre-PAR

PAR Number	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	8/22/2010 12:50:00 PM	Y	1	2	Asphalt	Dry	Unknown	Unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		4'10"		None				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Unknown	Unknown		USAA Insurance					
Incident Loc	Montana Rd and Lee Trevino Rd, El Paso TX	Incident Desc	A vehicle cut in front of me and I hit them from behind, the seatbelts did not lock and the airbags did not deploy.					
Component	Seatbelts and Airbags	Damage Desc	Front End Crushed					
Vehicle Loc	Sun City Towing, 9365 Escobar Dr, El Paso, TX 79907	Add'l Info	Passenger Address and DOB unknown					
Emgcy Svc Names	El Paso Police Dept El Paso Fire Dept	Maint Loc	Unknown					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	None	
Vehicle Speed	55	Weather Condition	Clear		Prop Owner	N/A	Property Type	N/A	
Last Service Date		Loc Last Service			Property Location	N/A	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	N/A		Prop Damage Description	N/A			
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt		Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	Front End Crushed	Explain Other	Srv Date and Location: Unknown						

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelt
			Medical Rpt#		Treatment Location	Treated By
			Sprained Wrist	Unknown	Del Sol Medical Center, El Paso TX	Unknown Dr.
			Street Address	City	State	Zip Code
			Fortless	TX		
Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	Seatbelt
			Medical Rpt#		Treatment Location	Treated By
			Back and Neck Strain	Unknown	Del Sol Medical Center	Unknown Dr.
			Street Address	City	State	Zip Code

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 06:19:21 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name		Contact First Name		Account	BAC Code		
Comments							
- sprained wrist - went to Del Sol Medical Center, El Paso TX							
- Back and Neck Strain - went to Del Sol Medical Center, El Paso TX							

Joa G/PARIATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 05:09:03 PM	CUNNING1	CUNNING1	Scheduled Follow-up		Scheduled Alarm		ESIS pickup
Contact Last Name		Contact First Name	Account		BAC Code		
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 05:08:54 PM	CUNNING1	GARCIAJR	Notify CRM		Done	8/24/2010 06:18:48 PM	ESIS - Medical Treatment
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 05:02:48 PM	CUNNING1	CUNNING1	BRC PAR	Initial Contact-AVM	Done	8/24/2010 05:08:52 PM	CRS Called RCCDVM Mark Heinz 303-519-2528
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

CRS Left Message: SR#, Cust Name and VIN, involved dir El Paso Saturn, Inc. in El Paso TX, cust alleges vehicle seatbelts and airbags failed during a collision, sending case to esis for processing due to medical treatment, message is for information only, no need to reply, phone# if you have any questions.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 05:00:44 PM	CUNNING1	CUNNING1	BRC PAR	Initial Contact-Dealer	Done	8/24/2010 05:06:24 PM	CRS called Dir Srv Mgr
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

CRS Left Message with Srv Adv

CRS Adv: Cust name and VIN, alleges vehicle airbags and seatbelts failed during a collision, need vehicle history on those systems, case is going to ESIS, they may contact him in the future if they need any assistance. Phone#

Patrick Cunningham/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:54:16 PM	CUNNING1	CUNNING1	BRC PAR	Initial Contact-Phone	Done	8/24/2010 05:00:02 PM	Cust called in to initiate Case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Adv: I need to verify your contact information and the allegation.

Cust sts: Contact information, a vehicle pulled in front of me and I hit them from behind.

CRS Read Required statement

Cust sts: Yes, please proceed.

CRS Adv: Need to get some additional information in regards to your case.

Cust sts: Pre-PAR and PAR Detail Information, A vehicle cut in front of me and I hit them from behind, the seatbelts did not lock and the airbags did not deploy. Both me and my passenger were injured and received treatment. The insurance company has been contacted.

CRS Adv required ESIS statement.

Cust sts: Please send the file.

CRS Adv: Someone from ESIS will contact you with 7-10 business days.

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:53:56 PM	CUNNING1	CUNNING1	BRC PAR	Acknowledgement	Done	8/24/2010 04:54:16 PM	Cust called in to initiate Case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Made Contact

See Initial Contact for Conversation Notes

Patrick Cunningham/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:52:20 PM	CUNNING1	CUNNING1	Research		Done	8/24/2010 04:53:55 PM	Research on VIN
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Research Completed:
No Previous Related Repairs
Recalls - Product Safety Recall N090226 09226 FUEL ODOR OR SPOTTING ON GROUND - REPLACE FUEL PUMP MODULE 01/27/2010 Open
No Other SR's

Patrick Cunningham/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:50:18 PM	CUNNING1	CUNNING1	BRC PAR	Case Assigned	Done	8/24/2010 04:52:20 PM	Case Assigned to Patrick Cunningham X 31395
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:40:39 PM	CUNNING1	CUNNING1	Ownership Changed	Ownership Escalated to BRC	Done	8/24/2010 04:40:39 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:37:58 PM	CUNNING1	CUNNING1	Ownership Changed		Done	8/24/2010 04:37:58 PM	Service Request Ownership has changed FROM: OCANAES TO: CUNNING1
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/24/2010 04:23:17 PM	OCANAES	OCANAES	Inbound Call Customer	Complex Request	Done	8/24/2010 04:31:49 PM	cust alleges was in a wreck and seatbelts and airbags did not deploy or lock
Contact Last Name	Contact First Name	Account	SAC Code				

Comments

cust alleges I was driving and a vehicle on the right side shoulder came into my lane I couldn't avoid him and hit the tail end of the veh the paramedics came to the scene and stated that at the speed the other veh was going as well as the speed I was driving at the seat belts should have locked and the airbags should have deployed. My seatbelt didn't lock and neither did the passengers and neither air bags deployed even on impact. The passenger no suffers from whip lash and a sprain back and you sprain wrist.

crs adv: will transfer you to the appropriate dept

Esmeralda Ocaña/cac/ab/11/ M0

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front
C28	Inoperative	Restraints - Seat Belt System / Buckles / Tether Anchor



Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary



This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable)

For this

-- View V

Vehicle Information

VIN: 1G8AJ55F47Z Model: ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC
Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
Order Type: T - DEALER STOCK
Field Actions: 1 Open

- View V

- View V

- Comp

- View V

- Transa

- Detail

- View V

- Inform

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N090226	09226	FUEL ODOR OR SPOTTING ON GROUND - REPLACE FUEL PUMP MODULE	01/27/2010	Open

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.667.8271) and for XM Radio contact 877.GET.XMST (877.438.9677).

OnStar Equipped: Y

OnStar Status: Inactive

XM Equipped: N

XM Radio ID:

XM Status: NA

OnStar Vehicle Diagnostics: N

DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Saturn 36/36K Bumper to Bumper	07/29/2010	09/07/2006	8 MI	09/07/2009	36,008 MI
	Saturn 72/100K Corrosion	07/29/2010	09/07/2006	8 MI	09/07/2012	100,008 MI
	Saturn 60/100K Powertrain	07/29/2010	09/07/2006	8 MI	09/07/2011	100,008 MI
	Saturn 96/80M Emission select components	07/29/2010	09/07/2006	8 MI	09/07/2014	80,008 MI
	Special Coverage 10187	07/29/2010	09/07/2006	8 MI	09/07/2016	100,008 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
02/15/2010	0148567	ZREG—Regular Vehicle Transaction		Z4631 - 1-DAY CAR RENTAL - SATURN U.S.	47,198 MI
02/15/2010	0148567	ZREG—Regular Vehicle Transaction		L1200 - Fuel Tank Fuel Pump Module Replacement	47,198 MI
12/09/2009	0147792	ZSET—Service Event		I9232 - GM PERFORMANCE - MODULE REPLACE/IGNITION	46,551 MI
08/26/2008	0140882	ZREG—Regular Vehicle Transaction		Z4632 - 2-DAY CAR RENTAL - SATURN U.S.	35,822 MI
08/26/2008	0140882	ZREG—Regular Vehicle Transaction		B4260 - Front Side Door Lock Replacement - Right Side	35,822 MI
08/08/2008	0140570	ZREG—Regular Vehicle Transaction		E7200 - Ignition Lock Cylinder Replacement	35,306 MI
08/08/2008	0140570	ZREG—Regular Vehicle Transaction		Z4633 - 3-DAY CAR RENTAL - SATURN U.S.	35,306 MI
08/08/2008	0140570	ZREG—Regular Vehicle Transaction		E7650 - Module, Ignition Lock Cylinder (Housing) - R&R Or Replace	35,306 MI
06/02/2008	0139318	ZSET—Service Event		D9995 - Customer Concern Not Duplicated - HVAC	33,438 MI
06/02/2008	0139318	ZSET—Service Event		D9995 - Customer Concern Not Duplicated - HVAC	33,438 MI
06/02/2008	0139318	ZSET—Service Event		D9995 - Customer Concern Not Duplicated - HVAC	33,438 MI
12/28/2007	0136303	ZSET—Service Event		M5090 - DETAIL CAR (WAX & BUFF)	25,490 MI
12/11/2007	0135964	ZREG—Regular Vehicle Transaction		E2180 - Insulator And/Or Bracket, Front Stabilizer Shaft At Frame - Replace	25,485 MI
12/11/2007	0135964	ZSET—Service Event		M5090 - DETAIL CAR (WAX & BUFF)	25,485 MI
12/11/2007	0135964	ZSET—Service Event		M5130 - Non-Saturn Accessory Installation	25,485 MI

12/11/2007	0135964	ZSET—Service Event	M5005 - TOP OFF ALL FLUIDS	25,485 MI
12/11/2007	0135964	ZSET—Service Event	M6000 - SATURN USED CAR SERVICE INSPECTION	25,485 MI
09/10/2007	0133960	ZSET—Service Event	M5005 -	20,968 MI
06/29/2007	0132386	ZSET—Service Event	M5025 -	18,566 MI
06/29/2007	0132386	ZSET—Service Event	M5005 -	18,566 MI
05/04/2007	0131160	ZSET—Service Event	M5005 -	15,260 MI
03/16/2007	0130076	ZSET—Service Event	D1345 -	12,077 MI
03/16/2007	0130076	ZSET—Service Event	M5025 -	12,077 MI
03/16/2007	0130076	ZSET—Service Event	M5005 -	12,077 MI
02/02/2007	0129053	ZSET—Service Event	J9995 -	9,204 MI
02/02/2007	0129053	ZSET—Service Event	M5005 -	9,204 MI
12/15/2006	0128127	ZSET—Service Event	M5005 -	5,991 MI
10/27/2006	0127100	ZSET—Service Event	M5005 -	2,854 MI
09/22/2006	0126375	ZREG—Regular Vehicle Transaction	C2021 - Sunshade Replacement - Left Side	964 MI
09/07/2006	0126023	ZSET—Service Event	M5090 -	8 MI
09/07/2006	0126023	ZSET—Service Event	M5200 -	8 MI
09/07/2006	0126023	ZSET—Service Event	J9995 -	8 MI
09/07/2006	0126016	ZSET—Service Event	X0078 -	7 MI
09/07/2006	0126016	ZSET—Service Event	M5165 -	7 MI
09/07/2006	0126016	ZSET—Service Event	M5145 -	7 MI
09/07/2006	0126016	ZSET—Service Event	M5130 -	7 MI
09/07/2006	0126016	ZSET—Service Event	M5130 -	7 MI
06/15/2006	0124146	ZPDI—Pre-Delivery Inspection	Z7000 -	2 MI
06/15/2006	0124146	ZSET—Service Event	M5130 -	2 MI

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors



Mr. GMVIS 2

August 25, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available)

For this

- View V

Vehicle Information

VIN: 1G8AJ55F47Z

Model: ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC

Service Contract No

Branded Title No

Warranty Block No

PDI Status Yes

Order Type: T - DEALER STOCK

Field Actions: [1 Open](#)

- View V

View V

- Comp

View V

- Transa

Detail

View V

Inform

Vehicle Build

Model ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC

Order Number KDTMS6

Gross Vehicle Weight: 0

Build Date: 06/07/2006

Build Plant: Z-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

13L - BRIGHT SILVER METALLIC

13U - SILVER NICKEL

17C - GRAY CLOTH

17I - GRAY

1SZ - DISCOUNT OPTION PKG

24U - AERO BLUE

40U - CREAM WHITE

6AA - SUSPENSION

7AA - SUSPENSION

8AA - SUSPENSION

9AA - SUSPENSION

AK5 - DR & PASS SEAT RESTRAINT SYSTEM

AR9 - DLXE FRT BKT SEAT

B37 - FLOOR MATS FRONT & REAR

BBC - BODY COLOR APPLIQUES

C60 - A/C W/DUST & POLLEN FILTER

D35 - O/S MIRROR

FE1 - SOFT RIDE SUSPENSION SYSTEM

FE9 - FEDERAL EMISSIONS

FY1 - RATIO - 3.63

IPC - TRIM INTERIOR DESIGN

J41 - POWER BRAKE SYSTEM

K62 - 105 AMP GENERATOR

L61 - 2.2L 4CYL DOHC 16V 145 HP ENG. W/DUAL
BALANCE SHAFTS

MN5 - 4 SPEED AUTO TRANS

MX0 - MERCHANDISED TRANS AUTO PROVIS

NK5 - STANDARD STEERING WHEEL

NT7 - EMISSION SYSTEM FEDERAL

P2W - WHEEL COVER, FLUSH SPORT

PG1 - 15" STYLED WHEEL COVERS

QTU - P195/60R15 TOURING TIRES

R6H - SDS CHARGE

R6K - TURN-BY TURN

R6P - SPECIAL PAINT

R7Y - COMMUNICATIONS PLUS

R9N - LEATHER APPOINTMENTS

RF3 - MERCHANDISED PKG SATURN

SLM - SALES PROCESSING STOCK ORDERS

U1C - AM/FM STEREO W/CD & INPUT JACK

UE1 - ONSTAR SERVICE: INCLUDES 1 YEAR SAFE AND
SOUND PLANUH8 - CLUSTER INST, COOL TEMP, TRIP
ODOM, TACH

US6 - FIXED ANTENNA, PAINTED, RADIO

UX7 - SPEAKER SYSTEM 4

V73 - VEHICLE STATEMENT USA/CANADA

VK3 - LICENSE PLATE FRONT FRT

Added Option Codes


#08 - GM Performance - Module Replace/Reprogram

-BA -

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Mr. GMVIS 2

August 25, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary



This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

For this

- View V

Vehicle Information

VIN: 1G8AJ55F47Z

Model: ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions: [1 Open](#)

- View V

View V

Comp

View V

Transa

Detail

View V

Inform

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY

Source Plant: S-

Date Scanned: 06/07/2006

Traceability: 606050503

Part / Number Broadcast: AXD

Time Scanned: 10:22:00

Scan Station:

Component Code: 61-TRANSMISSION

Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO

Date Scanned: 06/07/2006

Traceability: 04D2 EN10

Part / Number Broadcast: 7EHJ

Time Scanned: 10:22:00

Scan Station

Component Code: 86-ELECTRONIC CONTROL MODULE (ECM)

Source Plant: M-DELCO ELECTRONICS MILWAUKEE,
WISCONSIN

Date Scanned: 06/07/2006

Traceability: 06146H4SW

Part / Number Broadcast
YPFB

Time Scanned: 10:22:00

Scan
Station:

Component Code: 87-BODY CONTROL MODULE

Source Plant: 6-

Date Scanned: 06/07/2006

Traceability: 530426146

Part / Number Broadcast: 8903

Time Scanned: 10:22:00

Scan Station:

Component Code: AB-IR-MODULE ASM-INFLATOR

Source Plant: I-INLAND

Date Scanned: 06/06/2006

Traceability: H153D1910

Part / Number Broadcast: 2526

Time Scanned: 21:41:00

Scan Station:

Component Code: AL-IR-MODULE ASM-I/P

Source Plant: I-INLAND

Date Scanned: 06/06/2006

Traceability: 301152026

Part / Number Broadcast: 1596

Time Scanned: 13:30:00

Scan Station:

Component Code: AS-SENSING DIAGNOSTIC MODULE

Source Plant: K-DELCO ELECTRONICS KOKOMO,IN

Date Scanned: 06/07/2006

Traceability: 1614557VW

Part / Number Broadcast: 0731

Time Scanned: 10:22:00

Scan Station:

Component Code: BK-INTERNATIONAL TRANS. CONTROL
MODULE

Source Plant: K-

Date Scanned: 06/07/2006

Traceability: 061460030

Part / Number Broadcast:
YMAR

Time Scanned: 10:22:00

Scan
Station

Component Code: DU—
Source Plant: 2-
Date Scanned: 06/06/2006

Traceability: 65316093
Part / Number Broadcast: 9677
Time Scanned: 13:30:00

Scan Station

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



GlobalWarranty

Mr. GMVIS 2

August 25, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN 1G8AJ55F47Z

Model: ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions: [1. Open](#)

For this:

[View V](#)[-](#)[-](#)[-](#)[View V](#)[View V](#)[Comp](#)[View V](#)[Transa](#)[Detail](#)[View V](#)[Inform](#)

Job Card Date: 02/15/2010

Job Card Number: 0148567

Repair Service Agent: 121781

Odometer Reading: 47,198 MI

SATURN OF EL PASO

Authorization Code: A

7750 GATEWAY BLVD EAST

EL PASO TX 79916-1718

91559119000000

Process Date:

02/17/2010

Transaction Type:

ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Policy

Customer Complaint Code:

0090-No Customer Complaint - Other Issues

Job Card Line # 2

Transaction Adjustment:

Cause Code: 9090-Other - Field Action / Tech Bulletin

Labour Op Z4631-1-DAY CAR RENTAL - SATURN U.S.

Causal Part Number

[See other Parts and/or Net Items](#)

Line Total: USD 37.00

Job Card Date: 02/15/2010

Job Card Number: 0148567

Repair Service Agent: 121781

Odometer Reading: 47,198 MI

SATURN OF EL PASO

Authorization Code:

7750 GATEWAY BLVD EAST

EL PASO TX 79915-1718

91559119000000

Process Date:

02/15/2010

Transaction Type:

ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Warranty

Customer Complaint Code
0324-Engine/Fuel/Exhaust - Excessive Fuel
Consumption

Job Card Line #: 1

Transaction Adjustment: Cause Code: 9090-Other - Field Action /
Tech Bulletin

Labour Op L1200-Fuel Tank Fuel Pump Module Replacement

Causal Part Number 000000000019168894-MODULEKIT,F/TNKF/PMP(W/O

See other Parts and/or Net Items

Line Total: USD 296.92

Job Card Date: 12/09/2009

Job Card Number: 0147792

Repair Service Agent: 121781

Odometer Reading: 46,551 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date:
12/14/2009

Transaction Type:
ZSET---Service Event

Transaction Expense Category:
Service Agent Installed Option

Customer Complaint Code:

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op I9232-GM PERFORMANCE - MODULE REPLACE/IGNITION

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 08/26/2008

Job Card Number: 0140882

Repair Service Agent: 121781

Odometer Reading: 35,822 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date:
08/27/2008

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code
0090-No Customer Complaint - Other
Issues

Job Card Line #: 2

Transaction Adjustment:

Cause Code: 9090-Other - Field Action / Tech
Bulletin

Labour Op Z4632-2-DAY CAR RENTAL - SATURN U.S.

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 74.00

Job Card Date: 08/26/2008

Job Card Number: 0140882

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000Odometer Reading 35,822 MI
Authorization Code:

Process Date:
08/27/2008Transaction Type:
ZREG---Regular Vehicle Transaction
Transaction Expense Category:
WarrantyCustomer Complaint Code:
0890-Interior - Other issues

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 9094-Other - Follow operation

Labour Op B4260-Front Side Door Lock Replacement - Right Side

Causal Part Number 000000000015900268-LOCKASM-FRTS/D

-See other Parts and/or Net ItemsLine Total: USD 116.12

Job Card Date: 08/08/2008

Job Card Number: 0140570

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000Odometer Reading: 35,306 MI
Authorization Code: R

Process Date:
08/12/2008Transaction Type:
ZREG---Regular Vehicle
TransactionTransaction Expense Category:
WarrantyCustomer Complaint Code:
0821-Interior - Instrument Panel

Job Card Line #: 3

Transaction Adjustment:

Cause Code: 2051-Surface (interior) -
Worn/Stripped

Labour Op E7200-Ignition Lock Cylinder Replacement

Causal Part Number 000000000015785084-CYLINDERASM-IGNLK(UNCODED)

-See other Parts and/or Net ItemsLine Total: USD 78.68

Job Card Date: 08/08/2008

Job Card Number: 0140570

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000Odometer Reading 35,306 MI
Authorization Code:

Process Date:
08/11/2008

Transaction Type:
ZREG—Regular Vehicle Transaction
Transaction Expense Category:
Warranty
Customer Complaint Code
0090-No Customer Complaint - Other
issues

Job Card Line #: 2 Transaction Adjustment Cause Code: 9090-Other - Field Action / Tech
Bulletin

Labour Op Z4633-3-DAY CAR RENTAL - SATURN U.S.

Causal Part Number

-See other Parts and/or Net Items

Line Total USD 111.00

Job Card Date: 08/08/2008

Job Card Number: 0140570

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 35,306 MI

Authorization Code: R

Process Date
08/11/2008

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code
0821-Interior - Instrument Panel

Job Card Line #: 1

Transaction Adjustment

Cause Code: 2051-Surface (Interior) -
Worn/Stripped

Labour Op E7650-Module, Ignition Lock Cylinder (Housing) - R&R Or Replace

Causal Part Number 000000000015857948-HOUSINGKIT-IGN&STARTSW

-See other Parts and/or Net Items

Line Total: USD 162.29

Job Card Date: 06/02/2008

Job Card Number: 0139318

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading 33,438 MI

Authorization Code

Process Date:
06/17/2008

Transaction Type:
ZSET—Service Event

Transaction Expense Category
Customer Complaint Code

-

Job Card Line #: 3

Transaction Adjustment:

Cause Code: -

Labour Op D9995-Customer Concern Not Duplicated - HVAC

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 06/02/2008

Job Card Number: 0139318

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 33,438 MI
Authorization Code

Process Date
06/17/2008

Transaction Type:
ZSET—Service Event
Transaction Expense Category:
Customer Complaint Code
-

Job Card Line #: 2 Transaction Adjustment:
Labour Op D9995-Customer Concern Not Duplicated - HVAC
Causal Part Number

Cause Code: -

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 06/02/2008

Job Card Number: 0139318

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 33,438 MI
Authorization Code

Process Date
06/17/2008

Transaction Type:
ZSET—Service Event
Transaction Expense Category:
Customer Complaint Code:
-

Job Card Line #: 1 Transaction Adjustment:
Labour Op D9995-Customer Concern Not Duplicated - HVAC
Causal Part Number

Cause Code: -

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 12/28/2007

Job Card Number: 0136303

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 25,490 MI
Authorization Code

Process Date
12/28/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:
Customer Complaint Code

Job Card Line #: 1 Transaction Adjustment:
Labour Op M5090-DETAIL CAR (WAX & BUFF)
Causal Part Number

Cause Code: -

Line Total: USD 0.00

Job Card Date: 12/11/2007

Job Card Number: 0135964

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 25,485 MI
Authorization Code:

Process Date
04/03/2008

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code:
0126-Drivability - Noise

Job Card Line #: 7 Transaction Adjustment:

Cause Code: 1021-Surface (exterior) -
Damaged/Cracked

Labour Op E2180-Insulator And/Or Bracket, Front Stabilizer Shaft At Frame - Replace

Causal Part Number 00000000015820162-INSULATOR-FRTSTABSHF

--See other Parts and/or Net Items

Line Total: USD 63.53

Job Card Date: 12/11/2007

Job Card Number: 0135964

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 25,485 MI
Authorization Code:

Process Date
04/03/2008

Transaction Type:
ZSET—Service Event

Transaction Expense Category:
Customer Complaint Code

Job Card Line #: 6 Transaction Adjustment:
Labour Op M5090-DETAIL CAR (WAX & BUFF)
Causal Part Number

Cause Code: -

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 12/11/2007**Job Card Number:** 0135964**Repair Service Agent:** 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000**Odometer Reading:** 25,485 MI
Authorization Code:

Process Date:
04/03/2008**Transaction Type:**
ZSET—Service Event**Transaction Expense Category:****Customer Complaint Code:****Job Card Line #** 3**Transaction Adjustment:****Cause Code:** -**Labour Op M5130-Non-Saturn Accessory Installation****Causal Part Number****--See other Parts and/or Net Items****Line Total:** USD 0.00

Job Card Date: 12/11/2007**Job Card Number:** 0135964**Repair Service Agent:** 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000**Odometer Reading:** 25,485 MI
Authorization Code:

Process Date:
04/03/2008**Transaction Type:**
ZSET—Service Event**Transaction Expense Category:****Customer Complaint Code:****Job Card Line #** 2**Transaction Adjustment:****Cause Code:** -**Labour Op M5005-TOP OFF ALL FLUIDS****Causal Part Number****--See other Parts and/or Net Items****Line Total:** USD 0.00

Job Card Date: 12/11/2007**Job Card Number:** 0135964**Repair Service Agent:** 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000**Odometer Reading:** 25,485 MI
Authorization Code:

Process Date:
04/03/2008

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

-

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op M6000-SATURN USED CAR SERVICE INSPECTION

Causal Part Number

-See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 09/10/2007

Job Card Number: 0133960

Repair Service Agent: 121781

Odometer Reading: 20,968 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date:
11/21/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

-See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 06/29/2007

Job Card Number: 0132386

Repair Service Agent: 121781

Odometer Reading: 18,566 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date:
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line # 2

Transaction Adjustment:

Cause Code: -

Labour Op M5025-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 06/29/2007
Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Job Card Number: 0132386
Odometer Reading: 18,566 MI
Authorization Code:

Process Date:
11/20/2007
Transaction Type:
ZSET---Service Event
Transaction Expense Category:
Customer Complaint Code
0000-Converted Claim
Job Card Line #: 1
Labour Op M5005-
Causal Part Number
--See other Parts and/or Net Items

Transaction Adjustment:

Cause Code: -

Line Total: USD 0.00

Job Card Date: 05/04/2007
Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Job Card Number: 0131160
Odometer Reading: 15,260 MI
Authorization Code

Process Date:
11/20/2007
Transaction Type:
ZSET---Service Event
Transaction Expense Category:
Customer Complaint Code:
0000-Converted Claim
Job Card Line #: 1
Labour Op M5005-
Causal Part Number
--See other Parts and/or Net Items

Transaction Adjustment:

Cause Code: -

Line Total: USD 0.00

Job Card Date: 03/16/2007
Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Job Card Number: 0130076
Odometer Reading: 12,077 MI
Authorization Code:

Process Date:
11/20/2007
Transaction Type:
ZSET---Service Event
Transaction Expense Category:
Customer Complaint Code

0000-Converted Claim

Job Card Line #: 3

Transaction Adjustment:

Cause Code: -

Labour Op D1345-

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 03/16/2007

Job Card Number: 0130076

Repair Service Agent: 121781

Odometer Reading: 12,077 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date:

11/20/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code

0000-Converted Claim

Job Card Line #: 2

Transaction Adjustment:

Cause Code: -

Labour Op M5025-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 03/16/2007

Job Card Number: 0130076

Repair Service Agent: 121781

Odometer Reading: 12,077 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date

11/20/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

--See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 02/02/2007

Job Card Number: 0129053

Repair Service Agent: 121781

Odometer Reading: 9,204 MI

SATURN OF EL PASO

Authorization Code:

7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Process Date
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 2

Transaction Adjustment:

Cause Code: -

Labour Op J9995-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 02/02/2007

Job Card Number: 0129053

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 9,204 MI
Authorization Code

Process Date
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 12/15/2006

Job Card Number: 0128127

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 5,991 MI
Authorization Code:

Process Date
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 10/27/2006

Job Card Number: 0127100

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 2,854 MI
Authorization Code

Process Date
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 09/22/2006

Job Card Number: 0126375

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 964 MI
Authorization Code:

Process Date
09/26/2006

Transaction Type:
ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op C2021-Sunshade Replacement - Left Side

Causal Part Number 00000000022728745-SUNSHADEASM

See other Parts and/or Net Items

Line Total: USD 42.19

Job Card Date: 09/07/2006

Job Card Number: 0126023

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 8 MI
Authorization Code:

Process Date
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 3

Transaction Adjustment:

Cause Code: -

Labour Op M5090-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126023

Repair Service Agent: 121781

Odometer Reading: 8 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date:
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 2

Transaction Adjustment:

Cause Code: -

Labour Op M5200-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126023

Repair Service Agent: 121781

Odometer Reading: 8 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date:
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op J9995-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126016

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 7 MI
Authorization Code

Process Date:
11/20/2007Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 5

Transaction Adjustment:

Cause Code: -

Labour Op X0078-

Causal Part Number

-See other Parts and/or Net ItemsLine Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126016

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 7 MI
Authorization Code

Process Date:
11/20/2007Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 4

Transaction Adjustment:

Cause Code: -

Labour Op M5165-

Causal Part Number

-See other Parts and/or Net ItemsLine Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126016

Repair Service Agent: 121781
SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Odometer Reading: 7 MI
Authorization Code

Process Date:
11/20/2007Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 3

Transaction Adjustment:

Cause Code: -

Labour Op M5145-

Causal Part Number

-See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126016

Repair Service Agent: 121781

Odometer Reading: 7 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code

Process Date

11/20/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 2

Transaction Adjustment:

Cause Code: -

Labour Op M5130-

Causal Part Number

Line Total: USD 0.00

Job Card Date: 09/07/2006

Job Card Number: 0126016

Repair Service Agent: 121781

Odometer Reading: 7 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date

11/20/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op M5130-

Causal Part Number

-See other Parts and/or Net Items

Line Total: USD 0.00

Job Card Date: 06/15/2006

Job Card Number: 0124146

Repair Service Agent: 121781

Odometer Reading: 2 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date:
11/20/2007

Transaction Type:
ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op Z7000-

Causal Part Number

Line Total: USD 84.22

Job Card Date: 06/15/2008

Job Card Number: 0124146

Repair Service Agent: 121781

Odometer Reading: 2 MI

SATURN OF EL PASO
7750 GATEWAY BLVD EAST
EL PASO TX 79915-1718
91559119000000

Authorization Code:

Process Date:
11/20/2007

Transaction Type:
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line # 2

Transaction Adjustment:

Cause Code: -

Labour Op M5130-

Causal Part Number


-See other Parts and/or Net Items

Line Total: USD 0.00

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors



Mr. GMVIS 2

August 25, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information



This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

For this

- View v

Vehicle Information

VIN 1G8AJ55F47Z

Model: ZAJ69-2007 ION.2 BASE SEDAN - AUTOMATIC

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions: [1 Open](#)

-

-

-

- View v

View v

Compt

View v

- Transa

Detail

- View v

Informi

Invoice Information

Invoicing Service Agent: 121781

Invoice Date: 09/07/2006

SATURN OF EL PASO

7750 GATEWAY BLVD EAST

EL PASO TX 79915-1718 91559119000000

Ship to Information

Invoicing Service Agent: 121781

Ship to Date: N/A

SATURN OF EL PASO

7750 GATEWAY BLVD EAST

EL PASO TX 79915-1718 91559119000000

Delivery Information

Delivery Service Agent: 121781

Delivery Date: 09/07/2006

SATURN OF EL PASO

Delivery Type:

7750 GATEWAY BLVD EAST

Delivery Odometer: 8

EL PASO TX 79915-1718 91559119000000

In Service Information

Invoicing Service Agent: 2210153

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Kelly Kufel
Claims Administrator

December 15, 2010

[REDACTED]
Fortless, TX [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: 697440
Our Client: General Motors LLC
Date/Event: 8/22/10
Vehicle: 2007 Saturn Ion
VIN: 1G8AJ55F47Z [REDACTED]

Dear Ms. [REDACTED]

This will confirm that we have completed our review of your claim regarding your 2007 Saturn Ion. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Kelly Kufel
Claims Administrator

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G8AJ55F47Z [REDACTED]
User	TONY GENNUSA
Case Number	697440
EDR Data Imaging Date	11/03/2010
Crash Date	08/22/2010
Filename	1G8AJ55F47Z [REDACTED].ACM.CDRX
Saved on	Wednesday, November 3 2010 at 09:51:10
Collected with CDR version	Crash Data Retrieval Tool 3.5.1
Reported with CDR version	Crash Data Retrieval Tool 3.5.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

SUBJECT VEHICLE LOCATED AT COPART, 501 VALLEY CHILE RD., EL PASO, TX.
S/V HAS POWER VIA JUMPER CABLES. KEY ON POWER UP. DOWNLOADED VIA DLC.
S/V MILEAGE: 50,866
S/V AIRBAG LIGHT REMAINS OFF.

Data Limitations

Recorded Crash Events:

There are two types of Recorded Crash Events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). It contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event may be overwritten by another Non-Deployment Event. This event will be cleared by the SDM, after approximately 250 ignition cycle. This event can be overwritten by a second Deployment Event, referred to as a Deployment Level Event, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds before a Deployment Event. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events, if they occur within five seconds of one another. If a Deployment Level Event occurs within five seconds after the Deployment Event, the Deployment Level Event will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Longitudinal Velocity Change reflects the change in longitudinal velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Longitudinal Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 100 milliseconds of data after deployment criteria is met and up to 50 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 150 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module present to send the pre-crash data

-Driver's Belt Switch Circuit Status indicates the status of the driver's seat belt switch circuit. If the vehicle's electrical system is compromised during a crash, the state of the Driver's Belt Switch Circuit may be reported other than the actual state.

-The Time between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events

is greater than five seconds, "N/A" is displayed in place of the time.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-All data should be examined in conjunction with other available physical evidence from the vehicle and scene.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

-Vehicle Speed, Engine Speed, and Percent Throttle data are transmitted by the Powertrain Control Module (PCM), via the vehicle's communication network, to the SDM.

-Brake Switch Circuit Status data is transmitted by either the ABS module or the PCM, via the vehicle's communication network, to the SDM. Depending on vehicle option content, the Brake Switch Circuit Status data may not be available.

-The SDM may obtain Belt Switch Circuit Status data a number of different ways, depending on the vehicle architecture. Some switches are wired directly to the SDM, while others may obtain the data from various vehicle control modules, via the vehicle's communication network.


01014_SDMDW_r002

System Status At Non-Deployment

SIR Warning Lamp Status	OFF
Driver's Belt Switch Circuit Status	BUCKLED
Passenger Belt Switch Circuit Status (If Equipped)	BUCKLED
Driver Seat Position Status (If Equipped)	Forward
Passenger Seat Position Status (If Equipped)	Forward
Passenger SIR Suppression Switch Circuit Status (if equipped)	Air Bag Not Suppressed
Ignition Cycles At Non-Deployment	10620
Ignition Cycles At Investigation	10633
Maximum SDM Recorded Velocity Change (MPH)	-8.00
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	217.5
A Deployment was Commanded Prior to this Event	No
Event Recording Complete	Yes

Seconds Before AE	Vehicle Speed (MPH)	Engine Speed (RPM)	Percent Throttle
-5	62	2176	11
-4	61	2176	0
-3	61	2176	10
-2	59	2112	0
-1	34	960	0

Seconds Before AE	Brake Switch Circuit State
-8	OFF
-7	OFF
-6	OFF
-5	OFF
-4	OFF
-3	OFF
-2	ON
-1	ON



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Recorded Velocity Change	0.00	-0.44	-0.88	-1.32	-1.76	-3.07	-3.95	-5.27	-6.14	-6.58	-7.46	-7.46	-7.90	-7.90	-7.90

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 A0 52 00 00 00 00
$02 AB C3 00 00 00 00
$03 41 53 36 31 34 35
$04 4B 35 37 56 57 31
$05 02 41 00 00 C3 00
$06 15 26 07 31 00 00
$10 FA CE FE 00 00 00
$11 94 00 00 00 00 7F
$12 60 40 FF FF 00 00
$13 0A 00 00 00 00 00
$14 F3 04 ED 05 50 00
$18 7F 7F 80 4A FF 00
$1C 38 FA 41 FA FA FA
$1D FA 38 FA 41 FA FA
$1E FA FA 00 00 00 00
$1F 00 05 00 00 00 00
$20 60 00 00 7D 80 00
$21 FF FF FF FF FF FF
$22 FF FF FF FF 00 00
$23 00 01 02 03 04 07
$24 09 0C 0E 0F 11 11
$25 12 12 12 00 00 00
$26 36 5F 62 62 63 C0
$27 00 00 1A 00 1B 00
$28 0F 21 22 22 22 00
$29 FA D0 F0 00 00 00
$2A 00 00 00 25 00 00
$2B 00 00 00 00 00 00
$2C 00 00 FF 00 02 48
$2D 00 00 00 00 00 00
$2E 00 00 00 00 00 00
$30 FF FF FF FF FF 00
$31 FF FF FF FF FF FF
$32 FF FF FF FF 00 00
$33 FF FF FF FF FF FF
$34 FF FF FF FF FF FF
$35 FF FF FF FF FF FF
$36 FF FF FF FF FF FF
$37 FF FF FF FF FF FF
$38 FF FF FF FF FF 00
$39 FF FF FF FF FF FF
$3A FF FF FF FF FF 00
$3B FF FF FF FF 00 00
$3C FF FF FF FF FF FF
$3D FF FF FF FF 00 00
$3E FF FF FF 00 00 00
$40 FF FF FF FF FF 00
$41 FF FF FF FF FF FF
$42 FF FF FF FF 00 00
$43 FF FF FF 00 00 00
$44 FF 00 00 00 00 00
$50 00 00 00 00 4D 2B
$51 57 AA 00 00 00 00
$60 FF FF FF FF FF FF
$61 FF 00 00 00 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.